

---

---

## MRF24J40 Silicon Errata

---

---

The MRF24J40 RF transceiver you have received conforms functionally to the Device Data Sheet (DS39776C), except for the anomalies described in this document.

### 1. Module: RX MAC

If the RX filter is configured for Promiscuous mode, packets with a reserved packet type in the MAC frame type field may cause the RX module to put an incorrect packet length in the RX buffer.

#### Work around

When operating in Promiscuous mode, flush the RX buffer by setting the RXFLUSH bit (RXFLUSH<0>) after every RX interrupt.

#### Date Codes that pertain to this issue

All engineering and production devices.

### 2. Module: Security Module

When the device is performing encryption or decryption, there is a very small chance that the encryption or decryption result may be incorrect.

#### Work around

During decryption operations, repeat the decryption one or more times if a MIC error is indicated on the first attempt.

During encryption operations, verify the encryption by immediately decrypting the packet and checking it against the original for errors. If an error is found, repeat the encryption and verification.

#### Date Codes that pertain to this issue

All engineering and production devices.

### 3. Module: RX MAC

Under certain conditions, such as channel scanning, unexpected packets may be received at alternative channels spaced at 20 MHz intervals. This occurs when the interfering sources contain sufficient intensity and proximity to the receiver.

For example, if the device is tuned to the 2,425 MHz channel, spurious signals can be detected at 2,405 MHz, 2,445 MHz and 2,465 MHz.

#### Work around

To prevent this system degradation, do one of the following:

- Add a “Channel ID” to the “Frame Payload” of the MAC layer.  
This enables the firmware to filter out unexpected packets.
- Increase the distance between the nodes.
- Reduce the transmitted power of the other nodes.

#### Date Codes that pertain to this issue

All engineering and production devices.

### 4. Module: RX MAC

After initializing the MRF24J40 and after successful reception and transmission of packets, the module suddenly stops receiving packets. At this stage, all register settings, SPI operations, and interrupts appear normal. Performing a reset on the module restores communications.

This issue is seen on a very small percentage (<1%) of MRF24J40 modules (MRF24J40MA, MB, MC, MD, and ME). The issue is random and intermittent, which means that the time of the apparent issue only occurs at random times. A deterministic test has not been found to isolate the issue.

## **Work around**

Please ensure that the Initialization settings for MRF24J40 are used as described in section 3.2 of the MRF24J40 Data Sheet (DS39776C). Specifically, use the following settings for the registers as these control the internal frequency synthesizer in the MRF24J40:

RFCON0 (0x200) = 0x03 - Initialize RFOPT = 0x03

RFCON1 (0x201) = 0x02 - Initialize VCOOPT = 0x02

If the issue persists after performing the settings, one of the following workarounds can be implemented based on the type of customer application:

- Reprogram the channel information (refer to the steps in Programming Channel Information) if the receiver is dormant (without receiving any packets). For example, if the device must receive a packet in a determined amount of time but no packet is received during the specified period, the host MCU can reprogram the channel information to resume packet reception.
- In the customer main application while loop, continuously reprogram the channel information.

Reprogramming channel information resets the internal RF State Machine and enables the module to start communicating with other devices.

## **Programming Channel Information**

Perform the following steps:

1. Program RFCON0 (0x200 <7:4>)
2. Reset RF State Machine  
RFRST (RFCTL 0x36<2>) = 1  
RFRST (RFCTL 0x36<2>) = 0
3. Delay at least 192  $\mu$ s before attempting to transmit a packet to enable the RF circuitry to calibrate. For more information, refer to Section 3.4 of the MRF24J40 Data Sheet.

Applications using MiWi™ Stack can call the MiApp function to perform the programming channel information:

```
MiApp_SetChannel(uint8_t channelNum)
```

## **Date Codes that pertain to this issue**

Issue appears in modules with MRF24J40 date codes from the year 2013 to present.

## **5. Module: RX MAC SLEEP**

Transmission and reception of packets may not be successful under certain conditions, if the WAKE pin on the device is used to wake up the device from sleep.

For example: performing a *sleep* → *Wake-up (using the WAKE pin)* → *Transmission of Packet* on MRF24J40.

## **Work around**

The following is the work around for such scenarios:

1. Perform an external hardware reset, by asserting the  $\overline{\text{RESET}}$  pin 13 low. The MRF24J40 will be released from reset approximately 250  $\mu$ s after the  $\overline{\text{RESET}}$  pin is released.
2. Perform a Software Reset on MRF24J40, SOFTRST (0x2A) = 0x07.
3. Re-initialize the RF configuration in the Application.

Applications using MiWi Stack can call the MiApp function to perform the preceding work around by enabling a macro, which enables the wake up of MRF24J40 using  $\overline{\text{RESET}}$  pin 13.

In the “bool MiMAC\_PowerState(uint8\_t PowerState)” function, modify the case POWER\_STATE\_OPERATE to disable wake up from WAKE pin and enable the wake up from the  $\overline{\text{RESET}}$  pin.

## APPENDIX A: DOCUMENT REVISION HISTORY

### Rev A Document (12/2006)

Original revision. Silicon errata issues 1 (RX MAC), 2 (SPI Interface), 3 (Security Module) and 4 (TX/RX PHY).

### Rev B Document (4/2007)

Added silicon issue 5 (SPI Interface).

### Rev C Document (3/2009)

Removed silicon issues 2 (SPI Interface, SDO pin) and 4 (TX/RX PHY) which were assimilated into the data sheet. Deleted issue 5 (SPI Interface). Added issue 3 (RX MAC).

### Rev D Document (6/2015)

Added silicon issue 4 (RX MAC).

### Rev E Document (5/2019)

Added silicon issue 5 (RX MAC)

---

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

*Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*

**QUALITY MANAGEMENT SYSTEM  
CERTIFIED BY DNV  
= ISO/TS 16949 =**

### Trademarks

The Microchip name and logo, the Microchip logo, AnyRate, AVR, AVR logo, AVR Freaks, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, Helder, JukeBlox, KeeLoq, Klear, LANCheck, LINK MD, maXStylus, maXTouch, MediaLB, megaAVR, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, Prochip Designer, QTouch, SAM-BA, SpyNIC, SST, SST Logo, SuperFlash, tinyAVR, UNI/O, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

ClockWorks, The Embedded Control Solutions Company, EtherSynch, Hyper Speed Control, HyperLight Load, IntellIMOS, mTouch, Precision Edge, and Quiet-Wire are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KlearNet, KlearNet logo, memBrain, Mindi, MiWi, motorBench, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICKit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2018, Microchip Technology Incorporated, All Rights Reserved.  
ISBN: 978-1-5224-4516-6



# MICROCHIP

## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

#### Atlanta

Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

#### Austin, TX

Tel: 512-257-3370

#### Boston

Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

#### Chicago

Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

#### Dallas

Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

#### Detroit

Novi, MI  
Tel: 248-848-4000

#### Houston, TX

Tel: 281-894-5983

#### Indianapolis

Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453  
Tel: 317-536-2380

#### Los Angeles

Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608  
Tel: 951-273-7800

#### Raleigh, NC

Tel: 919-844-7510

#### New York, NY

Tel: 631-435-6000

#### San Jose, CA

Tel: 408-735-9110  
Tel: 408-436-4270

#### Canada - Toronto

Tel: 905-695-1980  
Fax: 905-695-2078

### ASIA/PACIFIC

**Australia - Sydney**  
Tel: 61-2-9868-6733

**China - Beijing**  
Tel: 86-10-8569-7000

**China - Chengdu**  
Tel: 86-28-8665-5511

**China - Chongqing**  
Tel: 86-23-8980-9588

**China - Dongguan**  
Tel: 86-769-8702-9880

**China - Guangzhou**  
Tel: 86-20-8755-8029

**China - Hangzhou**  
Tel: 86-571-8792-8115

**China - Hong Kong SAR**  
Tel: 852-2943-5100

**China - Nanjing**  
Tel: 86-25-8473-2460

**China - Qingdao**  
Tel: 86-532-8502-7355

**China - Shanghai**  
Tel: 86-21-3326-8000

**China - Shenyang**  
Tel: 86-24-2334-2829

**China - Shenzhen**  
Tel: 86-755-8864-2200

**China - Suzhou**  
Tel: 86-186-6233-1526

**China - Wuhan**  
Tel: 86-27-5980-5300

**China - Xian**  
Tel: 86-29-8833-7252

**China - Xiamen**  
Tel: 86-592-2388138

**China - Zhuhai**  
Tel: 86-756-3210040

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444

**India - New Delhi**  
Tel: 91-11-4160-8631

**India - Pune**  
Tel: 91-20-4121-0141

**Japan - Osaka**  
Tel: 81-6-6152-7160

**Japan - Tokyo**  
Tel: 81-3-6880-3770

**Korea - Daegu**  
Tel: 82-53-744-4301

**Korea - Seoul**  
Tel: 82-2-554-7200

**Malaysia - Kuala Lumpur**  
Tel: 60-3-7651-7906

**Malaysia - Penang**  
Tel: 60-4-227-8870

**Philippines - Manila**  
Tel: 63-2-634-9065

**Singapore**  
Tel: 65-6334-8870

**Taiwan - Hsin Chu**  
Tel: 886-3-577-8366

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830

**Taiwan - Taipei**  
Tel: 886-2-2508-8600

**Thailand - Bangkok**  
Tel: 66-2-694-1351

**Vietnam - Ho Chi Minh**  
Tel: 84-28-5448-2100

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**Finland - Espoo**  
Tel: 358-9-4520-820

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Garching**  
Tel: 49-8931-9700

**Germany - Haan**  
Tel: 49-2129-3766400

**Germany - Heilbronn**  
Tel: 49-7131-67-3636

**Germany - Karlsruhe**  
Tel: 49-721-625370

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Germany - Rosenheim**  
Tel: 49-8031-354-560

**Israel - Ra'anana**  
Tel: 972-9-744-7705

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Padova**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Norway - Trondheim**  
Tel: 47-7288-4388

**Poland - Warsaw**  
Tel: 48-22-3325737

**Romania - Bucharest**  
Tel: 40-21-407-87-50

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**Sweden - Gothenberg**  
Tel: 46-31-704-60-40

**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820