

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Errata sheet affecting TLE986x and TLE987x BF step

Infineon Technologies AG
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0
Chairman of the Supervisory Board: Dr. Wolfgang Eder
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider
Registered Office: Neubiberg
Commercial Register: München HRB 126492

N° 092/19

Errata sheet affecting TLE986x and TLE987x BF step

► **Products affected:** Please refer to attached affected product list 1_cip09219

► **Detailed Change Information:**

Subject: Errata sheet affecting TLE986x and TLE987x BF step

Reason: Documented deviation from specification

Description:	<u>Old</u>	<u>New</u>
		see 3_cip09219 errata sheets

► **Product Identification:** not applicable

► **Impact of Change:** No change of product in form, fit and function.

► **Attachments:**
1_cip09219 affected product list
3_cip09219 errata sheets

► **Intended start of delivery:** not applicable

If you have any questions, please do not hesitate to contact your local Sales office.

TLE986xQX Family - BF-Step

TLE987xQX Family - BF-Step

Overview

This document lists the errata of the TLE986xQX family and the TLE987xQX family.

It is strongly recommended that the device behavior and possible proposed workarounds are considered for the application.

Referenced documents:

Table 1 Reference Documents

Document type	Document reference	Issue Date
Data Sheet	see Table 2	
User Manual	TLE986xQX-Users-Manual-14-Infineon.pdf	2019-02-26
User Manual	TLE987xQX-Users-Manual-14-Infineon.pdf	2018-08-03
BootROM User Manual	TLE986xQX-BootROM-User-Manual-14-Infineon.pdf	2016-09-22
BootROM User Manual	TLE987xQX-BootROM-User-Manual-14-Infineon.pdf	2016-09-22

Affected Products, BF-Step only:

Table 2 List of affected products

Device	Reference Data Sheet	Issue Date
TLE9861QXA20	TLE9861QXA20-BF-Data-Sheet-10-Infineon.pdf	2017-03-03
TLE9867QXA20	TLE9867QXA20-BF-Data-Sheet-10-Infineon.pdf	2017-03-03
TLE9867QXA40	TLE9867QXA40-BF-Data-Sheet-10-Infineon.pdf	2017-03-03
TLE9867QXW20	TLE9867QXW20-BF-Data-Sheet-11-Infineon.pdf	2017-03-08
TLE9868QXB20	TLE9868QXB20-BF-Data-Sheet-11-Infineon.pdf	2017-06-19
TLE9869QXA20	TLE9869QXA20-BF-Data-Sheet-10-Infineon.pdf	2017-03-03
TLE9871QXA20	TLE9871QXA20-BF-Data-Sheet-10-Infineon.pdf	2017-03-03
TLE9873QXW40	TLE9873QXW40-BF-Data-Sheet-11-Infineon.pdf	2017-03-13
TLE9877QXA20	TLE9877QXA20-BF-Data-Sheet-10-Infineon.pdf	2017-03-03
TLE9877QXA40	TLE9877QXA40-BF-Data-Sheet-10-Infineon.pdf	2017-02-02
TLE9877QXW40	TLE9877QXW40-BF-Data-Sheet-11-Infineon.pdf	2017-03-23
TLE9879QXA20	TLE9879QXA20-BF-Data-Sheet-10-Infineon.pdf	2017-03-03
TLE9879QXA40	TLE9879QXA40-BF-Data-Sheet-10-Infineon.pdf	2017-02-02
TLE9879QXW40	TLE9879QXW40-BF-Data-Sheet-11-Infineon.pdf	2017-03-23
TLE9879-2QXA40	TLE9879-2QXA40-BF-Data-Sheet-10-Infineon.pdf	2018-01-16

Table of Contents

1	Product Errata	3
1.1	BootROM - USER_NVM_ECC_CHECK (0000048454-124)	3
1.1.1	Workaround	3
1.1.2	Planned Fixes	4
1.2	PORT2 CTRAP active level (0000057330-1)	5
1.2.1	Planned Fixes	5
1.3	CPU->SHPR2 wrong address (0000057330-2)	6
1.3.1	Planned Fixes	7
1.4	MON Wake-up/monitoring threshold voltage (0000048438-7)	7
1.4.1	Planned Fixes	7
1.5	SCU->OSC_CON Bit5 (0000057330-3)	8
1.5.1	Planned Fixes	9
1.6	RESET Pin Pull-up (0000057330-4)	9
1.6.1	Planned Fixes	9
2	Latest documentation information	9
2.1	ADC1 Accuracy (0000057330-8)	9
2.2	ADC2 Accuracy (0000057330-9)	10
2.3	Operational Amplifier (0000057330-10)	10
2.4	DC Parameters of Port 0, Port 1, TMS and Reset (0000057330-11)	10
3	Revision History	11

Product Errata

1 Product Errata

This chapter lists the errata of the referenced products and documentation.

1.1 BootROM - USER_NVM_ECC_CHECK (0000048454-124)

Implemented

The function USER_NVM_ECC_CHECK uses for its operation 32 bytes on the user stack plus 1 byte in user RAM at address 0x18000015, this is not clearly specified in the BootROM User Manual.

1.1.1 Workaround

Adjust the project IRAM settings to exclude this address from the RAM area usable by the linker. In order to maintain memory alignment a hole of four bytes, from 0x18000014 to 0x18000017 is recommended. **Figure 1** displays an example for the TLE9871QXA20. **Table 3** lists the recommended IRAM settings for each device.

Table 3 List of recommended IRAM settings per device

Device	IRAM1 Start	IRAM1 Size	IRAM2 Start	IRAM2 Size
TLE9861QXA20	0x18000018	0xBE8	0x18000000	0x14
TLE9867QXA20	0x18000018	0x17E8	0x18000000	0x14
TLE9867QXA40	0x18000018	0x17E8	0x18000000	0x14
TLE9867QXW20	0x18000018	0x17E8	0x18000000	0x14
TLE9869QXA20	0x18000018	0x17E8	0x18000000	0x14
TLE9871QXA20	0x18000018	0xBE8	0x18000000	0x14
TLE9873QXW40	0x18000018	0xBE8	0x18000000	0x14
TLE9877QXA20	0x18000018	0x17E8	0x18000000	0x14
TLE9877QXA40	0x18000018	0x17E8	0x18000000	0x14
TLE9877QXW40	0x18000018	0x17E8	0x18000000	0x14
TLE9879QXA20	0x18000018	0x17E8	0x18000000	0x14
TLE9879QXA40	0x18000018	0x17E8	0x18000000	0x14
TLE9879QXW40	0x18000018	0x17E8	0x18000000	0x14
TLE9879-2QXA40	0x18000018	0x17E8	0x18000000	0x14




Figure 1 Example IRAM settings for the TLE9871QXA20

1.1.2 Planned Fixes

Fix with next user documentation update.

Product Errata

1.2 PORT2 CTRAP active level (0000057330-1)

Specified

In the Port 2 Input Function table the P2.3 - CTRAP#_1 alternate function is specified to be a high-active input.

Table 10 Port 2 Input Functions

Port Pin	Input/Output	Select	Connected Signal(s)	From/to Module
P2.1	Input	GPI	P2_DATA.P1	
		INP1	CCPOS0_0	CCU6
		INP2	T5INB	GPT12T5
		INP3	T12HR_1	CCU6
		INP4	T5EUDB	GPT12T5
		INP5	CC61_1	CCU6
		ANALOG	AN1	ADC
P2.3	Input	GPI	P2_DATA.P3	
		INP1	CCPOS1_0	CCU6
		INP2	T3IND	GPT12T3
		INP3	CTRAP#_1	CCU6
		INP4	T21EX_2	Timer 21
		INP5	CC60_1	CCU6
		INP6	EXINT0_3	SCU
		ANALOG	AN3	ADC

Figure 2 Extraction from Table 10, specified

Implemented

The P2.3 - CTRAP#_1 alternate function is implemented to be low-active.

Table 10 Port 2 Input Functions

Port Pin	Input/Output	Select	Connected Signal(s)	From/to Module
P2.1	Input	GPI	P2_DATA.P1	
		INP1	CCPOS0_0	CCU6
		INP2	T5INB	GPT12T5
		INP3	T12HR_1	CCU6
		INP4	T5EUDB	GPT12T5
		INP5	CC61_1	CCU6
		ANALOG	AN1	ADC
P2.3	Input	GPI	P2_DATA.P3	
		INP1	CCPOS1_0	CCU6
		INP2	T3IND	GPT12T3
		INP3	CTRAP#_1	CCU6
		INP4	T21EX_2	Timer 21
		INP5	CC60_1	CCU6
		INP6	EXINT0_3	SCU
		ANALOG	AN3	ADC

Figure 3 Extraction from Table 10, implemented

1.2.1 Planned Fixes

Fix with next user documentation update.

Product Errata

1.3 CPU->SHPR2 wrong address (0000057330-2)

Specified

The address of the register SHPR2 is specified wrongly.




Figure 4 Register view of specified SHPR2 register

Implemented

The implemented address for the register SHPR2 is 0xE000ED1C.




Figure 5 Register view of implemented SHPR2 register

Product Errata

1.3.1 Planned Fixes

Fix with next user documentation update.

1.4 MON Wake-up/monitoring threshold voltage (0000048438-7)

Scope

This erratum applies to the following devices only:

- TLE9861QXA20
- TLE9867QXA20
- TLE9867QXA40
- TLE9869QXA20
- TLE9871QXA20
- TLE9877QXA20
- TLE9877QXA40
- TLE9879QXA20
- TLE9879QXA40
- TLE9879-2QXA40

Specified

The MON Wake-up/monitoring threshold is specified without effective temperature range.

Wake-up/monitoring threshold voltage	V_{MONth}	$0.4 \cdot V_S$	$0.5 \cdot V_S$	$0.6 \cdot V_S$	V	Without external serial resistor R_S (with $R_S:DV = I_{PD/PU} \cdot R_S$); $V_S = 5.5V$ to $18V$	P_11.1.1
--------------------------------------	-------------	-----------------	-----------------	-----------------	---	--	----------

Figure 6 Wake-up/Monitoring threshold voltage specified without temperature range

Implemented

The MON Wake-up/monitoring threshold is specified for a temperature range of $T_j = -40^\circ C$ to $85^\circ C$.

Wake-up/monitoring threshold voltage	V_{MONth}	$0.4 \cdot V_S$	$0.5 \cdot V_S$	$0.6 \cdot V_S$	V	Without external serial resistor R_S (with $R_S:DV = I_{PD/PU} \cdot R_S$); $V_S = 5.5V$ to $18V$; $T_j = -40^\circ C$ to $85^\circ C$	P_11.1.1
--------------------------------------	-------------	-----------------	-----------------	-----------------	---	---	----------

Figure 7 Wake-up/Monitoring threshold voltage specified with temperature range

1.4.1 Planned Fixes

Fix with next user documentation update.

Product Errata

1.5 SCU->OSC_CON Bit5 (0000057330-3)

Specified

Bit5 in the register SCU->OSC_CON is mentioned in the User Manual to be read-only with always read as '0'. Furthermore the reset value of this register upon user mode entry is declared to be 0x98.

OSC_CON
OSC Control Register (0B0_H) Reset Value: 10_H

7	6	5	4	3	2	1	0
OSCTRIM_8	Res	Res	XPD	OSC2L	OSCDTRST	OSCSS	
rw	r	r	rw	rh	rwh	rw	

Field	Bits	Type	Description
OSCTRIM_8	7	rw	OSC_PLL Trim Configuration Bit [8] This bit field enables the trimming for the OSC_PLL. User should always set this bit with any write. This bit is a protected bit. When the Protection Scheme is activated, this bit cannot be written directly. For more information on Protection Scheme, see Section 6.12 .
Res	6	r	Reserved This bit field is always read as zero.
Res	5	r	Reserved This bit field is always read as zero.

Figure 8 Extraction of the specified OSC_CON register

Implemented

The Bit5 of the register SCU->OSC_CON is always read as '1'. In case of a write access to OSC_CON the Bit5 should remain set. The reset value upon user mode entry is 0xB8.

OSC_CON
OSC Control Register (0B0_H) Reset Value: 10_H

7	6	5	4	3	2	1	0
OSCTRIM_8	Res	Res	XPD	OSC2L	OSCDTRST	OSCSS	
rw	r	rw	rw	rh	rwh	rw	

Field	Bits	Type	Description
OSCTRIM_8	7	rw	OSC_PLL Trim Configuration Bit [8] This bit field enables the trimming for the OSC_PLL. User should always set this bit with any write. This bit is a protected bit. When the Protection Scheme is activated, this bit cannot be written directly. For more information on Protection Scheme, see Section 6.12 .
Res	6	r	Reserved This bit field is always read as zero.
Res	5	rw	Reserved User should always set this bit with any write. This bit is a protected bit. When the Protection Scheme is activated, this bit cannot be written directly. For more information on Protection Scheme, see Section 6.12 .

Figure 9 Extraction of the implemented OSC_CON register

Latest documentation information

1.5.1 Planned Fixes

Fix with next user documentation update.

1.6 RESET Pin Pull-up (0000057330-4)

Specified

Figure 10 shows an extraction of Table 2 of the Pin Definitions and Functions. The column “Reset State” defines the state of the pin in the reset condition of the device.

Table 2 Pin Definitions and Functions

Symbol	Pin Number	Type	Reset State ¹⁾	Function
RESET	22	I/O	–	Reset input, not available during Sleep Mode

Figure 10 Extraction of Table 2, specified RESET pin conditions

Implemented

Figure 11 shows an extraction of Table 2 of the Pin Definitions and Functions. In the device reset condition the RESET pin is either being pulled low from external or driven low from internal, the device furthermore implements an internal pull-up which prevents the RESET pin from floating.

Table 2 Pin Definitions and Functions

Symbol	Pin Number	Type	Reset State ¹⁾	Function
RESET	22	I/O	PU	Reset input, not available during Sleep Mode

Figure 11 Extraction of Table 2, implemented RESET pin conditions

1.6.1 Planned Fixes

Fix with next user documentation update.

2 Latest documentation information

This chapter provides extended information on referenced documentation.

2.1 ADC1 Accuracy (0000057330-8)

The accuracies stated include the ADC1 total unadjusted error (TUE_{10B}) which includes the V_{AREF} tolerance. This applies to the following specification items:

- P_8.1.39
- P_8.1.71
- P_8.1.74
- P_8.1.77¹⁾
- P_8.1.78¹⁾
- P_8.1.80¹⁾

2.2 ADC2 Accuracy (0000057330-9)

The accuracies stated include the following tolerance:

- ADC2 offset error - P_8.3.19
- ADC2 gain error - P_8.3.20
- ADC2 differential non-linearity error - P_8.3.28¹⁾
- ADC2 integral non-linearity error - P_8.3.29¹⁾
- V_{BG} - P_8.3.1

This applies to the following specification items:

- P_8.1.70
- P_8.1.73
- P_8.1.44
- P_8.1.47
- P_8.1.62
- P_8.1.68
- P_8.1.5
- P_8.1.48
- P_8.1.6
- P_8.2.5
- P_8.2.6
- P_8.2.7
- P_8.1.75¹⁾

2.3 Operational Amplifier (0000057330-10)

In the referenced data sheet, chapter 29.13.1 the used footnotes are:

1. Typical $V_{ZERO} = 0.4 * VAREF$
2. This parameter is not subject to production test.

2.4 DC Parameters of Port 0, Port 1, TMS and Reset (0000057330-11)

Table 31 in the referenced data sheet applies as well to TMS and Reset.

1) applies to Grade 0 devices only

Revision History

3 Revision History

Revision	Date	Changes
1.0	2017-05-17	Errata obsolete
1.1	2018-05-02	Errata obsolete
		ADC1 Accuracy Addendum
		ADC2 Accuracy Addendum
1.2	2019-09-17	BootROM - USER_NVM_ECC_CHECK (0000048454-124) added
		PORT2 CTRAP active level (0000057330-1) added
		CPU->SHPR2 wrong address (0000057330-2) added
		MON Wake-up/monitoring threshold voltage (0000048438-7) added
		SCU->OSC_CON Bit5 (0000057330-3) added
		RESET Pin Pull-up (0000057330-4) added
		Operation Amplifier (0000057330-10) added
		DC Parameters of Port 0, Port 1, TMS and Reset (0000057330-11) added
		ADC1 Accuracy (0000057330-8) added
		ADC2 Accuracy (0000057330-9) added

Trademarks of Infineon Technologies AG

All referenced product or service names and trademarks are the property of their respective owners.

Edition 2019-09-17

Published by

Infineon Technologies AG

81726 Munich, Germany

© 2019 Infineon Technologies AG.

All Rights Reserved.

Do you have a question about any aspect of this document?

Email: erratum@infineon.com

Document reference

<Doc_Number>

IMPORTANT NOTICE

The information contained in this application note is given as a hint for the implementation of the product only and shall in no event be regarded as a description or warranty of a certain functionality, condition or quality of the product. Before implementation of the product, the recipient of this application note must verify any function and other technical information given herein in the real application. Infineon Technologies hereby disclaims any and all warranties and liabilities of any kind (including without limitation warranties of non-infringement of intellectual property rights of any third party) with respect to any and all information given in this application note.

The data contained in this document is exclusively intended for technically trained staff. It is the responsibility of customer's technical departments to evaluate the suitability of the product for the intended application and the completeness of the product information given in this document with respect to such application.

For further information on technology, delivery terms and conditions and prices, please contact the nearest Infineon Technologies Office (www.infineon.com).

WARNINGS

Due to technical requirements products may contain dangerous substances. For information on the types in question please contact your nearest Infineon Technologies office.

Except as otherwise explicitly approved by Infineon Technologies in a written document signed by authorized representatives of Infineon Technologies, Infineon Technologies' products may not be used in any applications where a failure of the product or any consequences of the use thereof can reasonably be expected to result in personal injury.



Sales name	SP number	OPN	Package
TLE9861QXA20	SP001583362	TLE9861QXA20XUMA2	PG-VQFN-48
TLE9867QXA20	SP001583368	TLE9867QXA20XUMA2	PG-VQFN-48
TLE9867QXA40	SP001583374	TLE9867QXA40XUMA2	PG-VQFN-48
TLE9867QXW20	SP001380954	TLE9867QXW20XUMA1	PG-VQFN-48
TLE9868QXB20	SP001404498	TLE9868QXB20XUMA2	PG-VQFN-48
TLE9869QXA20	SP001583382	TLE9869QXA20XUMA2	PG-VQFN-48
TLE9871QXA20	SP001583398	TLE9871QXA20XUMA2	PG-VQFN-48
TLE9873QXW40	SP001380956	TLE9873QXW40XUMA1	PG-VQFN-48
TLE9877QXA20	SP001583420	TLE9877QXA20XUMA2	PG-VQFN-48
TLE9877QXA40	SP001583424	TLE9877QXA40XUMA2	PG-VQFN-48
TLE9877QXW40	SP001380958	TLE9877QXW40XUMA1	PG-VQFN-48
TLE9879-2QXA40	SP001611352	TLE98792QXA40XUMA1	PG-VQFN-48
TLE9879QXA20	SP001583428	TLE9879QXA20XUMA2	PG-VQFN-48
TLE9879QXA40	SP001583434	TLE9879QXA40XUMA2	PG-VQFN-48
TLE9879QXW40	SP001380960	TLE9879QXW40XUMA1	PG-VQFN-48