



Product Change Notification / SYST-24BTCZ526

Date:

26-Nov-2020

Product Category:

8-bit Microcontrollers

PCN Type:

Document Change

Notification Subject:

ERRATA - PIC16(L)F18424/44/25/45 Family Silicon Errata and Data Sheet Clarification

Affected CPNs:

[SYST-24BTCZ526_Affected_CPN_11262020.pdf](#)

[SYST-24BTCZ526_Affected_CPN_11262020.csv](#)

Notification Text:

SYST-24BTCZ526

Microchip has released a new Product Documents for the PIC16(L)F18424/44/25/45 Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [PIC16\(L\)F18424/44/25/45 Family Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change:

This revision includes the following updates to Data Sheet Clarifications:

- 1) Adding Silicon issue 1.2.2 for Electrical Spec
- 2) Other minor corrections.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 26 Nov 2020

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

PIC16(L)F18424/44/25/45 Family Silicon Errata and Data Sheet Clarification

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

PIC16F18424-E/JQ
PIC16F18424-E/P
PIC16F18424-E/SL
PIC16F18424-E/ST
PIC16F18424-E/STVAO
PIC16F18424-I/JQ
PIC16F18424-I/P
PIC16F18424-I/SL
PIC16F18424-I/ST
PIC16F18424T-E/SL
PIC16F18424T-E/STVAO
PIC16F18424T-I/JQ
PIC16F18424T-I/SL
PIC16F18424T-I/ST
PIC16F18425-E/JQ
PIC16F18425-E/P
PIC16F18425-E/SL
PIC16F18425-E/ST
PIC16F18425-E/STVAO
PIC16F18425-I/JQ
PIC16F18425-I/P
PIC16F18425-I/SL
PIC16F18425-I/ST
PIC16F18425T-E/STV01
PIC16F18425T-E/STVAO
PIC16F18425T-I/JQ
PIC16F18425T-I/SL
PIC16F18425T-I/ST
PIC16F18444-E/GZ
PIC16F18444-E/P
PIC16F18444-E/SO
PIC16F18444-E/SS
PIC16F18444-I/GZ
PIC16F18444-I/P
PIC16F18444-I/SO
PIC16F18444-I/SS
PIC16F18444T-I/GZ
PIC16F18444T-I/SO
PIC16F18444T-I/SS
PIC16F18445-E/GZ
PIC16F18445-E/P
PIC16F18445-E/SO
PIC16F18445-E/SS
PIC16F18445-E/SSVAO
PIC16F18445-I/GZ
PIC16F18445-I/P

PIC16F18445-I/SO
PIC16F18445-I/SS
PIC16F18445T-I/GZ
PIC16F18445T-I/SO
PIC16F18445T-I/SS
PIC16LF18424-E/JQ
PIC16LF18424-E/P
PIC16LF18424-E/SL
PIC16LF18424-E/ST
PIC16LF18424-I/JQ
PIC16LF18424-I/P
PIC16LF18424-I/SL
PIC16LF18424-I/ST
PIC16LF18424T-I/JQ
PIC16LF18424T-I/SL
PIC16LF18424T-I/ST
PIC16LF18425-E/JQ
PIC16LF18425-E/P
PIC16LF18425-E/SL
PIC16LF18425-E/ST
PIC16LF18425-I/JQ
PIC16LF18425-I/JQVAO
PIC16LF18425-I/P
PIC16LF18425-I/SL
PIC16LF18425-I/ST
PIC16LF18425T-I/JQ
PIC16LF18425T-I/JQVAO
PIC16LF18425T-I/SL
PIC16LF18425T-I/ST
PIC16LF18444-E/GZ
PIC16LF18444-E/P
PIC16LF18444-E/SO
PIC16LF18444-E/SS
PIC16LF18444-I/GZ
PIC16LF18444-I/P
PIC16LF18444-I/SO
PIC16LF18444-I/SS
PIC16LF18444T-I/GZ
PIC16LF18444T-I/SO
PIC16LF18444T-I/SS
PIC16LF18445-E/GZ
PIC16LF18445-E/P
PIC16LF18445-E/SO
PIC16LF18445-E/SS
PIC16LF18445-I/GZ
PIC16LF18445-I/P
PIC16LF18445-I/SO
PIC16LF18445-I/SS
PIC16LF18445T-I/GZ

PIC16LF18445T-I/SO

PIC16LF18445T-I/SS

PIC16(L)F18424/44/25/45 Family Silicon Errata and Data Sheet Clarification

Preface

The PIC16(L)F18424/44 and PIC16(L)F18425/45 devices that you have received conform functionally to the current device data sheet (www.microchip.com/DS40002002 and www.microchip.com/DS40002000), except for the anomalies described in this document. The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in the table below. The errata described in this document will be addressed in future revisions of the PIC16(L)F18424/44 and PIC16(L)F18425/45 silicon.



Notice: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of the 'Silicon Issue Summary' table apply to the current silicon revision (A1).

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate website (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:


1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
 - 4.1. For MPLAB IDE 8, select *Programmer > Reconnect*.
 - 4.2. For MPLAB X IDE, select *Window > Dashboard* and click the **Refresh Debug Tool Status** icon (.
5. Depending on the development tool used, the part number and Device Revision ID value appear in the **Output** window.

Table 1. Silicon Device Identification

Part Number	Device ID	Revision ID
		A1
PIC16F18424/25	0x30CA/0x30CC	0x8005
PIC16LF18424/25	0x30CB/0x30CD	0x8005
PIC16F18444/45	0x30CE/0x30D0	0x8005
PIC16LF18444/45	0x30CF/0x30D1	0x8005
Note: Refer to the Device/Revision ID section in the current " <i>PIC16(L)F184XX Memory Programming Specification</i> " (DS40001970) for a detailed information on Device Identification and Revision IDs for your specific device.		

Silicon Issue Summary

Module	Feature	Item No.	Issue Summary	Affected Revisions
				A1
NVM	WRERR bit Operation	1.1.1	NVMERR bit is set by device Reset after being cleared by software.	X
Electrical Specifications	Minimum V _{DD} Specification	1.2.1	VDDMIN specifications are changed for LF devices only.	X
	PFM Endurance	1.2.2	The PFM endurance is lower than specified.	X
Analog-to-Digital Converter With Computation (ADC ²)	ADC ² Burst Average mode	1.3.1	ADC ² Burst Average mode while in "Non-continuous Double Sample" mode is buggy.	X
Windowed Watchdog Timer	Window Operation	1.4.1	Window feature of the WWDT does not operate correctly in DOZE mode	X
Note: Only those issues indicated in the last column apply to the current silicon revision.				

1. Silicon Errata Issues



Notice: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the bold font in the following tables apply to the current silicon revision.

1.1 Module: Nonvolatile Memory (NVM)

1.1.1 WRERR Bit Operation

When a Reset is issued while an NVM high voltage operation is in progress, the WRERR bit in the NVMCON1 register is set as expected. After clearing the WRERR bit, if a Reset reoccurs, the WRERR bit is set again regardless of whether an NVM operation is in progress or not. A successful write operation will clear the WRERR condition.

Work around

None.

Affected Silicon Revisions

A1							
X							

1.2 Module: Electrical Specifications

1.2.1 Minimum V_{DD} Specification for LF Devices

V_{DD_MIN} at -40°C to 25°C = 2.3V.

Table 1-1. Supply Voltage

PIC16(L)F18424/44/25/45			Standard Operating Conditions (Unless Otherwise Stated)				
Param. No.	Sym.	Characteristic	Min.	Typ.	Max.	Units	Conditions
D002	VDD		1.8	-	3.6	V	FOSC ≤ 16 MHz, TA > 25°C
			2.3	-	3.6	V	FOSC ≤ 16 MHz, -40°C ≤ TA ≤ 25°C
			2.5	-	3.6	V	FOSC > 16 MHz

Work around

None.

Affected Silicon Revisions

A1							
X							

1.2.2 Endurance of PFM is Lower than Specified

The minimum value for the Program Flash Memory (PFM) endurance specification called out as parameter number MEM30 is 1K cycles.

Work around

None.

Affected Silicon Revisions

A1							
X							

1.3 Module: Analog-to-Digital Converter with Computation (ADCC)

1.3.1 ADCC Burst Average Mode

When the ADCC is operated in Burst Average mode (ADMD = 0b011 in the ADCON2 register) while enabling non-continuous operation and double-sampling (ADCONT = 0 in the ADCON0 register and ADDSEN = 1 in the ADCON1 register), the value in the ADCNT register does not increment beyond '0b1' toward the value in the ADRPT register.

Work around

When operating the ADCC in Burst Average mode with double-sampling, enable continuous operation of the module (ADCONT = 1 in the ADCON0 register) and set the Stop-on-Interrupt bit (the ADSOI bit in the ADCON3 register). After the interrupt occurs, perform appropriate threshold calculations in the software and retrigger ADCC as necessary.

Alternatively, if the CPU is in Low-Power Sleep mode, the ADCC in non-continuous Burst-Average mode can be operated with a single ADC conversion (ADDSEN = 0 in the ADCON1 register). Doing so compromises noise immunity for lower power consumption by preventing the device from waking up to perform threshold calculations in the software.

Affected Silicon Revisions

A1							
X							

1.4 Module: Windowed Watchdog Timer (WWDT)

1.4.1 Window Operation in Doze Mode

When the windowed mode of operation is enabled in Doze mode, a window violation error is issued even though the window is open and has been armed. This condition occurs only when the window size is set to a value other than 100% open.

Work around

Method 1:

Use the windowed mode of operation in any other than Doze mode. If disabling the Doze mode is not an option, use the WWDT module without the window being enabled.

Method 2:

If the device is in Doze mode, perform the arming process for the window in Normal mode and return to the Doze mode.

Method 3:

If there is an Interrupt Service Routine (ISR) in the application code, the arming within the window can be done inside the ISR with the ROI bit of the CPUDOZE register being set.

Affected Silicon Revisions

A1							
X							

2. Appendix A: Revision History

Doc Rev.	Date	Comments
B	11/2020	Adding Silicon issue 1.2.2 for Electrical Spec; Other minor corrections.
A	07/2018	Initial document release.

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods being used in attempts to breach the code protection features of the Microchip devices. We believe that these methods require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Attempts to breach these code protection features, most likely, cannot be accomplished without violating Microchip's intellectual property rights.
- Microchip is willing to work with any customer who is concerned about the integrity of its code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable." Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Legal Notice

Information contained in this publication is provided for the sole purpose of designing with and using Microchip products. Information regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL OR CONSEQUENTIAL LOSS, DAMAGE, COST OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICKit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SMART-I.S., storClad, SQL, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2020, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-5224-7112-7

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.

Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: www.microchip.com/support Web Address: www.microchip.com	Australia - Sydney Tel: 61-2-9868-6733 China - Beijing Tel: 86-10-8569-7000 China - Chengdu Tel: 86-28-8665-5511 China - Chongqing Tel: 86-23-8980-9588 China - Dongguan Tel: 86-769-8702-9880 China - Guangzhou Tel: 86-20-8755-8029 China - Hangzhou Tel: 86-571-8792-8115 China - Hong Kong SAR Tel: 852-2943-5100 China - Nanjing Tel: 86-25-8473-2460 China - Qingdao Tel: 86-532-8502-7355 China - Shanghai Tel: 86-21-3326-8000 China - Shenyang Tel: 86-24-2334-2829 China - Shenzhen Tel: 86-755-8864-2200 China - Suzhou Tel: 86-186-6233-1526 China - Wuhan Tel: 86-27-5980-5300 China - Xian Tel: 86-29-8833-7252 China - Xiamen Tel: 86-592-2388138 China - Zhuhai Tel: 86-756-3210040	India - Bangalore Tel: 91-80-3090-4444 India - New Delhi Tel: 91-11-4160-8631 India - Pune Tel: 91-20-4121-0141 Japan - Osaka Tel: 81-6-6152-7160 Japan - Tokyo Tel: 81-3-6880-3770 Korea - Daegu Tel: 82-53-744-4301 Korea - Seoul Tel: 82-2-554-7200 Malaysia - Kuala Lumpur Tel: 60-3-7651-7906 Malaysia - Penang Tel: 60-4-227-8870 Philippines - Manila Tel: 63-2-634-9065 Singapore Tel: 65-6334-8870 Taiwan - Hsin Chu Tel: 886-3-577-8366 Taiwan - Kaohsiung Tel: 886-7-213-7830 Taiwan - Taipei Tel: 886-2-2508-8600 Thailand - Bangkok Tel: 66-2-694-1351 Vietnam - Ho Chi Minh Tel: 84-28-5448-2100	Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393 Denmark - Copenhagen Tel: 45-4485-5910 Fax: 45-4485-2829 Finland - Espoo Tel: 358-9-4520-820 France - Paris Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79 Germany - Garching Tel: 49-8931-9700 Germany - Haan Tel: 49-2129-3766400 Germany - Heilbronn Tel: 49-7131-72400 Germany - Karlsruhe Tel: 49-721-625370 Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44 Germany - Rosenheim Tel: 49-8031-354-560 Israel - Ra'anana Tel: 972-9-744-7705 Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781 Italy - Padova Tel: 39-049-7625286 Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340 Norway - Trondheim Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820