



Product Change Notification / SYST-01AYJC109

Date:

02-Apr-2021

Product Category:

16-Bit - Microcontrollers and Digital Signal Controllers

PCN Type:

Document Change

Notification Subject:

ERRATA - PIC24FJ1024GA610/GB610 Family Silicon Errata and Data Sheet Clarification

Affected CPNs:

[SYST-01AYJC109_Affected_CPN_04022021.pdf](#)

[SYST-01AYJC109_Affected_CPN_04022021.csv](#)

Notification Text:

SYST-01AYJC109

Microchip has released a new Product Documents for the PIC24FJ1024GA610/GB610 Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [PIC24FJ1024GA610/GB610 Family Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change: 1) Added silicon issue 21 (Power).

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 02 Apr 2021

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[PIC24FJ1024GA610/GB610 Family Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

**MICROCHIP****PIC24FJ1024GA610/GB610 FAMILY**

PIC24FJ1024GA610/GB610 Family Silicon Errata and Data Sheet Clarification

The PIC24FJ1024GA610/GB610 family devices conform functionally to the current Device Data Sheet (DS30010074G), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).

The errata described in this document will be addressed in future revisions of the PIC24FJ1024GA610/GB610 family silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (**A6**).

Data Sheet clarifications and corrections start on [page 11](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers and emulation tools, which are available at the Microchip corporate website (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
 - a) For MPLAB IDE 8, select *Programmer > Reconnect*.
 - b) For MPLAB X IDE, select *Window > Dashboard* and click the **Refresh Debug Tool Status** icon ().
5. Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC24FJ1024GA610/GB610 family silicon revisions are shown in [Table 1](#).

TABLE 1: SILICON DEVREV VALUES

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾				
		A2	A3	A4	A5	A6
PIC24FJ128GA606	6000h	0x02	0x03	0x04	0x05	0x06
PIC24FJ256GA606	6008h					
PIC24FJ512GA606	6010h					
PIC24FJ1024GA606	6018h					
PIC24FJ128GA610	6001h					
PIC24FJ256GA610	6009h					
PIC24FJ512GA610	6011h					
PIC24FJ1024GA610	6019h					
PIC24FJ128GB606	6004h					
PIC24FJ256GB606	600Ch					

Note 1: The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format "DEVID DEVREV".

2: Refer to the "PIC24FJ1024GA610/GB610 Family Flash Programming Specification" (DS30010057) for detailed information on Device and Revision IDs for your specific device.

PIC24FJ1024GA610/GB610 FAMILY

TABLE 1: SILICON DEVREV VALUES (CONTINUED)

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾				
		A2	A3	A4	A5	A6
PIC24FJ512GB606	6014h	0x02	0x03	0x04	0x05	0x06
PIC24FJ1024GB606	601Ch					
PIC24FJ128GB610	6005h					
PIC24FJ256GB610	600Dh					
PIC24FJ512GB610	6015h					
PIC24FJ1024GB610	601Dh					

Note 1: The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format "DEVID DEVREV".

2: Refer to the "PIC24FJ1024GA610/GB610 Family Flash Programming Specification" (DS30010057) for detailed information on Device and Revision IDs for your specific device.

PIC24FJ1024GA610/GB610 FAMILY

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾					
				A2	A3	A4	A5	A6	
Power	Low-Voltage Retention Regulator	1.	If a wake-up trigger occurs within 2 μ S of entering Retention Sleep, the part may not properly wake from Retention Sleep.	X					
Power	CPU	2.	Part fails to start from power-on when the temperature is below -10°C and VDD is $\leq$ 2.7V.	X					
Power	Low-Voltage Retention Regulator	3.	Repeated Wake Retention Sleep cycling can cause the internal LDO to exceed its maximum voltage output specification.	X					
ADC	Charge Injection	4.	At the beginning of conversion, a small current can be injected into the ADC input pin. This will cause a voltage spike dependent on the source resistance.	X	X	X	X	X	
I ² C	Slave Addressing	5.	When AHEN (I2CxCONH[1]) = 1, a slave interrupt is asserted for invalid address or software NACK (after 9th clock).	X	X	X	X	X	
MCCP/SCCP	Output Compare	6.	Single Edge Output Compare Event Status bit (SCEVT) is not setting for MOD[3:0] = 0010.	X	X	X	X	X	
Reset	Trap Conflict	7.	The TRAPR bit is not getting set when a hard trap conflict occurs.	X	X	X	X	X	
I ² C	Slave Mode	8.	In 10-Bit Addressing Slave mode, on receiving the upper address byte (A9 and A8 bits), the Acknowledge Time Status bit (ACKTIM) is not asserted during the Acknowledgment sequence.	X	X	X	X	X	
Primary XT Oscillator (POSC)	Primary Oscillator Start-up Timer (OST)	9.	OST may indicate oscillator is ready for use too early.	X	X	X	X	X	
Power	Sleep Mode	10.	Sleep current may exceed the value specified in the data sheet.	X	X				
Power	Retention Sleep Mode	11.	When the device wakes up from Retention Sleep mode (RETEN bit (RCON[12]) = 1, LPCFG bit (FPOR[2]) = 0), a device Reset may occur. The BOR, POR and EXTR bits in RCON register are set erroneously for this Reset.	X	X				
I/O	Schmitt Trigger	12.	Schmitt trigger may have glitches for slow signal rise/fall times.	X	X	X			
SPI	Slave Mode	13.	The SRMT bit may be set when the FIFO or Shift register is not empty.	X	X	X	X	X	
ADC	Electrical Characteristics	14.	At cold temperatures, ADC characteristics may be beyond the data sheet specification.	X	X	X	X		
Power	BOR	15.	The main BOR may not function.	X	X	X			
I/O	I/O	16.	I/O is not tri-stated if TRISx bit is changed from '0' to '1'.	X	X	X	X	X	
ADC	Current	17.	ADC draws additional current when enabled.	X	X	X	X		
Oscillator	96 MHz PLL Mode	18.	PLL in 96 MHz mode may not operate under certain conditions.	X	X	X	X		
Oscillator	Fail-Safe Clock Monitor	19.	When FSCM is enabled and selected clock fails, an oscillator trap may not occur.	X	X	X	X	X	
Oscillator	OSCFDIV	20.	OSCFDIV clock may not be functional after power-up.	X	X	X	X		
Power	Retention Sleep Mode	21.	Reset when device wakes up.	X	X	X	X	X	

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

PIC24FJ1024GA610/GB610 FAMILY

Silicon Errata Issues

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (**A6**).

1. Module: Power

If a wake-up trigger occurs within 2 μ S of entering Retention Sleep, the part may not properly wake from Retention Sleep.

Work around

None.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X							

2. Module: Power

Part fails to start from power-on when the temperature is below -10°C and VDD is ≤ 2.7 V.

Work around

Ensure the VDD and AVDD are 2.75V or higher, or that the device will not be exposed to temperatures below -10°C.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X							

3. Module: Power

Repeated Wake Retention Sleep cycling can cause the internal LDO to exceed its maximum voltage output specification if the VREGS bit (RCON[8]) = 1.

Work around

The code must execute for 1 ms minimum before returning to Retention Sleep mode or VREGS can be set to '0' in the application.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X							

4. Module: ADC

At the beginning of conversion, a small current can be injected into the ADC input pin. This will cause a voltage spike dependent on the source resistance.

Work around

Any of the following solutions can be used:

- Use external buffer on transducer output if the source resistance is greater than 2 k Ω .
- Increase the TAD time to be 1 μ S or greater.
- Increase the sample time to be longer than 1 μ S.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X	X			

5. Module: I²C

When AHEN (I2CxCONH[1]) = 1, a slave interrupt is asserted for an invalid address or software NACK (after 9th clock).

Work around

User application should ignore the extra interrupt until a Stop condition is seen on the data bus.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X	X			

PIC24FJ1024GA610/GB610 FAMILY

6. Module: MCCP/SCCP

The Single Edge Compare Event Status bit, SCEVT (CCPxSTATL[3]), may not set for Single Edge mode (drive output low on match (MOD[3:0] = 0010)). In this case, the comparator output is still driven low on the first CCPxRA match, but will not be reset by writing '0' to the SCEVT bit.

All MCCPs/SCCPs are affected.

Work around

This mode may be used to trigger a single event before the module must be reinitialized by clearing and setting CCPON (CCP1CON1L[15]).

The Capture/Compare Interrupt Flag (CCPxIF) still occurs on a match with CCPxRA, and can be used to update the user that a compare event has been triggered and the module needs to be reset.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X	X			

7. Module: Reset

If a lower priority address error trap occurs while a higher priority oscillator failure trap is being processed, the TRAPR bit (RCON[15]) is not set. A Trap Conflict Reset does not occur as expected and the device may stop executing code.

Work around

None. However, a Reset (such as $\overline{\text{MCLR}}$, POR or WDT) will recover the device.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X	X			

8. Module: I²C

In I²C Slave 10-Bit Addressing mode, on receiving the upper address byte (A9 and A8 bits), the Acknowledge Time Status bit, ACKTIM (I2CxSTAT[13]), is not asserted during an Acknowledgment sequence.

This issue is not seen during the reception of the lower address byte (A7 to A0) and data bytes. The hardware asserts the ACKTIM bit on the falling edge of the eighth clock and deasserts on the rising edge of the ninth clock. In this case, ACKTIM is not asserted on the upper address byte reception.

When AHEN (I2CxCONL[1]) = 1, the clock is stretched after the 8th falling edge and the ACKTIM bit is asserted until the clock is released. If AHEN = 0, the clock is not stretched and ACKTIM is asserted during the Acknowledgment sequence, which is of a very short duration.

Therefore, the user application can see this issue of the ACKTIM bit not getting asserted when AHEN = 1.

Work around

Instead of polling for ACKTIM to be asserted, poll for the RBF flag (I2CxSTAT[1]).

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X	X			

PIC24FJ1024GA610/GB610 FAMILY

9. Module: Primary XT Oscillator (POSC)

The Primary Oscillator Start-up Timer (OST) may indicate the oscillator is ready for use too early. Clocking the device before the oscillator is ready may result in incorrect execution and exceptions. This issue exists when the POSC is requested at power-on, during clock switching, when waking from Sleep or when a peripheral module requests the POSC directly. This issue affects the XT mode only.

Work around

1. Use HS Primary Oscillator mode.
2. Make sure that the XT Primary Oscillator clock is ready before using it by following these steps:
 - a) Running on a non-POSC source, request the POSC clock using a peripheral such as REFO.
 - b) Provide a delay to stabilize the POSC.
 - c) Switch to the POSC source.

[Example 1](#) shows a work around for the device power-on and [Example 2](#) explains the work around when the device wakes from Sleep.

EXAMPLE 1: USING POSC AT POWER-ON

```
#pragma config FNOSC = FRC           // Oscillator Selection bits (Fast RC oscillator (FRC))
// Clock Switching Enabled (Fail-safe Clock Monitor can be enabled or disabled)
#pragma config FCKSM = CSECMD
-----
int main()
{
    // configure REFO to request POSC
    REFOCONLbits.ROSEL = 2;           // POSC
    REFOCONLbits.ROOUT = 0;           // disable output
    REFOCONLbits.ROEN = 1;            // enable module

    // wait for POSC stable clock
    // this delay may vary depending on different application conditions
    // such as voltage, temperature, layout and components
    { // delay for 9 ms
        unsigned int delaysms = 9;
        while(delaysms--) asm volatile("repeat #(8000000/1000/2) \n nop");
    }

    // switch to POSC = 2
    __builtin_write_OSCCONH(2);
    __builtin_write_OSCCONL(1);
    while(OSCCONbits.OSWEN == 1);     // wait for switch
```


PIC24FJ1024GA610/GB610 FAMILY

EXAMPLE 2: USING POSC WHEN WAKING FROM SLEEP

```
// Clock Switching Enabled (Failsafe Clock Monitor can be enabled or disabled)
#pragma config FCKSM = CSECMD
-----
// switch to FRC = 0 before entering sleep
__builtin_write_OSCCONH(0);
__builtin_write_OSCCONL(1);
while(OSCCONbits.OSWEN == 1);    // wait for switch

// enter sleep mode
Sleep();

// configure REFO to request POSC
REFOCONLbits.ROSEL = 2;          // POSC
REFOCONLbits.ROOUT = 0;          // disable output
REFOCONLbits.ROEN = 1;           // enable module

// wait for POSC stable clock
// this delay may vary depending on different application conditions
// such as voltage, temperature, layout and components
{ // delay for 9 ms
    unsigned int delay_ms = 9;
    while(delayms--) asm volatile("repeat #(8000000/1000/2) \n nop");
}

// switch to POSC = 2
__builtin_write_OSCCONH(2);
__builtin_write_OSCCONL(1);
while(OSCCONbits.OSWEN == 1);    // wait for switch
```

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X	X			

PIC24FJ1024GA610/GB610 FAMILY

10. Module: Power

The Sleep current may exceed a value specified in the data sheet. The issue affects regular (non-Retention) Sleep modes.

Work around

Set the RETEN bit (RCON[12]) = 1 and disable the Retention Sleep mode by setting the LPCFG Configuration bit (FPOR[2]) = 1.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X						

11. Module: Power

When the device wakes up from Retention Sleep mode (RETEN bit (RCON[12]) = 1, LPCFG bit (FPOR[2]) = 0), occasionally a device Reset may occur. The BOR, POR and EXTR bits in the RCON register are set erroneously for this Reset.

Work around

To provide a consistent behavior when the device wakes up from the Retention Sleep mode, the software RESET instruction should be inserted following the SLEEP instruction. In this case, a Reset will always be generated when the device wakes up from Retention Sleep. [Example 3](#) shows the software RESET instruction implementation:

EXAMPLE 3: SOFTWARE RESET AFTER SLEEP INSTRUCTION

```
// ENTER SLEEP MODE.
asm volatile (``pwrsav #0``);
// SOFTWARE RESET RIGHT AFTER SLEEP.
asm volatile (``reset``);
```

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X						

12. Module: I/O

If the input signal rise or fall time is greater than 200 nS, the I/O Schmitt trigger output may have glitches.

Work around

The rise/fall times must be less than 200 nS.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X					

13. Module: SPI

In SPI Slave mode, the SRMT bit may be set when the TX FIFO or Shift register is not empty.

Work around

The following work arounds can be implemented in the application to detect when the FIFO and Shift register are empty:

1. Check the SPITBF bit before checking the SRMT bit. If the SPITBF flag is cleared and the SRMT flag is set, then all data were transmitted. [Example 4](#) demonstrates the SPITBF and SRMT bits polling.
2. Read the SRMT bit twice, back-to-back. If the SRMT bit is set two reads in a row, then the FIFO and Shift Register are empty. [Example 5](#) demonstrates the SRMT bit polling using double read.

EXAMPLE 4: EMPTY STATUS DETECTION USING SPITBF AND SRMT BITS POLLING

```
// Both flags must indicate empty status.
while(SPI1STATLbits.SPITBF);
while(!SPI1STATLbits.SRMT);
```

EXAMPLE 5: EMPTY STATUS DETECTION USING SRMT BIT POLLING WITH BACK-TO-BACK READS

```
// If SRMT bit is set two reads in a row then
it set correctly.
asm volatile("loop:\n"
            "btsc SPI1STATL, #7\n"
            "btss SPI1STATL, #7\n"
            "bra loop");
```

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X	X			

PIC24FJ1024GA610/GB610 FAMILY

14. Module: ADC

When the ADC input voltage is above $(AV_{DD} - 0.2)V$, and the device operates in the temperature range of 0°C to -40°C, the INL and Gain error can get bigger as the ADC input voltage increases, up to -11 LSB Gain and -13 LSB INL.

Work around

Choose the ADC positive reference (V_{REF+}) below $(AV_{DD} - 0.2)V$. This ensures the ADC input voltage will operate to ADC full scale without affecting the ADC specification.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X				

15. Module: Power

The main BOR may not occur when the operating voltage drops below the BOR trip voltage.

Work around

Ensure the device operating voltage does not violate the specified values. Use an external supervisor circuit to reset the device if the operating voltage can be outside the specified values.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X					

16. Module: I/O

5V tolerant I/Os may not be set to a high-impedance state if the corresponding TRISx bit is changed from '0' to '1'. The I/O state change from output to high-impedance may be delayed up to 100 mS, depending on external connections. On Silicon Revision A5 and later, only the following I/Os are affected by this issue: RA2, RA3, RA14, RA15, RD9, RD10, RE6, RE7, RF4, RF5, RG2 and RG3.

Work around

Set I/O to low level ($LATx$ bit = 0) before switching to input ($TRISx$ bit = 1).

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X	X			

17. Module: ADC

On some devices, the current draw may increase when the ADC is enabled. This current draw is not affected by the device Power Save modes or ADC configuration. This additional current does not affect the ADC or device performance.

Work around

Disable the ADC when it is not converting or not used in the application.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X				

18. Module: Oscillator

The PLL in 96 MHz mode may not function when the device starts up and the capacitor on the VCAP pin is discharged. This condition is applicable in both Two-Speed Oscillator Start-up and clock switching at run time.

Work around

1. The 8x/6x/4x PLL modes are functional and available for use.
2. If 96 MHz PLL mode is required for application (ex: USB), connect a 1 μF capacitor between VDD and VCAP to precharge the VCAP capacitor.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X				

19. Module: Oscillator

If a clock failure event occurs when Fail-Safe Clock Monitor (FSCM) is enabled, the oscillator trap may not occur. Instead of the oscillator trap, a clock failure condition can result in instruction misexecution, with other traps or Resets generated.

Work around

None.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X	X			

PIC24FJ1024GA610/GB610 FAMILY

20. Module: Oscillator

On start-up with the VCAP capacitor discharged, the OSCFDIV oscillator may not function. This condition is applicable in both Two-Speed Oscillator Start-up and clock switching at run time. If the OSCFDIV oscillator is selected by default in the FNOSC_x Configuration bits, the device may not start.

Work around

Use another clock source option, such as FRC.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X				

21. Module: Power

For a temperature below -20°C, a device Reset may occur occasionally when the device wakes up from Retention Sleep mode (RETEN bit (RCON[12]) = 1, LPCFG bit (FPOR[2]) = 0). The BOR, POR and EXTR bits in the RCON register are set erroneously for this Reset.

Work around

None.

Affected Silicon Revisions

A2	A3	A4	A5	A6			
X	X	X	X	X			

PIC24FJ1024GA610/GB610 FAMILY

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (30010074G):

Note: Corrections are shown in bold . Where possible, the original bold text formatting has been removed for clarity.

None.

PIC24FJ1024GA610/GB610 FAMILY

APPENDIX A: DOCUMENT REVISION HISTORY

Rev A Document (11/2015)

Initial release of this document; issued for Silicon Revision A2.

Rev B Document (11/2015)

Added data sheet clarification 1 (Device Names and Peripherals).

Rev C Document (3/2016)

Added silicon revision A3.

Removed data sheet clarification 1 (Device Names and Peripherals).

Rev D Document (7/2016)

Added silicon issue 9 (Primary XT and HS Oscillator (POSC)) and silicon issue 10 (Power).

Added data sheet clarifications 1 and 2 (DC Characteristics).

Rev E Document (12/2016)

Added silicon issue 11 (Power).

Removed data sheet clarifications 1 and 2 (DC Characteristics).

Rev F Document (4/2017)

Added Silicon Revision A4.

Added silicon issue 12 (I/O) and silicon issue 13 (SPI).

Added data sheet clarification 1 (Electrical Characteristics).

Rev G Document (7/2017)

Added silicon issues 14 (ADC) and 15 (Power).

Removed data sheet clarification 1 (Electrical Characteristics) because the issue was corrected in the latest data sheet revision.

Rev H Document (3/2018)

Added Silicon Revision A5.

Added silicon issue 16 (I/O).

Rev J Document (1/2019)

Added Silicon issue 17 (ADC).

Added data sheet clarification 1 (Electrical Characteristics).

Rev K Document (7/2019)

Added silicon revision A6.

Added silicon issue 18 (Oscillator).

Rev L Document (2/2020)

Added silicon issue 19 (Oscillator).

Updated silicon issue 9 (Primary XT Oscillator (POSC)).

Removed data sheet clarification 1 (Electrical Characteristics) because the issue was corrected in the latest data sheet revision.

Rev M Document (10/2020)

Added silicon issue 20 (Oscillator).

Rev N Document (3/2021)

Added silicon issue 21 (Power).

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods being used in attempts to breach the code protection features of the Microchip devices. We believe that these methods require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Attempts to breach these code protection features, most likely, cannot be accomplished without violating Microchip's intellectual property rights.
- Microchip is willing to work with any customer who is concerned about the integrity of its code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable." Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication is provided for the sole purpose of designing with and using Microchip products. Information regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL OR CONSEQUENTIAL LOSS, DAMAGE, COST OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maxStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2015-2021, Microchip Technology Incorporated, All Rights Reserved.

ISBN: 978-1-5224-7998-7

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX
Tel: 512-257-3370

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Novi, MI
Tel: 248-848-4000

Houston, TX
Tel: 281-894-5983

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453
Tel: 317-536-2380

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608
Tel: 951-273-7800

Raleigh, NC
Tel: 919-844-7510

New York, NY
Tel: 631-435-6000

San Jose, CA
Tel: 408-735-9110
Tel: 408-436-4270

Canada - Toronto
Tel: 905-695-1980
Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733

China - Beijing
Tel: 86-10-8569-7000

China - Chengdu
Tel: 86-28-8665-5511

China - Chongqing
Tel: 86-23-8980-9588

China - Dongguan
Tel: 86-769-8702-9880

China - Guangzhou
Tel: 86-20-8755-8029

China - Hangzhou
Tel: 86-571-8792-8115

China - Hong Kong SAR
Tel: 852-2943-5100

China - Nanjing
Tel: 86-25-8473-2460

China - Qingdao
Tel: 86-532-8502-7355

China - Shanghai
Tel: 86-21-3326-8000

China - Shenyang
Tel: 86-24-2334-2829

China - Shenzhen
Tel: 86-755-8864-2200

China - Suzhou
Tel: 86-186-6233-1526

China - Wuhan
Tel: 86-27-5980-5300

China - Xian
Tel: 86-29-8833-7252

China - Xiamen
Tel: 86-592-2388138

China - Zhuhai
Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444

India - New Delhi
Tel: 91-11-4160-8631

India - Pune
Tel: 91-20-4121-0141

Japan - Osaka
Tel: 81-6-6152-7160

Japan - Tokyo
Tel: 81-3-6880-3770

Korea - Daegu
Tel: 82-53-744-4301

Korea - Seoul
Tel: 82-2-554-7200

Malaysia - Kuala Lumpur
Tel: 60-3-7651-7906

Malaysia - Penang
Tel: 60-4-227-8870

Philippines - Manila
Tel: 63-2-634-9065

Singapore
Tel: 65-6334-8870

Taiwan - Hsin Chu
Tel: 886-3-577-8366

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600

Thailand - Bangkok
Tel: 66-2-694-1351

Vietnam - Ho Chi Minh
Tel: 84-28-5448-2100

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4485-5910
Fax: 45-4485-2829

Finland - Espoo
Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching
Tel: 49-8931-9700

Germany - Haan
Tel: 49-2129-3766400

Germany - Heilbronn
Tel: 49-7131-72400

Germany - Karlsruhe
Tel: 49-721-625370

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Rosenheim
Tel: 49-8031-354-560

Israel - Ra'anana
Tel: 972-9-744-7705

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Padova
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Norway - Trondheim
Tel: 47-7288-4388

Poland - Warsaw
Tel: 48-22-3325737

Romania - Bucharest
Tel: 40-21-407-87-50

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Gothenberg
Tel: 46-31-704-60-40

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820

SYST-01AYJC109 - ERRATA - PIC24FJ1024GA610/GB610 Family Silicon Errata and Data Sheet Clarification

Affected Catalog Part Numbers(CPN)

PIC24FJ1024GA606-E/MR
PIC24FJ1024GA606-E/PT
PIC24FJ1024GA606-I/MR
PIC24FJ1024GA606-I/PT
PIC24FJ1024GA606T-I/MR
PIC24FJ1024GA606T-I/PT
PIC24FJ1024GA610-E/BG
PIC24FJ1024GA610-E/PT
PIC24FJ1024GA610-I/BG
PIC24FJ1024GA610-I/PT
PIC24FJ1024GA610-I/PTC01
PIC24FJ1024GA610T-I/BG
PIC24FJ1024GA610T-I/PT
PIC24FJ1024GA610T-I/PTC01
PIC24FJ1024GB606-E/MR
PIC24FJ1024GB606-E/PT
PIC24FJ1024GB606-I/MR
PIC24FJ1024GB606-I/PT
PIC24FJ1024GB606-I/PTC02
PIC24FJ1024GB606T-I/MR
PIC24FJ1024GB606T-I/PT
PIC24FJ1024GB610-E/BG
PIC24FJ1024GB610-E/PT
PIC24FJ1024GB610-I/BG
PIC24FJ1024GB610-I/PT
PIC24FJ1024GB610-I/PTREL
PIC24FJ1024GB610T-I/BG
PIC24FJ1024GB610T-I/PT
PIC24FJ128GA606-E/MR
PIC24FJ128GA606-E/PT
PIC24FJ128GA606-I/MR
PIC24FJ128GA606-I/PT
PIC24FJ128GA606T-I/MR
PIC24FJ128GA606T-I/PT
PIC24FJ128GA610-E/BG
PIC24FJ128GA610-E/PT
PIC24FJ128GA610-I/BG
PIC24FJ128GA610-I/PT
PIC24FJ128GA610T-I/BG
PIC24FJ128GA610T-I/PT
PIC24FJ128GB606-E/MR
PIC24FJ128GB606-E/PT

PIC24FJ128GB606-I/MR
PIC24FJ128GB606-I/PT
PIC24FJ128GB606T-I/MR
PIC24FJ128GB606T-I/PT
PIC24FJ128GB610-E/BG
PIC24FJ128GB610-E/PT
PIC24FJ128GB610-I/BG
PIC24FJ128GB610-I/PT
PIC24FJ128GB610T-I/BG
PIC24FJ128GB610T-I/PT
PIC24FJ256GA606-E/MR
PIC24FJ256GA606-E/PT
PIC24FJ256GA606-I/MR
PIC24FJ256GA606-I/PT
PIC24FJ256GA606T-I/MR
PIC24FJ256GA606T-I/PT
PIC24FJ256GA610-E/BG
PIC24FJ256GA610-E/PT
PIC24FJ256GA610-I/BG
PIC24FJ256GA610-I/PT
PIC24FJ256GA610T-I/BG
PIC24FJ256GA610T-I/PT
PIC24FJ256GB606-E/MR
PIC24FJ256GB606-E/PT
PIC24FJ256GB606-I/MR
PIC24FJ256GB606-I/PT
PIC24FJ256GB606T-I/MR
PIC24FJ256GB606T-I/PT
PIC24FJ256GB610-E/BG
PIC24FJ256GB610-E/PT
PIC24FJ256GB610-I/BG
PIC24FJ256GB610-I/PT
PIC24FJ256GB610T-I/BG
PIC24FJ256GB610T-I/PT
PIC24FJ512GA606-E/MR
PIC24FJ512GA606-E/PT
PIC24FJ512GA606-I/MR
PIC24FJ512GA606-I/PT
PIC24FJ512GA606T-I/MR
PIC24FJ512GA606T-I/PT
PIC24FJ512GA610-E/BG
PIC24FJ512GA610-E/PT
PIC24FJ512GA610-I/BG
PIC24FJ512GA610-I/PT
PIC24FJ512GA610T-I/BG
PIC24FJ512GA610T-I/PT
PIC24FJ512GB606-E/MR

PIC24FJ512GB606-E/PT
PIC24FJ512GB606-I/MR
PIC24FJ512GB606-I/PT
PIC24FJ512GB606-I/PTC03
PIC24FJ512GB606T-I/MR
PIC24FJ512GB606T-I/PT
PIC24FJ512GB606T-I/PTC01
PIC24FJ512GB606T-I/PTC03
PIC24FJ512GB610-E/BG
PIC24FJ512GB610-E/PT
PIC24FJ512GB610-I/BG
PIC24FJ512GB610-I/PT
PIC24FJ512GB610T-I/BG
PIC24FJ512GB610T-I/PT