

Product Change Notification / SYST-23UFEG663

| | _ | ı | _ | _ |
|---|---|----|---|---|
| | а | Т | Δ | • |
| u | a | L. | ┖ | _ |

24-Feb-2022

Product Category:

Ethernet PHYs

PCN Type:

Document Change

Notification Subject:

ERRATA - KSZ9131RNX Silicon Errata and Data Sheet Clarification

Affected CPNs:

SYST-23UFEG663_Affected_CPN_02242022.pdf SYST-23UFEG663_Affected_CPN_02242022.csv

Notification Text:

SYST-23UFEG663

Microchip has released a new Product Documents for the KSZ9131RNX Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at KSZ9131RNX Silicon Errata and Data Sheet Clarification.

Notification Status: Final

Description of Change: 1) Added Module 3: 1000M EEE needs 100M Advertisement Enabled 2) Changed silicon revision

letter from "C0" to "C."

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 24 Feb 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

| Markings to Distinguish Revised from Unrevised Devices: N/A |
|---|
| Attachments: |
| KSZ9131RNX Silicon Errata and Data Sheet Clarification |
| |
| Please contact your local Microchip sales office with questions or concerns regarding this notification. |
| Terms and Conditions: |
| If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our <u>PCN</u> home page select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the <u>PCN FAQ</u> section. |
| If you wish to <u>change your PCN profile, including opt out,</u> please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections. |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |

$SYST-23UFEG663-ERRATA-KSZ9131RNX\ Silicon\ Errata\ and\ Data\ Sheet\ Clarification$

Affected Catalog Part Numbers (CPN)

KSZ9131RNXC

KSZ9131RNXC-TR

KSZ9131RNXI

KSZ9131RNXI-TR

KSZ9131RNXU-TRVAO

KSZ9131RNXU-VAO

KSZ9131RNXV-TRVAO

KSZ9131RNXV-VAO



KSZ9131RNX

Silicon Errata and Data Sheet Clarification

This document describes known silicon errata for the Microchip KSZ9131RNX device family, which includes the following variants:


- KSZ9131RNXC
- KSZ9131RNXI
- KSZ9131RNXU
- KSZ9131RNXV

The silicon errata discussed in this document are for silicon revisions as listed in Table 1. The silicon revision can be determined by the device's top marking as indicated in Figure 1. A summary of KSZ9131RNX silicon errata is provided in Table 2.

TABLE 1: AFFECTED SILICON REVISIONS

| Part Numbers | Silicon Revision |
|---|------------------|
| KSZ9131RNXC, KSZ9131RNXI, KSZ9131RNXU, KSZ9131RNXV | С |

FIGURE 1: TOP MARKING DATE CODE INDICATION



Note: The purpose of Figure 1 is to detail the top markings of an example part and highlight the location of the silicon revision code. Other top marking values may differ (lot codes, location of manufacture, etc.).

TABLE 2: SILICON ISSUE SUMMARY

| Item Number | Silicon Issue Summary | Affected Silicon Revisions | |
|----------------|---|-------------------------------|--|
| 1. | RXER Counter Does Not Increment | С | |
| 2. | LED1 in Single-LED Mode Behaves Incorrectly | С | |
| 3. | 1000M EEE needs 100M Advertisement Enabled | С | |

Silicon Errata Issues

Module 1: RXER Counter Does Not Increment

DESCRIPTION

The RXER Counter in register 0x15 does not increment in the presence of receive errors.

END USER IMPLICATIONS

The RXER counter register does not record the number of errors detected on the receiver path.

Workaround

An alternative to the RXER counter is to monitor the idle error count register (register 0x0A) for idle errors.

PLAN

This erratum will not be corrected in a future revision.

Module 2: LED1 in Single-LED Mode Behaves Incorrectly

DESCRIPTION

LED1 is in the ON state (LED1 low) when KSZ9131RNX has no link. This state is invalid based on the expected Single-LED mode values from Table 4-9 of the KSZ9131RNX Data Sheet.

END USER IMPLICATIONS

LED1 should be off when the KSZ9131RNX has no link. However, LED1 is on in a No-Link condition. The user may think there is a link due to LED1 being on. For KSZ9131RNX link indication, the user should look at LED2 for true link (ON) or not (OFF).

Workaround

To fix this, Register 0x1E (30d), bit 9 must be set to 1. Then LED1 will behave as in Table 4-9 of the KSZ9131RNX Data Sheet (LED1 Off - No Link, LED1 On/Toggle - Link/Activity). LED1 will be high, which will turn off the LED associated with LED1 when there is no link

PLAN

This erratum will not be corrected in a future revision.

Module 3: 1000M EEE needs 100M Advertisement Enabled

DESCRIPTION

The device needs both 100M advertisement and 100M EEE advertisement enabled to enter the 1000M EEE Low-Power mode.

END USER IMPLICATIONS

Without both 100M advertisement and 100M EEE advertisement enabled, the device will only operate at normal power in 1000M when no traffic is present (Idle mode).

The IEEE802.3az specification states 1000M EEE and 100M EEE shall operate independently of each other. However, the 100M Advertisement in the Auto-Negotiation Advertisement register and the 100M EEE Advertisement in the EEE Advertisement Register must be enabled for 1000M EEE Low-Power mode. Also, the 1000M Advertisement in Register 0x04 and the 1000M EEE Advertisement in MMD Address 0x07, Register 0x3C (MMD 7.60 decimal) must be enabled.

Workaround

No configuration from default values is necessary to enable 1000M EEE. However, if these registers values are changed, then these register bits must be set to enable 1000M EEE.

Register 0x04, bits[8:7] = 01, 10, or 11 Register 0x09, bit 9 = 1 MMD Address 7 Register 3C, bits[2:1] = 11

PLAN

This erratum will not be corrected in a future revision.

KSZ9131RNX

APPENDIX A: DOCUMENT REVISION HISTORY

TABLE A-1: REVISION HISTORY

| Revision Level & Date | Section/Figure/Entry | Correction |
|---------------------------|--------------------------------|--|
| DS80000693C (02-23-22) | Module 3 | Added Module 3: 1000M EEE needs 100M Advertisement Enabled |
| | Table 1, Table 2, and Figure 1 | Changed silicon revision letter from "C0" to "C." |
| DS80000693B (07-19-21) | Module 2 | Added Module 2 : LED1 in Single-LED Mode Behaves Incorrectly |
| DS80000693A (10-21-19) | All | Initial release |

| K | SZ | 'Q | 1 | 31 | IR | N | X |
|---|----|------|---|----------|----|----|------------------------|
| | J | _ 3/ | • | . | | 14 | $\boldsymbol{\Lambda}$ |

| NOTES: | | | |
|--------|--|--|--|
| | | | |
| | | | |

KSZ9131RNX

THE MICROCHIP WEB SITE

Microchip provides online support via our WWW site at www.microchip.com. This web site is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the web site contains the following information:

- **Product Support** Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- General Technical Support Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- Business of Microchip Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

CUSTOMER CHANGE NOTIFICATION SERVICE

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip web site at www.microchip.com. Under "Support", click on "Customer Change Notification" and follow the registration instructions.

CUSTOMER SUPPORT

Users of Microchip products can receive assistance through several channels:

- · Distributor or Representative
- · Local Sales Office
- · Field Application Engineer (FAE)
- · Technical Support

Customers should contact their distributor, representative or Field Application Engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

Technical support is available through the web site at: http://microchip.com/support

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that
 we are guaranteeing the product is "unbreakable". Code protection is constantly evolving. Microchip is committed to continuously
 improving the code protection features of our products.

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at https://www.microchip.com/en-us/support/design-help/client-support-services.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WAR- RANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON- INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDI- RECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, NVM Express, NVMe, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, Symmcom, and Trusted Time are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2022, Microchip Technology Incorporated and its subsidiaries.

All Rights Reserved.

ISBN:978-1-5224-9861-2

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



Worldwide Sales and Service

AMERICAS

Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200

Fax: 480-792-7277 Technical Support:

http://www.microchip.com/ support

Web Address: www.microchip.com

Atlanta Duluth, GA

Tel: 678-957-9614 Fax: 678-957-1455

Austin, TX Tel: 512-257-3370

Boston

Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088

Chicago Itasca, IL

Tel: 630-285-0071 Fax: 630-285-0075

Dallas Addison

Addison, TX Tel: 972-818-7423 Fax: 972-818-2924

Detroit Novi, MI

Tel: 248-848-4000

Houston, TX Tel: 281-894-5983

Indianapolis Noblesville, IN

Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380

Los Angeles

Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800

Raleigh, NC Tel: 919-844-7510

New York, NY Tel: 631-435-6000

San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270

Canada - Toronto Tel: 905-695-1980 Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney Tel: 61-2-9868-6733

China - Beijing Tel: 86-10-8569-7000

China - Chengdu Tel: 86-28-8665-5511

China - Chongqing Tel: 86-23-8980-9588

China - Dongguan Tel: 86-769-8702-9880

China - Guangzhou Tel: 86-20-8755-8029

China - Hangzhou Tel: 86-571-8792-8115

China - Hong Kong SAR Tel: 852-2943-5100

China - Nanjing Tel: 86-25-8473-2460

China - Qingdao Tel: 86-532-8502-7355

China - Shanghai Tel: 86-21-3326-8000

China - Shenyang

Tel: 86-24-2334-2829 China - Shenzhen

Tel: 86-755-8864-2200

China - Suzhou Tel: 86-186-6233-1526

China - Wuhan Tel: 86-27-5980-5300

China - Xian Tel: 86-29-8833-7252

China - Xiamen Tel: 86-592-2388138

China - Zhuhai Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore Tel: 91-80-3090-4444

India - New Delhi Tel: 91-11-4160-8631

India - Pune Tel: 91-20-4121-0141

Japan - Osaka Tel: 81-6-6152-7160

Japan - Tokyo Tel: 81-3-6880- 3770

Korea - Daegu

Tel: 82-53-744-4301 **Korea - Seoul** Tel: 82-2-554-7200

Malaysia - Kuala Lumpur Tel: 60-3-7651-7906

Malaysia - Penang Tel: 60-4-227-8870

Philippines - Manila Tel: 63-2-634-9065

Singapore Tel: 65-6334-8870

Taiwan - Hsin Chu Tel: 886-3-577-8366

Taiwan - Kaohsiung Tel: 886-7-213-7830

Taiwan - Taipei Tel: 886-2-2508-8600

Thailand - Bangkok Tel: 66-2-694-1351

Vietnam - Ho Chi Minh Tel: 84-28-5448-2100

EUROPE

Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393

Denmark - Copenhagen Tel: 45-4485-5910 Fax: 45-4485-2829

Finland - Espoo Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching Tel: 49-8931-9700

Germany - Haan Tel: 49-2129-3766400

Germany - Heilbronn Tel: 49-7131-72400

Germany - Karlsruhe Tel: 49-721-625370

Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44

Germany - Rosenheim Tel: 49-8031-354-560

Israel - Ra'anana Tel: 972-9-744-7705

Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781

Italy - Padova Tel: 39-049-7625286

Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340

Norway - Trondheim Tel: 47-7288-4388

Poland - Warsaw Tel: 48-22-3325737

Romania - Bucharest Tel: 40-21-407-87-50

Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91

Sweden - Gothenberg Tel: 46-31-704-60-40

Sweden - Stockholm Tel: 46-8-5090-4654

UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820