

## Product Change Notification / SYST-03MKAM000

١ ـ	1	_	
ıa	т	Δ	۰
		·	

04-May-2022

## **Product Category:**

8-bit Microcontrollers

## **PCN Type:**

**Document Change** 

## **Notification Subject:**

ERRATA - PIC16F15225/45 Silicon Errata and Data Sheet Clarifications

#### **Affected CPNs:**

SYST-03MKAM000\_Affected\_CPN\_05042022.pdf SYST-03MKAM000\_Affected\_CPN\_05042022.csv

## **Notification Text:**

SYST-03MKAM000

Microchip has released a new Product Documents for the PIC16F15225/45 Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at PIC16F15225/45 Silicon Errata and Data Sheet Clarifications.

Notification Status: Final

#### Description of Change:

- Added silicon errata item 1.5.1.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 4 May 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:
PIC16F15225/45 Silicon Errata and Data Sheet Clarifications
Please contact your local Microchip sales office with questions or concerns regarding this notification.
Terms and Conditions:
If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our <u>PCN</u> home page select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the <u>PCN FAQ</u> section.
If you wish to <u>change your PCN profile, including opt out,</u> please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.



# PIC16F15225/45 Silicon Errata and Data Sheet Clarifications

The PIC16F15225/45 devices that you have received conform functionally to the current device data sheet (DS20006389**C**), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in the table below.

The errata described in this document will be addressed in future revisions of the PIC16F15225/45 silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current.

**Table 1. Silicon Device Identification** 

Part Number	Device ID	Revision ID		
rait Number	Device iD	В0	B1	
PIC16F15225	0x30EF	0x2040	0x2041	
PIC16F15245	0x30F0	0x2040	0x2041	

## **Silicon Issue Summary**

Table 2. Silicon Issue Summary

Madula	Feature	ltem	Item Issue Summery		Affected Revisions		
Module	reature	No.	Issue Summary	В0	B1		
Pulse-Width Modulation (PWM)	PWM mode	1.1.1	Duty cycle values are incorrect	Х	X		
Enhanced Universal Synchronous Asynchronous Receiver Transmitter (EUSART)	Transmit mode	1.2.1	Possible duplicate byte transmitted	X	X		
Host Synchronous Serial Port (MSSP)	Start and Stop interrupt function	1.3.1	A race condition can cause the Start and/or Stop flags to be set when I <sup>2</sup> C is enabled	Х	X		
In-Circuit Serial Programming <sup>™</sup>	Low-Voltage Programming	1.4.1	Low-Voltage Programming is not possible when V <sub>DD</sub> is below BORV while BOR is enabled	Х	X		
Watchdog Timer (WDT)	Watchdog Timer Reset	1.5.1	WDT reset may not work properly while device is not in Sleep	Х	Х		

**Note:** Only those issues indicated in the last column apply to the current silicon revision.

#### 1. Silicon Errata Issues

CAUTION

**Notice:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the bold font in the following tables apply to the current silicon revision.

#### 1.1 Module: Pulse-Width Modulation (PWM)

#### 1.1.1 Wrong Duty Cycle for CCP Module

While in PWM mode and the Timer2 prescaler is configured to 1:1, the duty cycle of the PWM output is as expected. When the Timer2 prescaler is changed to a value other than 1:1, while T2PR = 0 (PWM resolution of two bits), the expected duty cycle is wrong. The corrected duty cycle values are shown in the table below.

Table 1-1. Corrected Duty Cycle Values

Prescaler/CCPR	0	1	2	3	4
1:1	0%	25%	50%	75%	100%
1:2	50%	75%	50%	75%	100%
1:41:128	75%	75%	75%	75%	100%

#### Work around

None.

#### Affected Silicon Revisions

В0	B1			
Х	Х			

# 1.2 Module: Enhanced Universal Synchronous Asynchronous Receiver Transmitter (EUSART)

#### 1.2.1 Double Byte Transmit

Under certain conditions, a byte written to the TXREG register can be transmitted twice. This happens when a byte is written to TXREG just as the TSR register becomes empty. This new byte is immediately transferred to the TSR register, but also remains in the TXREG register until the completion of the current instruction cycle. If the new byte in the TSR register is transmitted before this instruction cycle has completed, the duplicate in the TXREG register will subsequently be transferred to the TSR register on the following instruction clock cycle and transmitted.

#### Work around

Method 1: Monitor the Transmit Interrupt Flag (TXIF) bit. Writes to the TXREG register can be performed once the TXIF bit is set, indicating that the TXREG register is empty. If using this method, ensure that the second byte is filled in the TXREG before bit 6 of the first byte is transmitted. If the delay is more than six bit times, there is a possibility of double byte transmission.

Method 2: Monitor the TMRT bit of the TXxSTA register. Writes to the TXREG register can be performed once the TMRT bit is set, indicating that the Transmit Shift Register (TSR) is empty. This work around can be applied if back-to-back transmissions are not necessary.

#### Affected Silicon Revisions

В0	B1			
Χ	Х			

#### 1.3 Module: Host Synchronous Serial Port (MSSP)

#### 1.3.1 The I<sup>2</sup>C Start and/or Stop Flags May Be Set When I<sup>2</sup>C Is Enabled

When I<sup>2</sup>C is enabled, erroneous Start and/or Stop conditions may be detected. This can generate erroneous I<sup>2</sup>C interrupts if enabled.

#### Work around

Use the following procedure to correctly detect the Start and Stop conditions:

- 1. Disable the Start and Stop conditions interrupt functions.
- 2. Enable the I<sup>2</sup>C module.
- 3. Wait 250 ns + six instructions cycles (F<sub>OSC</sub>/4).
- Clear the Start and Stop conditions interrupt flags.
- 5. Enable the Start and Stop conditions interrupt functions if used.

#### Affected Silicon Revisions

В0	B1			
X	Х			

## 1.4 Module: Low-Voltage In-Circuit Serial Programming<sup>™</sup> (LVP)

#### 1.4.1 Low-Voltage Programming Not Possible

Low-Voltage Programming is not possible when  $V_{\text{DD}}$  is below the selected BORV voltage level, while BOR is enabled.

#### Work around

Method 1: Disable BOR to use Low-Voltage Programming.

Method 2: Raise V<sub>DD</sub> above the selected BORV level while using Low-Voltage Programming.

#### Affected Silicon Revisions

В0	B1			
Х	Х			

## 1.5 Module: Watchdog Timer (WDT)

#### 1.5.1 Watchdog Timer Reset

The Watchdog Timer (WDT) Reset feature may not work properly outside of Sleep mode. Reliance on WDT Reset while executing a program is not recommended. Operation in Sleep is not impacted by this errata.

#### Work around

Use an independent timer to emulate a watchdog feature, outside of Sleep mode, using the following steps:

- 1. Configure the chosen timer for the desired timeout period
- 2. Enable the timer interrupt
- 3. Enable Peripheral and Global interrupts
- 4. Enable the timer, which starts the count
- 5. At the end of the Main loop, restore the timer values
- 6. If the timer interrupt occurs, issue a RESET command

A code example using Timer1 is shown below.

```
void __interrupt() isr(void)
{
    if( TMRIIF && TMR1IE )
    {
        asm("RESET");
    }
}

void main(void)
{
    configure_TMR1();
    GIE = 1;
    PEIE = 1;

    T1CONbits.ON = 1;

    while(1)
    {
        // user code here
        restore_TMR1();
    }
}
```

#### **Affected Silicon Revisions**

В0	B1			
Х	Х			

## 2. Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS20006389**C**):

#### Note:

Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

#### 2.1 None

There are no known data sheet clarifications as of this publication date.

**Appendix A: Revision History** 

# 3. Appendix A: Revision History

Doc Rev.	Date	Comments
С	5/2022	Added silicon errata item 1.5.1.
В	10/2021	Updated Table 2. Added silicon erratum items 1.1.1, 1.2.1, 1.3.1, and 1.4.1. Added new silicon Rev B1.
А	11/2020	Initial document release

## **Microchip Information**

## The Microchip Website

Microchip provides online support via our website at <a href="www.microchip.com/">www.microchip.com/</a>. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- General Technical Support Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- Business of Microchip Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

## **Product Change Notification Service**

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

## **Customer Support**

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- · Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

## **Microchip Devices Code Protection Feature**

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code
  protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright
  Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code
  protection does not mean that we are guaranteeing the product is "unbreakable". Code protection is constantly
  evolving. Microchip is committed to continuously improving the code protection features of our products.

## **Legal Notice**

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded

by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at <a href="https://www.microchip.com/en-us/support/design-help/client-support-services">www.microchip.com/en-us/support/design-help/client-support-services</a>.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

#### **Trademarks**

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet- Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, Anyln, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, NVM Express, NVMe, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, Symmcom, and Trusted Time are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2020-2022, Microchip Technology Incorporated and its subsidiaries. All Rights Reserved.

ISBN: 978-1-6683-0356-6

DS80000927C-page 9

# **Quality Management System**

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



# **Worldwide Sales and Service**

India - Bangalore   Australa - Sydney   Tel: 61-2-9868-6733   Tel: 91-80-0390-4444   Tel: 43-724-2244-39   Tel: 49-724-2244-39   Tel: 49-724-2244-39   Tel: 49-724-2244-39   Tel: 49-724-2244-39   Tel: 49-724-2244-39   Tel: 49-724-2244-39   Tel: 49-724-2274-39   Tel: 49-727-7277   Technical Support:   Tel: 58-10-5568-7000   Tel: 91-11-14160-8531   Denmark - Copenhagen   Tel: 48-5485-5910   Tel: 91-20-412-1041   Fex: 45-4485-5910   Tel: 91-20-412-1041   Fex: 45-4485-5822   Tel: 91-20-412-1041   Tel: 91	AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
2355 West Chandler Blvd,   Tel: 61-2-9868-673				
Chandlet, AZ 8824-8199	•	· ·		
Tel: 480-732-7200				
Fax: 480-782-7277	,			
Technical Support:   Tel: 88-28-8685-5511   Tel: 91-20-4121-0141   Japan - Osaka   Japan - Tokyo   Tel: 82-69-80-800   Japan - Tokyo   Japan - Japan				. •
Vew National Conting Communication   Japan - Osaka   Finland - Espoo		_		
Web Address:   Tel: 86-23-8860-9588   Tel: 81-6-6182-7160   Tel: 2869-4520-820	• •			
www.microchip.com         China - Dongguan         Japan - Tokyo         France - Paris           Attanta         Tel: 88-769-8702-9880         Tel: 81-3-8869-3770         Tel: 32-169-36-32-20           Duluth, GA         China - Guangzhou         Korea - Daegu         Fa: 33-169-30-90-79           Tel: 68-897-9614         Tel: 86-20-875-8029         Korea - Baegu         Fa: 33-169-30-90-79           Tel: 78-897-1455         China - Hangzhou         Korea - Seoul         Tel: 48-23-34-44-4001         Tel: 48-2931-9700           Austin, TX         Tel: 86-59-875-8115         Tel: 82-25-54-7200         Germany - Hall           Boston         Tol: 68-571-8792-8115         Tel: 80-3-7651-7906         Tel: 49-2712-93766400           Tel: 74-760-0087         Tel: 86-25-8473-2460         Tel: 60-3-7651-7906         Germany - Hall           Fax: 774-760-0088         China - Clingdao         Philippines - Manila         Tel: 49-7131-72400         Tel: 49-7131-72400           Chiago         Tel: 86-25-430-252-552-7555         Tel: 630-285-0071         Tel: 86-25-3478-56         Tel: 632-2680-9065         Germany - Hulbironn           Tel: 630-285-0071         Tel: 86-21-3326-8000         Tel: 66-334-8870         Fax: 49-89-627-144-4           Tel: 91-27-818-7423         Tel: 86-22-334-2829         Tel: 86-35-78-3366         Tel: 498-80-27-144-4			·	•
Atlanta				
Duluth, GA	•		, ,	
Tel: 678-957-9614				
Fax: 678-957-1455	,			
Austin, TX				_
Tel: 512-257-3370				
Boston	•			•
Vestborough, MA			· ·	
Tel: 774-760-0087 Fax: 774-760-0088 China - Qingdao Chicago Tel: 86-25-8473-2460 Philippines - Manila Tel: 49-721-252370 China - Gingdao Tel: 86-532-8502-7355 Tel: 36-2634-9065 Germany - Munich Tel: 49-8721-4252370 Tel: 36-2634-9065 Germany - Munich Tel: 49-8721-4252370 Tel: 36-2634-9065 Germany - Munich Tel: 49-8721-4252370 Tel: 36-2634-9065 Tel: 49-89-627-144-0 Tel: 49-89-627-144-0 Tel: 49-89-627-144-0 Tel: 49-89-627-144-0 Tel: 49-89-627-144-44 Tel: 49-89-627-144-49 Tel: 49-89-62-14-77 Tel: 49-89-62-14-77 Tel: 49-89-62-2508-8600 Tel: 49-89-62-2508-8600 Tel: 49-89-62-2508-8600 Tel: 49-89-62-2508-8600 Tel: 49-89-62-2508 Tel: 49-89-62-2508-8600 Tel: 49-89-62-2508 Tel: 49-89				·
Fax: 774-760-0088	_	, , ,		
Chicago   Tel: 86-532-8502-7355   Tel: 63-2-634-9065   Germany - Munich   Tel: 63-2-634-9065   Tel: 49-89-627-144-4   Tel: 630-285-0071   Tel: 68-21-3326-8000   Tel: 65-6334-8870   Fax: 49-89-627-144-44   Tel: 86-21-3326-8000   Tel: 65-6334-8870   Fax: 49-89-627-144-44   Tel: 86-24-2334-2829   Tel: 86-234-2334-2829   Tel: 886-3-577-8366   Tel: 49-8031-354-560   Tel: 97-8-818-7423   Tel: 86-754-886-2200   Tel: 886-3-577-8366   Tel: 49-8031-354-560   Tel: 97-8-744-7705   Tel: 972-8-744-7705   Tel: 86-72-13-7830   Tel: 972-9-744-7705   Tel: 886-72-13-7830   Tel: 972-9-744-7705   Tel: 886-72-13-7830   Tel: 972-9-744-7705   Tel: 886-72-13-7830   Tel: 972-9-744-7705   Tel: 886-72-13-7830   Tel: 972-9-744-7705   Tel: 886-2-2508-8600   Tel: 39-0331-742611   Tel: 39-0331-742611   Tel: 248-48-4000   Tel: 86-27-5980-5300   Tel: 66-2-694-1351   Tel: 39-0331-426781   Tel: 248-848-4000   Tel: 86-27-5980-5300   Tel: 66-2-694-1351   Tel: 39-049-7625286   Tel: 86-29-8833-7252   Tel: 86-29-8833-7253   Tel: 86-592-2388138   Tel: 86-592-2388138   Tel: 86-592-2388138   Tel: 86-756-3210040   Tel: 86-7500-80-800   Tel: 86-7500-80-800   Tel: 86-7500-80-800   Tel: 86-7500-80-800   Tel: 86-7500-80-800   Tel: 86-7500-80-800   Te				•
Itasca, IL		_	1	
Tel: 630-285-0071 Fax: 630-285-0075 China - Shenyang Tel: 86-21-3326-8000 China - Shenyang Tel: 86-24-2334-2829 Tel: 86-24-2334-2829 Tel: 86-24-2334-2829 Tel: 86-35-77-8366 Tel: 49-8031-354-560 Addison, TX China - Shenzhen Taiwan - Haohsiung Israel - Ra'anana Tel: 972-818-7423 Tel: 86-755-8864-2200 Tel: 86-72-13-7830 Tel: 972-818-7924 China - Suzhou Taiwan - Taipei Tel: 86-86-7-213-7830 Tel: 972-97-44-7705 Taiwan - Taipei Tel: 86-86-7-213-7830 Tel: 972-97-44-7705 Taiwan - Taipei Tel: 86-86-7-213-7830 Tel: 972-97-44-7705 Taiwan - Taipei Tel: 86-86-7-213-7830 Tel: 96-2508-8600 Tel: 30-0331-742611 Novi, MI China - Wuhan Thailand - Bangkok Tel: 30-0331-742611 Tel: 248-848-4000 Tel: 86-27-5980-5300 Tel: 66-2-694-1351 Tel: 86-26-2694-1351 Tel: 86-27-5980-5300 Tel: 66-2-694-1351 Tel: 81-94-9593 Tel: 86-833-7252 Tel: 84-28-5448-2100 Tel: 81-99-049-7625286 Tel: 31-416-690399 Tel: 317-773-8323 Tel: 317-773-8323 Tel: 317-773-8323 Tel: 317-773-8323 Tel: 36-592-2388138 Tel: 317-73-8323 Tel: 317-73-8453 Tel: 317-73-5453 Tel: 317-73-5453 Tel: 317-73-8453 Tel:	_			•
Fax: 630-285-0075	,			
Dallas				
Addison, TX		, ,		· •
Tel: 972-818-7423 Fax: 972-818-7423 Fax: 972-818-2924 China - Suzhou Tel: 86-7-213-7830 Tel: 972-9-744-7705 Taiwan - Taipei Italy - Milan Detroit Tel: 86-186-6233-1526 Tel: 886-22-2508-8600 Tel: 39-0331-742611 Tel: 288-248-848-4000 Tel: 38-27-5980-5300 Tel: 38-29-481351 Tel: 48-29-30331-466781 Tel: 28-84-848-4000 Tel: 28-27-5980-5300 Tel: 62-26-94-1351 Tel: 39-049-7625286 Tel: 39-049-7625286 Tel: 86-29-8833-7252 Tel: 86-29-8833-7252 Tel: 86-29-8833-7252 Tel: 86-59-2388138 Tel: 86-59-2388138 Tel: 86-59-2388138 Tel: 317-773-8453 Tel: 86-756-3210040 Tel: 88-756-3210040 Tel: 88-758-8800 Tel: 88-758-8800 Tel: 88-758-8800 Tel: 88-756-3210040 Tel: 88-758-8800 Tel: 88-758-88				
Fax: 972-818-2924	·			
Detroit				
Novi, MI			· ·	· •
Tel: 248-848-4000 Houston, TX China - Xian Tel: 86-27-5980-5300 Tel: 66-2-694-1351 Vietnam - Ho Chi Minh Tel: 39-049-7625286 Tel: 39-049-7625286 Tel: 281-894-5983 Tel: 86-29-8833-7252 Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340 Norway - Trondheim Tel: 317-773-8323 China - Zhuhai Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 949-462-9523 Fax: 949-462-9523 Fax: 949-462-9523 Fax: 949-462-9523 Fax: 949-462-9508 Tel: 919-844-7510 Raleigh, NC Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110				
Houston, TX	•		_	
Tel: 281-894-5983 Indianapolis China - Xiamen Noblesville, IN Tel: 86-592-2388138 Tel: 317-773-8323 China - Zhuhai Tel: 317-773-5453 Tel: 86-756-3210040 Tel: 317-536-2380 Los Angeles Los Angeles Tel: 949-462-9523 Fax: 949-462-9608 Tel: 949-2462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110  Tel: 86-29-8833-7252 Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 81-28-5448-2100 Netherlands - Drunen Tel: 31-416-690349 Fax: 31-416-690340 Norway - Trondheim Tel: 47-728434388 Poland - Warsaw Tel: 47-728434388 Poland - Warsaw Tel: 40-21-407-87-50 Spain - Madrid Tel: 49-21-407-87-50 Sweden - Southenberg Tel: 46-31-708-08-90 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham				•
Indianapolis				
Tel: 86-592-2388138			101. 04 20 0440 2 100	
Tel: 317-773-8323	•			
Fax: 317-773-5453       Tel: 86-756-3210040       Tel: 47-72884388         Tel: 317-536-2380       Poland - Warsaw         Los Angeles       Tel: 48-22-3325737         Mission Viejo, CA       Romania - Bucharest         Tel: 949-462-9523       Tel: 40-21-407-87-50         Fax: 949-462-9608       Spain - Madrid         Tel: 951-273-7800       Tel: 34-91-708-08-90         Raleigh, NC       Fax: 34-91-708-08-91         Tel: 919-844-7510       Sweden - Gothenberg         New York, NY       Tel: 46-31-704-60-40         Tel: 631-435-6000       Sweden - Stockholm         Tel: 408-735-9110       UK - Wokingham	•			
Tel: 317-536-2380       Poland - Warsaw         Los Angeles       Tel: 48-22-3325737         Mission Viejo, CA       Romania - Bucharest         Tel: 949-462-9523       Tel: 40-21-407-87-50         Fax: 949-462-9608       Spain - Madrid         Tel: 951-273-7800       Tel: 34-91-708-08-90         Raleigh, NC       Fax: 34-91-708-08-91         Tel: 919-844-7510       Sweden - Gothenberg         New York, NY       Tel: 46-31-704-60-40         Tel: 631-435-6000       Sweden - Stockholm         San Jose, CA       Tel: 46-8-5090-4654         Tel: 408-735-9110       UK - Wokingham				•
Los Angeles       Tel: 48-22-3325737         Mission Viejo, CA       Romania - Bucharest         Tel: 949-462-9523       Tel: 40-21-407-87-50         Fax: 949-462-9608       Spain - Madrid         Tel: 34-91-708-08-90       Tel: 34-91-708-08-90         Raleigh, NC       Fax: 34-91-708-08-91         Tel: 919-844-7510       Sweden - Gothenberg         New York, NY       Tel: 46-31-704-60-40         Tel: 631-435-6000       Sweden - Stockholm         San Jose, CA       Tel: 46-8-5090-4654         Tel: 408-735-9110       UK - Wokingham		101. 55 755 52 755 15		
Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham				
Tel: 949-462-9523 Fax: 949-462-9608 Spain - Madrid Tel: 34-91-708-08-90 Raleigh, NC Fax: 34-91-708-08-91 Sweden - Gothenberg New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110  Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham				
Fax: 949-462-9608       Spain - Madrid         Tel: 951-273-7800       Tel: 34-91-708-08-90         Raleigh, NC       Fax: 34-91-708-08-91         Tel: 919-844-7510       Sweden - Gothenberg         New York, NY       Tel: 46-31-704-60-40         Tel: 631-435-6000       Sweden - Stockholm         San Jose, CA       Tel: 46-8-5090-4654         Tel: 408-735-9110       UK - Wokingham	• •			
Tel: 951-273-7800  Raleigh, NC  Tel: 919-844-7510  New York, NY  Tel: 631-435-6000  San Jose, CA  Tel: 408-735-9110  Tel: 408-735-9110  Tel: 34-91-708-08-90  Fax: 34-91-708-08-91  Sweden - Gothenberg  Tel: 46-31-704-60-40  Sweden - Stockholm  Tel: 46-8-5090-4654  UK - Wokingham				
Raleigh, NC       Fax: 34-91-708-08-91         Tel: 919-844-7510       Sweden - Gothenberg         New York, NY       Tel: 46-31-704-60-40         Tel: 631-435-6000       Sweden - Stockholm         San Jose, CA       Tel: 46-8-5090-4654         Tel: 408-735-9110       UK - Wokingham	Tel: 951-273-7800			<b>'</b>
Tel: 919-844-7510       Sweden - Gothenberg         New York, NY       Tel: 46-31-704-60-40         Tel: 631-435-6000       Sweden - Stockholm         San Jose, CA       Tel: 46-8-5090-4654         Tel: 408-735-9110       UK - Wokingham				
New York, NY       Tel: 46-31-704-60-40         Tel: 631-435-6000       Sweden - Stockholm         San Jose, CA       Tel: 46-8-5090-4654         Tel: 408-735-9110       UK - Wokingham	• '			
Tel: 631-435-6000         Sweden - Stockholm           San Jose, CA         Tel: 46-8-5090-4654           Tel: 408-735-9110         UK - Wokingham				_
San Jose, CA         Tel: 46-8-5090-4654           Tel: 408-735-9110         UK - Wokingham	· ·			
Tel: 408-735-9110 UK - Wokingham				
	•			UK - Wokingham
Tel: 408-436-4270 Tel: 44-118-921-5800				_
Canada - Toronto Fax: 44-118-921-5820				
Tel: 905-695-1980				
Fax: 905-695-2078	Fax: 905-695-2078			

### Affected Catalog Part Numbers (CPN)

PIC16F15225-E/MG

PIC16F15225-E/P

PIC16F15225-E/SL

PIC16F15225-E/ST

PIC16F15225-I/MG

PIC16F15225-I/P

PIC16F15225-I/SL

PIC16F15225-I/ST

PIC16F15225T-I/SL

PIC16F15245-E/P

PIC16F15245-E/REB

PIC16F15245-E/REBVAO

PIC16F15245-E/SO

PIC16F15245-E/SOVAO

PIC16F15245-E/SS

PIC16F15245-I/P

PIC16F15245-I/REB

PIC16F15245-I/SO

PIC16F15245-I/SS

PIC16F15245-I/SSVAO

PIC16F15245T-E/REBVAO

PIC16F15245T-E/SOVAO

PIC16F15245T-I/REB

PIC16F15245T-I/SO

PIC16F15245T-I/SS

PIC16F15245T-I/SSVAO