



Product Change Notification / SYST-03GVPS609

Date:

04-May-2022

Product Category:

8-bit Microcontrollers

PCN Type:

Document Change

Notification Subject:

ERRATA - PIC16F15213/14/23/24/43/44 Silicon Errata and Data Sheet Clarifications

Affected CPNs:

[SYST-03GVPS609_Affected_CPN_05042022.pdf](#)

[SYST-03GVPS609_Affected_CPN_05042022.csv](#)

Notification Text:

SYST-03GVPS609

Microchip has released a new Product Documents for the PIC16F15213/14/23/24/43/44 Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at [PIC16F15213/14/23/24/43/44 Silicon Errata and Data Sheet Clarifications](#).

Notification Status: Final

Description of Change:

- Added silicon errata item 1.6.1.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 4 May 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[PIC16F15213/14/23/24/43/44 Silicon Errata and Data Sheet Clarifications](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

PIC16F15213-E/MF
PIC16F15213-E/MFVAO
PIC16F15213-E/P
PIC16F15213-E/SN
PIC16F15213-E/SNVAO
PIC16F15213-I/MF
PIC16F15213-I/P
PIC16F15213-I/SN
PIC16F15213T-E/MFVAO
PIC16F15213T-E/SN
PIC16F15213T-E/SNVAO
PIC16F15213T-I/MF
PIC16F15213T-I/SN
PIC16F15214-E/MF
PIC16F15214-E/MFVAO
PIC16F15214-E/P
PIC16F15214-E/SN
PIC16F15214-I/MF
PIC16F15214-I/P
PIC16F15214-I/SN
PIC16F15214T-E/MFVAO
PIC16F15214T-E/SN
PIC16F15214T-I/MF
PIC16F15214T-I/SN
PIC16F15223-E/MG
PIC16F15223-E/P
PIC16F15223-E/SL
PIC16F15223-E/SLVAO
PIC16F15223-E/ST
PIC16F15223-I/MG
PIC16F15223-I/P
PIC16F15223-I/SL
PIC16F15223-I/ST
PIC16F15223T-E/MG
PIC16F15223T-E/SLVAO
PIC16F15223T-I/MG
PIC16F15223T-I/SL
PIC16F15223T-I/ST
PIC16F15224-E/MG
PIC16F15224-E/MGVAO
PIC16F15224-E/P
PIC16F15224-E/SL
PIC16F15224-E/SLVAO
PIC16F15224-E/ST
PIC16F15224-I/7NVAO
PIC16F15224-I/MG

PIC16F15224-I/MGVAO
PIC16F15224-I/P
PIC16F15224-I/SL
PIC16F15224-I/ST
PIC16F15224T-E/MG
PIC16F15224T-E/MGVAO
PIC16F15224T-E/SLVAO
PIC16F15224T-I/MG
PIC16F15224T-I/MGVAO
PIC16F15224T-I/SL
PIC16F15224T-I/ST
PIC16F15243-E/P
PIC16F15243-E/REB
PIC16F15243-E/SO
PIC16F15243-E/SS
PIC16F15243-I/P
PIC16F15243-I/REB
PIC16F15243-I/SO
PIC16F15243-I/SS
PIC16F15243T-I/REB
PIC16F15243T-I/SO
PIC16F15243T-I/SS
PIC16F15244-E/P
PIC16F15244-E/REB
PIC16F15244-E/SO
PIC16F15244-E/SS
PIC16F15244-I/P
PIC16F15244-I/REB
PIC16F15244-I/SO
PIC16F15244-I/SS
PIC16F15244-I/SSV01
PIC16F15244-I/SSVAO
PIC16F15244T-I/REB
PIC16F15244T-I/SO
PIC16F15244T-I/SS
PIC16F15244T-I/SSV02
PIC16F15244T-I/SSVAO



PIC16F15213/14/23/24/43/44

PIC16F15213/14/23/24/43/44 Silicon Errata and Data Sheet Clarifications

The PIC16F15213/14/23/24/43/44 devices that you have received conform functionally to the current device data sheet (DS40002195D), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in the table below.

The errata described in this document will be addressed in future revisions of the PIC16F15213/14/23/24/43/44 silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current.

Table 1. Silicon Device Identification

Part Number	Device ID	Revision ID		
		A3	A5	A6
PIC16F15213	0x30E3	0x2003	0x2005	0x2006
PIC16F15214	0x30E6	0x2003	0x2005	0x2006
PIC16F15223	0x30E4	0x2003	0x2005	0x2006
PIC16F15224	0x30E7	0x2003	0x2005	0x2006
PIC16F15243	0x30E5	0x2003	0x2005	0x2006
PIC16F15244	0x30E8	0x2003	0x2005	0x2006

Silicon Issue Summary

Table 2. Silicon Issue Summary

Module	Feature	Item No.	Issue Summary	Affected Revisions		
				A3	A5	A6
Nonvolatile Memory (NVM)	Self-write operation	1.1.1	Self-write operation may not work above 85°C with V _{DD} above 5.3V	X		
Pulse-Width Modulation (PWM)	PWM mode	1.2.1	Duty cycle values are incorrect	X	X	X
Enhanced Universal Synchronous Asynchronous Receiver Transmitter (EUSART)	Transmit mode	1.3.1	Possible duplicate byte transmitted	X	X	X
Host Synchronous Serial Port (MSSP)	Start and Stop interrupt function	1.4.1	A race condition can cause the Start and/or Stop flags to be set when I ² C is enabled	X	X	X
In-Circuit Serial Programming™	Low-Voltage Programming	1.5.1	Low-Voltage Programming is not possible when V _{DD} is below BORV while BOR is enabled	X	X	X
Watchdog Timer (WDT)	Watchdog Timer Reset	1.6.1	WDT reset may not work properly while device is not in Sleep	X	X	X

Note: Only those issues indicated in the last column apply to the current silicon revision.

1. Silicon Errata Issues

CAUTION

Notice: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the bold font in the following tables apply to the current silicon revision.

1.1 Module: Nonvolatile Memory (NVM)

1.1.1 Self-Write Operation

When performing self-write operations at 85°C or above, the writes may not occur at V_{DD} voltages above 5.3V.

Work around

Perform self-write operations at a temperature below 85°C while operating at V_{DD} voltages above 5.3V.

Affected Silicon Revisions

A3	A5	A6					
X							

1.2 Module: Pulse-Width Modulation (PWM)

1.2.1 Wrong Duty Cycle for CCP Module

While in PWM mode and the Timer2 prescaler is configured to 1:1, the duty cycle of the PWM output is as expected. When the Timer2 prescaler is changed to a value other than 1:1, while $T2PR = 0$ (PWM resolution of two bits), the expected duty cycle is wrong. The corrected duty cycle values are shown in the table below.

Table 1-1. Corrected Duty Cycle Values

Prescaler/CCPR	0	1	2	3	4
1:1	0%	25%	50%	75%	100%
1:2	50%	75%	50%	75%	100%
1:4...1:128	75%	75%	75%	75%	100%

Work around

None.

Affected Silicon Revisions

A3	A5	A6					
X	X	X					

1.3 Module: Enhanced Universal Synchronous Asynchronous Receiver Transmitter (EUSART)

1.3.1 Double Byte Transmit

Under certain conditions, a byte written to the TXREG register can be transmitted twice. This happens when a byte is written to TXREG just as the TSR register becomes empty. This new byte is immediately transferred to the TSR register, but also remains in the TXREG register until the completion of the current instruction cycle. If the new byte in the TSR register is transmitted before this instruction cycle has completed, the duplicate in the TXREG register will subsequently be transferred to the TSR register on the following instruction clock cycle and transmitted.

Work around

Method 1: Monitor the Transmit Interrupt Flag (TXIF) bit. Writes to the TXREG register can be performed once the TXIF bit is set, indicating that the TXREG register is empty. If using this method, ensure that the second byte is filled in the TXREG before bit 6 of the first byte is transmitted. If the delay is more than six bit times, there is a possibility of double byte transmission.

Method 2: Monitor the TMRT bit of the TXxSTA register. Writes to the TXREG register can be performed once the TMRT bit is set, indicating that the Transmit Shift Register (TSR) is empty. This work around can be applied if back-to-back transmissions are not necessary.

Affected Silicon Revisions

A3	A5	A6					
X	X	X					

1.4 Module: Host Synchronous Serial Port (MSSP)

1.4.1 The I²C Start and/or Stop Flags May Be Set When I²C Is Enabled

When I²C is enabled, erroneous Start and/or Stop conditions may be detected. This can generate erroneous I²C interrupts if enabled.

Work around

Use the following procedure to correctly detect the Start and Stop conditions:

1. Disable the Start and Stop conditions interrupt functions.
2. Enable the I²C module.
3. Wait 250 ns + six instructions cycles ($F_{OSC}/4$).
4. Clear the Start and Stop conditions interrupt flags.
5. Enable the Start and Stop conditions interrupt functions if used.

```

SSPxCON3bits.SCIE = 0;           // Disable Start condition interrupt
SSPxCON3bits.PCIE = 0;           // Disable Stop condition interrupt
SSPxCON1bits.SSPEN = 1;          // Enable I2C
Delay();                          // Wait for 250 ns + 6 instruction cycles (FOSC/4)
PIRxbits.SSPxIF = 0;             // Clear the MSSP interrupt flag
SSPxCON3bits.SCIE = 1;           // Enable Start condition interrupt if used
SSPxCON3bits.PCIE = 1;           // Enable Stop condition interrupt if used
    
```

Affected Silicon Revisions

A3	A5	A6					
X	X	X					

1.5 Module: Low-Voltage In-Circuit Serial Programming™ (LVP)

1.5.1 Low-Voltage Programming Not Possible

Low-Voltage Programming is not possible when V_{DD} is below the selected BORV voltage level, while BOR is enabled.

Work around

Method 1: Disable BOR to use Low-Voltage Programming.

Method 2: Raise V_{DD} above the selected BORV level while using Low-Voltage Programming.

Affected Silicon Revisions

A3	A5	A6					
X	X	X					

1.6 Module: Watchdog Timer (WDT)

1.6.1 Watchdog Timer Reset

The Watchdog Timer (WDT) Reset feature may not work properly outside of Sleep mode. Reliance on WDT Reset while executing a program is not recommended. Operation in Sleep is not impacted by this errata.

Work around

Use an independent timer to emulate a watchdog feature, outside of Sleep mode, using the following steps:

1. Configure the chosen timer for the desired timeout period
2. Enable the timer interrupt
3. Enable Peripheral and Global interrupts
4. Enable the timer, which starts the count
5. At the end of the Main loop, restore the timer values
6. If the timer interrupt occurs, issue a RESET command

A code example using Timer1 is shown below.

```

void __interrupt() isr(void)
{
    if( TMR1IF && TMR1IE )
    {
        asm("RESET");
    }
}

void main(void)
{
    configure_TMR1();
    GIE = 1;
    PEIE = 1;

    T1CONbits.ON = 1;

    while(1)
    {
        // user code here
        restore_TMR1();
    }
}

```

PIC16F15213/14/23/24/43/44

Silicon Errata Issues

Affected Silicon Revisions

A3	A5	A6					
X	X	X					

2. Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS40002195D):

Note:

Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

2.1 None

There are no known data sheet clarifications as of this publication date.

3. Appendix A: Revision History

Doc. Rev.	Date	Comments
E	5/2022	Added silicon errata item 1.6.1.
D	10/2021	Updated Table 2. Added silicon errata items 1.2.1, 1.3.1, 1.4.1 and 1.5.1.
C	2/2021	Added silicon revision A6
B	10/2020	Adding silicon revision A5
A	9/2020	Initial document release

Microchip Information

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable". Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

Legal Notice

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded

by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at www.microchip.com/en-us/support/design-help/client-support-services.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, NVM Express, NVMe, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQL, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, Symmcom, and Trusted Time are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2020-2022, Microchip Technology Incorporated and its subsidiaries. All Rights Reserved.

ISBN: 978-1-6683-0351-1

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.

Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: www.microchip.com/support Web Address: www.microchip.com	Australia - Sydney Tel: 61-2-9868-6733 China - Beijing Tel: 86-10-8569-7000 China - Chengdu Tel: 86-28-8665-5511 China - Chongqing Tel: 86-23-8980-9588 China - Dongguan Tel: 86-769-8702-9880 China - Guangzhou Tel: 86-20-8755-8029 China - Hangzhou Tel: 86-571-8792-8115 China - Hong Kong SAR Tel: 852-2943-5100 China - Nanjing Tel: 86-25-8473-2460 China - Qingdao Tel: 86-532-8502-7355 China - Shanghai Tel: 86-21-3326-8000 China - Shenyang Tel: 86-24-2334-2829 China - Shenzhen Tel: 86-755-8864-2200 China - Suzhou Tel: 86-186-6233-1526 China - Wuhan Tel: 86-27-5980-5300 China - Xian Tel: 86-29-8833-7252 China - Xiamen Tel: 86-592-2388138 China - Zhuhai Tel: 86-756-3210040	India - Bangalore Tel: 91-80-3090-4444 India - New Delhi Tel: 91-11-4160-8631 India - Pune Tel: 91-20-4121-0141 Japan - Osaka Tel: 81-6-6152-7160 Japan - Tokyo Tel: 81-3-6880-3770 Korea - Daegu Tel: 82-53-744-4301 Korea - Seoul Tel: 82-2-554-7200 Malaysia - Kuala Lumpur Tel: 60-3-7651-7906 Malaysia - Penang Tel: 60-4-227-8870 Philippines - Manila Tel: 63-2-634-9065 Singapore Tel: 65-6334-8870 Taiwan - Hsin Chu Tel: 886-3-577-8366 Taiwan - Kaohsiung Tel: 886-7-213-7830 Taiwan - Taipei Tel: 886-2-2508-8600 Thailand - Bangkok Tel: 66-2-694-1351 Vietnam - Ho Chi Minh Tel: 84-28-5448-2100	Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393 Denmark - Copenhagen Tel: 45-4485-5910 Fax: 45-4485-2829 Finland - Espoo Tel: 358-9-4520-820 France - Paris Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79 Germany - Garching Tel: 49-8931-9700 Germany - Haan Tel: 49-2129-3766400 Germany - Heilbronn Tel: 49-7131-72400 Germany - Karlsruhe Tel: 49-721-625370 Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44 Germany - Rosenheim Tel: 49-8031-354-560 Israel - Ra'anana Tel: 972-9-744-7705 Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781 Italy - Padova Tel: 39-049-7625286 Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340 Norway - Trondheim Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820