

Product Change Notification / SYST-11UTWE009

Date:

15-Aug-2022

Product Category:

8-bit Microcontrollers

PCN Type:

Document Change

Notification Subject:

ERRATA - AVR32/16DD14/20 Silicon Errata and Data Sheet Clarification Revision

Affected CPNs:

SYST-11UTWE009_Affected_CPN_08152022.pdf SYST-11UTWE009_Affected_CPN_08152022.csv

Notification Text:

SYST-11UTWE009

Microchip has released a new Errata for the AVR32/16DD14/20 Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at AVR32/16DD14/20 Silicon Errata and Data Sheet Clarification.

Notification Status: Final

Description of Change: Added new silicon revision (Rev. A2)

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 15 Aug 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices::N/A

Attachments:

AVR32/16DD14/20 Silicon Errata and Data Sheet Clarification

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our PCN home page select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the PCN FAQ section.

If you wish to <u>change your PCN profile, including opt out</u>, please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.



AVR32/16DD14/20

AVR16/32DD14/20 Silicon Errata and Data Sheet Clarification

The AVR32/16DD14/20 devices you have received conform functionally to the current device data sheet (www.microchip.com/DS40002413), except for the anomalies described in this document. The errata described in this document will likely be addressed in future revisions of the AVR32/16DD14/20 devices.

Notes:

- This document summarizes all the silicon errata issues from all the silicon revisions, previous and current
- Refer to the Device/Revision ID section in the current device data sheet (www.microchip.com/DS40002413) for more detailed information on Device Identification and Revision IDs for your specific device, or contact your local Microchip sales office for assistance

Table of Contents

1.	Silico	n Issue Summary
2.	Silico	n Errata Issues
	2.1.	Errata Details4
	2.2.	Device
	2.3.	NVMCTRL - Nonvolatile Memory Controller
	2.4.	TCD - 12-Bit Timer/Counter Type D5
	2.5.	USART - Universal Synchronous and Asynchronous Receiver and Transmitter5
3.	Data	Sheet Clarifications
	3.1.	None
4.	Docur	nent Revision History7
	4.1.	Revision History
Mic	rochip	Information8
	The M	ficrochip Website
	Produ	ct Change Notification Service
	Custo	mer Support8
	Micro	chip Devices Code Protection Feature8
	Legal	Notice
	Trade	marks9
	Qualit	y Management System
	World	wide Sales and Service11

1. Silicon Issue Summary

Legend

- Erratum is not applicable.
- **X** Erratum is applicable.

Peripheral	Short Description	Valid for Silicon Revision	
		Rev. A1 ⁽¹⁾	Rev. A2
Device	2.2.1. Multiple High Voltage Pulses in Series can Force Pin PF7 to Remain in UPDI Configuration	Х	X X
	2.2.2. The CLKSEL Fuse can Force PF7 to Remain in UPDI Configuration	Х	-
NVMCTRL	2.3.1. Flash Multi-Page Erase Can Erase Write Protected Section	Х	Х
TCD	2.4.1. Halting TCD and Waiting for SW Restart Does Not Work if Compare Value A is 0 or Dual Slope Mode is Used	Х	Х
USART	2.5.1. Receiver Non-Functional after Detection of Inconsistent Synchronization Field	Х	Х

Note:

1. This revision is the initial release of the silicon.

2. Silicon Errata Issues

2.1 Errata Details

- Erratum is not applicable.
- **X** Erratum is applicable.

2.2 Device

2.2.1 Multiple High Voltage Pulses in Series can Force Pin PF7 to Remain in UPDI Configuration

If applying multiple high voltage pulses to the Reset pin within a 100 ms timeframe, pin PF7 will remain as a UPDI pin even if no UPDI key is given. If PF7 is configured as GPIO pin (UPDIPINCFG is '0' in FUSE.SYSCFG0), it will only return to GPIO mode after a Reset is issued by either POR or BOD.

Work Around

None.

Affected Silicon Revisions

Rev. A1	Rev. A2
X	X

2.2.2 The CLKSEL Fuse can Force PF7 to Remain in UPDI Configuration

When the CLKSEL fuse is configured to OSC32K and a high voltage pulse is applied to the Reset pin, pin PF7 will remain as a UPDI pin even if no UPDI key is given. If PF7 is configured to GPIO pin (UPDIPINCFG is '0' in FUSE.SYSCFG0), it will only return to GPIO mode after a Reset is issued by POR.

Work Around

Do not configure the PF7 pin to the GPIO mode if the CLKSEL fuse is configured to OSC32K.

Affected Silicon Revisions

Rev. A1	Rev. A2
X	-

2.3 NVMCTRL - Nonvolatile Memory Controller

2.3.1 Flash Multi-Page Erase Can Erase Write Protected Section

When using Flash Multi-Page Erase mode, only the first page in the selected address range is verified to be within a section that is not write-protected. If the address range includes any write-protected Application Data pages, it will erase them.

Work Around

None.

AVR32/16DD14/20

Silicon Errata Issues

Affected Silicon Revisions

Rev. A1	Rev. A2
X	X

2.4 TCD - 12-Bit Timer/Counter Type D

2.4.1 Halting TCD and Waiting for SW Restart Does Not Work if Compare Value A is 0 or Dual Slope Mode is Used

Halting TCD and waiting for software restart (INPUTMODE in TCDn.INPUTCTRLA is ' 0×7 ') does not work if compare value A is 0 (CMPASET in TCDn.CMPASET is ' 0×0 ') or Dual Slope mode is used (WGMODE in TCDn.CTRLB is ' 0×3 ').

Work Around

Configure the compare value A (CMPASET in TCDn.CMPASET) to be different from 0 and do not use Dual Slope mode (WGMODE in TCDn.CTRLB is not '0x3').

Affected Silicon Revisions

Rev. A1	Rev. A2
X	X

2.5 USART - Universal Synchronous and Asynchronous Receiver and Transmitter

2.5.1 Receiver Non-Functional after Detection of Inconsistent Synchronization Field

The USART Receiver becomes non-functional when the Inconsistent Synchronization Field Interrupt Flag (ISFIF) in the Status (USARTn.STATUS) register is set. The ISFIF interrupt flag is set when the Receiver Mode (RXMODE) bit field in the Control B (USARTn.CTRLB) register is configured to Generic Auto-Baud (GENAUTO) mode or LIN Constrained Auto-Baud (LINAUTO) mode, and the received synchronization frame does not conform to the conditions described in the data sheet. Clearing the flag does not re-enable the USART Receiver.

Work Around

When the ISFIF interrupt flag is set, disable and re-enable the USART Receiver by first writing a '0' and then write a '1' to the Receiver Enable (RXEN) bit in the Control B (USARTn.CTRLB) register.

Affected Silicon Revisions

Rev. A1	Rev. A2
X	X

3. Data Sheet Clarifications

Note the following typographic corrections and clarifications for the latest version of the device data sheet (www.microchip.com/DS40002413).

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

3.1 None

There are no known data sheet clarifications as of this publication date.

4. Document Revision History

Note: The document revision is independent of the silicon revision.

4.1 Revision History

Doc. Rev.	Date	Comments
С	08/2022	Added new silicon revision (Rev. A2)
В	06/2022	Changed the revision of the initial release of the silicon
А	05/2022	Initial document release

Microchip Information

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip products:

- · Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable". Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

Legal Notice

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded

by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at www.microchip.com/en-us/support/design-help/client-support-services.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet- Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, KoD, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2022, Microchip Technology Incorporated and its subsidiaries. All Rights Reserved.

ISBN: 978-1-6683-1004-5

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



Worldwide Sales and Service

ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
Australia - Sydney	India - Bangalore	Austria - Wels
Tel: 61-2-9868-6733	Tel: 91-80-3090-4444	Tel: 43-7242-2244-39
		Fax: 43-7242-2244-393
		Denmark - Copenhagen
		Tel: 45-4485-5910
-		Fax: 45-4485-2829
		Finland - Espoo
	•	Tel: 358-9-4520-820
		France - Paris
•••		Tel: 33-1-69-53-63-20
		Fax: 33-1-69-30-90-79
-		Germany - Garching
		Tel: 49-8931-9700
-		Germany - Haan
		Tel: 49-2129-3766400
		Germany - Heilbronn
		Tel: 49-7131-72400
		Germany - Karlsruhe
		Tel: 49-721-625370
-		Germany - Munich
		Tel: 49-89-627-144-0
•	•••	Fax: 49-89-627-144-44
		Germany - Rosenheim
		Tel: 49-8031-354-560
		Israel - Ra'anana
	-	Tel: 972-9-744-7705
		Italy - Milan Tel: 39-0331-742611
		Fax: 39-0331-466781
	-	Italy - Padova
		Tel: 39-049-7625286
		Netherlands - Drunen
	Tel: 64-26-5446-2100	Tel: 31-416-690399
		Fax: 31-416-690340
		Norway - Trondheim Tel: 47-72884388
Tel: 86-756-3210040		Poland - Warsaw
		Tel: 48-22-3325737
		Romania - Bucharest
		Tel: 40-21-407-87-50
		Spain - Madrid
		Tel: 34-91-708-08-90
		Fax: 34-91-708-08-91
		Sweden - Gothenberg
		Tel: 46-31-704-60-40
		Sweden - Stockholm
		Tel: 46-8-5090-4654
		UK - Wokingham
		Tel: 44-118-921-5800
		Fax: 44-118-921-5820
	China - Beijing Tel: 86-10-8569-7000 China - Chengdu Tel: 86-28-8665-5511 China - Chongqing Tel: 86-23-8980-9588 China - Dongguan Tel: 86-769-8702-9880 China - Guangzhou Tel: 86-20-8755-8029 China - Hangzhou Tel: 86-20-8755-8029 China - Hangzhou Tel: 86-571-8792-8115 China - Hong Kong SAR Tel: 852-2943-5100 China - Nanjing Tel: 86-25-8473-2460 China - Qingdao Tel: 86-532-8502-7355 China - Shanghai Tel: 86-21-3326-8000 China - Shenyang Tel: 86-24-2334-2829 China - Shenzhen Tel: 86-755-8864-2200 China - Suzhou Tel: 86-186-6233-1526 China - Suzhou Tel: 86-186-6233-1526 China - Wuhan Tel: 86-27-5980-5300 China - Xian Tel: 86-29-8833-7252 China - Xiam Tel: 86-592-2388138 China - Zhuhai Tel: 86-756-3210040	China - Beijing India - New Delhi Tel: 86-10-8569-7000 Tel: 91-11-4160-8631 China - Chengdu India - Pune Tel: 86-28-8665-5511 Tel: 91-20-4121-0141 China - Chongqing Japan - Osaka Tel: 86-28-8800-9588 Tel: 81-6-6152-7160 China - Dongguan Japan - Tokyo Tel: 86-769-8702-9880 Tel: 81-3-6880- 3770 China - Guangzhou Korea - Daegu Tel: 86-71-8792-8115 Tel: 82-253-744-4301 China - Hangzhou Korea - Seoul Tel: 86-571-8792-8115 Tel: 82-2-554-7200 China - Hong Kong SAR Malaysia - Kuala Lumpur Tel: 86-571-8792-8115 Tel: 60-3-7651-7906 China - Nanjing Malaysia - Penang Tel: 86-25-8473-2460 Tel: 60-4-227-8870 China - Nanjing Malaysia - Penang Tel: 86-32-8502-7355 Tel: 63-2634-9065 China - Shanghai Singapore Tel: 86-21-3326-8000 Tel: 86-35-77-8366 China - Shenyang Taiwan - Hsin Chu Tel: 86-186-6233-1526 Tel: 886-7-213-7830 China - Suzhou Taiwan - Taipei Tel: 86-27-5980-5300 Te

SYST-11UTWE009 - ERRATA - AVR32/16DD14/20 Silicon Errata and Data Sheet Clarification Revision

Affected Catalog Part Numbers(CPN)

AVR32DD14-E/SL AVR16DD14-E/SL AVR32DD20-E/SO AVR16DD20-E/REB AVR16DD20-E/REB AVR16DD20-E/REB AVR32DD14-I/SL AVR16DD14-I/SL AVR32DD20-I/SO AVR16DD20-I/REB