



Product Change Notification / SYST-31MBNE432

Date:

05-Sep-2022

Product Category:

8-bit Microcontrollers

PCN Type:

Document Change

Notification Subject:

ERRATA - ATmega32A Silicon Errata and Data Sheet Clarifications

Affected CPNs:

[SYST-31MBNE432_Affected_CPN_09052022.pdf](#)

[SYST-31MBNE432_Affected_CPN_09052022.csv](#)

Notification Text:

SYST-31MBNE432

Microchip has released a new Errata for the ATmega32A Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at [ATmega32A Silicon Errata and Data Sheet Clarifications](#).

Notification Status: Final

Description of Change: Initial document release. • Content moved from the data sheet and restructured to the new document template

• Updated the die revision list to reflect die revisions in production Data Sheet Clarifications added: • Errata section in data sheet is no longer valid • 3.2. Watchdog Timer • 3.3. WDTCR

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 05 Sep 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[ATmega32A Silicon Errata and Data Sheet Clarifications](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.



ATmega32A

ATmega32A Silicon Errata and Data Sheet Clarification

Introduction

The ATmega32A devices you have received conform functionally to the current device data sheet ([DS40002072](#)), except for the anomalies described in this document. The errata described in this document will likely be addressed in future revisions of the ATmega32A devices.

Note:

- This document summarizes all the silicon errata issues from all silicon revisions, previous and current.

Table of Contents

Introduction.....	1
1. Silicon Issue Summary.....	3
2. Silicon Errata Issues.....	4
2.1. Errata Details.....	4
2.2. Analog Comparator.....	4
2.3. Interrupts.....	4
2.4. JTAG Interface.....	4
2.5. Memories.....	5
3. Data Sheet Clarifications.....	6
3.1. Errata Section in Data Sheet is no Longer Valid.....	6
3.2. Watchdog Timer.....	6
3.3. Watchdog Timer Control Register.....	7
4. Document Revision History.....	9
4.1. Revision History.....	9
Microchip Information.....	10
The Microchip Website.....	10
Product Change Notification Service.....	10
Customer Support.....	10
Microchip Devices Code Protection Feature.....	10
Legal Notice.....	10
Trademarks.....	11
Quality Management System.....	12
Worldwide Sales and Service.....	13

1. Silicon Issue Summary

- Erratum is not applicable.
- X** Erratum is applicable.

Peripheral	Short Description	Valid for Silicon Revision		
		Rev. G ⁽¹⁾	Rev. I	Rev. K
Analog Comparator	2.2.1. First Analog Comparator Conversion May be Delayed	X	X	X
Timer	2.3.1. Interrupts May Be Lost When Writing the Timer Registers in the Asynchronous Timer (Timer/Counter 2)	X	X	X
JTAG Interface	2.4.1. IDCODE Masks Data From TDI Input	X	X	X
Memories	2.5.1. Reading EEPROM by Using ST or STS to Set EERE Bit Triggers Unexpected Interrupt Request	X	X	X

Note:

1. This revision is the initial release of the silicon.

2. Silicon Errata Issues

2.1 Errata Details

- Erratum is not applicable.
- X Erratum is applicable.

2.2 Analog Comparator

2.2.1 First Analog Comparator Conversion May be Delayed

If a slow-rising V_{CC} powers the device, the first Analog Comparator conversion will take longer than expected on some devices.

Work Around

When the device has been powered or reset, disable and enable the Analog Comparator before the first conversion.

Affected Silicon Revisions

ATmega32A		
Rev. G	Rev. I	Rev. K
X	X	X

2.3 Interrupts

2.3.1 Interrupts May Be Lost When Writing the Timer Registers in the Asynchronous Timer (Timer/Counter 2)

The interrupt will be lost if writing one of the registers Timer/Counter 2 Control Register (TCCR2), Timer/Counter 2 Register (TCNT2), or Timer/Counter 2 Output Compare Register (OCR2) when the Timer/Counter 2 Register is 0x00.

Work Around

Always check that the asynchronous Timer/Counter register (TCNT2) neither has the value 0xFF nor 0x00 before writing to the Timer/Counter 2 Control Register (TCCR2), Timer/Counter 2 Register (TCNT2), or Timer/Counter 2 Output Compare Register (OCR2).

Affected Silicon Revisions

ATmega32A		
Rev. G	Rev. I	Rev. K
X	X	X

2.4 JTAG Interface

2.4.1 IDCODE Masks Data From TDI Input

The JTAG instruction IDCODE is not working correctly. Data to succeeding devices are replaced by all-ones during Update-DR.

Work Around

- The problem is not visible if ATmega32A is the only device in the scan chain
- Select the Device ID Register of the ATmega32A by issuing the IDCODE instruction or by entering the Test-Logic-Reset state of the TAP controller to read out the contents of its Device ID Register and possibly data from succeeding devices of the scan chain. Issue the BYPASS instruction to the ATmega32A while reading the Device ID Registers of preceding devices of the boundary scan chain
- If the Device IDs of all devices in the boundary scan chain are captured simultaneously, the ATmega32A must be the first device in the chain

Affected Silicon Revisions

ATmega32A		
Rev. G	Rev. I	Rev. K
X	X	X

2.5 Memories

2.5.1 Reading EEPROM by Using ST or STS to Set EERE Bit Triggers Unexpected Interrupt Request

Reading EEPROM using the ST or STS command to set the EERE bit in the EECR register triggers an unexpected EEPROM interrupt request.

Work Around

Always use OUT or SBI to set EERE in EECR.

Affected Silicon Revisions

ATmega32A		
Rev. G	Rev. I	Rev. K
X	X	X

3. Data Sheet Clarifications

Note the following typographic corrections and clarifications for the latest version of the device data sheet ([DS40002072](#)).

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

3.1 Errata Section in Data Sheet is no Longer Valid

A clarification for the Errata section in the device data sheet has been made.

The errata content has been moved to a separate document, *ATmega32A Silicon Errata and Data Sheet Clarification* (this document).

See the *Silicon Errata Issues* section of this document for the latest errata.

3.2 Watchdog Timer

A clarification has been made for the typical Watchdog Timer oscillator frequency.

The Watchdog Timer is clocked from a separate On-chip Oscillator which runs at **1.25 MHz**. A typical value at $V_{CC} = 5V$ and a temperature of 25°C. See characterization data for typical values at other V_{CC} levels and/or temperatures. The Watchdog Reset interval can be adjusted by controlling the Watchdog Timer prescaler, as shown in Table 11-1 on page 50. The WDR – Watchdog Reset – instruction resets the Watchdog Timer. The Watchdog Timer is also reset when it is disabled and when a Chip Reset occurs. Eight different clock cycle periods can be selected to determine the reset period. If the reset period expires without another Watchdog Reset, the ATmega32A resets and executes from the Reset Vector. For timing details on the Watchdog Reset, refer to page 47.

3.3 Watchdog Timer Control Register

Name: WDTCR
Offset: -
Reset: 0x00
Property: -

Bit	7	6	5	4	3	2	1	0
				WDTOE	WDE		WDP[2:0]	
Access				R/W	R/W	R/W	R/W	R/W
Reset				0	0	0	0	0

Bit 4 – WDTOE Watchdog Turn-off Enable

Set this bit when the WDE bit is written to logic zero. Otherwise, the Watchdog will not be disabled. Once written to one, hardware will clear this bit after four clock cycles. Refer to the description of the WDE bit for a Watchdog disable procedure.

Bit 3 – WDE Watchdog Enable

When the WDE is written to logic one, the Watchdog Timer is enabled, and if the WDE is written to logic zero, the Watchdog Timer function is disabled. WDE can only be cleared if the WDTOE bit has logic level one. Follow this procedure to disable an enabled Watchdog Timer:

1. In the same operation, write a logic one to WDTOE and WDE. Write a logic one to WDE even though it is set to one before the disable operation starts.
2. Within the following four clock cycles, write a logic 0 to WDE, which disables the Watchdog.

Bits 2:0 – WDP[2:0] Watchdog Timer Prescaler

The WDP2, WDP1, and WDP0 bits determine the Watchdog Timer prescaling when the Watchdog Timer is enabled. The table below shows the different prescaling values and their corresponding Timeout Periods.

Table 3-1. Watchdog Timer Prescale Select

WDP2	WDP1	WDP0	Number of WDT Oscillator Cycles	Typical Time-Out at $V_{CC} = 3.0V$	Typical Time-Out at $V_{CC} = 5.0V$
0	0	0	16K (16,384)	14 ms	13 ms
0	0	1	32K (32,768)	28 ms	26 ms
0	1	0	64K (65,536)	56 ms	52 ms
0	1	1	128K (131,072)	0.11s	0.10s
1	0	0	256K (262,144)	0.22s	0.21s
1	0	1	512K (524,288)	0.45s	0.42s
1	1	0	1,024K (1,048,576)	0.89s	0.84s
1	1	1	2,048K (2,097,152)	1.8s	1.7s

The following code example shows one assembly and one C function for turning off the WDT. It assumes that interrupts are controlled (e.g, by disabling interrupts globally) so that no interrupts will occur during the execution of these functions.

Assembly Code Example

```
WDT_off:
    ; reset WDT
    wdr
    ; Write logical one to WDTOE and WDE
    in r16, WDTCR
    ori r16, (1<<WDTOE) | (1<<WDE)
    out WDTCR, r16
    ; Turn off WDT
    ldi r16, (0<<WDE)
    out WDTCR, r16
    ret
```

C Code Example

```
void WDT_off(void)
{
    /* reset WDT */
    WDR();
    /* Write logical one to WDTOE and WDE */
    WDTCR |= (1<<WDTOE) | (1<<WDE);
    /* Turn off WDT */
    WDTCR = 0x00;
}
```

4. Document Revision History

Note: The document revision is independent of the silicon revision.

4.1 Revision History

Doc Rev.	Date	Comments
A	09/2022	<p>Initial document release.</p> <ul style="list-style-type: none">• Content moved from the data sheet and restructured to the new document template• Updated the die revision list to reflect die revisions in production <p>Data Sheet Clarifications added:</p> <ul style="list-style-type: none">• Errata section in data sheet is no longer valid• 3.2. Watchdog Timer• 3.3. WDTCR

Microchip Information

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable". Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

Legal Notice

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded

by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at www.microchip.com/en-us/support/design-help/client-support-services.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, KoD, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQL, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2022, Microchip Technology Incorporated and its subsidiaries. All Rights Reserved.

ISBN: 978-1-6683-1000-7

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.

Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: www.microchip.com/support Web Address: www.microchip.com	Australia - Sydney Tel: 61-2-9868-6733 China - Beijing Tel: 86-10-8569-7000 China - Chengdu Tel: 86-28-8665-5511 China - Chongqing Tel: 86-23-8980-9588 China - Dongguan Tel: 86-769-8702-9880 China - Guangzhou Tel: 86-20-8755-8029 China - Hangzhou Tel: 86-571-8792-8115 China - Hong Kong SAR Tel: 852-2943-5100 China - Nanjing Tel: 86-25-8473-2460 China - Qingdao Tel: 86-532-8502-7355 China - Shanghai Tel: 86-21-3326-8000 China - Shenyang Tel: 86-24-2334-2829 China - Shenzhen Tel: 86-755-8864-2200 China - Suzhou Tel: 86-186-6233-1526 China - Wuhan Tel: 86-27-5980-5300 China - Xian Tel: 86-29-8833-7252 China - Xiamen Tel: 86-592-2388138 China - Zhuhai Tel: 86-756-3210040	India - Bangalore Tel: 91-80-3090-4444 India - New Delhi Tel: 91-11-4160-8631 India - Pune Tel: 91-20-4121-0141 Japan - Osaka Tel: 81-6-6152-7160 Japan - Tokyo Tel: 81-3-6880-3770 Korea - Daegu Tel: 82-53-744-4301 Korea - Seoul Tel: 82-2-554-7200 Malaysia - Kuala Lumpur Tel: 60-3-7651-7906 Malaysia - Penang Tel: 60-4-227-8870 Philippines - Manila Tel: 63-2-634-9065 Singapore Tel: 65-6334-8870 Taiwan - Hsin Chu Tel: 886-3-577-8366 Taiwan - Kaohsiung Tel: 886-7-213-7830 Taiwan - Taipei Tel: 886-2-2508-8600 Thailand - Bangkok Tel: 66-2-694-1351 Vietnam - Ho Chi Minh Tel: 84-28-5448-2100	Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393 Denmark - Copenhagen Tel: 45-4485-5910 Fax: 45-4485-2829 Finland - Espoo Tel: 358-9-4520-820 France - Paris Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79 Germany - Garching Tel: 49-8931-9700 Germany - Haan Tel: 49-2129-3766400 Germany - Heilbronn Tel: 49-7131-72400 Germany - Karlsruhe Tel: 49-721-625370 Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44 Germany - Rosenheim Tel: 49-8031-354-560 Israel - Ra'anana Tel: 972-9-744-7705 Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781 Italy - Padova Tel: 39-049-7625286 Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340 Norway - Trondheim Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820

SYST-31MBNE432 - ERRATA - ATmega32A Silicon Errata and Data Sheet Clarifications

Affected Catalog Part Numbers(CPN)

ATMEGA32A-PU
ATMEGA32A-MU
ATMEGA32A-AU
ATMEGA32A-PN
ATMEGA32A-MN
ATMEGA32A-AN
ATMEGA32A-MNR
ATMEGA32A-ANR
ATMEGA32A-MUR
ATMEGA32A-AUR
ATMEGA32A-AURA5