



Product Change Notification / SYST-16TKLM388

Date:

17-Nov-2022

Product Category:

8-bit Microcontrollers

PCN Type:

Document Change

Notification Subject:

ERRATA - PIC18F26/45/46Q10 Silicon Errata and Data Sheet Clarifications

Affected CPNs:

[SYST-16TKLM388_Affected_CPN_11172022.pdf](#)

[SYST-16TKLM388_Affected_CPN_11172022.csv](#)

Notification Text:

SYST-16TKLM388

Microchip has released a new Errata for the PIC18F26/45/46Q10 Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at [PIC18F26/45/46Q10 Silicon Errata and Data Sheet Clarifications](#).

Notification Status: Final

Description of Change: Added silicon erratum item 1.10.1

Impacts to Data Sheet: None

Change Implementation Status: Complete

Date Document Changes Effective: 17 Nov 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[PIC18F26/45/46Q10 Silicon Errata and Data Sheet Clarifications](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

PIC18F26/45/46Q10 Silicon Errata and Data Sheet Clarifications

The PIC18F26/45/46Q10 devices you have received conform functionally to the current device data sheet (DS40001996D), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in the table below.

The errata described in this document will be addressed in future revisions of the PIC18F26/45/46Q10 silicon.

Note: This document summarizes all silicon errata issues from all silicon revisions, previous and current.

Table 1. Silicon Device Identification

| Part Number | Device ID | Revision ID | | |
|-------------|-----------|-------------|--------|--------|
| | | A5 | B0 | B2 |
| PIC18F26Q10 | 0x7180 | 0xA045 | 0xA0C0 | 0xA0C2 |
| PIC18F45Q10 | 0x7140 | 0xA045 | 0xA0C0 | 0xA0C2 |
| PIC18F46Q10 | 0x7120 | 0xA045 | 0xA0C0 | 0xA0C2 |



Important: Refer to the **Device/Revision ID** section in the current “**PIC18F2X/4XQ10 Memory Programming Specification**” (DS40001874) for more detailed information on Device Identification and Revision IDs for your specific device.

Table 2. Silicon Issue Summary

| Module | Feature | Item No. | Issue Summary | Affected Revisions | | |
|--|------------------------|------------------------|---|--------------------|----|----|
| | | | | A5 | B0 | B2 |
| Electrical Specifications | Sleep current | 1.1.1. | Higher current after DFM write | X | | |
| Resets | RMCLR flag | 1.2.1. | POR may clear the RMCLR bit by mistake | X | X | X |
| Resets | LPBOR | 1.2.2. | Trip point rises with temperature | | X | |
| CWG | Auto-shutdown sources | 1.3.1. | CLC2 and CLC6 not available | X | | |
| ADCC | FVR reference | 1.4.1. | Missing codes when using FVR as reference | X | X | X |
| ADCC | Burst average | 1.4.2. | ADCNT may not increment | X | | |
| ADCC | ADCRC (FRC) oscillator | 1.4.3. | Oscillator continues to run in Sleep mode after conversion | X | | |
| ADCC | Input slew rate | 1.4.4. | Unreliable conversion results with fast falling slew rate | X | X | X |
| WWDT | Window operation | 1.5.1. | The window feature of WWDT does not operate correctly in Doze mode | X | | |
| NVM | NVMERR | 1.6.1. | The NVMERR bit is set by device Reset after being cleared by the software | X | | |
| NVM | Self-writes | 1.6.2. | Do not write above 85°C | X | | |
| MSSP | SPI | 1.7.1. | SSPBUF may be corrupted by writes to other GPR/SFRs | X | | |
| Oscillator | HFINTOSC | 1.8.1. | 5% variation over temperature range | X | | |
| Oscillator | XT mode | 1.8.2. | Maximum clock frequency limited to 2 MHz for XT mode | X | X | |
| In-Circuit Debug | Software breakpoints | 1.9.1. | Software breakpoints are not available | X | X | X |
| PFM-Program Flash Memory | Self-Write | 1.10.1 | The first instruction following a self-write instruction may not execute. | X | X | X |
| Note: Only issues indicated in the last column apply to the current silicon revision. | | | | | | |

1. Silicon Errata Issues

CAUTION

Notice: This document summarizes all silicon errata issues from all revisions of silicon, previous and current. Only the issues indicated by the bold font in the following tables apply to the current silicon revision.

1.1 Module: Electrical Specifications

1.1.1 Sleep Current - Higher Sleep Current After DFM Write Operation

The system clock will stay Active when performing a DFM write operation during Sleep mode once completing the write operation, meaning a higher Sleep current will be experienced when the device remains in this state.

Work around

Once completing the DFM write operation, wake the device up from Sleep mode and re-execute a new Sleep command.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | | |

1.2 Module: Resets

1.2.1 The RMCLR Flag in the PCON0 Register Cleared by Mistake

On an initial power-up of the device or when executing a software Reset, the RMCLR flag in the PCON0 register may be improperly cleared by a Power-on Reset (POR) or software Reset (RI), thereby indicating a false MCLR event.

Work around

None.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | X | X |

1.2.2 Low-Power Brown-out Reset (LPBOR) Mode

The Brown-out Reset trip level increases proportionally with temperature to a level where BOR is never released. LPBOR cannot be used reliably because the trip level relative to temperature is indeterminate.

Work around

Use the Normal-Power BOR mode.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| | | |

| | | |
|--|---|--|
| | X | |
|--|---|--|

1.3 Module: Complementary Waveform Generator (CWG)

1.3.1 CWG Auto-Shutdown Sources

Shutdown sources AS6E (CLC2_out) and AS7E (CLC6_out) are unavailable.

Work around

Route the CLC output through PPS to an output pin, and use the AS0E source selection (the pin selected by CWGxPPS) and PPS controls to select the same pin as the shutdown source.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | | |

1.4 Module: Analog-to-Digital Converter with Computation (ADCC)

1.4.1 Missing Codes with FVR Reference

Using the FVR as the positive voltage reference for the ADC can cause an increase in missing codes.

Work around

Method 1:

Increase the bit conversion time, known as T_{AD} , to 8 μ s or higher.

Method 2:

Use V_{DD} as the positive voltage reference to the ADC.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | X | X |

1.4.2 ADCC Burst Average Mode

When the ADCC is operated in Burst Average mode (ADMD = 0b011 in the ADCON2 register) while enabling noncontinuous operation and double-sampling (ADCONT = 0 in the ADCON0 register and ADDSEN = 1 in the ADCON1 register), the value in the ADCNT register does not increment beyond '0b1' toward the value in the ADRPT register.

Work around

When operating the ADCC in Burst Average mode with double-sampling, enable continuous module operation (ADCONT = 1 in the ADCON0 register) and set the Stop-on-Interrupt bit (the ADSOI bit in the ADCON3 register). After the interrupt occurs, perform appropriate threshold calculations in the software and retrigger ADCC as necessary.

Alternatively, if the CPU is in Low-Power Sleep mode, the ADCC in noncontinuous Burst Average mode can be operated with a single ADC conversion (ADDSEN = 0 in the ADCON1 register). Doing so compromises noise immunity for lower power consumption by preventing the device from waking up to perform threshold calculations in the software.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | | |

1.4.3 ADCRC (FRC) Oscillator Operation in Sleep Mode

If the part is in Sleep mode and the ADCRC (FRC) oscillator is used as clock source to the ADC, the oscillator continues to run after the conversion is complete, increasing the current consumption in Sleep mode. The oscillator will stop after the device exits Sleep mode and resumes normal code execution.

Work around

None.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | | |

1.4.4 Unreliable Conversion Results with Fast Falling Slew Rate

When the ADC input falls by greater than 3.2V, with a slew rate faster than $-11 \text{ V}/\mu\text{s}$, the following ADC conversion will have the Most Significant bit (MSb) improperly set. This is likely to happen when the ADC input channel is switched from one with a high input level to another with a low input level.

Work around

When switching between input channels, discard the first conversion result after the switch. Subsequent conversions will not be affected.

Affected Silicon Revisions

| A4 | B0 | B2 |
|----|----|----|
| X | X | X |

1.5 Module: Windowed Watchdog Timer (WWDT)

1.5.1 Window Operation in Doze Mode

When enabling the Windowed operation mode in Doze mode, a window violation error is issued even though the window is open and armed. This condition occurs only when the window size is set to a value other than 100% open.

Work around

Method 1:

Use the Windowed operation mode in any mode other than Doze. If disabling the Doze mode is not an option, use the WWDT module without enabling the window.

Method 2:

If the device is in Doze mode, perform the arming process for the window in Normal mode and return to the Doze mode.

Method 3:

If there is an Interrupt Service Routine (ISR) in the application code, the arming within the window can be done inside the ISR with the ROI bit of the CPUDOZE register being set.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | | |

1.6 Module: Nonvolatile Memory (NVM)**1.6.1 NVMERR**

When a Reset is issued while an NVM high-voltage operation is in progress, the NVMERR bit in the NVMCON0 register is set as expected. After clearing the NVMERR bit, if a Reset reoccurs, the NVMERR bit is set again regardless of whether an NVM operation is in progress or not. A successful write operation will clear the NVMERR condition.

Work around

None.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | | |

1.6.2 PFM Writes Above 85° Celsius

Do not perform write operations on the Program Flash Memory (PFM) when the temperature exceeds 85°C.

Work around

Perform PFM writes below 85°C.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | | |

1.7 Module: Host Synchronous Serial Port (MSSP)**1.7.1 MSSP SPI Client Mode**

When operating in SPI Client mode, if the incoming SCK clock signal arrives during any of the conditions below, the SSPBUF Transmit Shift Register (TSR) may become corrupted. The byte transmitted to the client cannot be ensured to be correct, and the state of the WCOL bit may or may not indicate a write collision.

These conditions include:

- A write to an SFR
- A write to RAM following an SFR read
- A write to RAM before an SFR read

Work around**Method 1 (Interrupt based using \overline{SS}):**

1. Connect the \overline{SS} line to both the \overline{SS} input and either an INT or IOC input pin.
2. Enable INT or IOC interrupts (interrupt on falling edge if available, otherwise, check that $\overline{SS} == 0$ when the interrupt occurs).
3. Load SSPBUF with the data to be transmitted.

4. Continue program execution.
5. When invoking the Interrupt Service Routine (ISR), do either of the following:
 - a. Add a delay that ensures the first SCK clock will be complete, or
 - b. Poll SSPSTAT.BF (while(BF == 0)), and wait for the transmission/reception to complete.

Method 2 (Bit polling based using \overline{SS}):

1. Load SSPBUF with the data to be transmitted.
2. Poll the \overline{SS} line and wait for the \overline{SS} to go active (while(!PORTx. \overline{SS} == 0)).
3. When \overline{SS} is active (\overline{SS} == 0), do either of the following:
 - a. Add a delay that ensures the first SCK clock will be complete, or
 - b. Poll SSPSTAT.BF (while(BF == 0)), and wait for the transmission/reception to complete.

Once one of these two methods is complete, it is safe to return to program execution.

Method 3 (\overline{SS} not available):

1. Load SSPBUF with the data to be transmitted.
2. Poll SSPSTAT.BF (while(BF == 0)), and wait for the transmission/reception to complete.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | | |

1.8 Module: Oscillator

1.8.1 Internal HFINTOSC Oscillator Varies up to 5%

The internal HFINTOSC oscillator frequency varies up to 5% over the voltage and temperature range.

Work around

For systems requiring more precision, use an external crystal or ceramic resonator in one of the external oscillator modes.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | | |

1.8.2 Maximum Clock Frequency Limited to 2 MHz for XT Mode

The maximum clock frequency for the intermediate gain setting that supports quartz crystal and ceramic resonator operation (XT mode) is being reduced from 4 MHz to 2 MHz.

Work around

For crystal or resonator frequencies above 2 MHz, use HS mode.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | X | |

1.9 Module: In-Circuit Debug

1.9.1 Software Breakpoints Are Not Available

When debugging code, software breakpoints will not be available.

Work around

None.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | X | X |

1.10 Module: Program Flash Memory (PFM)

1.10.1 The First Instruction Following a Self-Write Instruction May Not Execute

When performing a self-write operation to Program Flash Memory, the first instruction following a self-write instruction may not execute.

Work around

Add two all-zero `NOP()` macros immediately after the self-write instruction. The all-zero `NOP()` macros are included automatically when the `#include <xc.h>` directive is used in user software.

Affected Silicon Revisions

| A5 | B0 | B2 |
|----|----|----|
| X | X | X |

2. Data Sheet Clarifications

2.1 None

There are no known data sheet clarifications as of this publication date.

3. **Appendix A: Revision History**

| Doc Rev. | Date | Comments |
|----------|---------|--|
| H | 11/2022 | Added silicon erratum item 1.10.1 |
| G | 07/2021 | Removed silicon erratum item 1.4.5. Minor editorial corrections. |
| F | 02/2021 | Added silicon erratum items 1.4.5 and 1.9.1 |
| E | 11/2020 | Updated the Revision ID for silicon Rev B0 |
| D | 09/2020 | Added new silicon Rev B2 |
| C | 05/2020 | Added new silicon Rev B0. Added issue 1.2.2 and 1.8.2. |
| B | 05/2019 | Added oscillator drift erratum. Removed data sheet clarifications. |
| A | 03/2019 | Initial document release |

Microchip Information

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable". Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

Legal Notice

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded

by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at www.microchip.com/en-us/support/design-help/client-support-services.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet- Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePicta, TimeProvider, TrueTime, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, KoD, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQL, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2019-2022, Microchip Technology Incorporated and its subsidiaries. All Rights Reserved.

ISBN: 978-1-5224-922-0

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.

Worldwide Sales and Service

| AMERICAS | ASIA/PACIFIC | ASIA/PACIFIC | EUROPE |
|--|--|---|---|
| Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: www.microchip.com/support Web Address: www.microchip.com | Australia - Sydney Tel: 61-2-9868-6733 China - Beijing Tel: 86-10-8569-7000 China - Chengdu Tel: 86-28-8665-5511 China - Chongqing Tel: 86-23-8980-9588 China - Dongguan Tel: 86-769-8702-9880 China - Guangzhou Tel: 86-20-8755-8029 China - Hangzhou Tel: 86-571-8792-8115 China - Hong Kong SAR Tel: 852-2943-5100 China - Nanjing Tel: 86-25-8473-2460 China - Qingdao Tel: 86-532-8502-7355 China - Shanghai Tel: 86-21-3326-8000 China - Shenyang Tel: 86-24-2334-2829 China - Shenzhen Tel: 86-755-8864-2200 China - Suzhou Tel: 86-186-6233-1526 China - Wuhan Tel: 86-27-5980-5300 China - Xian Tel: 86-29-8833-7252 China - Xiamen Tel: 86-592-2388138 China - Zhuhai Tel: 86-756-3210040 | India - Bangalore Tel: 91-80-3090-4444 India - New Delhi Tel: 91-11-4160-8631 India - Pune Tel: 91-20-4121-0141 Japan - Osaka Tel: 81-6-6152-7160 Japan - Tokyo Tel: 81-3-6880-3770 Korea - Daegu Tel: 82-53-744-4301 Korea - Seoul Tel: 82-2-554-7200 Malaysia - Kuala Lumpur Tel: 60-3-7651-7906 Malaysia - Penang Tel: 60-4-227-8870 Philippines - Manila Tel: 63-2-634-9065 Singapore Tel: 65-6334-8870 Taiwan - Hsin Chu Tel: 886-3-577-8366 Taiwan - Kaohsiung Tel: 886-7-213-7830 Taiwan - Taipei Tel: 886-2-2508-8600 Thailand - Bangkok Tel: 66-2-694-1351 Vietnam - Ho Chi Minh Tel: 84-28-5448-2100 | Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393 Denmark - Copenhagen Tel: 45-4485-5910 Fax: 45-4485-2829 Finland - Espoo Tel: 358-9-4520-820 France - Paris Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79 Germany - Garching Tel: 49-8931-9700 Germany - Haan Tel: 49-2129-3766400 Germany - Heilbronn Tel: 49-7131-72400 Germany - Karlsruhe Tel: 49-721-625370 Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44 Germany - Rosenheim Tel: 49-8031-354-560 Israel - Ra'anana Tel: 972-9-744-7705 Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781 Italy - Padova Tel: 39-049-7625286 Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340 Norway - Trondheim Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820 |

SYST-16TKLM388 - ERRATA - PIC18F26/45/46Q10 Silicon Errata and Data Sheet Clarifications

Affected Catalog Part Numbers(CPN)

PIC18F26Q10-E/SP
PIC18F26Q10-E/ML
PIC18F26Q10-E/MLV02
PIC18F26Q10-E/MLVAO
PIC18F26Q10-E/SS
PIC18F26Q10-E/SSV03
PIC18F26Q10-E/SSVAO
PIC18F26Q10-E/SO
PIC18F26Q10-E/SOVAO
PIC18F45Q10-E/MP
PIC18F46Q10-E/MP
PIC18F46Q10-E/MPVAO
PIC18F45Q10-E/MPVAO
PIC18F45Q10-E/P
PIC18F46Q10-E/P
PIC18F26Q10-E/STX
PIC18F45Q10-E/PT
PIC18F46Q10-E/PT
PIC18F45Q10-E/PTVAO
PIC18F46Q10-E/PTVAO
PIC18F26Q10-I/SP
PIC18F26Q10-I/ML
PIC18F26Q10-I/SSC01
PIC18F26Q10-I/SS
PIC18F26Q10-I/SSVAO
PIC18F26Q10-I/SO
PIC18F45Q10-I/MP
PIC18F46Q10-I/MP
PIC18F45Q10-I/P
PIC18F46Q10-I/P
PIC18F26Q10-I/STX
PIC18F45Q10-I/PTC02
PIC18F45Q10-I/PT
PIC18F46Q10-I/PT
PIC18F45Q10-I/PTVAO
PIC18F46Q10-I/PTVAO
PIC18F26Q10T-I/ML
PIC18F26Q10T-I/SS020
PIC18F26Q10T-I/SSC01
PIC18F26Q10T-I/SS
PIC18F26Q10T-I/SSV01
PIC18F26Q10T-I/SSVAO

PIC18F26Q10T-I/SO
PIC18F45Q10T-I/MP
PIC18F46Q10T-I/MP
PIC18F26Q10T-I/STX
PIC18F45Q10T-I/PTC02
PIC18F45Q10T-I/PT
PIC18F46Q10T-I/PT
PIC18F45Q10T-I/PTVAO
PIC18F46Q10T-I/PTVAO
PIC18F26Q10T-E/MLVAO
PIC18F45Q10T-E/MP
PIC18F46Q10T-E/MPVAO
PIC18F45Q10T-E/MPVAO
PIC18F46Q10T-E/PTVAO