

## Product Change Notice

Alps PCN: JJ1108116\_Package Change\_Rev.1

Date: November 29, 2016

**Type of Change:** Packaging Change

**Title of Change:** 2016 Notice of Packaging Change

**Description of Change:** **Revised affected Alps part numbers from PCN dated 11/08/2016.**  
 Alps cardboard supplier changed the material-pulp used for desulfurization cardboard. There is no impact for strength of packing box, desulfurization status, and environmental status. This change has no impact to ALPS products. It is only for packing boxes.

**Contact Information:** Sales and Marketing Contact  
[Sales@alps.com](mailto:Sales@alps.com)  
 Alps Electric (North America), Inc.

**Product Affected:** Variable Resistors and Switches

### Affected Alps Part Numbers

| Part Number     | Part Number        | Part Number      | Part Number      |
|-----------------|--------------------|------------------|------------------|
| E11B15DX3MF20S  | RK097111080J       | RK0971211E02     | RKJXK122400Y     |
| EC05E1220202    | RK097111090W       | RK09712140X0     | RS15M111J002     |
| EC05E1220203    | RK0971110910       | RK09712200E9     | RSA0K11A900L     |
| EC09E1524404    | RK097111091M       | RK09712200JQ     | RSA0K11K9A16     |
| EC11B15202AA    | RK0971110D6Y       | RK09712200MC     | RSA0K11K-9T-A103 |
| EC11B1524209    | RK0971110F25C1B103 | RK0971221Z05     | RSA0K11V900C     |
| EC11B15242AE    | RK0971110Z18       | RK0971222008     | RSA0K11V900G     |
| EC11B15242AF    | RK0971110Z59       | RK09714100X4     | RSA0K12A1013     |
| EC11B152443W    | RK0971111001       | RK0971610-F15-C1 | RSA0K12V9011     |
| EC11B15244BU    | RK09711110CX       | RK097221001Y     | SRBQ490100       |
| EC11B2024305    | RK09711110EL       | RK0972211015     | SRRM264300       |
| EC45AG520402    | RK09711110FE       | RK0972420C06     | SSCW110101       |
| EM20B4004100    | RK09711110FV       | RK1631110TBK     |                  |
| EM20B4014000    | RK09711110GY       | RK1631110TQ6     |                  |
| R097111U103BK20 | RK0971111Z32       | RK163112001W     |                  |
| R09711X103BK15  | RK0971114Z07       | RK1631210AXK     |                  |
| R09711X104BK15  | RK0971114Z0N       | RK16312A0BG4     |                  |
| RDC503013A      | RK097111T065       | RK181111000E     |                  |
| RDC506002A      | RK097111TD2M       | RK271111001T     |                  |
| RK09710ELC07    | RK097111TD2P       | RK2711120026     |                  |
| RK09710ELC09    | RK097111U00T       | RK271122004D     |                  |
| RK09711100HL    | RK097111UZ03       | RK27112A00AK     |                  |
| RK09711100RA    | RK097111UZ09       | RK27112A00CC     |                  |
| RK09711100VW    | RK097111UZ0D       | RK27112MCA1R     |                  |

**Alps Sites Affected:** Americas

**Effective Date:** Immediately

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.