



Date 1/OCT/2020

TO:

Notice of Discontinued Products

We regret to inform you that we will discontinue products of Wound-type double-layer capacitors because of limited sales since our announcement of Not Recommended for New Design in APR last year.

We apologize for any convenience this may cause you

[Detail]

Affected Product	Electric double layer capacitor, all wound series HZ, HW, HL Part number: EECHZ0E***, EECHW0D***, EECHL0E*** (See Appendix)					
Schedule	Combined Order Information Last Time Order Last Time Shipment	:by :by : by	30/June/2021 30/September/2021 30/ September/2022			
Replacement available	Please contact with our sales window					
Request	Please send back below customer acknowledgement form to us within 2 months after issue date of this Notice. If we have not received a returned acknowledgement form on or before above date we will conclude that the acknowledgement has been received and approved.					

Mrs. Moto
Hiroyuki Hamato
Factory manager
Uji factory
Device Solutions Business Division
Industrial Solutions Company

Device Solutions Business Division
Industrial Solutions Company
Panasonic Corporation

Device Solutions Division
Industrial Solutions Company
Panasonic Corporation

Masaki Yoshino Department Director

Strategic Marketing Department

1. Condition of Usage ((\square	being mas produced	☐ for Preparing)		
2.	Combined Order	(□	Necessary	☐ Unnecessary)		
amo	anv Name :			Date / /		
mp	any Name :			Date / /		



APPENDIX

Electric Double Layer Capacitor(Gold Capacitor) Wound type (EOL Model List)

Series	Model No.	Diameter Φ	Maximum working voltage (V.DC)	Capacitance (F)
	EECHZ0E335	8.0	2.5	3.3
HZ	EECHZ0E475	10.0	2.5	4.7
	EECHZ0E106	10.0	2.5	10
	EECHW0D226	18.0	2.3	22
HW	EECHW0D306	18.0	2.3	30
ПVV	EECHW0D506	18.0	2.3	50
	EECHW0D706	18.0	2.1	70
	EECHL0E506	18.0	2.7	50
	EECHL0E107	18.0	2.7	100
HL	EECHL0E255 (85℃)	8.0	2.7 (2.5)	2.5
	EECHL0E405 (85℃)	10.0	2.7 (2.5)	4.0
	EECHL0E755 (85℃)	10.0	2.7 (2.5)	7.5

^{*}Individual parts number not listed in the catalogue are also object of EOL.

MPN's Affected

EECHZ0E335

EECHZ0E475

EECHZ0E106

EECHW0D226

EECHW0D306

EECHW0D506

EECHW0D706

EECHL0E255

EECHL0E405

EECHL0E755

EECHL0E506

EECHL0E107

EEC-HZ0E335

EEC-HZ0E475

EEC-HZ0E106

EEC-HW0D226

EEC-HW0D226

EEC-HW0D506

EEC-HW0D706

EEC-HL0E255

EEC-HL0E405

EEC-HL0E755

EEC-HL0E506

EEC-HL0E107