

Information note

N° 054/21

Dear customer,

With this Infineon Technologies AG information note, we would like to inform you about the following

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico



On 16 April 2020, Infineon acquired Cypress.
We are now in the process of merging and consolidating our tools and processes for PCN, Information Notes, Errata and Product Discontinuance.
For further details, please visit our website:
<https://www.infineon.com/cms/en/about-infineon/company/cypress-acquisition/>

Infineon Technologies AG
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0
Chairman of the Supervisory Board: Dr. Wolfgang Eder
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Constanze Hufenbecher, Dr. Sven Schneider
Registered Office: Neubiberg
Commercial Register: München HRB 126492

Information note

N° 054/21

► **Products affected** Please refer to attached affected product list 1_cip05421

► **Detailed change information**

Subject Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Rectificadores Internacionales, S.A. de C.V., Tijuana , Mexico.

Reason Standardization of packing material across Infineon sites

| Description | Old | New |
|-------------|--|--|
| | <ul style="list-style-type: none"> Outer packing box and plastic tube with legacy IR logo | <ul style="list-style-type: none"> Legacy IR logo removed from packing box and plastic tube |

► **Product identification** Please refer to 3_cip05421

► **Impact of change** Infineon does not see any negative impact on quality, function and reliability as it is only standardization of packing material

► **Attachments**

| | |
|------------|------------------------------|
| 1_cip05421 | affected product list |
| 3_cip05421 | customer information package |

► **Intended start of delivery** 2021-11-15

If you have any questions, please do not hesitate to contact your local sales office.

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

Customer Information Package
Information Note: 054/21



Changes and identification

Before




After



“INTERNATIONAL RECTIFIER” + Logo removed

Changes and identification

Before



After



“INTERNATIONAL RECTIFIER” + Logo removed



Part of your life. Part of tomorrow.

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|-----------------|-------------|-------------------|-------------|
| 420-190020PH | SP005344979 | 420190020PHAUMA1 | PG-TDSON-8 |
| 420-190021PH | SP005285748 | 420190021PHAUMA1 | PG-TSDSON-8 |
| 64-0084PBF | SP001569772 | 64-0084PBF | TO220 |
| 64-0085PBF | SP001574846 | 64-0085PBF | TO220 |
| 64-0088PBF | SP001569396 | 64-0088PBF | TO220 |
| 64-0090PBF | SP001574300 | 64-0090PBF | TO220 |
| 64-0098PBF | SP001569380 | 64-0098PBF | TO220 |
| 64-0100PBF | SP001575066 | 64-0100PBF | TO220 |
| 64-0102PBF | SP001560754 | 64-0102PBF | TO220 |
| 64-0103PBF | SP001559136 | 64-0103PBF | TO220 |
| 64-0105PBF | SP001574292 | 64-0105PBF | TO220 |
| 64-2079PBF | SP001569756 | 64-2079PBF | D2PAK |
| 64-2092PBF | SP001562784 | 64-2092PBF | D2PAK |
| 64-2093PBF | SP001575058 | 64-2093PBF | D2PAK |
| 64-2095PBF | SP001575050 | 64-2095PBF | D2PAK7P |
| 64-2096PBF | SP001569370 | 64-2096PBF | D2PAK7P |
| 64-2101PBF | SP001520996 | 64-2101PBF | D2PAK |
| 64-2105PBF | SP001519330 | 64-2105PBF | TO262 |
| 64-2116PBF | SP001562776 | 64-2116PBF | D2PAK |
| 64-2120PBF | SP001562760 | 64-2120PBF | D2PAK |
| 64-2123PBF | SP001560764 | 64-2123PBF | D2PAK |
| 64-2127PBF | SP001574284 | 64-2127PBF | D2PAK7P |
| 64-2127PBF-1 | SP005416752 | 64-2127PBF-1ARSA1 | D2PAK7P |
| 64-2128PBF-CU-V | SP001693762 | 64-2128PBF-CU-V | D2PAK |
| 64-2129PBF | SP001553618 | 64-2129PBF | D2PAK |
| 64-2131PBF | SP001562752 | 64-2131PBF | D2PAK7P |
| 64-2132PBF | SP001569748 | 64-2132PBF | D2PAK |
| 64-2134PBF | SP001561216 | 64-2134PBF | D2PAK |
| 64-2135PBF-V | SP001693770 | 64-2135PBF-V | D2PAK |
| 64-2138PBF | SP001574276 | 64-2138PBF | D2PAK |
| 64-2139PBF | SP001562858 | 64-2139PBF | D2PAK |
| 64-2140PBF | SP001569346 | 64-2140PBF | D2PAK |
| 64-2141PBF-V | SP001693778 | 64-2141PBF-V | D2PAK |
| 64-2144PBF | SP001562470 | 64-2144PBF | D2PAK |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|------------|-------------|------------|--------------|
| 64-2150PBF | SP001574268 | 64-2150PBF | D2PAK |
| 64-2152PBF | SP001575010 | 64-2152PBF | D2PAK |
| 64-2155PBF | SP001550640 | 64-2155PBF | D2PAK7P |
| 64-2157PBF | SP001561198 | 64-2157PBF | D2PAK |
| 64-2161PBF | SP001559164 | 64-2161PBF | D2PAK |
| 64-2163PBF | SP001650232 | 64-2163PBF | D2PAK |
| 64-4045PBF | SP001521504 | 64-4045PBF | DPAK |
| 64-4084PBF | SP001519310 | 64-4084PBF | D2PAK7P |
| 64-4102PBF | SP001562966 | 64-4102PBF | DPAK |
| 64-4103PBF | SP001560800 | 64-4103PBF | DPAK |
| 64-4104PBF | SP001562308 | 64-4104PBF | DPAK |
| 64-4105PBF | SP001550670 | 64-4105PBF | DPAK |
| 64-4125PBF | SP001519818 | 64-4125PBF | DPAK |
| 64-4127PBF | SP001569330 | 64-4127PBF | DPAK |
| 64-4131PBF | SP001562572 | 64-4131PBF | DPAK |
| 64-4132PBF | SP001569322 | 64-4132PBF | DPAK |
| 64-4133PBF | SP001559184 | 64-4133PBF | DPAK |
| 64-4135PBF | SP001553668 | 64-4135PBF | DPAK |
| 64-4138PBF | SP001561190 | 64-4138PBF | IPAK |
| 64-4158PBF | SP001561180 | 64-4158PBF | DPAK |
| 64-4162PBF | SP001574252 | 64-4162PBF | DPAK |
| 64-4163PBF | SP001562554 | 64-4163PBF | D2PAK |
| 64-6010PBF | SP001574244 | 64-6010PBF | TO247 |
| 64-9090PBF | SP001562516 | 64-9090PBF | MG-WDSO-N-4 |
| 64-9091PBF | SP001531774 | 64-9091PBF | MG-WDSO-N-5 |
| 64-9142PBF | SP001553718 | 64-9142PBF | MG-WDSO-N-5 |
| 64-9143PBF | SP001525600 | 64-9143PBF | MG-WDSO-N-5 |
| 64-9148PBF | SP001559234 | 64-9148PBF | MG-WDSO-N-5 |
| 64-9166PBF | SP001560856 | 64-9166PBF | MG-WDSO-N-5 |
| 64-9172PBF | SP001574218 | 64-9172PBF | MG-WDSO-N-8 |
| 64-9174PBF | SP001582854 | 64-9174PBF | MG-WDSO-N-11 |
| 64-9175PBF | SP001587294 | 64-9175PBF | MG-WDSO-N-5 |
| 64-9178PBF | SP001698082 | 64-9178PBF | DIRECTFET |
| 64-9179PBF | SP001709332 | 64-9179PBF | DIRECTFET |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|---------------|-------------|-----------------|------------|
| 64-9180PBF | SP001728634 | 64-9180PBF | DIRECTFET |
| 64-9182PBF | SP005423145 | 64-9182PBFATMA1 | MG-WDSO-5 |
| 92-9070 | SP001780398 | 929070X5SA1 | n.a. |
| 92-9071 | SP001781668 | 929071X5SA1 | n.a. |
| 92-9073 | SP001794192 | 929073X5SA1 | n.a. |
| 94-2299 | SP001521450 | 94-2299 | D2PAK |
| 94-2354PBF | SP001561128 | 94-2354PBF | TO220 |
| 94-2358PBF | SP001560922 | 94-2358PBF | D2PAK |
| 94-4059PBF | SP001613642 | 94-4059PBF | TO220 |
| 94-4103PBF | SP001614182 | 94-4103PBF | DPAK |
| 94-4297PBF | SP001522660 | 94-4297PBF | DPAK |
| 94-4366 | SP001794236 | 944366X5SA1 | n.a. |
| 94-4373PBF | SP001613632 | 94-4373PBF | TO220 |
| 94-4918PBF | SP001522624 | 94-4918PBF | DPAK |
| 94-6331 | SP001780408 | 946331XTMA1 | PG-SOT23-3 |
| 94-6332 | SP001794268 | 946332XTMA1 | PG-TDSON-8 |
| 94-6333 | SP001794258 | 946333XTMA1 | PG-SOT23-3 |
| 94-9525 | SP001797426 | 949525X5SA1 | n.a. |
| 94-9526 | SP001797440 | 949526X5SA1 | n.a. |
| 94-9527 | SP001797456 | 949527X5SA1 | n.a. |
| 94-9529 | SP001798258 | 949529X5SA1 | n.a. |
| 94-9532 | SP001797464 | 949532X5SA1 | n.a. |
| 94-9535 | SP001820148 | 949535X5SA1 | n.a. |
| 94-9536 | SP001820156 | 949536X5SA1 | n.a. |
| 98-0399 | SP001514702 | 98-0399 | n.a. |
| 98-0488 | SP001559312 | 98-0488 | n.a. |
| AUIPS2031RTRL | SP001513448 | AUIPS2031RTRL | PG-TO252-3 |
| AUIPS6031RTRL | SP001512958 | AUIPS6031RTRL | DPAK |
| AUIPS6121RTRL | SP001514062 | AUIPS6121RTRL | DPAK |
| AUIPS6125RTRL | SP001513600 | AUIPS6125RTRL | DPAK |
| AUIPS6126RTRL | SP001582476 | AUIPS6126RTRL | DPAK |
| AUIPS7081RTRL | SP001514442 | AUIPS7081RTRL | DPAK |
| AUIPS7081STRL | SP001513752 | AUIPS7081STRL | PG-TO263-5 |
| AUIPS7111STRL | SP001515350 | AUIPS7111STRL | PG-TO263-5 |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|------------------|-------------|--------------------|------------|
| AUIPS7121RTRL | SP001514630 | AUIPS7121RTRL | DKPAK |
| AUIPS7125RTRL | SP001512496 | AUIPS7125RTRL | DKPAK |
| AUIPS7141RTRL | SP001513106 | AUIPS7141RTRL | DKPAK |
| AUIPS7145RTRL | SP001513978 | AUIPS7145RTRL | DKPAK |
| AUIPS72211RTRL | SP001514282 | AUIPS72211RTRL | DKPAK |
| AUIPS7221RTRL | SP001512486 | AUIPS7221RTRL | DKPAK |
| AUIPS8121RTRL | SP001514874 | AUIPS8121RTRLXSMA1 | DKPAK |
| AUIR3316STRL | SP001513252 | AUIR3316STRL | PG-TO263-5 |
| AUIR3320STRL | SP001513822 | AUIR3320STRL | PG-TO263-5 |
| AUIRF1010ZS | SP001519530 | AUIRF1010ZS | D2PAK |
| AUIRF1010ZSTRL | SP001519002 | AUIRF1010ZSTRL | D2PAK |
| AUIRF1324S-7P | SP001517176 | AUIRF1324S-7P | D2PAK7P |
| AUIRF1324STRL | SP001518546 | AUIRF1324STRL | D2PAK |
| AUIRF1324WL | SP001516588 | AUIRF1324WL | TO262WL |
| AUIRF1404 | SP001522606 | AUIRF1404 | TO220 |
| AUIRF1404S | SP001522616 | AUIRF1404S | D2PAK |
| AUIRF1404STRL | SP001517298 | AUIRF1404STRL | D2PAK |
| AUIRF1404Z | SP001520218 | AUIRF1404Z | TO220 |
| AUIRF1404ZS | SP001515848 | AUIRF1404ZS | D2PAK |
| AUIRF1404ZSTRL | SP001522120 | AUIRF1404ZSTRL | D2PAK |
| AUIRF1405ZS | SP001519512 | AUIRF1405ZS | D2PAK |
| AUIRF1405ZS-7P | SP001518538 | AUIRF1405ZS-7P | D2PAK7P |
| AUIRF1405ZS-7TRL | SP001517288 | AUIRF1405ZS-7TRL | D2PAK7P |
| AUIRF1405ZSTRL | SP001522112 | AUIRF1405ZSTRL | D2PAK |
| AUIRF2804 | SP001518528 | AUIRF2804 | TO220 |
| AUIRF2804L | SP001522590 | AUIRF2804L | TO262 |
| AUIRF2804LRL306 | SP001519494 | AUIRF2804LRL306 | TO262 |
| AUIRF2804S-7P | SP001521640 | AUIRF2804S-7P | D2PAK7P |
| AUIRF2804STRL | SP001521004 | AUIRF2804STRL | D2PAK |
| AUIRF2804STRL7P | SP001519258 | AUIRF2804STRL7P | D2PAK7P |
| AUIRF2903ZSTRL | SP001521122 | AUIRF2903ZSTRL | D2PAK |
| AUIRF3004WL | SP001517752 | AUIRF3004WL | TO262WL |
| AUIRF3205 | SP001519502 | AUIRF3205 | TO220 |
| AUIRF3205Z | SP001518518 | AUIRF3205Z | TO220 |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|-----------------|-------------|-----------------|----------|
| AUIRF3205ZS | SP001518508 | AUIRF3205ZS | D2PAK |
| AUIRF3205ZSTRL | SP001521632 | AUIRF3205ZSTRL | D2PAK |
| AUIRF3305 | SP001517888 | AUIRF3305 | TO220 |
| AUIRF3710ZS | SP001522564 | AUIRF3710ZS | D2PAK |
| AUIRF3710ZSTRL | SP001519476 | AUIRF3710ZSTRL | D2PAK |
| AUIRF3710ZSTRR | SP001521606 | AUIRF3710ZSTRR | D2PAK |
| AUIRF3805 | SP001515808 | AUIRF3805 | TO220 |
| AUIRF3805S | SP001518016 | AUIRF3805S | D2PAK |
| AUIRF3805S-7P | SP001522074 | AUIRF3805S-7P | D2PAK7P |
| AUIRF3805S-7TRL | SP001516538 | AUIRF3805S-7TRL | D2PAK7P |
| AUIRF3805STRL | SP001521114 | AUIRF3805STRL | D2PAK |
| AUIRF4104S | SP001516518 | AUIRF4104S | D2PAK |
| AUIRF4104STRL | SP001518490 | AUIRF4104STRL | D2PAK |
| AUIRF4905 | SP001519228 | AUIRF4905 | TO220 |
| AUIRF4905S | SP001520184 | AUIRF4905S | D2PAK |
| AUIRF4905STRL | SP001517998 | AUIRF4905STRL | D2PAK |
| AUIRF5210STRL | SP001519458 | AUIRF5210STRL | D2PAK |
| AUIRF540Z | SP001516500 | AUIRF540Z | TO220 |
| AUIRF540ZS | SP001515788 | AUIRF540ZS | D2PAK |
| AUIRF540ZSTRL | SP001516510 | AUIRF540ZSTRL | D2PAK |
| AUIRF6215 | SP001521586 | AUIRF6215 | TO220 |
| AUIRF6215S | SP001520176 | AUIRF6215S | D2PAK |
| AUIRF6215STRL | SP001522066 | AUIRF6215STRL | D2PAK |
| AUIRF7640S2TR | SP001515728 | AUIRF7640S2TR | MG-WDSON |
| AUIRF7647S2TR | SP001520570 | AUIRF7647S2TR | MG-WDSON |
| AUIRF7648M2TR | SP001521562 | AUIRF7648M2TR | MG-WDSON |
| AUIRF7665S2TR | SP001519440 | AUIRF7665S2TR | MG-WDSON |
| AUIRF7669L2TR | SP001519182 | AUIRF7669L2TR | MG-WDSON |
| AUIRF7675M2TR | SP001522164 | AUIRF7675M2TR | MG-WDSON |
| AUIRF7732S2TR | SP001519174 | AUIRF7732S2TR | MG-WDSON |
| AUIRF7736M2TR | SP001517214 | AUIRF7736M2TR | MG-WDSON |
| AUIRF7737L2TR | SP001519412 | AUIRF7737L2TR | MG-WDSON |
| AUIRF7738L2TR | SP001515758 | AUIRF7738L2TR | MG-WDSON |
| AUIRF7739L2TR | SP001522042 | AUIRF7739L2TR | MG-WDSON |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|----------------|-------------|----------------|---------|
| AUIRF7749L2TR | SP001521068 | AUIRF7749L2TR | MG-WDSO |
| AUIRF7759L2TR | SP001517184 | AUIRF7759L2TR | MG-WDSO |
| AUIRF7769L2TR | SP001522786 | AUIRF7769L2TR | MG-WDSO |
| AUIRF7799L2TR | SP001522796 | AUIRF7799L2TR | MG-WDSO |
| AUIRF8736M2TR | SP001517194 | AUIRF8736M2TR | MG-WDSO |
| AUIRF8739L2TR | SP001516480 | AUIRF8739L2TR | MG-WDSO |
| AUIRFB8405 | SP001516720 | AUIRFB8405 | TO220 |
| AUIRFB8405-071 | SP001521030 | AUIRFB8405-071 | TO220 |
| AUIRFB8407 | SP001517430 | AUIRFB8407 | TO220 |
| AUIRFB8409 | SP001521544 | AUIRFB8409 | TO220 |
| AUIRFC8407TR | SP001521524 | AUIRFC8407TR | n.a. |
| AUIRFP4110 | SP001517386 | AUIRFP4110 | TO247 |
| AUIRFP4409 | SP001518024 | AUIRFP4409 | TO247 |
| AUIRFP4568 | SP001519624 | AUIRFP4568 | TO247 |
| AUIRFP4568-E | SP001521012 | AUIRFP4568-E | TO247 |
| AUIFR024N | SP001515958 | AUIFR024N | DPAK |
| AUIFR024NTRL | SP001522686 | AUIFR024NTRL | DPAK |
| AUIFR1010Z | SP001521238 | AUIFR1010Z | DPAK |
| AUIFR1010ZTRL | SP001515948 | AUIFR1010ZTRL | DPAK |
| AUIFR120ZTRL | SP001520338 | AUIFR120ZTRL | DPAK |
| AUIFR2407TRL | SP001520552 | AUIFR2407TRL | DPAK |
| AUIFR2905Z | SP001518150 | AUIFR2905Z | DPAK |
| AUIFR2905ZTR | SP001522230 | AUIFR2905ZTR | DPAK |
| AUIFR2905ZTRL | SP001520228 | AUIFR2905ZTRL | DPAK |
| AUIFR3504Z | SP001519606 | AUIFR3504Z | DPAK |
| AUIFR3504ZTRL | SP001516690 | AUIFR3504ZTRL | DPAK |
| AUIFR3607 | SP001521766 | AUIFR3607 | DPAK |
| AUIFR3607TRL | SP001519596 | AUIFR3607TRL | DPAK |
| AUIFR3710Z | SP001519588 | AUIFR3710Z | DPAK |
| AUIFR3710ZTRL | SP001516670 | AUIFR3710ZTRL | DPAK |
| AUIFR3806 | SP001518142 | AUIFR3806 | DPAK |
| AUIFR3806TRL | SP001521230 | AUIFR3806TRL | DPAK |
| AUIFR4104 | SP001515918 | AUIFR4104 | DPAK |
| AUIFR4104TRL | SP001522928 | AUIFR4104TRL | DPAK |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|-----------------|-------------|--------------------|---------|
| AUIRFR4105Z | SP001520528 | AUIRFR4105Z | DPAK |
| AUIRFR4105ZTRL | SP001517348 | AUIRFR4105ZTRL | DPAK |
| AUIRFR4292 | SP001520304 | AUIRFR4292 | DPAK |
| AUIRFR4292TRL | SP001520520 | AUIRFR4292TRL | DPAK |
| AUIRFR4615 | SP001522920 | AUIRFR4615 | DPAK |
| AUIRFR4615TRL | SP001518604 | AUIRFR4615TRL | DPAK |
| AUIRFR4620 | SP001518124 | AUIRFR4620 | DPAK |
| AUIRFR4620TRL | SP001516660 | AUIRFR4620TRL | DPAK |
| AUIRFR48Z | SP001522912 | AUIRFR48Z | DPAK |
| AUIRFR48ZTRL | SP001520288 | AUIRFR48ZTRL | DPAK |
| AUIRFR5305 | SP001517358 | AUIRFR5305 | DPAK |
| AUIRFR5305TR | SP001517328 | AUIRFR5305TR | DPAK |
| AUIRFR5305TRL | SP001519556 | AUIRFR5305TRL | DPAK |
| AUIRFR540Z | SP001521742 | AUIRFR540Z | DPAK |
| AUIRFR540ZTRL | SP001520296 | AUIRFR540ZTRL | DPAK |
| AUIRFR5410TRL | SP001521222 | AUIRFR5410TRL | DPAK |
| AUIRFR6215 | SP001517590 | AUIRFR6215 | DPAK |
| AUIRFR6215TRL | SP001522196 | AUIRFR6215TRL | DPAK |
| AUIRFR8401 | SP001518132 | AUIRFR8401 | DPAK |
| AUIRFR8401TRL | SP001520504 | AUIRFR8401TRL | DPAK |
| AUIRFR8403 | SP001517580 | AUIRFR8403 | DPAK |
| AUIRFR8403TRL | SP001518596 | AUIRFR8403TRL | DPAK |
| AUIRFR8403TRL | SP001871076 | AUIRFR8403TRLARMA1 | DPAK |
| AUIRFR8405 | SP001519800 | AUIRFR8405 | DPAK |
| AUIRFR8405TRL | SP001522904 | AUIRFR8405TRL | DPAK |
| AUIRFR9024NTRL | SP001518586 | AUIRFR9024NTRL | DPAK |
| AUIRFS3004-7P | SP001521206 | AUIRFS3004-7P | D2PAK7P |
| AUIRFS3004-7TRL | SP001515878 | AUIRFS3004-7TRL | D2PAK7P |
| AUIRFS3004TRL | SP001517570 | AUIRFS3004TRL | D2PAK |
| AUIRFS3006-7P | SP001522888 | AUIRFS3006-7P | D2PAK7P |
| AUIRFS3006-7TRL | SP001521716 | AUIRFS3006-7TRL | D2PAK7P |
| AUIRFS3107-7P | SP001516622 | AUIRFS3107-7P | D2PAK7P |
| AUIRFS3107-7TRL | SP001520264 | AUIRFS3107-7TRL | D2PAK7P |
| AUIRFS3107TRL | SP001521708 | AUIRFS3107TRL | D2PAK |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|-----------------|-------------|-----------------|---------|
| AUIRFS3206 | SP001521188 | AUIRFS3206 | D2PAK |
| AUIRFS3206TRL | SP001515868 | AUIRFS3206TRL | D2PAK |
| AUIRFS3207ZTRL | SP001518098 | AUIRFS3207ZTRL | D2PAK |
| AUIRFS3306TRL | SP001522172 | AUIRFS3306TRL | D2PAK |
| AUIRFS3607TRL | SP001520722 | AUIRFS3607TRL | D2PAK |
| AUIRFS4010 | SP001522400 | AUIRFS4010 | D2PAK |
| AUIRFS4010-7P | SP001516602 | AUIRFS4010-7P | D2PAK7P |
| AUIRFS4010-7TRL | SP001518838 | AUIRFS4010-7TRL | D2PAK7P |
| AUIRFS4010TRL | SP001520712 | AUIRFS4010TRL | D2PAK |
| AUIRFS4115 | SP001520256 | AUIRFS4115 | D2PAK |
| AUIRFS4115-7P | SP001519772 | AUIRFS4115-7P | D2PAK7P |
| AUIRFS4115-7TRL | SP001521180 | AUIRFS4115-7TRL | D2PAK7P |
| AUIRFS4115TRL | SP001518088 | AUIRFS4115TRL | D2PAK |
| AUIRFS4127 | SP001517544 | AUIRFS4127 | D2PAK |
| AUIRFS4127TRL | SP001518830 | AUIRFS4127TRL | D2PAK |
| AUIRFS4310 | SP001522392 | AUIRFS4310 | D2PAK |
| AUIRFS4310TRL | SP001517534 | AUIRFS4310TRL | D2PAK |
| AUIRFS4310ZTRL | SP001516740 | AUIRFS4310ZTRL | D2PAK |
| AUIRFS4410Z | SP001520704 | AUIRFS4410Z | D2PAK |
| AUIRFS4410ZTRL | SP001518070 | AUIRFS4410ZTRL | D2PAK |
| AUIRFS4610 | SP001522872 | AUIRFS4610 | D2PAK |
| AUIRFS6535 | SP001516136 | AUIRFS6535 | D2PAK |
| AUIRFS6535TRL | SP001521690 | AUIRFS6535TRL | D2PAK |
| AUIRFS8405 | SP001522864 | AUIRFS8405 | D2PAK |
| AUIRFS8405TRL | SP001517524 | AUIRFS8405TRL | D2PAK |
| AUIRFS8407 | SP001520236 | AUIRFS8407 | D2PAK |
| AUIRFS8407-7P | SP001518052 | AUIRFS8407-7P | D2PAK7P |
| AUIRFS8407-7TRL | SP001516126 | AUIRFS8407-7TRL | D2PAK7P |
| AUIRFS8407TRL | SP001520480 | AUIRFS8407TRL | D2PAK |
| AUIRFS8408-7P | SP001518804 | AUIRFS8408-7P | D2PAK7P |
| AUIRFS8408-7TRL | SP001522368 | AUIRFS8408-7TRL | D2PAK7P |
| AUIRFS8409 | SP001517498 | AUIRFS8409 | D2PAK |
| AUIRFS8409-7P | SP001522376 | AUIRFS8409-7P | D2PAK7P |
| AUIRFS8409-7TRL | SP001518044 | AUIRFS8409-7TRL | D2PAK7P |



Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|-------------------|-------------|-------------------|---------------|
| AUIRFS8409TRL | SP001521148 | AUIRFS8409TRL | D2PAK |
| AUIRFS8409-7P | SP001520354 | AUIRFS8409-7P | D2PAK7P |
| AUIRFS8409-7TRL | SP001518820 | AUIRFS8409-7TRL | D2PAK7P |
| AUIRFSL4010 | SP001517516 | AUIRFSL4010 | TO262 |
| AUIRFSL8403 | SP001520686 | AUIRFSL8403 | TO262 |
| AUIRFSL8407 | SP001517488 | AUIRFSL8407 | TO262 |
| AUIRFU8401 | SP001518756 | AUIRFU8401 | IPAK |
| AUIRFU8403 | SP001518276 | AUIRFU8403 | IPAK |
| AUIRFU8403-701TRL | SP001522360 | AUIRFU8403-701TRL | IPAK |
| AUIRFZ24NS | SP001517468 | AUIRFZ24NS | D2PAK |
| AUIRFZ44VZS | SP001517600 | AUIRFZ44VZS | D2PAK |
| AUIRFZ48N | SP001518286 | AUIRFZ48N | TO220 |
| AUIRG4BC30SSTRL | SP001511460 | AUIRG4BC30SSTRL | D2PAK |
| AUIRG4BC30SSTRR | SP001512160 | AUIRG4BC30SSTRR | D2PAK |
| AUIRG4PC40S-E | SP001511242 | AUIRG4PC40S-E | TO247 |
| AUIRG4PH50S | SP001512028 | AUIRG4PH50S | TO247 |
| AUIRG4PH50S-205 | SP001511698 | AUIRG4PH50S-205 | TO247 |
| AUIRGDC0250 | SP001511678 | AUIRGDC0250 | SUPER220 |
| AUIRGP4062D | SP001511212 | AUIRGP4062D | TO247COPAK |
| AUIRGP4062D-E | SP001511902 | AUIRGP4062D-E | TO247COPAK |
| AUIRGP4063D | SP001512458 | AUIRGP4063D | TO247COPAK |
| AUIRGP4063D-E | SP001512018 | AUIRGP4063D-E | TO247COPAK |
| AUIRGPS4070D0 | SP001582478 | AUIRGPS4070D0 | SUPER247COPAK |
| AUIRL1404ZSTRL | SP001518266 | AUIRL1404ZSTRL | D2PAK |
| AUIRL3705ZS | SP001520660 | AUIRL3705ZS | D2PAK |
| AUIRL3705ZSTRL | SP001516800 | AUIRL3705ZSTRL | D2PAK |
| AUIRL7732S2TR | SP001521366 | AUIRL7732S2TR | MG-WDSO |
| AUIRL7736M2TR | SP001521898 | AUIRL7736M2TR | MG-WDSO |
| AUIRL7766M2TR | SP001516036 | AUIRL7766M2TR | MG-WDSO |
| AUIRLR120NTRL | SP001516016 | AUIRLR120NTRL | DPAK |
| AUIRLR2703TRL | SP001521330 | AUIRLR2703TRL | DPAK |
| AUIRLR2905Z | SP001522326 | AUIRLR2905Z | DPAK |
| AUIRLR2905ZTRL | SP001519942 | AUIRLR2905ZTRL | DPAK |
| AUIRLR3110Z | SP001521338 | AUIRLR3110Z | DPAK |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|--------------------|-------------|----------------------|---------|
| AUIRLR3110ZTRL | SP001516790 | AUIRLR3110ZTRL | DPAK |
| AUIRLR3410 | SP001521872 | AUIRLR3410 | DPAK |
| AUIRLR3410TR | SP001519922 | AUIRLR3410TR | DPAK |
| AUIRLR3410TRL | SP001523020 | AUIRLR3410TRL | DPAK |
| AUIRLR3636 | SP001520390 | AUIRLR3636 | DPAK |
| AUIRLR3636TRL | SP001520624 | AUIRLR3636TRL | DPAK |
| AUIRLR3705Z | SP001516266 | AUIRLR3705Z | DPAK |
| AUIRLR3705ZTR | SP001521864 | AUIRLR3705ZTR | DPAK |
| AUIRLR3705ZTRL | SP001518218 | AUIRLR3705ZTRL | DPAK |
| AUIRLS3034-7TRL | SP001519894 | AUIRLS3034-7TRL | D2PAK7P |
| AUIRLS3036 | SP001521322 | AUIRLS3036 | D2PAK |
| AUIRLS3036-7P | SP001520858 | AUIRLS3036-7P | D2PAK7P |
| AUIRLS3036-7TRL | SP001518960 | AUIRLS3036-7TRL | D2PAK7P |
| AUIRLS3036TRL | SP001519912 | AUIRLS3036TRL | D2PAK |
| AUIRLS4030 | SP001519902 | AUIRLS4030 | D2PAK |
| AUIRLS4030-7P | SP001522310 | AUIRLS4030-7P | D2PAK7P |
| AUIRLS4030-7TRL | SP001520400 | AUIRLS4030-7TRL | D2PAK7P |
| AUIRLS4030TRL | SP001520410 | AUIRLS4030TRL | D2PAK |
| AUIRLS8409-7P | SP001521838 | AUIRLS8409-7P | D2PAK |
| AUIRLS8409-7TRL | SP001517666 | AUIRLS8409-7TRL | D2PAK |
| AUIRLU3114Z | SP001516750 | AUIRLU3114Z | IPAK |
| AUIRLU3114Z-701TRL | SP001523004 | AUIRLU3114Z-701TRL | IPAK |
| AUXALFR4104 | SP001521304 | AUXALFR4104 | DPAK |
| AUXCLF1010ZSTRL | SP001522416 | AUXCLF1010ZSTRL | D2PAK |
| AUXCLF1010ZSTRL | SP005407264 | AUXCLF1010ZSTRLARSA1 | D2PAK |
| AUXCLFC4310EKTR | SP001522974 | AUXCLFC4310EKTR | n.a. |
| AUXCLFC4311EKTR | SP001521286 | AUXCLFC4311EKTR | n.a. |
| AUXCLFR5305 | SP001516236 | AUXCLFR5305 | DPAK |
| AUXCLFR5410 | SP001520822 | AUXCLFR5410 | DPAK |
| AUXCLFR6215TR | SP001520608 | AUXCLFR6215TR | DPAK |
| AUXCLFR9024N | SP001518910 | AUXCLFR9024N | DPAK |
| AUXCLFZ24NSTRL | SP001519884 | AUXCLFZ24NSTRL | D2PAK |
| AUXCLL1404ZS | SP001521830 | AUXCLL1404ZS | D2PAK |
| AUXCLLR2905Z | SP001521276 | AUXCLLR2905Z | DPAK |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|------------------|-------------|-----------------------|---------------|
| AUXDIF4905 | SP001597414 | AUXDIF4905 | TO220 |
| AUXDIF6215STRL | SP001518900 | AUXDIF6215STRL | D2PAK |
| AUXDIFR3710ZTRL | SP001522964 | AUXDIFR3710ZTRL | DPAK |
| AUXDIFZ44ESTRL | SP001522954 | AUXDIFZ44ESTRL | D2PAK |
| AUXECF1324S-7P | SP001520804 | AUXECF1324S-7P | D2PAK7P |
| AUXECF2804S | SP001518872 | AUXECF2804S | D2PAK |
| AUXECL1404ZS | SP001517016 | AUXECL1404ZS | D2PAK |
| AUXEPF3805S | SP001520598 | AUXEPF3805S | D2PAK |
| AUXESFC2804TR | SP001516998 | AUXESFC2804TR | n.a. |
| AUXHBFB3306 | SP001517628 | AUXHBFB3306 | TO220 |
| AUXHBFR4104TRL | SP001522540 | AUXHBFR4104TRL | DPAK |
| AUXHKGP4062D-E | SP001662772 | AUXHKGP4062D-E | TO247COPAK |
| AUXKNG4PH50S-215 | SP001512066 | AUXKNG4PH50S-215 | TO247 |
| AUXMAFS4115TRL | SP001520588 | AUXMAFS4115TRL | D2PAK |
| AUXMAFS4310ZTRL | SP001522530 | AUXMAFS4310ZTRL | D2PAK |
| AUXNRF2804STRL | SP001516196 | AUXNRF2804STRL | D2PAK |
| AUXNS0306RTRL | SP001515514 | AUXNS0306RTRL | DPAK |
| AUXNS03092STRL | SP001515034 | AUXNS03092STRL | PG-TO263-7 |
| AUXNSF2804STRL7P | SP001631194 | AUXNSF2804STRL7P | D2PAK7P |
| AUXSOF8409-7TRL | SP001697602 | AUXSOF8409-7TRL | D2PAK7P |
| AUXTMF7749L2TR | SP001708674 | AUXTMF7749L2TR | DIRECTFET |
| AUXTMGPS4070D1 | SP001599982 | AUXTMGPS4070D1 | SUPER247COPAK |
| AUXTMGPS4070D2 | SP001599986 | AUXTMGPS4070D2 | SUPER247COPAK |
| AUXTWF1324WLTRL | SP001522526 | AUXTWF1324WLTRL | TO262WL |
| AUXVNGP4062D-E | SP001511846 | AUXVNGP4062D-E | TO247COPAK |
| IAUE303N08S5N009 | SP005580902 | IAUE303N08S5N009XQMA1 | MG-LH2LA-3 |
| IEWS20R5135IPB | SP004854708 | IEWS20R5135IPBXKMA1 | PG-TO247-6 |
| IRCZ44PBFHR | SP001798606 | n.a. | PG-TO220-5 |
| IRF100DM116 | SP001511076 | IRF100DM116XTMA1 | DIRECTFET |
| IRF135SA204 | SP001564264 | IRF135SA204 | D2PAK7P |
| IRF1404LPBF | SP001576598 | IRF1404LPBF | TO262 |
| IRF150DM115 | SP001511080 | IRF150DM115XTMA1 | DIRECTFET |
| IRF200S234 | SP001593688 | IRF200S234 | D2PAK |
| IRF2804LPBF | SP001550958 | IRF2804LPBF | TO262 |
| IRF2807PBF | SP001550978 | IRF2807PBF | TO220 |
| IRF3205LPBF | SP001564458 | IRF3205LPBF | TO262 |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|-----------------|-------------|-----------------|-------------|
| IRF3205PBF | SP001559536 | IRF3205PBF | TO220 |
| IRF3205ZLPBF | SP001564660 | IRF3205ZLPBF | TO262 |
| IRF3205ZPBF | SP001574672 | IRF3205ZPBF | TO220 |
| IRF3703PBF | SP001574662 | IRF3703PBF | TO220 |
| IRF3710PBF | SP001551058 | IRF3710PBF | TO220 |
| IRF3805STRL-7PP | SP001554002 | IRF3805STRL-7PP | D2PAK7P |
| IRF40DL237 | SP001597382 | IRF40DL237 | MG-WDSON-11 |
| IRF40DM229 | SP001576692 | IRF40DM229 | MG-WDSON-6 |
| IRF40SC240 | SP001646074 | IRF40SC240ARMA1 | PG-TO263-7 |
| IRF4905LPBF | SP001563376 | IRF4905LPBF | TO262 |
| IRF5210LPBF | SP001564364 | IRF5210LPBF | TO262 |
| IRF5305STRLPBF | SP001564840 | IRF5305STRLPBF | D2PAK |
| IRF530NPBF | SP001570120 | IRF530NPBF | TO220 |
| IRF540NLPBF | SP001571292 | IRF540NLPBF | TO262 |
| IRF540ZLPBF | SP001559652 | IRF540ZLPBF | TO262 |
| IRF60DM206 | SP001561876 | IRF60DM206 | DIRECTFET |
| IRF60DM206 | SP005573710 | IRF60DM206ATMA1 | MG-WDSON-8 |
| IRF60SC241 | SP001646066 | IRF60SC241ARMA1 | PG-TO263-7 |
| IRF630NPBF | SP005596441 | IRF630NPBFAKMA1 | TO220 |
| IRF640NLPBF | SP001563296 | IRF640NLPBF | TO262 |
| IRF6613TRPBF | SP001526876 | IRF6613TRPBF | MG-WDSON-5 |
| IRF6614TRPBF | SP001527924 | IRF6614TRPBF | MG-WDSON-5 |
| IRF6616TRPBF | SP001525524 | IRF6616TRPBF | MG-WDSON-5 |
| IRF6617TRPBF | SP001531694 | IRF6617TRPBF | MG-WDSON-5 |
| IRF6618TRPBF | SP001529242 | IRF6618TRPBF | MG-WDSON-5 |
| IRF6620TRPBF | SP001524564 | IRF6620TRPBF | MG-WDSON-5 |
| IRF6623TRPBF | SP001526818 | IRF6623TRPBF | MG-WDSON-5 |
| IRF6636TRPBF | SP001529234 | IRF6636TRPBF | MG-WDSON-5 |
| IRF6637TRPBF | SP001532298 | IRF6637TRPBF | MG-WDSON-5 |
| IRF6641TRPBF | SP001559700 | IRF6641TRPBF | MG-WDSON-5 |
| IRF6643TRPBF | SP001570070 | IRF6643TRPBF | DIRECTFET |
| IRF6644TRPBF | SP001563476 | IRF6644TRPBF | MG-WDSON-5 |
| IRF6645TRPBF | SP001562050 | IRF6645TRPBF | MG-WDSON-5 |
| IRF6646TRPBF | SP001564784 | IRF6646TRPBF | MG-WDSON-5 |
| IRF6648TRPBF | SP001570312 | IRF6648TRPBF | MG-WDSON-5 |
| IRF6662TRPBF | SP001576850 | IRF6662TRPBF | MG-WDSON-5 |
| IRF6665TRPBF | SP001559710 | IRF6665TRPBF | DIRECTFET |
| IRF6668TRPBF | SP001551178 | IRF6668TRPBF | DIRECTFET |
| IRF6674TRPBF | SP001564538 | IRF6674TRPBF | MG-WDSON-5 |
| IRF6712STRPBF | SP001529206 | IRF6712STRPBF | MG-WDSON-4 |
| IRF6714MTRPBF | SP001532368 | IRF6714MTRPBF | MG-WDSON-5 |
| IRF6715MTRPBF | SP001531626 | IRF6715MTRPBF | MG-WDSON-5 |
| IRF6716MTRPBF | SP001528284 | IRF6716MTRPBF | MG-WDSON-5 |
| IRF6717MTRPBF | SP001525458 | IRF6717MTRPBF | MG-WDSON-5 |
| IRF6722MTRPBF | SP001523908 | IRF6722MTRPBF | MG-WDSON-5 |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|-----------------|-------------|-----------------|-------------|
| IRF6724MTRPBF | SP001529188 | IRF6724MTRPBF | MG-WDSON-5 |
| IRF6726MTRPBF | SP001528276 | IRF6726MTRPBF | MG-WDSON-5 |
| IRF6727MTRPBF | SP001530240 | IRF6727MTRPBF | MG-WDSON-5 |
| IRF6775MTRPBF | SP001562042 | IRF6775MTRPBF | MG-WDSON-5 |
| IRF6785MTRPBF | SP001562032 | IRF6785MTRPBF | MG-WDSON-5 |
| IRF6795MTRPBF | SP001529342 | IRF6795MTRPBF | MG-WDSON-5 |
| IRF6797MTRPBF | SP001530232 | IRF6797MTRPBF | MG-WDSON-5 |
| IRF7480MTRPBF | SP001566252 | IRF7480MTRPBF | MG-WDSON-8 |
| IRF7483MTRPBF | SP001572118 | IRF7483MTRPBF | MG-WDSON-6 |
| IRF7580MTRPBF | SP001551448 | IRF7580MTRPBF | MG-WDSON-8 |
| IRF7739L1TRPBF | SP001555546 | IRF7739L1TRPBF | MG-WDSON-11 |
| IRF7748L1TRPBF | SP001565632 | IRF7748L1TRPBF | MG-WDSON-9 |
| IRF7749L1TRPBF | SP001555556 | IRF7749L1TRPBF | MG-WDSON-11 |
| IRF7759L2TRPBF | SP001563710 | IRF7759L2TRPBF | MG-WDSON-11 |
| IRF7769L1TRPBF | SP001566418 | IRF7769L1TRPBF | MG-WDSON-11 |
| IRF7779L2TRPBF | SP001572314 | IRF7779L2TRPBF | MG-WDSON-11 |
| IRF7780MTRPBF | SP001551498 | IRF7780MTRPBF | MG-WDSON-8 |
| IRF7946TRPBF | SP001566584 | IRF7946TRPBF | DIRECTFET |
| IRF8301MTRPBF | SP001555752 | IRF8301MTRPBF | DIRECTFET |
| IRF8302MTRPBF | SP001555742 | IRF8302MTRPBF | MG-WDSON-5 |
| IRF8304MTRPBF | SP001551618 | IRF8304MTRPBF | MG-WDSON-5 |
| IRF8327STRPBF | SP001554476 | IRF8327STRPBF | DIRECTFET |
| IRF9383MTRPBF | SP001565700 | IRF9383MTRPBF | MG-WDSON-5 |
| IRF9530NPBF | SP001570634 | IRF9530NPBF | TO220 |
| IRF9540NPBF | SP001560174 | IRF9540NPBF | TO220 |
| IRF9Z24NSTRLPBF | SP001554552 | IRF9Z24NSTRLPBF | D2PAK |
| IRF9Z34NPBF | SP001560182 | IRF9Z34NPBF | TO220 |
| IRF9Z34NSTRLPBF | SP001554544 | IRF9Z34NSTRLPBF | D2PAK |
| IRF9Z34NSTRRPBF | SP001551716 | IRF9Z34NSTRRPBF | D2PAK |
| IRFB260NPBF | SP001551726 | IRFB260NPBF | TO220 |
| IRFB4137PBF | SP001554580 | IRFB4137PBF | TO220 |
| IRFB428PBF | SP001554590 | IRFB428PBF | TO220 |
| IRFB4332PBF | SP001556040 | IRFB4332PBF | TO220 |
| IRFB438PBF | SP001572352 | IRFB438PBF | TO220 |
| IRFB448PBF | SP001570578 | IRFB448PBF | TO220 |
| IRFB4710PBF | SP001556118 | IRFB4710PBF | TO220 |
| IRFB52N15DPBF | SP001572332 | IRFB52N15DPBF | TO220 |
| IRFB7430PBF | SP001551786 | IRFB7430PBF | TO220 |
| IRFB7437PBF | SP001556080 | IRFB7437PBF | TO220 |
| IRFB7446PBF | SP001577760 | IRFB7446PBF | TO220 |
| IRFB7530PBF | SP001575524 | IRFB7530PBF | TO220 |
| IRFB7730PBF | SP001556128 | IRFB7730PBF | TO220 |
| IRFB812PBF | SP001563948 | IRFB812PBF | TO220 |
| IRFP054NPBF | SP001566178 | IRFP054NPBF | TO247 |
| IRFP064NPBF | SP001554926 | IRFP064NPBF | TO247 |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|-----------------|-------------|-----------------|---------|
| IRFP1405PBF | SP001572614 | IRFP1405PBF | TO247 |
| IRFP140NPBF | SP001575786 | IRFP140NPBF | TO247 |
| IRFP150NPBF | SP001564068 | IRFP150NPBF | TO247 |
| IRFP260NPBF | SP001552016 | IRFP260NPBF | TO247 |
| IRFP2907PBF | SP001571058 | IRFP2907PBF | TO247 |
| IRFP2907ZPBF | SP001571048 | IRFP2907ZPBF | TO247 |
| IRFP3006PBF | SP001556714 | IRFP3006PBF | TO247 |
| IRFP3077PBF | SP001566982 | IRFP3077PBF | TO247 |
| IRFP3206PBF | SP001578056 | IRFP3206PBF | TO247 |
| IRFP3306PBF | SP001564200 | IRFP3306PBF | TO247 |
| IRFP3415PBF | SP001566972 | IRFP3415PBF | TO247 |
| IRFP3703PBF | SP001556744 | IRFP3703PBF | TO247 |
| IRFP3710PBF | SP001552026 | IRFP3710PBF | TO247 |
| IRFP4004PBF | SP001556734 | IRFP4004PBF | TO247 |
| IRFP4110PBF | SP001556724 | IRFP4110PBF | TO247 |
| IRFP4127PBF | SP001566148 | IRFP4127PBF | TO247 |
| IRFP4137PBF | SP001571068 | IRFP4137PBF | TO247 |
| IRFP4310ZPBF | SP001572864 | IRFP4310ZPBF | TO247 |
| IRFP4368PBF | SP001556774 | IRFP4368PBF | TO247 |
| IRFP4468PBF | SP001554960 | IRFP4468PBF | TO247 |
| IRFP4568PBF | SP001560548 | IRFP4568PBF | TO247 |
| IRFP4710PBF | SP001575990 | IRFP4710PBF | TO247 |
| IRFP4868PBF | SP001556792 | IRFP4868PBF | TO247 |
| IRFP7430PBF | SP001554970 | IRFP7430PBF | TO247 |
| IRFP7530PBF | SP001560520 | IRFP7530PBF | TO247 |
| IRFP7537PBF | SP001564970 | IRFP7537PBF | TO247 |
| IRFP7718PBF | SP001571038 | IRFP7718PBF | TO247 |
| IRFP90N20DPBF | SP001552070 | IRFP90N20DPBF | TO247 |
| IRFP9140NPBF | SP001556802 | IRFP9140NPBF | TO247 |
| IRFR15N20DTRPBF | SP001555046 | IRFR15N20DTRPBF | DPAK |
| IRFR24N15DTRPBF | SP001578104 | IRFR24N15DTRPBF | DPAK |
| IRFR4104TRLPBF | SP001555120 | IRFR4104TRLPBF | DPAK |
| IRFR4104TRPBF | SP001571578 | IRFR4104TRPBF | DPAK |
| IRFR4104TRRPBF | SP001578128 | IRFR4104TRRPBF | DPAK |
| IRFR4615TRLPBF | SP001560646 | IRFR4615TRLPBF | DPAK |
| IRFR5305TRLPBF | SP001567854 | IRFR5305TRLPBF | DPAK |
| IRFR5305TRPBF | SP001557082 | IRFR5305TRPBF | DPAK |
| IRFR540ZTRLPBF | SP001567620 | IRFR540ZTRLPBF | DPAK |
| IRFR5410TRLPBF | SP001578112 | IRFR5410TRLPBF | DPAK |
| IRFR5410TRPBF | SP001557100 | IRFR5410TRPBF | DPAK |
| IRFR5410TRRPBF | SP001557118 | IRFR5410TRRPBF | DPAK |
| IRFR5505TRLPBF | SP001552238 | IRFR5505TRLPBF | DPAK |
| IRFR5505TRPBF | SP001573294 | IRFR5505TRPBF | DPAK |
| IRFR6215TRLPBF | SP001565112 | IRFR6215TRLPBF | DPAK |
| IRFR6215TRPBF | SP001571562 | IRFR6215TRPBF | DPAK |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|-----------------|-------------|-----------------|---------|
| IRFR6215TRRPBF | SP001557126 | IRFR6215TRRPBF | DPAK |
| IRFR7440TRPBF | SP001573310 | IRFR7440TRPBF | DPAK |
| IRFR7540TRLPBF | SP001565094 | IRFR7540TRLPBF | DPAK |
| IRFR7540TRPBF | SP001550214 | IRFR7540TRPBF | DPAK |
| IRFR7740TRPBF | SP001552218 | IRFR7740TRPBF | DPAK |
| IRFR812TRPBF | SP001571554 | IRFR812TRPBF | DPAK |
| IRFR8314TRPBF | SP001565102 | IRFR8314TRPBF | DPAK |
| IRFR9024NTRLPBF | SP001557198 | IRFR9024NTRLPBF | DPAK |
| IRFR9120NTRLPBF | SP001576108 | IRFR9120NTRLPBF | DPAK |
| IRFR9120NTRPBF | SP001557182 | IRFR9120NTRPBF | DPAK |
| IRFS3006TRLPBF | SP001567578 | IRFS3006TRLPBF | D2PAK |
| IRFS38N20DTRLP | SP001567672 | IRFS38N20DTRLP | D2PAK |
| IRFS4510TRLPBF | SP001557402 | IRFS4510TRLPBF | D2PAK |
| IRFS52N15DTRLP | SP001578238 | IRFS52N15DTRLP | D2PAK |
| IRFS52N15DTRRP | SP001568000 | IRFS52N15DTRRP | D2PAK |
| IRFS7430TRL7PP | SP001565252 | IRFS7430TRL7PP | D2PAK7P |
| IRFS7430TRLPBF | SP001571706 | IRFS7430TRLPBF | D2PAK |
| IRFS7434TRLPBF | SP001578486 | IRFS7434TRLPBF | D2PAK |
| IRFS7530TRL7PP | SP001557500 | IRFS7530TRL7PP | D2PAK7P |
| IRFS7530TRLPBF | SP001567992 | IRFS7530TRLPBF | D2PAK |
| IRFS7534TRL7PP | SP001573434 | IRFS7534TRL7PP | D2PAK7P |
| IRFS7730TRL7PP | SP001573426 | IRFS7730TRL7PP | D2PAK7P |
| IRFS7730TRLPBF | SP001557578 | IRFS7730TRLPBF | D2PAK |
| IRFS7734TRL7PP | SP001576166 | IRFS7734TRL7PP | D2PAK7P |
| IRFS7762TRLPBF | SP001557548 | IRFS7762TRLPBF | D2PAK |
| IRFSL3006PBF | SP001573396 | IRFSL3006PBF | TO262 |
| IRFSL3107PBF | SP001557588 | IRFSL3107PBF | TO262 |
| IRFSL3206PBF | SP001578476 | IRFSL3206PBF | TO262 |
| IRFSL3207ZPBF | SP001552364 | IRFSL3207ZPBF | TO262 |
| IRFSL3306PBF | SP001568072 | IRFSL3306PBF | TO262 |
| IRFSL4010PBF | SP001567760 | IRFSL4010PBF | TO262 |
| IRFSL4127PBF | SP001557538 | IRFSL4127PBF | TO262 |
| IRFSL4410ZPBF | SP001557638 | IRFSL4410ZPBF | TO262 |
| IRFSL5615PBF | SP001567730 | IRFSL5615PBF | TO262 |
| IRFSL7430PBF | SP001557608 | IRFSL7430PBF | TO262 |
| IRFSL7434PBF | SP001557628 | IRFSL7434PBF | TO262 |
| IRFSL7437PBF | SP001578458 | IRFSL7437PBF | TO262 |
| IRFSL7440PBF | SP001573650 | IRFSL7440PBF | TO262 |
| IRFSL7530PBF | SP001565198 | IRFSL7530PBF | TO262 |
| IRFSL7534PBF | SP001568208 | IRFSL7534PBF | TO262 |
| IRFSL7537PBF | SP001578438 | IRFSL7537PBF | TO262 |
| IRFSL7540PBF | SP001557648 | IRFSL7540PBF | TO262 |
| IRFSL7730PBF | SP001557668 | IRFSL7730PBF | TO262 |
| IRFSL7734PBF | SP001557658 | IRFSL7734PBF | TO262 |
| IRFSL7787PBF | SP001576372 | IRFSL7787PBF | TO262 |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|----------------|-------------|------------------|---------------|
| IRFU024NPBF | SP001552404 | IRFU024NPBF | IPAK |
| IRFU024NPBF | SP005572261 | IRFU024NPBFAKLA1 | IPAK |
| IRFU120NPBF | SP001557678 | IRFU120NPBF | IPAK |
| IRFU220NPBF | SP001567710 | IRFU220NPBF | IPAK |
| IRFU2405PBF | SP001571782 | IRFU2405PBF | IPAK |
| IRFU3410PBF | SP001578398 | IRFU3410PBF | IPAK |
| IRFU3607PBF | SP001557738 | IRFU3607PBF | IPAK |
| IRFU3910PBF | SP001578380 | IRFU3910PBF | IPAK |
| IRFU4615PBF | SP001571872 | IRFU4615PBF | IPAK |
| IRFU5305PBF | SP001550274 | IRFU5305PBF | IPAK |
| IRFU5410PBF | SP001557796 | IRFU5410PBF | IPAK |
| IRFU5505PBF | SP001557786 | IRFU5505PBF | IPAK |
| IRFU7440PBF | SP001565158 | IRFU7440PBF | IPAK |
| IRFU7540PBF | SP001565384 | IRFU7540PBF | IPAK |
| IRFU7546PBF | SP001571892 | IRFU7546PBF | IPAK |
| IRFU7740PBF | SP001573600 | IRFU7740PBF | IPAK |
| IRFU7746PBF | SP001552464 | IRFU7746PBF | IPAK |
| IRFU9024NPBF | SP001557756 | IRFU9024NPBF | IPAK |
| IRFZ44NLPBF | SP001557836 | IRFZ44NLPBF | TO262 |
| IRFZ44ZLPBF | SP001571852 | IRFZ44ZLPBF | TO262 |
| IRFZ46NLPBF | SP001557896 | IRFZ46NLPBF | TO262 |
| IRG7PH35UD-EP | SP001548020 | IRG7PH35UD-EP | TO247COPAK |
| IRG7PH35UDPBF | SP001537540 | IRG7PH35UDPBF | TO247COPAK |
| IRGB4056DPBF | SP001544890 | IRGB4056DPBF | TO220COPAK |
| IRGB4062DPBF | SP001544880 | IRGB4062DPBF | TO220COPAK |
| IRGB4620DPBF | SP001537640 | IRGB4620DPBF | TO220COPAK |
| IRGB4630DPBF | SP001537630 | IRGB4630DPBF | TO220COPAK |
| IRGP4062DPBF | SP001545058 | IRGP4062DPBF | TO247COPAK |
| IRGP4063DPBF | SP001549776 | IRGP4063DPBF | TO247COPAK |
| IRGP4063PBF | SP001546206 | IRGP4063PBF | TO247 |
| IRGP4066D-EPBF | SP001548120 | IRGP4066D-EPBF | TO247COPAK |
| IRGP4066DPBF | SP001545048 | IRGP4066DPBF | TO247COPAK |
| IRGP4068D-EPBF | SP001542408 | IRGP4068D-EPBF | TO247COPAK |
| IRGP4068DPBF | SP001535818 | IRGP4068DPBF | TO247COPAK |
| IRGP4069D-EPBF | SP001534110 | IRGP4069D-EPBF | TO247COPAK |
| IRGP4069DPBF | SP001535800 | IRGP4069DPBF | TO247COPAK |
| IRGP4640D-EPBF | SP001546168 | IRGP4640D-EPBF | TO247COPAK |
| IRGP4640DPBF | SP001535770 | IRGP4640DPBF | TO247COPAK |
| IRGP4650D-EPBF | SP001535810 | IRGP4650D-EPBF | TO247COPAK |
| IRGP4650DPBF | SP001535760 | IRGP4650DPBF | TO247COPAK |
| IRGP4660D-EPBF | SP001548232 | IRGP4660D-EPBF | TO247COPAK |
| IRGP4660DPBF | SP001534070 | IRGP4660DPBF | TO247COPAK |
| IRGPS46160DPBF | SP001545270 | IRGPS46160DPBF | SUPER247COPAK |
| IRL3705ZLPBF | SP001576270 | IRL3705ZLPBF | TO262 |
| IRL40DM247 | SP001778258 | IRL40DM247XTMA1 | MG-WDSO-8 |

Information note N° 054/21

Removal of legacy International Rectified (IR) logo from tube and packing box affecting products from assembly location Tijuana, Mexico

| Sales name | SP number | OPN | Package |
|----------------|-------------|---------------------|-------------|
| IRL40SC209 | SP001568434 | IRL40SC209 | D2PAK7P |
| IRL40SC228 | SP001550368 | IRL40SC228 | D2PAK7P |
| IRL60SC216 | SP001646070 | IRL60SC216ARMA1 | PG-TO263-7 |
| IRL6297SDTRPBF | SP001578724 | IRL6297SDTRPBF | MG-WDSON-6 |
| IRL7472L1TRPBF | SP001558732 | IRL7472L1TRPBF | MG-WDSON-11 |
| IRL7472L1TRPBF | SP003558876 | IRL7472L1TRPBFXTMA1 | MG-WDSON-11 |
| IRL7472L1TRPBF | SP005595000 | IRL7472L1TRPBFXTMA2 | MG-WDSON-11 |
| IRL7486MTRPBF | SP001567046 | IRL7486MTRPBF | MG-WDSON-8 |
| IRL8114PBF | SP001550392 | IRL8114PBF | TO220 |
| IRLB8748PBF | SP001567020 | IRLB8748PBF | TO220 |
| IRLC3615F | SP001552622 | IRLC3615F | n.a. |
| IRLR3636TRLPBF | SP001569134 | IRLR3636TRLPBF | DPAK |
| IRLR4132TRPBF | SP001567364 | IRLR4132TRPBF | DPAK |
| IRLR7843TRLPBF | SP001558496 | IRLR7843TRLPBF | DPAK |
| IRLR7843TRPBF | SP001569090 | IRLR7843TRPBF | DPAK |
| IRLR8743TRPBF | SP001552904 | IRLR8743TRPBF | DPAK |
| IRLR9343TRPBF | SP001552884 | IRLR9343TRPBF | DPAK |
| IRLS3813TRLPBF | SP001573098 | IRLS3813TRLPBF | D2PAK |
| IRLSL4030PBF | SP001558626 | IRLSL4030PBF | TO262 |
| IRLU024NPBF | SP001553260 | IRLU024NPBF | IPAK |
| IRLU120NPBF | SP001567330 | IRLU120NPBF | IPAK |
| IRLU3110ZPBF | SP001578962 | IRLU3110ZPBF | IPAK |
| IRLU3410PBF | SP001574164 | IRLU3410PBF | IPAK |
| IRLU7843PBF | SP001578952 | IRLU7843PBF | IPAK |
| IRS56303DCF | SP001539362 | IRS56303DCF | n.a. |