

# PRODUCT ADVISORY NOTICE

## KEEPING YOU INFORMED OF PRODUCT CHANGES

**TO: All 90 and 76 Series DIP Switch Customers, Sales Representatives and Distributors**


**DATE: December 1, 2021**

**SUBJECT: Temporary color change of 76HP, 90B and 90HB DIP actuators due to plastic material shortage**

### Description of Change

Due to a shortage of the natural colored plastic material used to mold the actuators of the affected DIP switches, the color will be temporarily changed to black to avoid production delays.

DIP Actuator Temporary Color Change Due to Material Shortage



Color of DIP actuators (currently natural) will be temporarily changed to black to prevent production delays.

### Part Numbers Affected

The 90B, 90HB & 76HP Series switches listed below produced between January 1, 2022 and April 30, 2022 may potentially be manufactured using black colored actuators instead of the typical natural color.

76HPSB02GWRT	90B08SLT	90HBJ08PT	90HBW04RT
76HPSB02GWT	90B08ST	90HBJ10PT	90HBW05PT
76HPSB04GWRT	90B10ST	90HBW02PRT	90HBW06PRT
76HPSB06GWRT	90B10T	90HBW02PT	90HBW07PRT
76HPSB08GWRT	90HBJ02PRT	90HBW02RT	90HBW07PT
76HPSB10GWRT	90HBJ03PRT	90HBW03PRT	90HBW08PRT
76YY24062GWR	90HBJ03PT	90HBW03PT	90HBW08PT
90B03ST	90HBJ04PT	90HBW03RT	90HBW08RT
90B04ST	90HBJ05PRT	90HBW04PRT	90HBW10PRT
90B06ST	90HBJ08PRT	90HBW04PT	90HBW10PT



# PRODUCT ADVISORY NOTICE

---

## KEEPING YOU INFORMED OF PRODUCT CHANGES

---

### **Potential Impact**

There is no change to the form, fit, or function of the products. The parts will be produced using the same plastic material, only in an alternative color (black).

### **Action Required**

Please forward this notification to the appropriate person(s) in your organization. If the change is acceptable, no action is necessary. If you have questions, contact your Business Development Manager.

