

16th October, 2019

Dear Sirs,

HIROSE ELECTIRC CO., LTD.
President and Representative Director, Kazunori Ishii
Director, Administration Group, Hiroshi Fukumoto

Impacts of Typhoon Hagibis (Second Report)

We inform about impacts of Typhoon Hagibis as follows.

1. Employees Safety

There were not any injuries for all of our group employees.

2. Impacts on Production Activities

(1) Our Group Production Subsidiaries

① TOHOKU HIROSE ELECTRIC CO., LTD.

Production Items: Multi-Pin Connectors

Damage: There was no damage to buildings and facilities.

Production Status: Today, the factory is producing as usual.

② KORIYAMA HIROSE ELECTRIC CO., LTD.

Production Items: Multi-Pin Connectors

Damage: A part of the factory was flooded by Abukuma River.

Production Status: Recovery efforts are underway at the factory. We are trying to restore our power as soon as possible. Shipment of our stock items is in progress and we are considering some production items are produced by our different subsidiaries and our cooperative companies.

③ ICHINOSEKI HIROSE ELECTRIC CO., LTD.

Production Items: Multi-Pin Connectors, Coaxial Connectors and Other Products

Damage: There was no damage to buildings and facilities.

Production Status: Today, the factory is producing as usual.

(2) Cooperative Companies

Some of our cooperative companies got damages but the main production of them has already been started. We are confirming more details about the damages at our cooperative companies. We will inform about the impacts of damages at our cooperative companies if the impacts affect our production.

3. Impacts of Damage

We will inform about impacts of damages once the impacts become clear.

Affected Parts

MI20A-50PDR-SF(71)
MI20A-50PD-SF-EJR(71)
MI20A-50PD-SF-EJL(71)
MI21A-50PD-SF-EJR(71)
MI21A-50PD-SF-EJR(91)
MI21A-50PD-SF-EJL(71)
MI21A-50PD-SF(71)
MI21-50PD-SF-EJR(91)
MI21-50PD-SF-EJL(91)
MI21-50PD-SF(71)
MI21-50PD-SF-EJRA(71)
GT13SC-2S-HU
RDBD-25S-LN(57)
RDBD-25S-LN(4-40)(55)
FI40-20S-CVS2(20)
NX30TA-15PAA(50)
ST40X-24S-CV(30)
UFLVHF6-04K2TTFVA12-295
UFLVHF6-04K4TTFVA13-277
UFLVHF6-04K4TTFVA14-277
DF1-SP(05)
HIF3-6PA-2.54DS(86)
DF7-7P-3.96DSA(55)
DF7-10P-3.96DSA(55)
DF7-1P-3.96DSA(35)
UK40-A-3S-1600
UK40-C-3S-2000A
UK40-A-3S-1700
UK40-A-3S
UK40-C-3S
RDBD-25SA-LN(55)
RDBD-25S(55)
RDBD-25S-LNA(57)
RDBD-25S(4-40)(55)
S-1634A-CA(50)
S-1634A-CA(51)
S-1645A-CA(50)
S-1620A-CA(51)
S-1624A-CA(51)
S-1628A-CA(50)
S-1628A-CA(51)
P-1620BA-CA(51)
P-1624BA-CA(50)
P-1628BA-CA(51)
P-1660BA-CA(50)
TM21R-5A-3232-LP(51)
FI30-20S(20)
FI30-20S(51)
FI-20-CV3(50)
FI30-20S-CV2(50)
FI30-20S-CV2(51)
3110-14SB(50)
NX-9T-CV
ST40X-18S-CV1(30)
ST40-BS-24S-CV(30)
UFLHF6-068K6TSA15-216.5NT

UFLHF6-068K1TSA16-298.5NT
UFLVHF6-04K4TTFVAA1-279.3
MS-147(39)
MS-156HFS(75)
MS-156BHF(75)
SX4EA-168S-1.27DSA(92)
HIF3A-60D-2.54R
HIF3-6P-2.54DS
HIF5C-26DA-2.54R(91)
HIF3BA-60D-2.54R(18)
HIF3CA-26PA-2.54DSA(91)
HIF3CAF-26PA-2.54DSA(71)
HIF3H-70DB-2.54DS(71)
HIF6B-50DA-1.27DSL(71)
HIF6B-50DA-1.27DSAL(71)
MI20-50RD-SF(51)
MI20-50RD-SF(71)
MI20A-50PD-SF-EJR(91)
MI21A-50PD-SF-EJR(81)
MI21A-50PD-SF-EJL(91)
MI21A-50PD-SF(83)
MI21A-50PD-SF(93)
MI21-50PD-SF(91)
DP3-88850-2-11
DP3-086616-0-11
DF7-7P-3.96DSA(35)
DF7-8P-3.96DSA(35)
DF7-8P-3.96DSA(55)
DF7-9P-3.96DSA(35)
DF7-9P-3.96DSA(55)
DF7-10P-3.96DSA(35)
DF7-6P-3.96DS(55)
DF7-7P-3.96DS(55)
DF7-10P-3.96DS(25)
DF7-4P-7.92DSA(35)
DF7-5P-7.92DSA(35)
DF7-1P-3.96DSA(55)
GT5T-1PP-HU(70)
GT13SC-2S-HU(21)
IX61G-A-10P
DF3-12S-2C
DF3-12EP-2C
DF11-6DS-2C
DF11-8DS-2C
DF11-14DS-2C
DF11-16DS-2C
DF11-20DS-2C
DF11-20DS-2C(20)
DF11-4DS-2C
DF51-3EP-2C
DF51-6EP-2C
PS3F-2RS/8S/10S
DF11-6DS-2C(20)
DF51-2EP-2C
DF51-4EP-2C
DF51-5EP-2C
GT25H2-24DP-2.2H(10)

PS3F-2R/8P/10P
IX60G-A-10P
IX60G-B-10P
IX61G-B-10P(02)
GT25RM-12DP-2.2H
MQ115-2PA-1B(22)
MQ115-8P-4B(22)
TM18R-TO-66(51)
PS3F-2RS/8S/10S(01)
PS3F-2R/8P/10P(01)
TQ10-B-40P
TQ10-D-40P
TQ10-D-40P(02)
MT10W-4P-FL
MT50W-10AP-FL
MT50W-10CS-CVL(7.1)
IX61G-A-10P(01)
IX61G-B-10P
IX61G-B-10P(01)
FX12C-80P-0.4SV
FX12C-80S-0.4SV
FX23-80S-0.5SH2.5(03)
FX23-140S-0.5SH2.5(03)
FX23M1-160S-0.5SV1
FX26-30P-1SV
FX26-40P-1SV
FX26-30S-1SV20
FX26-60S-1SV20
FH1-14S-2.54DS
FH1-16S-2.54DSA
FX10-144IP-44Q-8H
FX10-144IP-44Q-8PH
DF59SN-1P-FC/IN-TOOL
GT13SC-1/1PP-DS(71)
GT25D2-20DP-2.2H
WGT32FS-4DP4DP-0513
WGT32FS-4DS4DS-0515
WGT36S(B)GT36S(B)-0529
DF3-2EP-2C
DF3-3EP-2C
DF22-3P-7.92DSA(05)
IX80G-A-10P
IX80G-B-10P
IX30G-A-10S-CV(7.0)
IX40G-A-10S-CV(7.0)
IX40G-A-10S-CV(7.0)(01)
IX31G-A-10S-CV(7.0)
IX31G-B-10S-CV(7.0)
IX30G-B-10S-CV(7.0)
IX40G-B-10S-CV(7.0)
DF62B-2EP-2.2C
DF62WB-9EP-2.2C
DF62WE-9EP-2.2C
FX22-40P-0.5SH
FX22-80P-0.5SH
FX22-80S-0.5SH
GT16GT-1P-H(30)

GT25H2-24DP-2.2H
GT25H2-24DP-2.2H(99)
IX80G-B-10P(01)
IX30G-A-10S-CV(7.0)(01)
IX31G-A-10S-CV(7.0)(01)
IX31G-B-10S-CV(7.0)(01)
IX30G-B-10S-CV(7.0)(01)
IX30G-HRA-10S-CV(7.0)
IX40G-B-10S-CV(7.0)(01)
IX34G-B-10S-UNIT1(01)
IX40G-A-10S-UNIT(10)
IX40G-A-10S-UNIT(11)
IX40G-B-10S-UNIT(10)
IX40G-B-10S-UNIT(11)
IX30G-A-10S-UNIT(10)
IX30G-B-10S-UNIT(10)
IX31G-A-10S-UNIT(10)
IX31G-B-10S-UNIT(10)
DF7-3P-3.96DSA(55)
GT25H2-24DP-2.2H(38)
HR212-10R-8SC50A1F(71)
IX80G-A-10P(01)
IX30G-HRA-10S-CV(7.0)(01)
IX30G-HRB-10S-CV(7.0)
IX30G-HRB-10S-CV(7.0)(01)
IX31G-HRA-10S-CV(7.0)
IX31G-HRA-10S-CV(7.0)(01)
IX31G-HRB-10S-CV(7.0)
IX31G-HRB-10S-CV(7.0)(01)
IX40G-HRA-10S-CV(7.0)
IX40G-HRA-10S-CV(7.0)(01)
IX40G-HRB-10S-CV(7.0)
IX40G-HRB-10S-CV(7.0)(01)
IX34G-SMB-10S-CV(4.2)(01)
IX34GF-SMB-10S-CV(01)
IX32G-A-8S-CV(7.0)
IX32G-A-8S-CV(7.0)(01)
IX32G-B-8S-CV(7.0)
IX32G-B-8S-CV(7.0)(01)
IX30G-A-10S-UNIT(11)
IX30G-B-10S-UNIT(11)
IX31G-A-10S-UNIT(11)
IX31G-B-10S-UNIT(11)
DF62WC-9EP-2.2C
FX22-40P-0.5SH(20)
FX22-50P-0.5SH
FX22-60P-0.5SH
FX22-80P-0.5SH(20)
FX22-40S-0.5SH
FX22-40S-0.5SH(20)
FX22-50S-0.5SH
FX22-60S-0.5SH
FX22-80S-0.5SH(20)
FX26-40S-1SV18
FX26-60P-1SV5
DF7-2P-3.96DSA(35)
DF7-2P-3.96DSA(55)

DF7-3P-3.96DSA(35)
DF22-3P-7.92DSA(35)
WNY-00525
WNY-00525(31)
WNY-00525(31)-R