PRODUCT CHANGE NOTICE (PCN)

PCN#	WPC-180731-001	**Issuing Date**	July 31th, 2018

PRODUCT(S) AFFECTED :　　　　　　　　　　**Attachment**: □Yes　　■No

WIZ550S2E Rev1.2		
Hardware Version	Firmware Version	Supplying Schedule
No Revision	1.0.3 → 1.4.0	July 31th, 2018

Description of Change from Firmware Ver. 1.0.3 to Ver. 1.4.0

- Add function
    - AT Command sets
        - AT+MPASS : Change the module's name
        - AT+MNAME : Change the module's password
    - Modbus
        - Modbus TCP to Modbus RTU
        - Modbus TCP to Modbus ASCII
- Changed
    - ioLibrary Update
    - AT Command sets
        - AT+NMODE -> AT+MMODE
- Fixed bug
    - Time packing problem in UDP mode.
        - Before : Not work normally after the first time.
        - After : Work normally
    - UDP Send Fail in AT Mode
        - Problems caused by ioLibrary update
    - Receiving data in AT Mode
        - Occurs when data larger than the buffer size is received.

- V1.20 Configuration Tool down load link.
    - https://github.com/Wiznet/WIZnet_Configuration_Tool-Modbus/releases

DISTRIBUTORS NOTIFICATIOON :

The purpose of this note is to inform changes in the Firmware of WIZ550S2E. The purpose of all changes are for better convenience.

Please notify this change to the customers who are using the upgraded products.

DISTRIBUTOR ACKNOWLEDGEMENT : Distributors may use this form to acknowledge receipt of this notification. Please fill in the below form and return it to us.

Distributor		Date	
Name		Title	
E-mail			
Comments			

AFFECTED MPNS
WIZ550S2E
WIZ550S2E-232
WIZ550S2E-232-EVB
WIZ550S2E-485
WIZ550S2E-485-EVB