Product Change Notification
Current Date: 21-Jun-2022

TE Connectivity

Product Change Notification: P-22-022922   **PCN Date:** 15-JUN-22

Customer: Future Electronics(0000080100)   **Location:** WORLDWIDE   **Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Miniseal, Duraseal, Databus

Description of Changes

Markem-Imaje informed us that they will replace the INK ADDITIVE 5191 (MEK based), they will move from the current 5191 to 5199 (5191 was obsoleted).

Reason for Changes:

Product improvement.Vendor Markem-Imaje phase-out of pink MEK additive due to a shortage of a pink dye raw material used in MEK additives

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	20-JUN-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	20-DEC-2022

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
D36771-000	NO			"4-1200790-7"			

Customer: Future Electronics Ltd (1307660)   **Location:** Egham   **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
D36771-000	NO			"4-1200790-7"			

Customer: Future Electronics Ltd (2895038)   **Location:** Leipzig   **Agreement Number:** Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
D36771-000	NO			"4-1200790-7"			