

29th January, 2015



To: Valued Customer

From: Littelfuse Product Management

Subject: Change of sleeves to Pico 275 series fuses

With regards to the above reference, Littelfuse would like to inform you that we would be changing the sleeves for the Pico 275 series fuses.

Please see below for the comparison of the existing sleeve on the fuses vs the latest sleeve to be used on the fuses. The latest sleeves would allow the markings on the fuse to be more visible.

	Old Sleeve	New Delivery
Raw material		
Fuse Final part		

Affected ratings would be 20A, 25A and 30A of the 275 series.

Affected part numbers as given below and per attached.

Series	275		
Rating	20A	25A	30A
Affected part numbers	0275020.MRT1L	0275025.MRT1L	0275030.MRT1L
	0275020.MXEL	0275025.MXEL	0275030.MXEL
	0275020.MXL	0275025.MXL	0275030.MXL
	0275020.VXL	0275025.VXL	0275030.VXL

Timeframe

We would be doing a running change in production on 29th January 2015

Best regards,
Daniel Wang
Director
Global Product Management
Electronics Business Unit

Dwang@Littelfuse.com