

Product Change Notification


Effective 1 May 2016

As a result of simplifying our manufacturing capabilities regionally to reinforce our ability to deliver reliably and with speed, the sourcing of the below listed products are being shifted from our manufacturer in the US to a second qualified approved supplier in Asia. The initial vendor will be phased out over the next three months.

There are zero changes to the form, fit or hardware/firmware functionality of the modules. Affected part numbers are listed below.

AC4490-1000M-01	CL4490-1000-232	RM024-P10-C-30	BL620-US-01
AC4790-1000M-01	CL4490-1000-232-SP	RM024-P10-M-30	CC600-SA-01
AC4790-1000M-02	CL4490-1000-485	RM024-P125-C-30	DVK-BT800-01
AC4490-1X1	CL4490-1000-485-SP	RM024-P125-M-30	DVK-BT800-02
AC4790-1x1	CL4490-1000-PRO	RM024-S10-C-20	DVK-BT830-SA-01
AC4790-1x1-04	CL4490-1000-PRO-SP	RM024-S10-C-30	DVK-BT830-ST-01
AC4490-1X1V	CL4790-1000-232	RM024-S10-M-30	BA600-SA-01
AC4490LR-1000M-01	CL4790-1000-232-SP	RM024-S125-C-20	BB600-SA-01
AC4490LR-1000M-02	CL4790-1000-485	RM024-S125-C-30	BC600-SA-01
AC4490LR-1000M-03	CL4790-1000-485-SP	RM024-S125-M-30	CC600-SA Program
AC4790LR-1000M-01	PENTAIR-485-SP	RM024-X125-C-20	BISMS02BI-01
AC4790LR-1000M-02	DAK024-S10-C-02	TRM024-S10-C-01	BRBLU03-010A0-03
AC4490-200M-01	DAK024-S125-C-02	TRM024-S10-C-03	TRBLU2300200-07-01
AC4790-200M-01	DVK-RM024-CE	PRM240-01	
DVK-AC4490LR-1000M	DVK-RM024-FCC		
SDK-AC4790LR-1000M			

Sincerely,



Sue Magilavy

Operations Manager - Connectivity Solutions Business Unit

14 April 2016