



Product Change Notification

Current Date: 19-Oct-2017

TE Connectivity

Product Change Notification: E-17-013712

PCN Date: 10-OCT-17

Customer: Future Electronics(0000080100)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Univer Mate-N-Lok plug Housing

Description of Changes

Material upgrade for better supply chain.

Reason for Changes:

Product Improvement. Material upgrade for better supply chain.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

15-JAN-2018

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

15-FEB-2019

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-350777-2	NO						
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350715-4	NO			"C46515-000", "AMPS-0-0350715-4"			
350720-1	NO			"403049182", "AMPS-0-0350720-1", "D76178-000", "500-020-2570"			
350720-4	NO						
350735-4	NO						
350736-1	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
350766-1	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
350766-4	NO						
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350777-4	NO			"CF8009-000", "SIML-0-0350777-4"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
350779-4	NO						
350809-1	NO			"AMP-0-0350809-1", "E81588-000"			
350866-1	NO			"CU3088-000", "AMPS0-0350866-1"			
640581-1	NO			"405000886"			
640582-1	NO						

Customer: Future Electronics Inc.(1319890)

Location: HONG KONG

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
640582-1	NO						

Customer: Future Electronics Asia Pacific(2923061)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-350777-2	NO						
350715-4	NO			"C46515-000", "AMPS-0-0350715-4"			
350720-1	NO			"403049182", "AMPS-0-0350720-1", "D76178-000", "500-020-2570"			
350736-1	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
350766-1	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
350809-1	NO			"AMP-0-0350809-1", "E81588-000"			
640582-1	NO						

Customer: Future Electronics Inc.(1319888)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350715-4	NO			"C46515-000", "AMPS-0-0350715-4"			
350736-1	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
350766-1	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
640582-1	NO						

Customer: Future Electronics Inc.(1319888)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350715-4	NO			"C46515-000", "AMPS-0-0350715-4"			
350736-1	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
350766-1	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
640582-1	NO						

Customer: FUTURE ELEC- SAMPLES AUSTIN(546768)

Location: AUSTIN

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			

Customer: Future Electronics Inc(1290208)

Location: Southaven

Agreement Number: FUTAGR001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350720-1	NO			"403049182", "AMPS-0-0350720-1", "D76178-000", "500-020-2570"			
350736-1	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
350766-1	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
350809-1	NO			"AMP-0-0350809-1", "E81588-000"			
640581-1	NO			"405000886"			

Customer: Future Electronics UK(2833922)

Location: Hayes

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350736-1	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
350766-1	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
350809-1	NO			"AMP-0-0350809-1", "E81588-000"			
350866-1	NO			"CU3088-000", "AMPS0-0350866-1"			

Customer: Future Electronics EDC Services(2944409)

Location: Leipzig

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350720-1	NO			"403049182", "AMPS-0-0350720-1", "D76178-000", "500-020-2570"			
350766-1	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
350809-1	NO			"AMP-0-0350809-1", "E81588-000"			

Customer: Future Electronics-Disty Sample(773504)

Location: Pointe Claire

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			

Customer: Future Electronics Inc.(2883079)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350715-1	NO			"402723738", "AMP-0-0350715-1", "E04329-000"			
350715-4	NO			"C46515-000", "AMPS-0-0350715-4"			
350736-1	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
350766-1	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
640582-1	NO						

Customer: Future Electronics(3059283)

Location: Quebec

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350766-1	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
640581-1	NO			"405000886"			
640582-1	NO						

Customer: Future Electronics Ltd(2895038)

Location: Leipzig

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-350777-2	NO						
350715-4	NO		350715-4-LF	"C46515-000", "AMPS-0-0350715-4"			
350720-4	NO		350720-4-LF				
350735-4	NO		350735-4-LF				
350736-1	NO		350736-1-LF	"403431885", "AMPS-0-0350736-1", "D26199-000"			
350766-4	NO		350766-4-LF				
350777-1	NO		350777-1-LF	"403311533", "AMPS-0-0350777-1", "C55004-000"			
350777-4	NO		350777-4-LF	"CF8009-000", "SIML-0-0350777-4"			
350779-4	NO		350779-4-LF				
350809-1	NO		350809-1-LF	"AMP-0-0350809-1", "E81588-000"			
640581-1	NO		640581-1-LF	"405000886"			
640582-1	NO		640582-1-LF				

Customer: Future Electronics Inc(184927)

Location: Pointe Claire

Agreement Number: FUTAGR002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350736-1	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
350766-1	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
350809-1	NO			"AMP-0-0350809-1", "E81588-000"			
640581-1	NO			"405000886"			



Product Change Notification

Current Date: 23-Oct-2017

TE Connectivity

Product Change Notification: E-17-013712

PCN Date: 10-OCT-17

Creator: CANDY XU

PCN Classification: Form Fit Function Change

PCN Type: Standard

TE CONNECTIVITY EMPLOYEE CONFIDENTIAL

This PCN version contains confidential information and is not for distribution outside TE Connectivity.
The email version is suitable for external distribution.

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

[Get email version](#)

General Product Description:
Univer Mate-N-Lok plug Housing

Description of Changes
Material upgrade for better supply chain.

Reason for Changes:	
Product Improvement. Material upgrade for better supply chain.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	15-JAN-2018
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	15-FEB-2019

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-350736-9	NO					
1-350777-1	NO					
1-350777-2	NO					
1-350777-3	NO					
1-350777-4	NO					
1-350777-6	NO					
1-350777-9	NO					
1-350779-1	NO					
1-350779-3	NO					
2029387-1	NO					
350715-1	NO		"402723738", "AMP-0-0350715-1", "E04329-000"			
350715-4	NO		"C46515-000", "AMPS-0-0350715-4"			
350720-1	NO		"403049182", "AMPS-0-0350720-1", "D76178-000", "500-020-2570"			
350720-4	NO					
350735-4	NO					
350736-1	NO		"403431885", "AMPS-0-0350736-1", "D26199-000"			
350766-1	NO		"AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
350766-4	NO					
350777-1	NO		"403311533", "AMPS-0-0350777-1", "C55004-000"			
350777-4	NO		"CF8009-000", "SIML-0-0350777-4"			
350779-1	NO		"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
350779-4	NO					
350809-1	NO		"AMP-0-0350809-1", "E81588-000"			
350865-1	NO		"CU3087-000", "AMPS-0-0350865-1"			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
350866-1	NO		"CU3088-000", "AMPS0-0350866-1"			
640581-1	NO		"405000886"			
640582-1	NO					
794741-1	NO					