



31-Oct-2017

**PCN #:**P-17-014989

**Subject:**Inverted modular jack

**Description of Change:** The assembly line of following Part Numbers will be transferred from out side vendor to TE AMP ShangHai plant.

**Reason:** Dear Customer, we hereby inform you about a transfer of assembly line of modular jack. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the related products. The new manufacturing location operates under a certified quality management system. A TE-internal release test based on the relevant part specifications will be executed before delivery. If you require a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN.

**Impact of Change:**Manufacturing location change

**Key Dates:**

**Contact By Date:**08-Dec-2017

**Implementation Date:**08-Dec-2017

**Product Affected**

406534-6

5406544-2

5406556-1

5406552-4

3-406549-0

6368214-8

6368460-4

406507-3

2-406549-4

(Alias Part Numbers:

## Product Affected

"A69961-000"

"AMP-2-0406549-4")

6364173-5

6116353-8

5406554-2

2-406541-3

2170359-1

1761791-4

1364445-1

3-406549-1

5406552-2

1116353-6

2-406541-2

1-406541-4

5406967-4

1-406507-5

2170354-1

1-406525-2

1-406507-6

2-6116353-4

5406533-7

5406536-1

406967-3

406507-2

2-406534-4

5406528-1

1-406541-9

6116115-4

6364288-4

5406544-1

2-5406552-1

1-406507-1

6116132-5

406552-6

5406967-8

1-5406552-3

406508-6

1-406507-3

1761791-5

2-406549-9

## **Product Affected**

2-406549-2  
1761791-2  
2-406549-7  
6116353-2  
1-6116353-3  
6116075-7  
6116075-5  
406534-7  
3-406549-3  
2-6368144-1  
2170463-1  
5406536-8  
4-406541-8  
2-406541-7  
5406544-3  
5406554-7  
6116132-8  
1116075-2  
1761791-3  
1888298-1  
406967-5  
5406552-8  
3-6116353-1  
5406554-4  
5406552-7  
1-5406552-5  
1-5406552-8  
2170358-2  
1-5406552-4  
6364139-5  
1888566-2  
1-406541-8  
6116615-5  
5406534-2  
6116522-4  
3-406507-4  
5406556-4  
1761750-1  
1932219-2  
6368419-1

**Product Affected**

1116132-8

1888283-1

3-6116353-2

6116075-6

2-6116353-9

1761791-1

3-406507-5

2-406541-5

2-406541-0

2007073-2

6116615-4

6116522-1

1-5406552-1

1932389-1

5406533-5

6116522-2

6116075-1

5406554-9

2-406541-6

2-406549-8

(Alias Part Numbers:

"P04065-000")

5406554-8

5406552-9

1888612-1

1-406507-2

3-406549-8

5406526-1

1116132-6

1-5406533-8

6116353-4

6116615-6

406534-5

2-406541-4

1-5406552-9

6116075-4

(Alias Part Numbers:

"CF0103-000"

"AMP-0-6116075-4")

2007073-1

## **Product Affected**

6116173-5

1-406541-7

2007675-1

1932112-1

5406533-1

2170358-1

406507-6

3-406507-1

1-406507-7

5406552-5

3-406507-7

6368459-1

6116132-1

6116353-5

406536-7

406508-5

6116173-1

(Alias Part Numbers:

"CA6961-000"

"PER-0-6116173-1")

5406554-5

1888630-1

4-406549-8

6116301-1

1-5406552-6

5406967-5

2-406541-1

2-6116353-8

(Alias Part Numbers:

"CC1020-000"

"AMP-2-6116353-8")

6116173-4

3-406549-2

1-5406552-7

2-406507-4

1-406552-1

1368460-4

1368459-1

406525-3

1368419-1

**Product Affected**

1116173-1

406541-6

1368214-8

2-1368144-1

406541-5

1364288-1

1364173-5

1116522-1

1116353-8

1116353-5

1116353-4

1116353-1

1116173-5

1116173-4

1116132-5

1116132-4

1116132-1

1116075-7

1116075-6

1116075-5

1116075-4

1116075-1

406556-4

406556-1

406554-5

406554-4

406552-8

406552-7

406552-5

406552-4

406552-1

406549-8

(Alias Part Numbers:

"E56507-000"

"AMP-0-0406549-8")

406549-5

(Alias Part Numbers:

"1257120")

406549-4

(Alias Part Numbers:

**Product Affected**

"F23618-000"

"AMP-0-0406549-4")

406549-2

406549-1

(Alias Part Numbers:

"29-00045-01"

"1950351P009")

406544-1

406541-4

406541-1

406533-1

406528-1

406526-1

406525-1

(Alias Part Numbers:

"1054579")

7-406507-4

406507-7

406507-4

406507-1

(Alias Part Numbers:

"1119029")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.