




Product Change Notice: P4S Series Connectors

PCN.PGC10.12.12.2017

12.12.2017

<p>About This Notice:</p>	<p>To improve product reliability, Panasonic will be changing the plating specification for P4S Series Header Side Connectors to a Nickel barrier construction to better protect against solder rise.</p>						
<p>Effective Date:</p>	<p>March 1, 2018</p>						
<p>Change Details:</p>	<p>What is Ni barrier construction?</p> <div data-bbox="548 884 1198 1165" data-label="Image"> </div> <p data-bbox="1242 955 1502 1087">By providing an exposed Ni portion on mid part of Au plating, the function of preventing solder rising is improved.</p> <p data-bbox="990 1134 1258 1165">Cross sectional view of A-A</p> <ul data-bbox="487 1186 1518 1270" style="list-style-type: none"> * Depending on the product type, the lower part of the V notch may assume the Ni color. This will not affect contact reliability. * In previous products, the socket already has the Ni barrier. <p>Label Change</p> <table border="1" data-bbox="479 1344 1477 1722"> <thead> <tr> <th data-bbox="479 1344 982 1396">Before change</th> <th data-bbox="987 1344 1477 1396">After change</th> </tr> </thead> <tbody> <tr> <td data-bbox="479 1402 982 1564"> </td> <td data-bbox="987 1402 1477 1564"> </td> </tr> <tr> <td colspan="2" data-bbox="990 1575 1469 1711"> <p>Temporarily during the changeover period, a ● mark will be displayed above the quantity on the inner and outer labels of the changed product. This will continue for six months until the end of August 2018. The ● mark will not be displayed from September onward.</p> </td> </tr> </tbody> </table>	Before change	After change			<p>Temporarily during the changeover period, a ● mark will be displayed above the quantity on the inner and outer labels of the changed product. This will continue for six months until the end of August 2018. The ● mark will not be displayed from September onward.</p>	
Before change	After change						
<p>Temporarily during the changeover period, a ● mark will be displayed above the quantity on the inner and outer labels of the changed product. This will continue for six months until the end of August 2018. The ● mark will not be displayed from September onward.</p>							



na.industrial.panasonic.com

industrial@us.panasonic.com

1-800-344-2112

Affected Parts: See attached.

Datasheet(s): See attached.

Notes: Please note that part numbers, pricing and specifications will remain unchanged.