



Not Recommended for New Design: Various AQV258xxx PhotoMOS Relays

NRFND.PG0001. 12.26.2018

12.26.2018

About This Notice:	Panasonic has changed the status of part numbers AQV258HA, AQV258HAX and AQV258HAZ to Not Recommended For New Design due to plans for discontinuation in the future.
Features:	
Effective Date:	Immediate
Affected Parts and/or Replacements:	See attached.
Datasheet(s):	No datasheet available as these are custom part numbers.
Notes:	Custom part may be available after spec review activity.

Panasonic NRFND.PG0001.12.26.2018

Affected Parts

AQV258HA
AQV258HAX
AQV258HAZ