



Product Discontinuation Notice: MA Motion Sensors

PDN.PG36.9.17.2019

9.17.2019

Effective Date:	Immediate
Last Time Buy Date:	September 30, 2020
Last Eligible Ship Date:	September 31, 2021
Discontinuation Details:	The supplier for the ASIC for the MA Motion Sensor is discontinuing the component. The ASIC is critical for the functionality of the MA Motion Sensor so unfortunately Panasonic has to discontinue the product.
Suggested Replacement:	None
Affected Part Numbers:	See Attached.
Datasheets:	See Attached.
Notes:	

Panasonic PDN.PG36.9.17.2019 MA Motion Sensors

Affected Parts In Panasonic Industrial Devices Sales Company Of America ERP System

AMA115905
AMA1459
AMA145905
AMA145915
AMA1469
AMA146915
AMBA1402
AMBA140205
AMBA140206
AMBA140207
AMBA140208
AMBA140209
AMBA1409
AMBA140905
AMBA140906
AMBA140907
AMBA140908
AMBA140909
AMBA2109
AMBA210902
AMBA210903
AMBA210904
AMBA210905
AMBA210906
AMBA210907
AMBA2402
AMBA240202
AMBA240203
AMBA240204
AMBA240205
AMBA240206
AMBA240207
AMBA2409
AMBA240902
AMBA240903
AMBA240904
AMBA240905
AMBA240906
AMBA240907
AMBA310210
AMBA310908
AMBA3159

AMBA315914
AMBA315915
AMBA3402
AMBA340203
AMBA340204
AMBA340205
AMBA340206
AMBA340207
AMBA340208
AMBA340209
AMBA340210
AMBA340211
AMBA340212
AMBA340213
AMBA340214
AMBA340215
AMBA340216
AMBA340217
AMBA340218
AMBA340219
AMBA3409
AMBA340903
AMBA340904
AMBA340905
AMBA340906
AMBA340907
AMBA340908
AMBA340909
AMBA340910
AMBA340911
AMBA340912
AMBA340913
AMBA340914
AMBA340915
AMBA340916
AMBA340917
AMBA340918
AMBA340919
AMBA3452
AMBA345203
AMBA345204
AMBA345205
AMBA345206
AMBA345207
AMBA345208
AMBA345209
AMBA345210
AMBA345211
AMBA345212

AMBA345213
AMBA345214
AMBA345215
AMBA345216
AMBA345217
AMBA345218
AMBA345219
AMBA3454204
AMBA3459
AMBA345903
AMBA345904
AMBA345905
AMBA345906
AMBA345907
AMBA345908
AMBA345909
AMBA345910
AMBA345911
AMBA345912
AMBA345913
AMBA345914
AMBA345915
AMBA345916
AMBA345917
AMBA345918
AMBA345919
AMV9001
AMV9002
AMV9003