

Product Change Notice

Alps PCN: LO060820_Disti

Date: June 8, 2020

Type of Change: Packaging Change

Title of Change: 2020 Notice of Packaging Change_VR Products


Description of Change: Alps Alpine will be changing the label placement on the shipped boxes of our VR products. This change has no impact to Alps Alpine products. It is only for packaging purposes.

Contact Information: Sales and Marketing Contact
Sales@alps.com
 Alps Alpine North America, Inc.

Products Affected: Encoders, Multi-Control Devices, and Potentiometers

PACKAGE CHANGE

1. Description of change



* Quantity of products per box does not change.

2. Applied products

Please refer to the list of products below.

* It is also going to be applied to new products registered after May 1, 2020.

3. Reason of change

To standardize our products.

4. Date of change

Running change after October 2020 manufactured products.

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

LIST OF PRODUCTS

Part Number	Part Number	Part Number	Part Number
EC05E1220202	EC45AG520402	RK09K12A0A2K	RK27112A00B9
EC05E1220203	EC50A0920404	RK09K12A0A6R	RK27112A00CC
EC05E1220401	EC60B1520402	RK09K12A0B0W	RK27112A0A16
EC09E1520407	EM11B16140AE	RK09K12C0A19	RK39A1A00007
EC09E1524417	EM20B4014000	RK09K12C0A2S	RK39A1A00027
EC09E1524418	RD6R1A0008	RK09K12C0A4D	RK39A1A00028
EC10E1220501	RD7081015A	RK09K12C0A8K	RK45B1A00001
EC10E1220503	RD708A029A	RK09K12C0A8P	RK45B1A00002
EC10E1220505	RD7091008A	RK09L112003P	RK45C1A00003
EC10E1260502	RD7121008A	RK09L1120A2S	RK50112A0004
EC10E1260507	RD712A028A	RK09L1120A69	RK50114A0001
EC1110120005	RDC1010A12	RK09L114001T	RKJXK1210002
EC111012010H	RDC1014A09	RK09L1140A2U	RKJXK122000D
EC1110120201	RDC1022A05	RK09L1140A5E	RKJXK122400Y
EC11B15202AN	RDC10320RB	RK09L1140A5P	RKJXL100401V
EC11B15242AZ	RDC1047A03	RK09L1140A65	RKJXM1015004
EC11B15242B1	RDC401D07A	RK09L1140A66	RKJXM2E13004
EC11E09204A4	RDC501051A	RK09L122002M	RKJXS1004001
EC11E09244AQ	RDC501052A	RK09L1220A1B	RKJXT1F42001
EC11E09244BS	RDC502012A	RK09L124000Z	RKJXU1210006
EC11E0B2LB01	RDC503051A	RK09L1240A12	RKJXV1220001
EC11E15204A3	RDC503052A	RK09L12B0A31	RKJXV1224005
EC11E15244B2	RDC506018A	RK09L12B0A3Z	RKJXW1014002
EC11E15244G1	RDC803101A	RK09L12D0A1T	RKJXW2014001
EC11E152T409	RDC9010006	RK09L12D0A1W	RKJXY1000006
EC11E152U402	RDC9010007	RK09Y11L0001	RKJXY100000A
EC11E1534408	RDCC010002	RK10J11E002Y	RS08U111Z001
EC11E153440D	RK08H11100U3	RK10J11E0034	RS08U11AZ001
EC11E1820402	RK08H11100UD	RK10J11R001Y	RS15111A900B
EC11E18244A5	RK08H11100X7	RK10J11R0A0H	RS15H111CA04
EC11E18244AU	RK08H11100XC	RK10J12E0024	RS15H113C001
EC11E1834403	RK08H1110A04	RK10J12E002L	RS15H113CA05
EC11E183440C	RK08H1120A05	RK10J12E0A0A	RS15H11AA008
EC11EBB24C03	RK08H113003G	RK10J12R0052	RS15H11AA00G
EC11G1560414	RK08H113003Q	RK10J12R0A0B	RS15H11AA04M
EC11G1564411	RK08H12100F3	RK1191110001	RS15H121A009
EC11G1574402	RK08H12100GP	RK1191114001	RS15H12AA009
EC11J0920404	RK08H122005A	RK1191124001	RS15H12AA00F
EC11J0924411	RK08H123002K	RK11K1110A3D	RS201111J011

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

LIST OF PRODUCTS

Part Number	Part Number	Part Number	Part Number
EC11J0925403	RK09711100F8	RK11K1120060	RS20111A9A03
EC11J152040F	RK097111020N	RK11K1120A31	RS20H111C009
EC11J1524413	RK097111080J	RK11K1120A5T	RS20H113C008
EC11J1525402	RK097111080R	RK11K113002F	RS20H11AA015
EC11K0920404	RK0971110909	RK11K1130040	RS20H11AA019
EC11K0924404	RK097111091M	RK11K1130A07	RS20H11AA01U
EC11K0925416	RK0971110D57	RK11K1130A0M	RS20H11AA02T
EC11K1520406	RK0971110D7F	RK11K1130A2X	RS20H11CA00B
EC11K1524406	RK0971110D88	RK11K114001Z	RS20H123A01C
EC11K1525413	RK09711110AL	RK11K114003Y	RS20H12AC002
EC11M1565403	RK09711110EL	RK11K1140A23	RS3011114A02
EC11M1575403	RK0971111Z0P	RK11K1140A2S	RS301111A01G
EC11N1520401	RK0971111Z32	RK11K1140A3L	RS301111C01L
EC11N1520402	RK097111202P	RK11K1140A4Q	RS301111J00P
EC11N1524402	RK097111202Q	RK11K1140A9L	RS301111J00R
EC11N1524403	RK0971114D0B	RK12L1210C0R	RS30111A602N
EC11N1525404	RK0971114Z07	RK12L123000E	RS30111A9012
EC11N1525405	RK097111T064	RK12L1230C0K	RS30111AC00V
EC12D1524403	RK097111T065	RK12L1230C0T	RS30111AJ01K
EC12D1524406	RK097111TD2M	RK12L1230C1M	RS30111AJ01R
EC12D1564402	RK097111TD44	RK12L1270009	RS30112AC00J
EC12D1564404	RK097111TZ17	RK12L12A0C0R	RS30112AJA02
EC12E1220301	RK097111U00S	RK12L12C0A0A	RS30H111A00D
EC12E1220405	RK0971210097	RK12L12C0A0E	RS30H11AA009
EC12E1220406	RK09712100AV	RK12L12C0A0G	RS30H11AA00G
EC12E1220407	RK0971210Z2M	RK12L12C0C0V	RS30H11AA00P
EC12E1220813	RK0971214Z06	RK12L12H0005	RS30H11AAA02
EC12E1240301	RK097121TD57	RK14J11A0007	RS30H11AAA0B
EC12E1240405	RK097122008T	RK14J11A000G	RS30H121A00B
EC12E1240406	RK09712200HA	RK14J11A0A02	RS30H12AA003
EC12E24104A6	RK09712200MC	RK14J11R000H	RS4511119A04
EC12E2420301	RK09712200MT	RK14J11R000J	RS45111A900F
EC12E24204A2	RK09712200MY	RK14J12A0A0K	RS45111ABA02
EC12E24204A7	RK0971221Z05	RK14J12A0A0U	RS451121400A
EC12E24204A8	RK0971221Z11	RK14J12R0A01	RS45112A400G
EC12E24204A9	RK097122200G	RK14J12R0A09	RS60112A600N
EC12E2420801	RK0971224Z01	RK14J12R0A0C	RS60112A600U
EC12E2420802	RK097122T017	RK14K1210A1B	RS6011DP6002
EC12E2420803	RK097122TZ0A	RK14K1220024	RS6011DP6003

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

LIST OF PRODUCTS

Part Number	Part Number	Part Number	Part Number
EC12E2430401	RK097221004C	RK14K1220A0F	RS6011SP6003
EC12E2430404	RK097221005C	RK14K1220A25	RS6011SP6004
EC12E2430803	RK09D1110C0R	RK14K1230A0X	RS6011Y1600Q
EC12E2430804	RK09D113000F	RK14K1230A2X	RS6011Y19004
EC12E2440301	RK09D1130A1L	RK14K1240036	RS6011YA600M
EC12E24404A6	RK09D1130A1N	RK14K1240062	RS60K11A9010
EC12E24404A8	RK09D1130C1B	RK14K1240A4S	RS60K11K9A13
EC12E2460802	RK09D1130C2P	RK14K1240D04	RS60N111900H
EC18AGA20402	RK09D1130C3C	RK14K12A0A3C	RS60N11M9A0E
EC18AGB20401	RK09D1130C3W	RK14K12B0A0E	RS60N11M9A0F
EC20A1820401	RK09D117000B	RK14K12B0A0R	RS60N11S4006
EC20A1824401	RK09D117000C	RK14K12C0A0T	RS60N1219A04
EC21A0920401	RK09K11100E9	RK14K12C0A1S	RSA0K11A901L
EC21A0950402	RK09K1110A0J	RK14K12D0A18	RSA0K11K9A16
EC21A1520401	RK09K1110A2S	RK14K12D0A1X	RSA0K11V901S
EC21A1520407	RK09K1110AH8	RK1631110TBK	RSA0K12A1013
EC21A1540401	RK09K1110AK4	RK1631110TNP	RSA0K12K9A14
EC21C1520402	RK09K1110B1R	RK1631110TT3	RSA0N111900Q
EC28A1520401	RK09K1110B1V	RK1631110TTU	RSA0N11M9A0J
EC28A1550401	RK09K1110B26	RK1631110U0Q	RSA0N11M9A0K
EC28A1560401	RK09K113004U	RK1631110U1Q	RSA0N11S9A0K
EC28A1560501	RK09K1130081	RK16312101A2	RSA0N1219A03
EC28A1850402	RK09K1130A5R	RK1631210AWN	RSA0V11M9001
EC28A1870401	RK09K1130A6S	RK1631210AX9	SKRHAAE010
EC28C1520401	RK09K1130A70	RK16312A0B85	SKRHABE010
EC35A1520402	RK09K1130A8G	RK16312A0BKH	SKRHACE010
EC35A1550502	RK09K1130AAU	RK16312A0BKR	SKRHAE010
EC35AH120401	RK09K1130ACL	RK16812MG099	SLLB120100
EC35AH220403	RK09K1130ACM	RK16812MG09T	SLLB120200
EC35AH220502	RK09K1130AH1	RK16814MGA0K	SLLB120300
EC35AH240403	RK09K1130AJ3	RK203111000V	SLLB510100
EC35AH260502	RK09K1130AP5	RK203111001A	SLLB510200
EC35B154H401	RK09K1130AU2	RK203111001B	SLLB520100
EC35CH120401	RK09K1130AV7	RK271111001T	SLLB520200
EC40A1520403	RK09K1130BM4	RK2711120026	SRBE110301
EC40A1520405	RK09K1130D62	RK27112A00AK	SRBE210200

Alps Sites Affected: Americas

Effective Date: After October 2020

Note: Lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.