

**Dear Customer,**

With this INFINEON Technologies Information Note we would like to inform you about the following

## **Introduction of an additional plating subcon affecting products in packages SOT23 and TSSOP-10**

N° 083/19

## Introduction of an additional plating subcon affecting products in packages SOT23 and TSSOP-10

► **Products affected:**

Please refer to attached affected product list 1\_cip08319

► **Detailed Change Information:**

**Subject:** Introduction of an additional plating subcon affecting products in packages SOT23 and TSSOP-10

**Reason:** To ensure secure supply

**Description:** Old New

	<u>Old</u>	<u>New</u>
<b>Plating subcon:</b>	■ Technic, China	■ Technic, China <b>or</b> Welnew, China

► **Product Identification:**

Traceability assured via internal lot number.

► **Impact of Change:**

Based on the qualification performed, Infineon does not expect any negative impact on quality and reliability.  
No impact on fit, form and function

► **Attachments:**

Affected product list 1\_cip08319

► **Intended start of delivery:**

Mid of August 2020

If you have any questions, please do not hesitate to contact your local Sales office.



Sales Name	SP number	OPN	Package
TDA5103A	SP000305485	TDA5103AHTMA1	PG-TSSOP-10-3
TDA5150	SP000300415	TDA5150HTMA1	PG-TSSOP-10-3
TDA7100	SP000296466	TDA7100HTMA1	PG-TSSOP-10-3
TDA7110F	SP000611108	TDA7110FHTMA1	PG-TSSOP-10-3
TDA7116F	SP000611114	TDA7116FHTMA1	PG-TSSOP-10-3
TDK5100F	SP000014745	TDK5100FHTMA1	PG-TSSOP-10-3
TDK5100F	SP000245723	TDK5100FHTMA2	PG-TSSOP-10-3
TDK5100F	SP000875508	TDK5100FHTMA3	PG-TSSOP-10-3
TDK5101F	SP000014744	TDK5101FHTMA1	PG-TSSOP-10-3
TDK5101F	SP000245724	TDK5101FHTMA2	PG-TSSOP-10-3
TDK5101F	SP000875516	TDK5101FHTMA3	PG-TSSOP-10-3
TDK5110F	SP000056180	TDK5110FHTMA1	PG-TSSOP-10-3
TDK5110F	SP000245725	TDK5110FHTMA2	PG-TSSOP-10-3
TDK5110F	SP000875520	TDK5110FHTMA3	PG-TSSOP-10-3
TDK5111F	SP000056181	TDK5111FHTMA1	PG-TSSOP-10-3
TDK5111F	SP000248477	TDK5111FHTMA2	PG-TSSOP-10-3
TDK5116F	SP000056182	TDK5116FHTMA1	PG-TSSOP-10-3
TLE4961-1M	SP000923322	TLE49611MXTSA1	PG-SOT23-3-15
TLE4961-1M	SP001222068	TLE49611MXTMA1	PG-SOT23-3-15
TLE4961-2M	SP000997954	TLE49612MXTSA1	PG-SOT23-3-15
TLE4961-2M	SP001328230	TLE49612MXTMA1	PG-SOT23-3-15
TLE4961-3M	SP000909960	TLE49613MXTSA1	PG-SOT23-3-15
TLE4961-3M	SP001222072	TLE49613MXTMA1	PG-SOT23-3-15
TLE4961-4M	SP001042410	TLE49614MXTSA1	PG-SOT23-3-15
TLE4961-4M	SP001328234	TLE49614MXTMA1	PG-SOT23-3-15
TLE4961-5M	SP001013854	TLE49615MXTSA1	PG-SOT23-3-15
TLE4961-5M	SP001222078	TLE49615MXTMA1	PG-SOT23-3-15
TLE4963-1M	SP000930182	TLE49631MXTSA1	PG-SOT23-3-15
TLE4963-1M	SP001430474	TLE49631MXTMA1	PG-SOT23-3-15
TLE4963-2M	SP000978614	TLE49632MXTSA1	PG-SOT23-3-15
TLE4963-2M	SP001430440	TLE49632MXTMA1	PG-SOT23-3-15
TLE4964-1M	SP000923326	TLE49641MXTSA1	PG-SOT23-3-15
TLE4964-1M	SP001328238	TLE49641MXTMA1	PG-SOT23-3-15
TLE4964-2M	SP000923330	TLE49642MXTSA1	PG-SOT23-3-15
TLE4964-2M	SP001222084	TLE49642MXTMA1	PG-SOT23-3-15
TLE4964-3M	SP001013860	TLE49643MXTSA1	PG-SOT23-3-15
TLE4964-3M	SP001328242	TLE49643MXTMA1	PG-SOT23-3-15
TLE4964-4M	SP001042414	TLE49644MXTSA1	PG-SOT23-3-15
TLE4964-4M	SP001222088	TLE49644MXTMA1	PG-SOT23-3-15
TLE4964-5M	SP000997958	TLE49645MXTSA1	PG-SOT23-3-15
TLE4964-5M	SP001328246	TLE49645MXTMA1	PG-SOT23-3-15
TLE4964-6M	SP001042418	TLE49646MXTSA1	PG-SOT23-3-15
TLE4964-6M	SP001222092	TLE49646MXTMA1	PG-SOT23-3-15
TLE4965-5M	SP000978610	TLE49655MXTSA1	PG-SOT23-3-15
TLE4965-5M	SP001430478	TLE49655MXTMA1	PG-SOT23-3-15
TLE4968-1M	SP000923334	TLE49681MXTSA1	PG-SOT23-3-15
TLE4968-1M	SP001328250	TLE49681MXTMA1	PG-SOT23-3-15
TLI4961-1M	SP001031008	TLI49611MXTSA1	PG-SOT23-3-15
TLI4961-1M	SP001328254	TLI49611MXTMA1	PG-SOT23-3-15
TLI4963-1M	SP001370094	TLI49631MXTSA1	PG-SOT23-3-15
TLI4963-1M	SP001430482	TLI49631MXTMA1	PG-SOT23-3-15
TLI4963-2M	SP000930186	TLI49632MXTSA1	PG-SOT23-3-15
TLI4963-2M	SP001430486	TLI49632MXTMA1	PG-SOT23-3-15
TLI4965-5M	SP000930190	TLI49655MXTSA1	PG-SOT23-3-15
TLI4965-5M	SP001430490	TLI49655MXTMA1	PG-SOT23-3-15
TLV4961-1M	SP000965272	TLV49611MXTSA1	PG-SOT23-3-15
TLV4961-1M	SP001328258	TLV49611MXTMA1	PG-SOT23-3-15
TLV4961-3M	SP000965276	TLV49613MXTSA1	PG-SOT23-3-15
TLV4961-3M	SP001328262	TLV49613MXTMA1	PG-SOT23-3-15
TLV4964-1M	SP000965280	TLV49641MXTSA1	PG-SOT23-3-15
TLV4964-1M	SP001328266	TLV49641MXTMA1	PG-SOT23-3-15
TLV4964-2M	SP000965284	TLV49642MXTSA1	PG-SOT23-3-15
TLV4964-2M	SP001328270	TLV49642MXTMA1	PG-SOT23-3-15
TX98-3	SP000743718	TX983HTMA1	PG-TSSOP-10-3