



Product Change Notification / GBNG-11YGIP429

Date:

17-Nov-2020

Product Category:

Clock and Timing - Clock Generation, Clock and Timing - Oscillators

PCN Type:

Manufacturing Change

Notification Subject:

CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

Affected CPNs:

[GBNG-11YGIP429_Affected_CPN_11172020.pdf](#)

[GBNG-11YGIP429_Affected_CPN_11172020.csv](#)

Notification Text:

PCN Status: Final notification

PCN Type: Manufacturing Change

Microchip Parts Affected: Please open one of the icons found in the Affected CPNs section above.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

Description of Change: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

Pre Change:

With top mark DCPYYWW at the 2nd line marking.

Post Change:

With top mark DCPYYWW or DAPYYW at the 2nd line marking.

Pre and Post Change Summary:

	Pre Change	Post Change
Top mark	See attached pre and post marking change	

Impacts to Data Sheet: None

Change Impact:None

Reason for Change:

To improve manufacturability and traceability by implementing top marking changes for DSCxxx and DSxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages.

Change Implementation Status:

In Progress

Estimated First Ship Date:

November 19, 2020 (date code: 2047)

NOTE: Please be advised that after the estimated first ship date customers may receive pre and post change parts.

Time Table Summary:

	November 2020				
Workweek	45	46	47	48	49
Final PCN Issue Date			X		
Estimated Implementation Date			X		

Method to Identify Change:

Traceability code, top marking

Qualification Report:

Not applicable

Revision History:

November 17, 2020: Issued final notification. Provided estimated first ship date to be on November 19, 2020.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

Attachments:

PCN_GBNG-11YGIP429_Marking Pre and Post Change.pdf

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

TOP MARK PRE AND POST CHANGE

CCB 3433.001

PCN #: GBNG-11YGIP429



A Leading Provider of Smart, Connected and Secure Embedded Control Solutions



SMART | CONNECTED | SECURE

Pre and Post Change

Pre Change

Line 1	F	F	F	F	F	F	F	F
Line 2		D	C	P	Y	Y	W	W
Line 3	•				0	S	S	S

Post Change

Line 1	F	F	F	F	F	F	F	F
Line 2		D	C	P	Y	Y	W	W
Line 3	•				0	S	S	S

OR

Line 1	F	F	F	F	F	F	F	F
Line 2		D	A	P	Y	Y	W	W
Line 3	•				0	S	S	S

Pre and Post Change Summary

Line	Description	
1	<p>Frequency, 8 digits maximum with NO DECIMAL POINT Printed. Format#1: 7 digits with dot as decimal separator in CPN. Leading Zeroes will be printed. 4 Decimal places will be printed, Example: 0080000 = 8.0000MHz 0333330 = 33.3330MHz 1500000 = 150.0000MHz</p> <p>Format#2: 7 digits for kHz part, With “K” as decimal separator in CPN. Leading Zeroes will be printed. 3 Decimal places will be printed, Example: 032K768 = 32.768kHz</p> <p>Format#3: 8 digits with moving M character in CPN xMxxxxxx (<10MHz) xxMxxxxx (<100MHz) xxxMxxxx (≥100MHz) Example: 156M2500 = 156.2500MHz 27M00000 = 27.00000MHz</p>	
2	DCP	To be changed to Fixed as “DCP” or “DAP”
	YYWW	Manufacturing Year and Workweek (assigned by MRP system)
3	•	Pin one dot
	0SSS	Leading zero+ Lot Serial Number assigned by MRP system

Affected Catalog Part Numbers (CPN)

DSA1101DA2-025.0000TVAO
DSA1101DA2-050.0000TVAO
DSA1121DA2-025.0000TVAO
DSA1121DA2-027.0000TVAO
DSA1121DA2-050.0000TVAO
DSA1121DA2-100.0000TVAO
DSA1121DA2-125.0000TVAO
DSA1101DA3-054.0000TVAO
DSA1101DA3-122.8800TVAO
DSA1101DA3-125.0000TVAO
DSA1121DA3-004.0000TVAO
DSA1121DA3-008.0000TVAO
DSA1121DA3-016.0000TVAO
DSA1121DA3-020.0000TVAO
DSA1121DA3-030.0000TVAO
DSA2311KA1-R0075TVAO
DSA2311KA2-R0002TVAO
DSA2311KA2-R0005TVAO
DSA2311KA2-R0009TVAO
DSA2311KA2-R0011TVAO
DSA2311KA2-R0015TVAO
DSA2311KA2-R0021TVAO
DSA2311KA2-R0065TVAO
DSA2311KA2-R0067TVAO
DSA2311KA2-R0073TVAO
DSA2311KA2-R0076TVAO
DSA2311KA3-R0021TVAO
DSA2311KA3-R0041TVAO
DSA2311KA3-R0073TVAO
DSA2311KA1-R0024TVAO
DSC1001CC1-024.0000
DSC1001CC1-025.0000
DSC1001CC1-040.0000
DSC1001CC1-047.3333
DSC1001CC2-012.5000
DSC1001CC2-024.0000
DSC1001CC2-025.0000
DSC1001CC1-125.0000
DSC1001CC5-008.5920
DSC1001CC2-050.0000
DSC1001CC2-100.0000
DSC1001CC2-125.0000
DSC1001CC5-024.5760
DSC1001CC2-012.2880
DSC1001CC1-008.0000
DSC1001CC2-033.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CC1-027.0000
DSC1001BC1-020.0000
DSC1001BC1-024.0000
DSC1001DC1-004.9152
DSC1101DL5-052.8000T
DSC1123DL5-200.0000T
DSC1123DL1-125.0000T
DSC1101DL1-027.0000T
DSC2311KL1-R0002T
DSC1121DL2-008.0000T
DSC1101DL5-020.0000T
DSC1103DL5-125.0000T
DSC1101DL5-016.0000T
DSC1121DL2-032.0000T
DSC2311KL2-R0040T
DSC2311KL2-R0052T
DSC1121DE1-050.0000T
DSC1101DL2-050.6880T
DSC1103DL2-147.4560T
DSC1123DE2-399.6800T
DSC1123DE2-400.0000T
DSC2311KL1-R0054T
DSC1103DL2-156.2500T
DSC1101DL1-150.0000T
DSC1121DL5-026.0000T
DSC1121DL1-025.0000T
DSC1121DL1-033.0000T
DSC1104DL1-027.0000T
DSC1123DL5-135.0000T
DSC1123DL5-150.0000T
DSC1101DL5-024.5760T
DSC1101DL5-018.4320T
DSC1101DE5-040.0000T
DSC1101DE5-012.2880T
DSC1121DE2-025.0000T
DSC1101DE2-049.1520T
DSC1101DE2-045.1584T
DSC1123DL2-100.0000T
DSC2311KL2-R0002T
DSC1121DL2-072.0000T
DSC1121DL1-040.0000T
DSC1101DL3-PROGT
DSC1101DL5-PROGT
DSC1100DL3-PROGT
DSC1100DL5-PROGT
DSC2311KE2-R0016T
DSC1123DL5-176.5000T
DSC1123DL5-206.5000T
DSC1123DL5-136.5000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103DL1-025.0013T
DSC1103DL2-025.0012T
DSC1123DE1-148.3516T
DSC1101DE2-024.5760T
DSC1101DE2-022.5792T
DSC1101DE2-100.0000T
DSC1121DL5-072.0000T
DSC1121DE5-072.0000T
DSC1103DL2-100.0000T
DSC1124DL2-100.0000T
DSC1103DL2-122.8800T
DSC1103DL2-098.3040T
DSC1101DE2-012.0000T
DSC1104DE5-100.0000T
DSC1104DL3-100.0000T
DSC1124DL5-100.0000T
DSC1124DL1-100.0000T
DSC1103DL5-156.2500T
DSC1123DL2-250.0000T
DSC1121DE1-010.0000T
DSC2311KL2-R0071T
DSC1101DL2-033.3300T
DSC1104DL2-026.0000T
DSC2311KL1-R0072T
DSC1122DL2-220.0000T
DSC1124DL1-027.0000T
DSC1123DL2-050.0000T
DSC1121DE3-150.3330T
DSC1101DL1-020.0000T
DSC1123DE1-125.0000T
DSC1122DL1-072.0000T
DSC1102DL1-212.5000T
DSC2311KE2-R0002T
DSC2311KE2-R0081T
DSC1123DE1-156.2500T
DSC1103DL5-027.0000T
DSC1103DL5-100.0000T
DSC1101DL2-025.0000T
DSC1123DL1-025.0000T
DSC1122DE5-254.6500T
DSC1103DL5-063.5000T
DSC1103DL2-135.0000T
DSC2311KE1-R0085T
DSC1123DL2-156.2500T
DSC1123DL1-156.2500T
DSC2311KL2-R0091T
DSC2311KE2-R0090T
DSC1103DE5-254.6500T
DSC1123DL3-100.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA231TKL1-R0009TVAO

DSA1103DL1-125.0000TVAO

DSA1105DL1-027.0000TVAO

DSC1103CL3-250.0000

DSC1101CE1-080.0000

DSC1103CL1-020.0000

DSC1124CL5-027.0000

DSC1121CE1-030.0000

DSC1121CE2-030.0000

DSC1101CE3-024.0000

DSC1121CE5-025.0000

DSC1121CL5-027.0000

DSC1101CE5-045.1584

DSC1103CE5-135.0000

DSC1103CE1-100.0000

DSC1124CE2-027.0000

DSC1101CL2-026.0000

DSC1124CL5-100.0000

DSC1123CE5-393.2160

DSC1121CE1-124.2000

DSC1121CL2-020.5710

DSC1121CL5-125.0000

DSC1123CL2-026.0000

DSC1121CL2-024.0000

DSC1123CL3-125.0000

DSC1121CL5-003.3000

DSC1123CL3-100.0000

DSC1123CL3-250.0000

DSC1123CL3-093.4400

DSC557-0344FI1

DSC557-0343FI1

DSC2011FI2-E0002

DSC2044FI2-H0006

DSC2222FI1-F0006

DSC2022FI1-F0006

DSC2044FI2-F0022

DSC2211FI1-E0021

DSC2144FI2-F0022

DSC2110FI2-A0008

DSC2110FI2-A0006

DSC2011FI2-F0035

DSC2033FI2-F0003

DSC2011FI1-F0036

DSC2033FI2-F0037

DSC2033FI2-F0038

DSC2033FI2-F0039

DSC2041FI1-F0025

DSC2033FI2-F0040

DSC2144FI2-E0023

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC2123FI2-E0024

DSC2030FI5-B0011

DSC2030FI1-B0019

DSC2011FI2-F0042

DSC2022FI1-H0006

DSC2011FI1-F0043

DSC2122FI2-E0025

DSC2033FI2-F0044

DSC2030FI2-B0020

DSC2033FI1-F0039

DSC2222FI2-E0026

DSC2010FI2-A0018

DSC2010FI2-A0021

DSC2030FI2-C0009

DSC2030FI2-C0010

DSC1123DL3-100.0000

DSA2311KL1-R0009VAO

DSA1103DL1-125.0000VAO

DSA1105DL1-027.0000VAO

DSA1123DL1-100.0000VAO

DSA1124DL1-100.0000VAO

DSA1101DL2-026.0000VAO

DSA1103DL2-156.2500VAO

DSA1121DL2-033.3333VAO

DSA1123DL2-125.0000VAO

DSA1124DL2-024.0000VAO

DSA1124DL2-100.0000VAO

DSA1101DL3-016.0000VAO

DSA1101DL3-020.0000VAO

DSA1101DL3-025.0000VAO

DSA1101DL3-026.0000VAO

DSA1105DL3-033.3330VAO

DSA1123DL3-100.0000VAO

DSA1123DL3-125.0000VAO

DSA2311KL1-R0015VAO

DSA2311KL1-R0065VAO

DSA2311KL2-R0009VAO

DSA2311KL1-R0078VAO

DSA2311KL2-R0015VAO

DSA2311KL2-R0027VAO

DSA2311KL2-R0065VAO

DSA2311KL2-R0073VAO

DSA2311KL2-R0084VAO

DSA2311KL2-R0087VAO

DSC2011FE2-E0004

DSC2011FL1-E0002

DSC2011FL2-F0020

DSC2030FE1-C0001

DSC2031FE1-J0001

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC2033FE2-F0010

DSC2040FE1-D0001

DSC2041FE1-K0003

DSC2044FE1-H0002

DSC2044FE1-H0003

DSC2130FE1-C0003

DSC2010FE1-B0013

DSC2043FE1-F0023

DSC557-0333FL0

DSC2033FL2-F0028

DSC2044FL1-F0022

DSC2044FL1-H0005

DSC2044FE1-F0022

DSC2044FE1-F0024

DSC2041FE1-F0014

DSC557-0333FE0

DSC557-0341FE1

DSC557-0344FE0

DSC557-0344FE1

DSC557-0344FL1

DSC2044FE2-H0006

DSC2030FE5-B0018

DSC2022FE2-F0034

DSC2111FE1-E0022

DSC2033FL1-F0022

DSC2010FL2-B0014

DSC2041FE1-K0002

DSC2033FL2-F0004

DSC2031FL2-F0045

DSC2011FL2-E0005

DSC2110FL1-A0029

DSC2110FL2-C0011

DSC2144FL2-F0022

DSC2033FL2-F0051

DSC2033FL2-E0005

DSC2031FL2-F0052

DSC2210FL2-A0026

DSC2041FL1-F0014

DSC2011FE1-F0057

DSA557-0333FL0VAO

DSA557-0344FL0VAO

DSA557-0344FL1VAO

DSC1101CL2-016.3840T

DSC1101CL5-027.0000T

DSC1103CE1-200.0000T

DSC1103CE2-135.0000T

DSC1101CL2-002.5000T

DSC1103CE2-200.0000T

DSC1103CE5-150.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103CL5-106.2500T
DSC8123CL1T
DSC1121CE1-016.0000T
DSC1121CE1-025.0000T
DSC8123CL5T
DSC1121CE1-025.0012T
DSC1121CE1-075.0000T
DSC1121CE2-025.0000T
DSC1121CE2-100.0000T
DSC1121CL2-025.0000T
DSC1121CL2-050.0000T
DSC1121CL5-024.0000T
DSC1121CL5-048.0000T
DSC1123CE1-156.2500T
DSC1121BM1-060.0000T
DSC1121BM1-016.0000T
DSC1121BM1-026.0000T
DSC1121BM1-012.2880T
DSC1121BM2-131.0720T
DSC1121BM2-020.0000T
DSC1121BM2-025.0000T
DSC1121BM2-032.0000T
DSC1121BM1-032.0000T
DSC1123BM1-287.0000T
DSC1123BM1-166.0000T
DSC1121BM1-014.7456T
DSC1121BM1-005.5296T
DSC1121AM1-025.0000T
DSC1121AM1-030.0000T
DSC1121AM1-050.0000T
DSC1121AM2-010.0000T
DSC1121AM2-027.0000T
DSC1121AM2-125.0000T
DSC1101AM2-014.3950T
DSC1121AM1-010.0000T
DSC1101AM2-030.0000T
DSC1121AM1-020.0000T
DSC1121AM1-027.0000T
DSC1121AM1-012.2880T
DSC1103AM1-287.0000T
DSC1123AM1-287.0000T
DSC1121AM1-032.7680T
DSC1121AM1-014.7456T
DSC1001BI5-018.4320T
DSC1001BI2-029.4912T
DSC1001BI3-033.0000T
DSC1001BI3-050.0000T
DSC1001BI2-001.5440T
DSC1001BI1-033.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001BI1-133.0000T
DSC1003BI5-040.0000T
DSC1001BI2-011.0592T
DSC1001BI5-019.6800T
DSC1001BI1-003.6864T
DSC1004BI5-121.5000T
DSC1001BI2-003.1250T
DSC1001BI5-066.6660T
DSC1004BI5-005.0000T
DSC1001BI1-099.0000T
DSC1001BI2-099.0000T
DSC1001BI5-040.9600T
DSC1001BI2-003.6864T
DSC1001BI3-020.0000T
DSC1001BI2-040.6800T
DSC1001BI2-033.3300T
DSA1001BI2-125.0000TVAO
DSC1001DI1-001.8432T
DSC1001DI1-003.6864T
DSC1001DI1-004.0000T
DSC1001DI1-005.0000T
DSC1001DI1-005.0196T
DSC1001DI1-008.0000T
DSC1001DI1-010.0000T
DSC1001DI1-012.0000T
DSC1001DI1-014.7456T
DSC1001DI1-016.0000T
DSC1001DI1-016.3840T
DSC1001DI1-019.2000T
DSC1001DI1-020.0000T
DSC1001DI1-024.0000T
DSC1001DI1-024.5760T
DSC1001DI1-025.0000T
DSC1001DI1-026.0000T
DSC1001DI1-027.0000T
DSC1001DI1-033.3000T
DSC1001DI1-133.0000T
DSC1001DI1-033.3330T
DSC1001DI1-033.3333T
DSC1001CI5-024.0000
DSC1001CI5-025.0000
DSC1001CI5-026.0000
DSC1001CI5-032.7680
DSC1001CI5-037.1250
DSC1001CI5-040.0000
DSC1001CI5-050.0000
DSC1001CI2-054.0000
DSC1001CI5-100.0000
DSC1003CI1-050.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1003CI5-020.0000
DSC1003CI5-087.5000
DSC1001CI2-125.0000
DSC1001CI5-012.0000
DSC1004CI5-081.0000
DSC1001CI5-008.0000
DSC8001CI1
DSC8001CI2
DSC8001CI5
DSC1001CI5-012.2880
DSC8004CI2
DSC1001CI2-096.0000
DSC1003CI5-025.0000
DSC1001CI5-018.4320
DSC1001CI5-016.0000
DSC1001CI5-024.5760
DSC1001CI5-027.0000
DSC1001CI5-030.0000
DSC1001CI1-003.6864
DSC1001CI2-012.5000
DSC1001CI5-009.6000
DSC1001CI1-100.0000
DSC1001CI2-006.0000
DSC1001CI5-044.0000
DSC1001CI5-019.0000
DSC1001CI5-060.0000
DSC1001CI1-033.0000
DSC1001CI5-011.0592
DSC1001CI2-031.2500
DSC1001CI2-049.1520
DSC1001CI2-032.0000
DSC1001CI5-133.3330
DSC1001CI5-070.4550
DSC1001CI2-008.1920
DSC1001CI2-010.4857
DSC1001CI2-001.9521
DSC8003CI2
DSC1001CI2-007.3728
DSC1001CI2-150.0000
DSC1001CL5-044.0000
DSC1001CL1-016.6400
DSC1003CL2-050.0000
DSC1001CE1-100.0000
DSC1001CE1-110.0000
DSC1001CE1-032.0000
DSC1001CL3-024.0000
DSC1001CL3-072.0000
DSC1001CE2-019.2000
DSC1001CE2-108.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CE3-005.0000
DSC1001CL2-048.0000
DSC1001CL2-090.0000
DSC1001CE2-064.0000
DSC1001CL3-008.0000
DSC1001CL1-012.0000
DSC1001CL2-022.5792
DSC1001CL5-007.3728
DSC1001CL5-028.0000
DSC1004CL2-003.2768
DSC1001CL1-008.0000
DSC1001CL2-026.0000
DSC1001CL5-064.0000
DSC1001CE2-013.5600
DSC1001CE5-032.2123
DSC1001CE1-048.0000
DSC1001CL2-006.0052
DSC1001CL1-040.0000
DSC1003CL1-020.0000
DSC1001CL1-006.0053
DSC1121BM2-032.0000
DSC1121BM1-032.0000
DSC1123BM1-287.0000
DSC1123BM1-166.0000
DSC1121BM1-014.7456
DSC1121BM1-005.5296
DSC1101AM1-160.0000
DSC1101AM2-004.0000
DSC1101AM2-100.0000
DSC1121AM2-004.0000
DSC1121AM2-010.0000
DSC1121AM2-016.0000
DSC1121AM2-024.0000
DSC1121AM2-024.5760
DSC1121AM2-025.0000
DSC1121AM2-027.0000
DSC1121AM2-033.3330
DSC1121AM2-050.0000
DSC1121AM2-066.6660
DSC8121AM2
DSC1121AM2-125.0000
DSC1121AM1-100.0000
DSC1121AM2-008.0000
DSC1101AM2-014.3950
DSC1121AM1-010.0000
DSC1101AM2-030.0000
DSC1121AM1-020.0000
DSC1121AM1-027.0000
DSC1121AM1-012.2880

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103AM1-287.0000
DSC1123AM1-287.0000
DSC1121AM1-032.7680
DSC1121AM1-014.7456
DSC1121AM1-041.5000
DSC1121AM2-041.5000
DSC1121AM1-029.4912
DSC1121AM1-024.5760
DSC1121AM1-033.0000
DSC1101AM2-156.2500
DSC1121AM1-064.0000
DSC1101DM1-033.3330
DSC1101DM2-020.0000
DSC1101DM2-016.0000
DSC1101DM2-025.0000
DSC1101DM2-125.0000
DSC1121DM2-007.3728
DSC1121DM2-125.0000
DSC2311KM1-R0036
DSC2311KM2-R0005
DSC612NI3A-01KV
DSC6003JI2B-001.0000
DSC6003JI2B-003.5700
DSC6102JI2B-100.0000
DSC6001JI3B-008.0000
DSC6001JI3B-024.5760
DSC6101JI3B-075.0000
DSC6331JI1CB-027.0000
DSC6101JI1B-024.0000
DSC6003JI2B-012.0000
DSC6111JI1B-024.0000
DSC6011JI2B-002K000
DSC6011JI2B-032K768
DSC6011JI2B-250K000
DSC6011JI2B-432K000
DSC6011JI2B-720K000
DSC6013JI2B-001.0000
DSC6013JI2B-032K768
DSC6013JI2B-250K000
DSC6013JI2B-432K000
DSC6013JI2B-720K000
DSC6111JI2B-032K768
DSC6111JI2B-250K000
DSC6111JI2B-432K000
DSC6111JI2B-720K000
DSC6112JI2B-001.0000
DSC6112JI2B-032K768
DSC6112JI2B-250K000
DSC6112JI2B-432K000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6112JI2B-720K000
DSC6111JI2B-004K000
DSC6112JI2B-004K000
DSC6011JI1B-012.0000
DSC6011JI3B-025.0000
DSC6101JI2B-025.0000
DSC6102JI2B-025.0000
DSC6102JI2B-027.0000
DSC6013JI1B-032.7680
DSC6013JI1B-008.0000
DSC6111JI1B-025.0000
DSC6111JI2B-024.0000
DSC6001JI3B-439K000
DSC6101JI3B-439K000
DSC6011JI1B-025.0000
DSC6013JI1B-025.0000
DSC6112JI1B-050.0000
DSC6101JI2B-027.0000
DSC6011JI2B-025.0000
DSA6331JA2GB-025.0000VAO
DSA6001JA3B-004.0000VAO
DSA6001JA3B-010.0000VAO
DSA6001JA3B-016.0000VAO
DSA6041JA3B-016.0000VAO
DSC612PA3A-0118
DSC612PA3A-0119
DSC612PA3A-011A
DSC612PA3A-0176
DSC613PA2A-018W
DSC612PA3A-01EQ
DSC612PA3A-010K
DSC612PA1A-01H5
DSA612PA2A-01DMVAO
DSA612PA3A-0130VAO
DSA612PA3A-01DQVAO
DSC612RA3A-010S
DSC613RA2A-0106
DSC612RA3A-0138
DSC612RA1A-0173
DSC612RA1A-0174
DSC612RA3A-0181
DSC613RA3A-018B
DSC612RA3A-01B2
DSC612RA3A-014S
DSC612RA1A-01H5
DSC612RA1A-01JJ
DSC612RA3A-01JW
DSC612RA1A-0102
DSA612RA1A-01KGVVAO

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA612KA2A-01GMVAO

DSA613RA2A-01BGVAO

DSC6001HI2B-012.0000

DSC6001HI2B-024.0000

DSC6003HI2B-012.0000

DSC6001HI3B-032K768

DSC6003HI3B-010.0000

DSC6101HI3B-019.2000

DSC6003HI2B-025.0000

DSC6003HI2B-024.0000

DSC6011HI2B-002K000

DSC6011HI2B-032K768

DSC6011HI2B-250K000

DSC6011HI2B-432K000

DSC6011HI2B-720K000

DSC6013HI2B-001.0000

DSC6013HI2B-002K000

DSC6013HI2B-032K768

DSC6013HI2B-250K000

DSC6013HI2B-432K000

DSC6013HI2B-720K000

DSC6112HI2B-001.0000

DSC6111HI2B-032K768

DSC6111HI2B-250K000

DSC6111HI2B-432K000

DSC6111HI2B-720K000

DSC6112HI2B-032K768

DSC6112HI2B-250K000

DSC6112HI2B-432K000

DSC6112HI2B-720K000

DSC6111HI2B-004K000

DSC6112HI2B-004K000

DSC6001HI2B-048.0000

DSC6003HI3B-027.0000

DSC6111HI3B-010.0000

DSC6013HI2B-003.6864

DSC6021HI3B-016R

DSC6001HI2B-006.0000

DSC6001HI2B-008.0000

DSC6011HI1B-016.0000

DSC6011HI1B-024.0000

DSC6011HI1B-025.0000

DSC6011HI1B-009.6000

DSC6021HI2B-018E

DSC6011HI3B-064.0128

DSC6013HI3B-064.0128

DSC6003HI2B-019.2000

DSC6111HI1B-032K768

DSC6001HI1B-020.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121AI1-064.0000T
DSC1102AI1-050.0000T
DSC1122AI1-159.3750T
DSC1101AI1-025.0000T
DSC1121AI2-150.0000T
DSC1123AI1-150.0000T
DSC1123AI2-062.5000T
DSC1123AI1-120.0000T
DSC1123AI2-156.2570T
DSC1101AI2-080.0000T
DSC1101AI2-040.0000T
DSC1101AI2-064.0000T
DSC1123AI2-027.0000T
DSC1123AI2-050.0000T
DSC1122NI2-150.0000T
DSC1123NI1-100.0000T
DSC1123NI2-125.0000T
DSC1124NI1-100.0000T
DSC1124NI1-156.2500T
DSC1123NI2-312.5000T
DSC1101NI5-025.0000T
DSC1101NI5-020.0000T
DSC400-0101Q0096KE2
DSC400-3331Q0097KE1
DSC400-3331Q0097KE2
DSC400-3331Q0098KE1
DSC400-3331Q0098KE2
DSC400-3333Q0099KE1
DSC400-3333Q0099KE2
DSC400-3133Q0100KE1
DSC400-3133Q0100KE2
DSC400-0103Q0102KE1
DSC400-0103Q0102KE2
DSC400-0401Q0103KE1
DSC400-0401Q0103KE2
DSC400-2222Q0104KE1
DSC400-2222Q0104KE2
DSC400-2222Q0105KE1
DSC400-2222Q0105KE2
DSC400-3333Q0104KE1
DSC400-3333Q0104KE2
DSC400-0202Q0106KE1
DSC400-0202Q0106KE2
DSC400-0202Q0107KE1
DSC400-0202Q0107KE2
DSC400-0202Q0108KE1
DSC400-0202Q0108KE2
DSC400-0202Q0109KE1
DSC400-0202Q0109KE2

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6003MI2B-014.0000T
DSC6003MI2B-026.0000T
DSC6101MI2B-048.0000T
DSC6001MI3B-004.0960T
DSC6111MI2B-027.0000T
DSC6111MI2B-024.5454T
DSC6331MI2CB-008.0000T
DSC6331MI2DB-008.0000T
DSC6331MI2EB-008.0000T
DSC6011MI2B-025.0000T
DSC6011MI2B-056.0000T
DSC6101MI2B-006.1679T
DSC6003MI3B-032K768T
DSC6003MI3B-012.0000T
DSC6003MI2B-027.0000T
DSC6111MI2B-006.1679T
DSC6011MI1B-007.3728T
DSC6102MI2B-125K000T
DSC6101MI2B-008.0000T
DSC6001MI3B-032K768T
DSC6003MI2B-080.0000T
DSC6003MI2B-032K768T
DSC6003MI2B-050.0000T
DSC6111MI2B-025.0000T
DSC6001MI2B-007.3728T
DSC6001MI1B-007.3728T
DSC6011MI2B-007.3728T
DSC6021MI1B-01B1T
DSC6301MI2CB-008.0000T
DSC6001MI1B-032K768T
DSC6001MI2B-032K768T
DSC6001MI2B-027.0000T
DSC6102MI3B-038.4000T
DSC6001MI2B-032.7680T
DSC6111MI3B-033.3333T
DSC6011MI3B-048.0000T
DSC6101MI2B-024.0000T
DSC6101MI1B-050.0000T
DSC6101MI1B-024.0000T
DSC6011MI2B-004.0960T
DSC6311MI2CB-008.0000T
DSC6011MI3B-032.0000T
DSC6001MI1B-080.0000T
DSC6102MI1B-500K000T
DSC6101MI1B-019.2000T
DSC6111MI3B-025.0000T
DSC6011MI2B-024.0000T
DSC6011MI2B-006K144T
DSC6011MI3B-025.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6102MI3B-080.0000T
DSC6101MI1B-027.0000T
DSC6102MI2B-027.0000T
DSC6101MI2B-025.0000T
DSC6112MI2B-025.0000T
DSC6112MI2B-014.7456T
DSC6021MI2B-01K2T
DSC6112MI3B-060.0000T
DSC6121MI2B-01MPT
DSC6122MI2B-01MQT
DSC6101MI1B-020.0000T
DSC6011MI1B-012.2880T
DSA6001MI1B-024.5760TVAO
DSA6001MI2B-032.7680TVAO
DSA6003MI2B-032K768TVAO
DSA6311MI2CB-008.0000TVAO
DSA6003MI3B-032K768TVAO
DSA6102MI3B-038.4000TVAO
DSC612NI3A-010GT
DSC612NI3A-010TT
DSC613NI2A-0106T
DSC613NI3A-0105T
DSC612NI3A-010GB
DSC612NI3A-010TB
DSC400-1111Q0137KI1T
DSC400-1111Q0137KI2T
DSC400-0111Q0138KI1T
DSC400-0111Q0138KI2T
DSC400-0111Q0139KI1T
DSC400-0111Q0139KI2T
DSC400-0144Q0140KI1T
DSC400-0144Q0140KI2T
DSC400-1221Q0141KI1T
DSC400-1221Q0141KI2T
DSC400-0434Q0009KI1T
DSC400-0434Q0009KI2T
DSC400-0313Q0136KI1T
DSC400-0313Q0136KI2T
DSC400-1111Q0142KI1T
DSC400-1111Q0142KI2T
DSC400-1111Q0143KI1T
DSC400-1111Q0143KI2T
DSC400-0333Q0144KI1T
DSC400-0333Q0144KI2T
DSC400-3333Q0145KI1T
DSC400-3333Q0145KI2T
DSC400-3333Q0023KI1T
DSC400-3333Q0023KI2T
DSC400-3333Q0146KI1T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-3333Q0146KI2T
DSC400-1111Q0147KI1T
DSC400-1111Q0147KI2T
DSC400-1111Q0078KI1T
DSC400-1111Q0078KI2T
DSC400-0323Q0009KI1T
DSC400-0323Q0009KI2T
DSC400-1111Q0148KI1T
DSC400-1111Q0148KI2T
DSC400-1313Q0094KI1T
DSC400-1313Q0094KI2T
DSC400-1111Q0149KI1T
DSC400-1111Q0149KI2T
DSC400-1333Q0078KI1T
DSC400-1333Q0078KI2T
DSC400-1111Q0150KI1T
DSC400-1111Q0150KI2T
DSC400-3333Q0151KI1T
DSC400-3333Q0151KI2T
DSC400-4144Q0152KI1T
DSC400-4144Q0152KI2T
DSC1001DC1-025.0000
DSC1001DC1-027.0000
DSC1001DC1-050.0000
DSC1001DC2-004.9152
DSC1001DC2-025.0000
DSC1001DC2-027.0000
DSC1001DC5-012.0000
DSC1001DC5-024.5760
DSC1001DC5-038.8800
DSC1001DC5-040.0000
DSC1004DC1-020.0000
DSC1001DC5-037.4000
DSC1001DC5-012.8000
DSC1001DC1-100.0000
DSC1001AC1-024.0000
DSC1001AC1-033.3333
DSC1001AC1-040.0000
DSC1001AC1-075.0000
DSC1001AC2-027.0000
DSC1001AC2-125.0025
DSC1001AC1-027.0000
DSC1001AC1-008.0000
DSC1001AC1-125.0000
DSC1001CI1-001.0000
DSC1001CI1-008.0000
DSC1001CI1-012.0000
DSC1001CI1-012.2880
DSC1123DI5-100.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1123DI5-125.0000
DSC1123DI5-200.0000
DSC2311KI1-R0009
DSC2311KI2-R0001
DSC2311KI2-R0002
DSC2311KI2-R0005
DSC2311KI2-R0009
DSC2311KI2-R0011
DSC2311KI2-R0029
DSC2311KI2-R0041
DSC8101DI2
DSC8101DI5
DSC8102DI2
DSC8102DI5
DSC8103DI2
DSC8104DI5
DSC8121DI2
DSC8121DI5
DSC8122DI2
DSC8123DI2
DSC8124DI2
DSC1103DI5-125.0060
DSC2311KI2-R0043
DSC8123DI5
DSC1101DI1-025.0000
DSC2311KI1-R0046
DSC1121DI1-026.6000
DSC1122DI2-200.0000
DSC2311KI1-R0051
DSC2311KI2-R0049
DSC1103DI2-148.3500
DSC1103DI5-010.0000
DSC1103DI5-022.0000
DSC1103DI5-032.0000
DSC1121DI5-008.0000
DSC1004DI5-016.0000
DSC1001DI3-040.0000
DSC1004DI1-026.0000
DSC1001DI2-070.0000
DSC1001DI3-060.0000
DSC1001DI5-057.5580
DSC1003DI2-024.0000
DSC1003DI2-033.3333
DSC1001DI1-036.0000
DSC1001DI1-038.0000
DSC1001DI5-030.7200
DSC1001DI3-027.0000
DSC1001DI2-014.3181
DSC1001DI5-040.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DI1-069.1200
DSC1001DI5-032.4000
DSC1001DI5-041.1420
DSC1001DI5-014.7456
DSA1001DI1-005.0000VAO
DSA1001DI1-012.5000VAO
DSC613NI2A-0106B
DSC613NI3A-0105B
DSC613NI1A-016ET
DSC613NI1A-016GT
DSC613NI3A-01A6T
DSC612NI1A-01H3T
DSC612NI2A-01K7T
DSC612NI3A-013CT
DSC612NI3A-01KVT
DSC6003JI2B-001.0000T
DSC6003JI2B-003.5700T
DSC6102JI2B-100.0000T
DSC6001JI3B-008.0000T
DSC6001JI3B-024.5760T
DSC6101JI3B-075.0000T
DSC6331JI1CB-027.0000T
DSC6101JI1B-024.0000T
DSC6003JI2B-012.0000T
DSC6111JI1B-024.0000T
DSC6011JI2B-002K000T
DSC6011JI2B-032K768T
DSC6011JI2B-250K000T
DSC6011JI2B-432K000T
DSA1123DL1-100.0000TVAO
DSA1124DL1-100.0000TVAO
DSA1101DL2-026.0000TVAO
DSA1103DL2-156.2500TVAO
DSA1121DL2-033.3333TVAO
DSA1123DL2-125.0000TVAO
DSA1124DL2-024.0000TVAO
DSA1124DL2-100.0000TVAO
DSA1101DL3-016.0000TVAO
DSA1101DL3-020.0000TVAO
DSA1101DL3-025.0000TVAO
DSA1101DL3-026.0000TVAO
DSA1105DL3-033.3330TVAO
DSA1123DL3-100.0000TVAO
DSA1123DL3-125.0000TVAO
DSA2311KL1-R0015TVAO
DSA2311KL1-R0065TVAO
DSA2311KL2-R0009TVAO
DSA2311KL1-R0078TVAO
DSA2311KL2-R0015TVAO

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA2311KL2-R0027TVAO
DSA2311KL2-R0065TVAO
DSA2311KL2-R0073TVAO
DSA2311KL2-R0084TVAO
DSA2311KL2-R0087TVAO
DSC1001DL5-003.6864T
DSC1001DE2-001.0000T
DSC1001DE2-090.0000T
DSC1004DL5-025.0000T
DSC1001DE2-022.0000T
DSC1001DL5-037.1250T
DSC1001DL5-150.0000T
DSC1001DL2-033.3300T
DSC1001DE5-025.0000T
DSC1001DE1-024.5760T
DSC1001DL5-047.0016T
DSC1001DL1-005.0196T
DSC1001DL2-005.0196T
DSC1001DL5-005.0196T
DSC1001DE3-080.0000T
DSC1001DL1-150.0000T
DSC1001DE3-008.0000T
DSC1001DE5-150.0000T
DSC1003DL1-025.0000T
DSC1003DL1-016.0000T
DSC1003DL1-050.0000T
DSC1003DL1-048.0000T
DSC1003DL2-024.0000T
DSC1004DE1-026.0000T
DSC1001DL1-050.0000T
DSC1001DE5-049.1520T
DSC1001DE5-045.1584T
DSC1001DL1-040.0000T
DSC1001DL5-064.0000T
DSC1004DE2-025.0000T
DSC1001DL5-028.6363T
DSC1001DL5-006.0000T
DSC1001DL1-033.3330T
DSC1001DL5-029.4912T
DSC1001DL1-004.0000T
DSC1001DL2-100.0000T
DSC1001DL5-032.4000T
DSC1001DL5-049.5000T
DSC1001DL2-012.5000T
DSC1001DL1-012.5000T
DSC1001DL3-125.0000T
DSC1001DL5-026.5980T
DSC1001DL5-120.0000T
DSC1001DL5-087.0655T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DL2-049.5000TVAO
DSA1001DL1-008.0000TVAO
DSA1001DL1-010.2400TVAO
DSA1001DL1-016.6666TVAO
DSA1001DL1-020.0000TVAO
DSA1001DL1-024.0000TVAO
DSA1001DL1-024.5760TVAO
DSA1001DL1-024.8000TVAO
DSA1001DL1-024.9000TVAO
DSA1001DL1-025.0000TVAO
DSA1001DL1-025.1000TVAO
DSA1001DL1-033.3330TVAO
DSA1001DL1-048.0000TVAO
DSA1001DL1-054.0000TVAO
DSA1001DL1-060.0000TVAO
DSA1001DL1-074.2500TVAO
DSA1001DL1-100.0000TVAO
DSA1001DL1-125.0000TVAO
DSA1004DL1-100.0000TVAO
DSA1004DL1-125.0000TVAO
DSA1001DL2-006.0053TVAO
DSA1001DL2-007.2000TVAO
DSA1001DL2-008.0000TVAO
DSA1001DL2-010.0000TVAO
DSA1001DL2-016.0000TVAO
DSA1001DL2-020.0000TVAO
DSA1001DL2-024.0000TVAO
DSA1001DL2-024.5640TVAO
DSA1001DL2-024.5760TVAO
DSA1001DL2-025.0000TVAO
DSA1001DL2-026.0000TVAO
DSA1001DL2-027.0000TVAO
DSA1001DL2-028.6364TVAO
DSA1001DL2-030.0000TVAO
DSA1001DL2-033.0000TVAO
DSA1001DL2-033.3333TVAO
DSA1001DL2-036.8640TVAO
DSA1001DL2-037.1250TVAO
DSA1001DL2-040.0000TVAO
DSA1001DL2-048.0000TVAO
DSA1001DL2-049.5000TVAO
DSA1001DL2-050.0000TVAO
DSA1001DL2-054.0000TVAO
DSA1001DL2-066.0000TVAO
DSA1001DL2-072.0000TVAO
DSA1001DL2-080.0000TVAO
DSA1001DL2-087.0655TVAO
DSC1001CI2-088.0000
DSC1001CI2-020.0036

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CI2-020.0057
DSC1001CI1-003.5800
DSC1001CI1-125.0000
DSC1001CI2-029.5000
DSC1001CI5-026.6000
DSC1004CI5-025.0000
DSC1004CI5-026.6000
DSC1001CI5-099.9990
DSC1001CI2-024.9600
DSC1003CI1-025.0000
DSC1001BI1-010.0000
DSC1001BI1-032.0000
DSC1001BI1-048.0000
DSC1001BI1-050.0000
DSC1001BI1-054.0000
DSC1001BI1-060.0000
DSC1001BI1-075.0000
DSC1001BI1-027.0000
DSC1001BI2-005.5296
DSC1001BI2-012.0000
DSC1001BI2-012.2880
DSC1001BI2-016.0000
DSC1001BI2-022.8000
DSC1001BI2-024.0000
DSC1001BI2-025.0000
DSC1001BI2-040.0000
DSC1001BI5-040.0000
DSC1001BI2-033.3330
DSC1001BI2-042.5000
DSC1001BI2-048.0000
DSC1001BI2-050.0000
DSC1001BI2-008.0000
DSC1001BI2-002.0480
DSC1001BI2-100.0000
DSC1001BI2-125.0000
DSC1001BI2-133.0000
DSC1001BI5-010.0000
DSC1001BI2-024.5760
DSC1001BI5-025.0000
DSC1001BI2-007.3728
DSC1001BI2-027.0000
DSC1001BI5-050.0000
DSC1001BI5-100.0000
DSC1001BI5-125.0000
DSC1004BI2-033.0000
DSC1004BI2-100.0000
DSC8001BI2
DSC8001BI5
DSC8004BI2

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001BI1-038.4000
DSC1001BI2-148.5000
DSC1001BI5-008.0000
DSC1001BI5-016.0000
DSC1001BI5-024.0000
DSC1001BI5-032.0000
DSC1001BI1-008.0000
DSC1001BI2-018.4320
DSC1001BI5-020.0000
DSC1001BI5-133.3330
DSC1001BI1-004.0000
DSC1001BI2-030.0000
DSC1001BI2-016.3840
DSC1001BI1-012.2880
DSC1001BI1-022.1184
DSC1001BI1-024.0000
DSC1001BI1-024.5760
DSC1001BI1-025.0000
DSC1001BI1-040.0000
DSC1001BI1-125.0000
DSC1001BI2-014.7456
DSC1001BI2-020.0000
DSC1001BI2-014.3181
DSC1001BI1-020.0000
DSC1001BI5-090.0000
DSC1004BI2-010.0000
DSC1001BI1-066.6666
DSC1001BI2-133.3330
DSC8003BI2
DSC1001BI2-012.5000
DSC1001BI5-013.5600
DSC1001BI1-100.0000
DSC1001BI1-012.0000
DSC1001BI2-033.0000
DSC1001BI2-006.0000
DSC1001BI2-026.0000
DSC1001BI5-084.0000
DSC1001BI1-033.3330
DSC1001BI2-012.2888
DSC1001BI2-004.0000
DSC1003BI2-025.0000
DSC1001BI2-010.0000
DSC1001BI2-013.0810
DSC1003BI1-008.0000
DSC1001BI2-054.0000
DSC1001BI5-014.7456
DSC1001BI2-028.6363
DSC1001BI5-033.0000
DSC1001BI2-016.9344

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1004BI5-016.0000
DSC1001BI5-027.0000
DSC1001BI1-080.0000
DSC1001BI1-019.6608
DSC1001BI5-028.6363
DSC1001BI5-001.6000
DSC1003BI5-001.7000
DSC1001BI1-001.8432
DSC1001BI5-125.0031
DSC1001BI1-011.0592
DSC1001BI5-080.0000
DSC1003BI5-001.6500
DSC1003BI1-100.0000
DSC1001BI1-026.0000
DSC1001BI3-024.0000
DSC1001BI3-012.0000
DSC1001BI5-018.4320
DSC1001BI2-029.4912
DSC1001BI3-033.0000
DSC1001BI3-050.0000
DSC1001BI2-001.5440
DSC1001BI1-033.0000
DSC1001BI1-133.0000
DSC1003BI5-040.0000
DSC1001BI2-011.0592
DSC1001BI5-019.6800
DSC1001BI1-003.6864
DSC1001BI2-004.0000T
DSC1003BI2-025.0000T
DSC1001BI2-010.0000T
DSC1001BI2-013.0810T
DSC1003BI1-008.0000T
DSC1001BI2-054.0000T
DSC1001BI5-014.7456T
DSC1001BI2-028.6363T
DSC1001BI5-033.0000T
DSC1001BI2-016.9344T
DSC1004BI5-016.0000T
DSC1001BI5-027.0000T
DSC1001BI1-080.0000T
DSC1001BI1-019.6608T
DSC1001BI5-028.6363T
DSC1001BI5-001.6000T
DSC1003BI5-001.7000T
DSC1001BI1-001.8432T
DSC1001BI5-125.0031T
DSC1001BI1-011.0592T
DSC1001BI5-080.0000T
DSC1003BI5-001.6500T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1003BI1-100.0000T
DSC1001BI1-026.0000T
DSC1001BI3-024.0000T
DSC1001BI3-012.0000T
DSC1003AI2-025.0000
DSC1001AI1-050.0000
DSC1001AI2-010.0000
DSC1001AI2-027.0000
DSC1001AI2-011.7000
DSC1001AI2-012.3667
DSC1001AI5-040.0000
DSC1001AI5-024.0000
DSC1001AI1-033.0000
DSC1001AI2-040.0000
DSC1001AI1-049.1520
DSC1001AI5-012.2880
DSC1001AI1-016.0000
DSC1004AI5-099.7200
DSC1001AI1-001.0000
DSC1001AI5-066.0000
DSC1001AI1-066.0000
DSC1001AI1-020.0000
DSC1001AI1-013.1072
DSC1001AI1-024.5760
DSC1001AI1-030.0000
DSC1001AI5-050.0000
DSC1001AI1-008.0000
DSC1001AI1-032.7680
DSC1001AI2-002.0480
DSC1001AI1-033.3333
DSC1001AI2-065.5360
DSC1001AI2-032.7680
DSC1001AI1-003.5700
DSC1003AI2-075.0000
DSC1001AI5-028.6363
DSC1001AI2-075.0000
DSC1004AI1-012.0000
DSC1004AI1-004.9152
DSC1004AI1-007.3728
DSC1001AI2-150.0000
DSC1001AI1-007.3728
DSC1001AI1-004.9152
DSC1001AI1-012.0000
DSC1003AI3-100.0000
DSC1001AI2-033.3330
DSC1001AI5-016.3840
DSC1001AI5-010.0000
DSC1001AI5-106.2500
DSC1003AI5-003.6864

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1003AI5-012.0000
DSC1001AI1-014.3182
DSC1001AI3-025.0000
DSC1001AI3-030.0000
DSC1001AI1-033.3330
DSC1001AI1-024.5450
DSC1001AI5-001.7000
DSC1001AI5-014.7456
DSC1001AI2-029.4912
DSC1001AI3-100.0000
DSC1001AI1-075.0000
DSC1001AI2-129.6000
DSC1001AI3-040.0000
DSC1001AI2-066.6666
DSC1001AI1-029.4912
DSC1001AI5-002.0480
DSC1001AI1-026.0000
DSC1001AI1-016.3840
DSC1001AI1-032.0000
DSC1001AI5-003.6864
DSC1001CE1-004.0000
DSC1001CE1-012.2880
DSC1001CE1-012.0000
DSC1001CE1-014.3182
DSC1001CE1-019.6608
DSC1001CE1-024.0000
DSC1001CE1-024.5760
DSC1001CE1-025.0000
DSC1001CE1-033.8688
DSC1001CE1-037.1250
DSC1001CE1-060.0000
DSC1001CE1-064.8000
DSC1001CE1-069.2480
DSC8003CL5
DSC1001CE2-001.8432
DSC1001CE2-006.0000
DSC1001CE2-010.0000
DSC1001CE2-020.0000
DSC1001CE2-024.0000
DSC1001CE2-024.5760
DSC1001CE2-025.0000
DSC1001CE2-027.0000
DSC1001CE2-034.0000
DSC1001CE2-040.0000
DSC1001CE2-048.0000
DSC1001CE2-050.0000
DSC1001CL1-001.8432
DSC1001CL1-016.0000
DSC1001CL1-020.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CL1-025.0000
DSC1001CL1-030.0000
DSC1001CL1-032.0000
DSC1001CE2-100.0000
DSC1001CL1-066.0000
DSC2044FI2-H0004
DSC2110FI1-A0005
DSC2122FI1-F0006
DSC2130FI2-C0005
DSC2042FI1-M0005
DSC2133FI2-E0020
DSC2230FI2-C0006
DSC2233FI2-F0018
DSC2044FI1-H0001
DSC2033FI1-F0028
DSC2010FI2-B0014
DSC2011FI1-E0012
DSC2210FI2-A0006
DSC2210FI2-A0028
DSC2211FI2-E0018
DSC2033FI2-K0003
DSC2033FI2-F0030
DSC2033FI2-F0031
DSC2042FI1-F0014
DSC2033FI2-F0032
DSC2011FI1-F0033
DSC2233FI2-G0002
DSC2010FI2-B0015
DSC2133FI2-G0001
DSC2033FI1-F0025
DSC2033FI1-F0026
DSC2120FI1-A0027
DSC2030FI2-C0002
DSC2033FI2-F0022
DSC2033FI1-F0022
DSC557-0334FI1
DSC557-0343FI0
DSC557-0344FI0
DSC6001JI2B-025.0000
DSC6001JI2B-027.0000
DSC6001JI1B-025.0000
DSC6011JI1B-008.0000
DSC6111JI1B-098.3040
DSC6011JI3B-001.0640
DSC6111JI2B-100K000
DSC6111JI3B-100.0000
DSC6001JI3B-004K000
DSC6011JI3B-032K768
DSC6013JI1B-768K000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6001JI1B-460K800
DSC6331JI2BB-025.0000
DSC6331JI2IB-025.0000
DSC6001JI2B-001.8432
DSC6011JI2B-012.0000
DSC6101JI2B-100.0000
DSC6101JI2B-024.0000
DSC6003JI2B-025.0000
DSC6011JI1B-050.0000
DSC6331JI2EB-025.0000
DSC6001JI2B-116K000
DSC6101JI2B-050.0000
DSC6001JI2B-068.1818
DSC6331JI2BB-024.0000
DSC6013JI1B-012.0000
DSC6001JI1B-012.0000
DSC6001JI2B-032K000
DSC6101JI3B-100.0000
DSC6001JI3B-024.0000
DSC6003JI2B-032K768
DSC6023JI3B-019H
DSC6011JI1B-014.7456
DSC6003JI2B-004.5160
DSC6003JI2B-008.0000
DSC6003JI2B-027.0950
DSC6003JI2B-063.2220
DSC6011JI2B-016.0000
DSC6013JI1B-032K768
DSC6001JI3B-014.1875
DSC6101JI3B-485K000
DSC6013JI3B-032.0000
DSC6101JI2B-020.0000
DSC6001JI2B-024.0000
DSC6003JI2B-024.0000
DSC6013JI1B-300K000
DSC6111JI3B-012.0000
DSC6101JI1B-007K085
DSC6121JI2B-01BB
DSC6001JI1B-032K768
DSC6102JI3B-001.6800
DSC6003JI2B-307K000
DSC6331JI2KB-025.0000
DSC6001JI2B-032K768
DSC6001JI2B-012.2880
DSC6011JI3B-048K500
DSC6331JI1DB-025.0000
DSC6001JI1B-010.0000
DSC6011JI1B-001.0000
DSC6001JI3B-025.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6101JI2B-040K000
DSC6331JI2CB-027.0000
DSC6331JI2CB-024.0000
DSC6101JI2B-012.2880
DSC6331JI2FB-025.0000
DSC6111JI1B-200K000
DSC6001JI2B-022.5792
DSC6311JI1DB-036.0000
DSC6311JI1DB-075.0000
DSC6311JI1DB-100.0000
DSC6102JI1B-060.0000
DSC6101JI2B-019.2000
DSA1001DI1-019.2000VAO
DSA1001DI1-020.0000VAO
DSA1001DI1-024.5760VAO
DSA1001DI1-025.0000VAO
DSA1001DI1-033.0000VAO
DSA1001DI1-050.0000VAO
DSA1003DI1-050.0000VAO
DSA1001DI2-012.2880VAO
DSA1001DI2-019.2000VAO
DSA1001DI2-025.0000VAO
DSA1001DI2-026.0000VAO
DSA1001DI2-027.0000VAO
DSA1001DI2-033.3333VAO
DSA1001DI2-125.0000VAO
DSA1001DI3-012.0000VAO
DSA1001DI3-020.0000VAO
DSA1001DI3-024.0000VAO
DSA1001DI3-027.0000VAO
DSA1001DI3-050.0000VAO
DSA1001DI3-150.0000VAO
DSC1001AI1-005.0000
DSC1001AI1-012.2880
DSC1001AI2-006.0000
DSC1001AI2-012.0000
DSC1001AI1-025.0000
DSC1001AI2-014.7456
DSC1001AI2-024.0000
DSC1001AI2-025.0000
DSC1001AI2-008.0000
DSC1001AI2-033.3333
DSC1001AI2-048.0000
DSC1001AI2-050.0000
DSC1001AI2-054.0000
DSC1001AI2-080.0000
DSC1001AI2-083.3330
DSC1001AI2-100.0000
DSC1001AI2-125.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001AI2-016.0000
DSC1001AI5-002.4576
DSC1001AI2-025.0007
DSC1001AI2-026.0000
DSC1001AI2-032.0000
DSC1001AI2-014.3180
DSC1001AI5-025.0000
DSC1001AI5-072.0000
DSC1001AI5-144.0000
DSC1001AI5-150.0000
DSC8001AI1
DSC8001AI2
DSC8001AI5
DSC1001AI2-120.0000
DSC1001AI5-008.0000
DSC1001AI5-011.0592
DSC1001AI5-012.0000
DSC1001AI5-016.0000
DSC1001AI5-027.0000
DSC1001AI5-029.4912
DSC1001AI5-033.3330
DSC1001AI5-048.0000
DSC1001AI5-080.0000
DSC1001AI5-100.0000
DSC1001AI5-125.0000
DSC1001AI5-125.0060
DSC1001AI2-066.6600
DSC1001AI2-066.6670
DSC1001AI1-055.3330
DSC1001AI5-032.0000
DSC1001AI2-096.0000
DSC1001AI5-033.0000
DSC1001AI2-001.0000
DSC1001AI2-064.0000
DSC1004AI2-001.0000
DSC8003AI2
DSC1001AI5-070.6760
DSC1122CI5-100.0000T
DSC1102CI5-156.2500T
DSC1124CI5-133.0000T
DSC1124CI5-133.3300T
DSC1104CI2-316.0000T
DSC1103CI5-125.0000T
DSC1101CI1-008.0000T
DSC1101CI1-010.0000T
DSC1123CI2-035.0000T
DSC1101CI5-125.0000T
DSC1122CI5-050.0000T
DSC1121CI2-155.5200T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1122CI2-212.5000T
DSC1123CI2-060.0000T
DSC1123CI2-175.0000T
DSC1103CI5-045.0000T
DSC1123CI1-050.0000T
DSC1123CI5-096.0000T
DSC1123CI2-086.0000T
DSC1101CI5-100.0000T
DSC1124CI1-027.0000T
DSC1104CI1-027.0000T
DSC1123CI2-050.0000T
DSC1101CI5-027.0000T
DSC1103CI5-180.0000T
DSC1121CI2-008.0000T
DSC1101CI5-026.0000T
DSC1103CI5-156.2500T
DSC1103CI5-016.0000T
DSC1103CI2-106.2500T
DSC1103CI2-074.2500T
DSC1103CI2-050.0000T
DSC1102CI1-135.0000T
DSC1123CI5-233.2090T
DSC1104CI2-027.0000T
DSC1123CI5-150.0000T
DSC1123CI2-270.0000T
DSC1123CI3-148.5000T
DSC1122CI5-433.9200T
DSC1103CI5-150.0000T
DSC1123CI2-322.2650T
DSC1123CI2-266.5000T
DSC1121CI5-026.0000T
DSC1103CI3-200.0000T
DSC1103CI3-125.0000T
DSC1103CI5-250.0000T
DSC1103CI2-250.0000T
DSC1103CI2-300.0000T
DSC1124CI2-027.0000T
DSC1101CI1-012.0000T
DSC1102CI2-400.0000T
DSC1101CI2-133.0000T
DSC1101CI5-032.0000T
DSC1101CI2-032.0000T
DSC1104CI2-100.0000T
DSC1121CI2-080.0000T
DSC1124CI1-100.0000T
DSC1101CI1-050.0000T
DSC1101CI2-066.6667T
DSC1101CI2-125.0000T
DSC1123CI2-266.5250T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1101CI1-018.7500T
DSC1103CI2-052.0000T
DSC1103CI5-075.0300T
DSC1103CI5-033.3330T
DSC1103CI2-024.0000T
DSC1103CI2-025.0000T
DSC1123CI2-125.0987T
DSC1101CI5-048.0000T
DSC1102CI2-148.5000T
DSC1101CI5-072.0000T
DSC1123CI2-160.0000T
DSC1103CI1-026.0000T
DSC1103CI1-027.0000T
DSC1123CI2-180.0000T
DSC1123CI2-265.5250T
DSC1123CI2-144.0000T
DSC1123CI2-072.0000T
DSC1102CI2-156.2500T
DSC1103CI5-026.0000T
DSC1103CI5-027.0000T
DSC1101CI1-085.2070T
DSC1101CI5-024.0000T
DSC1101CI2-020.0000T
DSC1103CI5-103.1250T
DSC1103CI2-103.1250T
DSC1103CI3-100.0000T
DSC1103CI3-250.0000T
DSC1104CI3-027.0000T
DSC1102CI1-108.0000T
DSC1121CI2-045.1580T
DSC1121CI2-049.1520T
DSC1121CI2-045.1584T
DSC1121CI2-014.3181T
DSC1121CI5-045.1584T
DSC400-3331Q0153KI1T
DSC400-3331Q0153KI2T
DSC400-2222Q0031KI1T
DSC400-2222Q0031KI2T
DSC400-0333Q0154KI1T
DSC400-0333Q0154KI2T
DSC400-0111Q0155KI1T
DSC400-0111Q0155KI2T
DSC400-3133Q0156KI1T
DSC400-3133Q0156KI2T
DSC400-0133Q0157KI1T
DSC400-0133Q0157KI2T
DSC400-3113Q0158KI1T
DSC400-3113Q0158KI2T
DSC400-3113Q0159KI1T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-3113Q0159KI2T
DSC400-1111Q0160KI1T
DSC400-1111Q0160KI2T
DSC400-0333Q0162KI1T
DSC400-0333Q0162KI2T
DSC400-3333Q0163KI1T
DSC400-3333Q0163KI2T
DSA400-1111Q0004KI1TVAO
DSA400-1111Q0004KI2TVAO
DSA400-1111Q0085KI1TVAO
DSA400-1111Q0085KI2TVAO
DSA400-1111Q0161KI1TVAO
DSA400-1111Q0161KI2TVAO
DSA400-4134Q0152KI1TVAO
DSA400-4134Q0152KI2TVAO
DSA557-04444KI1TVAO
DSA557-054444KI1TVAO
DSC1101BM2-PROG
DSC1101DM2-PROG
DSA1101DA1-004.0000VAO
DSA1101DA1-007.3700VAO
DSA1101DA1-008.0000VAO
DSA1101DA1-016.0000VAO
DSA1101DA1-025.0000VAO
DSA1101DA1-026.9973VAO
DSA1101DA1-033.3330VAO
DSA1101DA1-040.0000VAO
DSA1121DA1-100.0000VAO
DSA1123DA1-100.0000VAO
DSA1125DA1-027.0000VAO
DSA1125DA1-033.3333VAO
DSA1101DA2-020.0000VAO
DSA1101DA2-025.0000VAO
DSA1101DA2-050.0000VAO
DSA1121DA2-025.0000VAO
DSA1121DA2-027.0000VAO
DSA1121DA2-050.0000VAO
DSA1121DA2-100.0000VAO
DSA1121DA2-125.0000VAO
DSA1101DA3-054.0000VAO
DSA1101DA3-122.8800VAO
DSA1101DA3-125.0000VAO
DSA1121DA3-004.0000VAO
DSA1121DA3-008.0000VAO
DSA1121DA3-016.0000VAO
DSA1121DA3-020.0000VAO
DSA1121DA3-030.0000VAO
DSA2311KA1-R0075VAO
DSA2311KA2-R0002VAO

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA2311KA2-R0005VAO
DSA2311KA2-R0009VAO
DSA2311KA2-R0011VAO
DSA2311KA2-R0015VAO
DSA2311KA2-R0021VAO
DSA2311KA2-R0065VAO
DSA2311KA2-R0067VAO
DSA2311KA2-R0073VAO
DSA2311KA2-R0076VAO
DSA2311KA3-R0021VAO
DSA2311KA3-R0041VAO
DSA2311KA3-R0073VAO
DSA2311KA1-R0024VAO
DSA1105DA1-022.5792VAO
DSC1101CM1-008.0000
DSC1101CM1-025.0000
DSC1101CM2-020.0000
DSC1101CM2-062.2080
DSC1121CM1-016.0000
DSC1121CM1-024.0000
DSC1121CM1-025.0000
DSC1121CM1-026.5625
DSC1121CM1-027.0000
DSC1121CM1-075.0000
DSC1121CM1-050.0000
DSC1121CM2-033.3333
DSC1121CM2-024.5454
DSC8121CM2
DSC1121CM2-027.0000
DSC1121CM2-062.2080
DSC1101CM1-075.0000
DSC1101CM1-005.0000
DSC1101CM1-033.3333
DSC1121CM2-040.0000
DSC1101CM2-008.0000
DSC1121CM2-006.7800
DSC1121CM1-012.0000
DSC1121CM1-012.2880
DSC8101CM2
DSC8121CM1
DSC1121CM1-040.0000
DSC1101CM2-012.0000
DSC1101CM2-048.0000
DSC1121CM1-066.6660
DSC1121CM1-100.0000
DSC1121CM1-036.0000
DSC1121CM1-018.0000
DSC1101CM1-040.0000
DSC1121CM2-008.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121CM2-025.0000
DSC1121CM1-030.0000
DSC1101CM3-024.0000
DSC1121CM1-014.7456
DSC1101CM1-032.0000
DSC1121CM1-032.0000
DSC1123CM1-375.0000
DSC1121CM2-003.1152
DSC1121CM1-003.1152
DSC1121CM1-005.5296
DSC1121CM2-024.0000
DSC1101BM2-025.0000
DSC1101BM2-100.0000
DSC1121BM1-008.0000
DSC1121BM1-025.0000
DSC1121BM1-030.0000
DSC1121BM1-048.0000
DSC1121BM1-100.0000
DSC1121BM2-007.3728
DSC8121BM2
DSC1101BM2-074.2500
DSC1121BM1-010.0000
DSC1121BM1-024.0000
DSC1101BM2-027.0000
DSC1121BM1-050.0000
DSC1121BM2-016.0000
DSC1121BM2-030.0000
DSC1101BM2-050.0000
DSC1101BM2-054.0000
DSC1121BM1-024.5760
DSC1121BM1-060.0000
DSC1121BM1-016.0000
DSC1121BM1-026.0000
DSC1121BM1-012.2880
DSC1121BM2-131.0720
DSC1121BM2-020.0000
DSC1121BM2-025.0000
DSA1001DL3-080.0000TVAO
DSA1001DL3-100.0000TVAO
DSA1001DL3-125.0000TVAO
DSA1001DL1-027.0000TVAO
DSA1001DL1-033.0000TVAO
DSC1001AE1-050.0000T
DSC1001AE1-016.6667T
DSC1001AE1-025.0000T
DSC1001AE1-033.3333T
DSC1001AE1-048.0000T
DSC1001AE1-125.0000T
DSC1001AE2-125.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001AE5-098.3040T
DSC1001AL5-007.3728T
DSC1001AL5-001.8432T
DSC1001AL5-004.0000T
DSC1001AL5-008.0000T
DSC1001AL5-012.0000T
DSC1001AL5-016.0000T
DSC1001AL5-016.3840T
DSC1001AL5-018.4320T
DSC1001AL5-080.0000T
DSC1001AL5-100.0000T
DSC1001AL5-032.0000T
DSC1001AL5-040.0000T
DSC1001AL5-050.0000T
DSC1001AL5-060.0000T
DSC8001AL5T
DSC1001AL5-125.0000T
DSC1003AE1-050.0000T
DSC1001AE1-066.6660T
DSC1004AL1-001.0000T
DSC1004AL2-001.0000T
DSC1001AE1-019.6608T
DSC1001AE1-024.0000T
DSC1001AE2-002.0480T
DSC1001AL5-024.0000T
DSC1001AE5-024.5760T
DSC1001AE1-027.0000T
DSC1001AL5-033.0000T
DSC1001AL5-025.0000T
DSC1001AE1-006.1440T
DSC1001AE1-111.0000T
DSC1001AL5-027.0000T
DSC1001AE1-014.3182T
DSC1001AE1-024.5761T
DSC1001AE1-003.6864T
DSC1001AE1-054.0000T
DSC1001AE5-040.0000T
DSC1121CL2-025.0000
DSC1121CL2-050.0000
DSC1121CL5-050.0000
DSC1122CE1-125.0000
DSC1123CE1-050.0000
DSC1123CE1-156.2500
DSC1123CE2-062.0000
DSC1123CE2-148.3516
DSC1123CE2-148.5000
DSC1123CE5-100.0000
DSC1123CE5-150.0000
DSC1123CE5-156.2500

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1123CL1-150.0000
DSC1123CL2-125.0000
DSC1123CL5-100.0000
DSC1124CE1-156.2500
DSC8101CL5
DSC8121CL5
DSC1124CL2-200.0000
DSC1101CL5-100.0000
DSC1103CE1-125.0000
DSC1123CE1-125.0000
DSC1101CL5-014.7456
DSC1121CE1-133.3333
DSC1103CE1-156.2500
DSC1124CE1-010.2400
DSC1121CE5-050.0000
DSC1121CL2-040.0000
DSC1124CL2-100.0000
DSC1101CL2-024.7500
DSC1101CL3-PROG
DSC1101CL5-PROG
DSC1101CE2-100.0000
DSC1123CL1-400.0000
DSC1123CL1-025.0000
DSC1103CE5-100.0000
DSC1103CL5-100.0000
DSC1123CL5-050.0000
DSC1123CL5-025.0000
DSC1103CE5-045.0000
DSC1121CE1-125.0000
DSC1123CE2-250.0000
DSC1123CE2-312.5000
DSC1103CE1-266.7000
DSC1103CE1-233.3000
DSC1123CE1-150.0000
DSC1124CE1-100.0000
DSC1121CL5-150.0000
DSC1124CL1-100.0000
DSC1122CL2-156.2500
DSC1121CE1-033.3333
DSC1121CE5-033.3333
DSC1101CE5-010.0000
DSC1121AM1-041.5000T
DSC1121AM2-041.5000T
DSC1121AM1-029.4912T
DSC1121AM1-024.5760T
DSC1121AM1-033.0000T
DSC1101AM2-156.2500T
DSC1121AM1-064.0000T
DSC1101DM1-033.3330T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1101DM2-020.0000T
DSC1101DM2-016.0000T
DSC1101DM2-056.2500T
DSC1101DM2-125.0000T
DSC1121DM2-003.3333T
DSC1121DM2-007.3728T
DSC1121DM2-125.0000T
DSC2311KM2-R0005T
DSC2311KM2-R0040T
DSC1101DM2-004.0000T
DSC2311KM2-R0002T
DSC2311KM2-R0050T
DSC1101DM1-012.0000T
DSC1101DM2-012.0000T
DSC1101DM1-033.3333T
DSC1101DM2-033.3333T
DSC1121DM1-033.3333T
DSC1101DM2-008.0000T
DSC1101DM2-024.0000T
DSC1121DM1-030.0000T
DSC1101DM1-080.0000T
DSC1121DM2-025.0000T
DSC1121DM2-033.0000T
DSC1001CL3-025.0000
DSC1001CL2-006.0053
DSC1001CE2-033.3333
DSC1001CL3-040.0000
DSC1004CL2-030.0000
DSA1001CL2-033.3300VAO
DSA1001CL2-033.3333VAO
DSA1001CL2-125.0000VAO
DSA1001CL3-080.0000VAO
DSA1001CL3-133.3330VAO
DSC1001BE1-025.0000
DSC1001BE1-040.0000
DSC1001BE1-048.0000
DSC1001BE1-024.0000
DSC1001BE1-125.0000
DSC1001BE2-024.0000
DSC1001BE2-025.0000
DSC1001BE2-027.0000
DSC1001BE2-033.3330
DSC1001BE2-050.0000
DSC1001BE2-100.0000
DSC1001BL1-002.1760
DSC1001BL2-050.0000
DSC1001BL5-010.0000
DSC1001BL5-100.0000
DSC8001BL2

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC800IBL5

DSC1001BL5-025.0000
DSC1001BL2-025.0000
DSC1001BL5-050.0000
DSC1001BL5-016.0000
DSC1001BL5-080.0000
DSC1001BE1-050.0000
DSC1001BE5-022.5792
DSC1001BE2-001.6000
DSC1001BE1-012.0000
DSC1001BE2-010.0000
DSC1001BL5-095.0000
DSC1001BL1-016.0000
DSC1001BE5-064.0000
DSC1001BL5-064.0000
DSC1001BL2-020.0000
DSC1003AE5-100.0000T
DSC1001AL5-066.0000T
DSC1001AE1-018.1059T
DSC1001AL5-030.0000T
DSC1001AE1-049.1520T
DSC1001AL1-001.0000T
DSC1001AL1-048.0000T
DSC1001AL5-016.7772T
DSC1001AE2-148.5000T
DSC1001AE2-048.0000T
DSC1001AE5-022.5792T
DSC1003AL5-025.0000T
DSC1001AE1-001.4850T
DSC1001AL2-016.0000T
DSC1001AE2-080.0000T
DSC1001AL1-020.0000T
DSC1001AE1-004.0000T
DSC1001AE1-099.0000T
DSC1001AE1-098.0000T
DSC1001AL2-025.0000T
DSC1001AE5-004.0000T
DSC1001AE5-020.0000T
DSC1001AE5-125.0000T
DSC1001AE5-012.0000T
DSC1003AE1-022.1184T
DSC1001AE1-010.0000T
DSC1003AE5-025.0000T
DSC1001AL5-001.0000T
DSC1001AE2-050.0000T
DSC1001AE2-054.0000T
DSC1001AE5-029.1621T
DSC1001AE5-031.6440T
DSC1001AL5-011.0592T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001AL1-050.0000T
DSC1001AL5-010.0000T
DSC1000AL3-PROGT
DSC1000AL5-PROGT
DSC1004AE2-024.0000T
DSC1001AL5-133.3330T
DSC1001AL2-020.0000T
DSC1001AL2-060.0000T
DSC1001AE3-013.5600T
DSC1001AE1-064.0000T
DSC1001AE1-040.0000T
DSC1003AE3-007.3728T
DSC1001AL5-014.7456T
DSC1001AE5-017.1776T
DSC1001AE5-001.2000T
DSC1001AL2-029.4912T
DSC1001AL2-050.0000T
DSC1003AL2-005.0000T
DSC1001AE1-003.5700T
DSC1001AL5-033.3330T
DSC1001AL2-024.0000T
DSC1001AL2-125.0000T
DSC1001AL1-025.0000T
DSC1001AL1-027.0000T
DSC1001AL2-100.0000T
DSC1001AL5-029.4912T
DSC1001CC1-010.0000T
DSC1001CC1-047.3333T
DSC1001CC1-076.0686T
DSC1001CC1-125.0000T
DSC1001CC5-008.5920T
DSC1001CC2-025.0000T
DSC1001CC5-004.1943T
DSC1001CC5-024.5760T
DSC1001CI1-132.0000T
DSC1001CC2-012.2880T
DSC1001CC1-008.0000T
DSC1001CC2-033.0000T
DSC1001CC2-024.0000T
DSC1001BC1-020.0000T
DSC1001BC1-024.0000T
DSC1001BC1-050.0000T
DSC1001DC1-025.0000T
DSC1001DC1-050.0000T
DSC1001DC1-072.0000T
DSC1001DC1-074.2500T
DSC1001DC5-038.8800T
DSC1004DC1-050.0000T
DSC1001DC5-037.4000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1004DC1-020.0000T
DSC1001DC5-012.8000T
DSC1001DC1-100.0000T
DSC1001AC2-025.0000T
DSC1001AC1-008.0000T
DSC1001AC1-125.0000T
DSC1001CI1-001.8432T
DSC1001CI1-007.5000T
DSC1001CI1-008.0000T
DSC1001CI1-010.0000T
DSC1001CI1-013.5600T
DSC1001CI1-014.7456T
DSC1001CI1-016.0000T
DSC1001CI1-019.2000T
DSC1001CI1-020.0000T
DSC1001CI1-024.0000T
DSC1001CI1-024.5760T
DSC1001CI1-025.0000T
DSC1001CI1-026.0000T
DSC1001CI1-027.0000T
DSC1001CI1-030.0000T
DSC1001CI2-004.0000T
DSC1001CI2-008.0000T
DSC1001CI1-033.3333T
DSC1001CI1-047.3333T
DSC1001CI2-018.4320T
DSC1001CI1-050.0000T
DSC1001CI1-076.0686T
DSC1001CI2-014.3181T
DSC1001CI2-001.0000T
DSC1001CI2-002.0480T
DSC1001CI2-003.5795T
DSC1001CI2-022.5792T
DSC1001CI2-006.1400T
DSC1001CI2-011.0592T
DSC1001CI2-012.0000T
DSC1001CI2-012.2880T
DSC1001CI2-014.7456T
DSC1001CI2-016.0000T
DSC1001CI2-024.0000T
DSC1001DE1-013.0000T
DSC1001DL2-012.2880T
DSC1001DL2-125.0000T
DSC1001DL2-004.0000T
DSC1001DL1-016.0000T
DSC1001DL2-023.0000T
DSC1001DE1-020.0000T
DSC1001DL2-026.6500T
DSC1001DL5-014.3181T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DE2-008.0000T
DSC1001DE2-012.0000T
DSC1001DE2-027.0000T
DSC1001DE2-025.0000T
DSC1001DL5-016.7722T
DSC1004DL1-025.0000T
DSC1004DL1-033.0000T
DSC1001DL2-048.0000T
DSC1001DL2-066.6700T
DSC1001DE1-024.3050T
DSC1001DL2-002.0000T
DSC1001DL1-004.0960T
DSC1001DL2-049.1520T
DSC6003ME1B-013.1072T
DSC6001ME1B-008.0000T
DSC6001ME2B-009.0000T
DSC6001ME1B-052.4280T
DSC6011ME2B-012.0000T
DSA6101ML2B-026.0000TVAO
DSA6101ML3B-014.7456TVAO
DSA6101ML3B-016.6666TVAO
DSA6101ML3B-025.0000TVAO
DSA6101ML3B-033.3333TVAO
DSA6011ML1B-025.0000TVAO
DSC612NL3A-012RT
DSC612NL3A-014ET
DSC612NL2A-014ET
DSC612NL2A-0151T
DSC613NE2A-016WT
DSC612NL3A-0142T
DSC612NL3A-019AT
DSA612NL2A-019BTVAO
DSA612NL2A-01C1TVAO
DSA612NL2A-01C3TVAO
DSA612NL2A-01C4TVAO
DSA612NL2A-01CPTVAO
DSC6001JL2B-027.0000T
DSC6101JL2B-033.3333T
DSC6003JL3B-004.0096T
DSC6003JL3B-007.3728T
DSC6101JL3B-038.4000T
DSC6101JL3B-050.0000T
DSC6003JL3B-004.0960
DSC6311JL1BB-028.6364T
DSC6311JL1AB-028.6364T
DSC6331JE1CB-024.0000T
DSC6001JE1B-024.0000T
DSC6003JE1B-024.0000T
DSC6101JL2B-026.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6111JE1B-033.3333T
DSC6011JE2B-032K768T
DSC6121JL2B-015GT
DSC6003JL2B-032K768T
DSC6011JE1B-025.0000T
DSC6011JL2B-025.0000T
DSC6011JE3B-003K898T
DSC6001JE1B-025.0000T
DSC6311JL2AB-027.0000T
DSC6311JL2BB-027.0000T
DSC6111JL2B-008.0000T
DSC6011JE1B-840K000T
DSC6121JL2B-0170T
DSC6101JL3B-025.0000T
DSC6001JE3B-040K000T
DSC1001DI2-064.0000
DSC1001DI3-024.0000
DSC1003DI2-024.5670
DSC1001DI5-032.7680
DSC1001DI1-011.0592
DSC1001DI3-012.0000
DSC1001DI2-033.0000
DSC1003DI5-025.0000
DSC1001DI5-011.0592
DSC1001DI2-133.0000
DSC1003DI1-012.0000
DSC1001DI2-002.0970
DSC1001DI3-100.0000
DSC1001DI3-133.0000
DSC1001DI1-064.0000
DSC1001DI5-019.6800
DSC1001DI1-025.0008
DSC1001DI5-090.0000
DSC1001DI5-014.3181
DSC1001DI1-116.6666
DSC1001DI2-066.6670
DSC1003DI2-050.0000
DSC1004DI2-050.0000
DSC1003DI1-052.0000
DSC1001DI5-009.2160
DSC1001DI2-060.0000
DSC1001DI5-005.0196
DSC1001DI5-037.4000
DSC1001DI1-028.6363
DSC1001DI3-012.2880
DSC1004DI5-024.0000
DSC400-3333Q0130KI2T
DSC400-3111Q0131KI1T
DSC400-3111Q0131KI2T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-4111Q0131KI1T
DSC400-4111Q0131KI2T
DSC400-1111Q0132KI1T
DSC400-1111Q0132KI2T
DSC400-0311Q0026KI1T
DSC400-0311Q0026KI2T
DSC400-0211Q0026KI1T
DSC400-0211Q0026KI2T
DSC400-1111Q0133KI1T
DSC400-1111Q0133KI2T
DSC400-1121Q0134KI1T
DSC400-1121Q0134KI2T
DSC400-1411Q0135KI1T
DSC400-1411Q0135KI2T
DSC400-0212Q0136KI1T
DSC400-0212Q0136KI2T
DSC2311KM2-R0040
DSC8121DM2
DSC2311KM2-R0002
DSC2311KM2-R0050
DSC1101DM1-012.0000
DSC1101DM2-012.0000
DSC1101DM2-004.0000
DSC1101DM1-033.3333
DSC1101DM2-033.3333
DSC1121DM1-033.3333
DSC1101DM2-008.0000
DSC1101DM2-024.0000
DSC1121DM1-030.0000
DSC1101DM1-080.0000
DSC1121DM2-025.0000
DSC1121DM2-033.0000
DSC1121DM2-016.6400
DSC1121DM2-014.7456
DSC2311KM1-R0002
DSC1101DM2-007.3700
DSC1121DM3-032.0000
DSC1101DM1-032.0000
DSC1101DM1-007.3700
DSC1101DM2-040.0000
DSC1121DM2-026.0000
DSC1121DM2-019.2000
DSC1101DM2-048.0000
DSC2311KM2-R0065
DSC1101DM1-020.0000
DSC2311KM2-R0073
DSC2311KM2-R0067
DSC2311KM2-R0015
DSC2311KM2-R0080

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC231TKMZ-R0089

DSC1101DM2-050.0000

DSC2010FM2-B0006

DSC2011FM1-E0005

DSC2011FM2-E0001

DSC2011FM2-E0015

DSC2010FM2-A0001

DSC2011FM1-E0015

DSC2011FM1-F0041

DSC2011FM2-E0005

DSC2011FM2-F0049

DSC2210FM2-A0030

DSC2210FM2-A0031

DSC1101CI1-148.3516

DSC1101CI1-148.5000

DSC1101CI2-014.7456

DSC1101CI2-025.0000

DSC1101CI5-040.0000

DSC1121CI2-156.0063

DSC1103CI3-135.0000

DSC1121CI2-045.0000

DSC1121CI2-055.0000

DSC1123CI3-100.0000

DSC1123CI3-135.0000

DSC1123CI3-165.0000

DSC1123CI3-200.0000

DSC1123CI1-100.0000

DSC1123CI1-156.2500

DSC1122CI2-050.0000

DSC1101BI5-022.5792

DSC1101BI5-024.5760

DSC1101BI5-050.0000

DSC1102BI5-108.0000

DSC1103BI2-150.0000

DSC1104BI5-100.0000

DSC1121BI2-025.0000

DSC1121BI2-050.0000

DSC1121BI2-125.0037

DSC1122BI5-036.7000

DSC1122BI2-150.0000

DSC1123BI1-200.0000

DSC1123BI2-025.0000

DSC1122BI2-133.3300

DSC1123BI2-050.0000

DSC1123BI2-125.0000

DSC1123BI2-156.2500

DSC1123BI5-100.0000

DSC1123BI2-100.0000

DSC1123BI5-155.5200

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1123BI5-156.2500
DSC1123BI5-200.0000
DSC1124BI1-100.0000
DSC1124BI2-125.0000
DSC8101BI2
DSC8101BI5
DSC8102BI2
DSC1123BI2-200.0000
DSC1123BI5-148.3516
DSC8104BI2
DSC1124BI2-100.0000
DSC8121BI2
DSC8122BI2
DSC8122BI5
DSC8123BI2
DSC8124BI2
DSC8103BI2
DSC1122BI2-156.2500
DSC1121BI2-080.0000
DSC1122BI2-100.0000
DSC1122BI2-114.2850
DSC1122BI2-155.5200
DSC1102BI1-100.0000
DSC1122BI1-100.0000
DSC1121BI2-012.2880
DSC1101BI5-133.0000
DSC1123BI2-148.5000
DSC1102BI2-125.0000
DSC1102BI2-153.6000
DSC1103BI2-125.0000
DSC1121BI2-025.0007
DSC1121BI2-156.2540
DSC1123BI1-156.2500
DSC1102BI2-100.0000
DSC1122BI5-400.0000
DSC1104BI2-100.0000
DSC1123BI1-125.0000
DSC1123BI1-100.0000
DSC1121BI2-100.0000
DSC1121BI2-125.0000
DSC8123BI5
DSC1122BI2-156.2539
DSC1124BI5-100.0000
DSC1103BI2-100.0000
DSC1103BI2-135.0000
DSC1103BI2-148.5000
DSC1102BI2-156.2500
DSC1102BI2-155.2500
DSC1102BI2-114.2850

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1101BI2-125.0000
DSC1121BI2-022.5792
DSC1101BI2-024.5760
DSC1123BI2-155.5200
DSC1121BI2-114.2850
DSC1121BI2-024.5760
DSC1121BI2-033.3330
DSC1102BI2-155.5200
DSC1122BI2-156.2570
DSC1123BI2-156.2570
DSC1123BI2-300.0000
DSC1122BI2-020.0000
DSC1122BI2-322.0000
DSC1123BI2-270.0000
DSC1123BI2-210.0000
DSC1123BI2-180.0000
DSC1123BI2-206.0000
DSC1123BI2-068.0000
DSC1121BI1-008.0000
DSC1121BI2-156.2500
DSC1124BI5-020.0000
DSC1123BI2-050.0013
DSC1001BL5-058.9824T
DSC1001BE1-060.0000T
DSC1003BL3-030.0000T
DSC1003BL3-008.1920T
DSC1001BE3-022.1184T
DSC1003BL3-020.0000T
DSC1003BL3-032.7680T
DSC1003BL3-013.8420T
DSC1003BL3-025.0000T
DSC1003BL3-010.2400T
DSC1003BL3-018.4320T
DSC1001BL5-032.0000T
DSC1001BE5-030.6400T
DSC1001BL5-106.2500T
DSC1001BL2-125.0000T
DSC1004BL2-025.0000T
DSC1004BL2-024.0000T
DSC1001BE1-004.0625T
DSC1001BE1-004.0960T
DSC1001BL2-012.0000T
DSC1001BE5-027.0000T
DSC1001BE5-030.0000T
DSC1001BE1-033.3333T
DSC1001BL2-012.5000T
DSC1001BL3-001.0000T
DSC1001DE1-024.0000T
DSC1001DE1-026.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DE1-027.0000T
DSC1001DE1-048.0000T
DSC1001DE1-054.0000T
DSC1001DE1-100.0000T
DSC1001DE1-125.0000T
DSC1001DE2-020.0000T
DSC1001DE2-024.0000T
DSC1001DE2-050.0000T
DSC1001DL1-008.0000T
DSC1001DE5-019.2000T
DSC1001DL1-025.0000T
DSC1001DL1-027.0000T
DSC1001DL2-012.0000T
DSC1001DL2-008.0000T
DSC1001DL2-020.0000T
DSC1001DL2-025.0000T
DSC1001DL2-024.0000T
DSC1001DL2-027.0000T
DSC1001DL2-030.0000T
DSC1001DL2-032.0000T
DSC1001DL2-050.0000T
DSC1001DL5-001.8432T
DSC1001DL5-007.3728T
DSC1001DL5-008.0000T
DSC1001DL5-010.0000T
DSC1001DL5-011.0592T
DSC1001DL5-016.0000T
DSC1001DL5-019.2000T
DSC1001DL5-020.0000T
DSC1001DL5-024.0000T
DSC1001DL5-024.5760T
DSC1001DL5-025.0000T
DSC1001DL5-026.0000T
DSC1001DL5-027.0000T
DSC1001DL5-030.0000T
DSC1001DL5-031.2500T
DSC1001DL5-033.0000T
DSC1001DL5-033.3330T
DSC1001DL5-048.0000T
DSC1001DL5-050.0000T
DSC1001DL5-048.0000D
DSC1003DL5-100.0000T
DSC1001DL5-075.0000T
DSC1001DL5-080.0000T
DSC1001DL5-100.0000B
DSC1001DL5-100.0000T
DSC1001DL5-125.0000T
DSC1003DL2-008.0000T
DSC1003DL2-050.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1003DL2-090.0000T
DSC1003DL2-148.5000T
DSC1003DL5-020.0000T
DSC1003DL5-125.0000T
DSC1001DE1-012.0000T
DSC1001DL5-015.3600T
DSC1003DL2-070.0000T
DSC612RI1A-01GCT
DSC612RI2A-01GET
DSC613RI2A-01GJT
DSC612RI1A-01GVT
DSC613RI3A-0131T
DSC613RI3A-01J3T
DSC612RI2A-01J8T
DSC612RI3A-01M3T
DSC613RI3A-01M7T
DSC613RI3A-01M8T
DSC612RI2A-01K9T
DSC612RI2A-01KAT
DSC612RI2A-01KKT
DSC612RI3A-013CT
DSC612RI1A-01JMT
DSC612RI3A-01K3T
DSC612RI3A-01P3T
DSA613RI3A-01BMTVAO
DSC6101HA2B-072.0000T
DSC6003HA3B-016.0000T
DSC6001HA3B-PROGT
DSC6003HA3B-PROGT
DSC6101HA3B-PROGT
DSC6003HA1B-020.0000T
DSC6101HA2B-072.5000T
DSC6001HA2B-029.4912T
DSC6101HA3B-024.0000T
DSC6111HA3B-024.0000T
DSC6111HA2B-024.0000T
DSC6332HA3AB-002.4576T
DSC6332HA3AB-031.9488T
DSC6301HA1FB-020.0000T
DSC6301HA1FB-020.0000B
DSC6021HA3B-01D0T
DSC6003HA3B-032K768T
DSC6011HA1B-032K768T
DSC6011HA2B-032K768T
DSC6011HA2B-025.0000T
DSC6011HA2B-008.0000T
DSC6013HA2B-048.0000T
DSC6011HA2B-029.4912T
DSA6101HA1B-005.0000TVAO

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA6101HA1B-008.0000TVAO

DSA6101HA1B-027.0000TVAO

DSA6301HA1AB-027.0000TVAO

DSA6001HA2B-029.4912TVAO

DSA6122HA3B-01ECTVAO

DSC6001MA2B-020.0000T

DSC6003MA3B-032K768T

DSC1101BL3-PROGT

DSC1101BL5-PROGT

DSC1100BL3-PROGT

DSC1100BL5-PROGT

DSC1121BE5-024.0000T

DSC1121BL5-012.0000T

DSC1124BE5-156.2500T

DSC1123BL5-200.0000T

DSC1122BE2-156.2500T

DSC1102BE2-312.5000T

DSC1121BL3-016.0000T

DSC1121BL3-012.2880T

DSC1121BE5-144.0800T

DSC1123BL1-100.0000T

DSC1123BL1-125.0000T

DSC1123BE2-200.0000T

DSC1103BE5-150.0000T

DSC1123BE1-025.0000T

DSC1101BL5-024.0000T

DSC1122BE5-123.0000T

DSC1101BE3-024.0000T

DSC1122BL2-018.4320T

DSC1101BL5-018.4320T

DSC1121BL5-025.0000T

DSC1123BL2-200.0000T

DSC1101BL5-022.1184T

DSC1103BE1-156.2500T

DSC1103BL1-100.0000T

DSC1104BE2-027.0000T

DSC1123BL2-212.5000T

DSC1123BL2-250.0000T

DSC1121BE5-098.3040T

DSC1103BL5-026.8800T

DSC1121BL2-040.6800T

DSC1123BE2-085.0000T

DSC1103BE5-100.0000T

DSC1101AE3-084.6720T

DSC1101AE3-090.3168T

DSC1104AE2-145.2000T

DSC1101AE5-022.5792T

DSC1101AE5-024.5760T

DSC1103AL1-287.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121AE5-012.0000T
DSC1102AE5-416.0000T
DSC1121AE5-005.2500T
DSC400-2222Q0118KI2T
DSC400-0244Q0009KI1T
DSC400-0244Q0009KI2T
DSC400-0101Q0119KI1T
DSC400-0101Q0119KI2T
DSC400-1111Q0120KI1T
DSC400-1111Q0120KI2T
DSC400-0111Q0026KI1T
DSC400-0111Q0026KI2T
DSC400-1111Q0121KI1T
DSC400-1111Q0121KI2T
DSC400-1114Q0122KI1T
DSC400-1114Q0122KI2T
DSC400-0321Q0123KI1T
DSC400-0321Q0123KI2T
DSC400-3333Q0124KI1T
DSC400-3333Q0124KI2T
DSC400-1331Q0125KI1T
DSC400-1331Q0125KI2T
DSC400-1333Q0126KI1T
DSC400-1333Q0126KI2T
DSC400-0223Q0127KI1T
DSC400-0223Q0127KI2T
DSC400-0133Q0128KI1T
DSC400-0133Q0128KI2T
DSC400-0331Q0128KI1T
DSC400-0331Q0128KI2T
DSC400-0101Q0129KI1T
DSC400-0101Q0129KI2T
DSC400-3333Q0130KI1T
DSC1123DI2-315.0000T
DSC1123DI2-312.0000T
DSC1124DI2-315.0000T
DSC1123DI2-312.2000T
DSC1122DI2-050.0000T
DSC2311KI1-R0054T
DSC1103DI5-360.0000T
DSC2311KI2-R0055T
DSC1101DI1-125.0000T
DSC1123DI2-025.0000T
DSC2311KI2-R0056T
DSC1101DI5-013.5288T
DSC2311KI2-R0057T
DSC1101DI5-032.0000T
DSC1122DI2-156.2500T
DSC1124DI1-100.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC2311KI2-R00581

DSC1101DI2-049.1520T

DSC1101DI1-038.0000T

DSC1121DI5-100.0000T

DSC2311KI2-R0059T

DSC1103DI2-100.0000T

DSC1103DI2-108.0000T

DSC1121DI5-072.0000T

DSC1121DI5-050.0000T

DSC1121DI5-032.0000T

DSC1121DI1-100.0000T

DSC2311KI1-R0041T

DSC2311KI2-R0060T

DSC1102DI5-135.0000T

DSC1123DI5-148.4258T

DSC1123DI2-148.4258T

DSC2311KI1-R0059T

DSC1101DI3-025.0000T

DSC1103DI2-135.0000T

DSC1121DI2-010.0000T

DSC1101DI1-100.0000T

DSC2311KI2-R0008T

DSC1102DI2-125.0000T

DSC1124DI1-027.0000T

DSC2311KI2-R0061T

DSC2311KI2-R0062T

DSC2311KI2-R0063T

DSC1101DI5-024.0000T

DSC1101DI5-100.0000T

DSC1101DI5-045.1584T

DSC1101DI5-049.1520T

DSC1101DI5-018.4320T

DSC1121DI3-050.0000T

DSC2311KI2-R0065T

DSC1124DI2-027.0000T

DSC1102DI2-156.2500T

DSC1103DI5-074.2500T

DSC1103DI5-200.0000T

DSC1103DI5-100.0000T

DSC2311KI2-R0066T

DSC1101DI3-012.0000T

DSC1123DI1-125.0000T

DSC2311KI2-R0067T

DSC1101DI2-060.0000T

DSC2311KI2-R0068T

DSC1124DI3-100.0000T

DSC2311KI1-R0069T

DSC2311KI2-R0070T

DSC1122DI5-272.8000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC112TDI2-100.0000T
DSC1124DI3-027.0000T
DSC400-1111Q0078KE2
DSC400-0323Q0009KE1
DSC400-0323Q0009KE2
DSC400-1111Q0148KE1
DSC400-1111Q0148KE2
DSC400-1313Q0094KE1
DSC400-1313Q0094KE2
DSC400-1111Q0149KE1
DSC400-1111Q0149KE2
DSC400-1333Q0078KE1
DSC400-1333Q0078KE2
DSC400-1111Q0150KE1
DSC400-1111Q0150KE2
DSC400-3333Q0151KE1
DSC400-3333Q0151KE2
DSC400-4144Q0152KE1
DSC400-4144Q0152KE2
DSC400-3331Q0153KE1
DSC400-3331Q0153KE2
DSC400-2222Q0031KE1
DSC400-2222Q0031KE2
DSC400-0333Q0154KE1
DSC400-0333Q0154KE2
DSC400-0111Q0155KE1
DSC400-0111Q0155KE2
DSC400-3133Q0156KE1
DSC400-3133Q0156KE2
DSC400-0133Q0157KE1
DSC400-0133Q0157KE2
DSC1123AI1-161.1328T
DSC1101AI5-080.0000T
DSC1101AI5-064.0000T
DSC1102AI1-156.2500T
DSC1102AI2-156.2500T
DSC1121AI2-013.0000T
DSC1103AI2-148.0000T
DSC1124AI1-100.0000T
DSC1121AI3-025.0000T
DSC1101AI2-027.0000T
DSC1101AI1-008.0000T
DSC1101AI5-060.0000T
DSC1121AI5-022.5792T
DSC1102AI5-156.2500T
DSC1122AI5-025.0007T
DSC1103AI2-300.0000T
DSC1123AI2-135.0000T
DSC1121AI2-008.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121AI2-016.0000T
DSC1121AI2-066.6660T
DSC1121AI2-033.3330T
DSC1121AI1-156.2500T
DSC1121AI1-090.0000T
DSC1101AI5-114.2850T
DSC1101AI3-125.0000T
DSC1103AI5-180.0000T
DSC1121AI5-008.0000T
DSC1123AI2-155.5200T
DSC1102AI2-106.0000T
DSC1102AI5-160.0000T
DSC1102AI5-400.0000T
DSC1121AI2-159.3750T
DSC1102AI2-156.2540T
DSC1121AI2-081.0000T
DSC1121AI2-041.5000T
DSC1121AI5-041.5000T
DSC1121AI1-041.5000T
DSC1123AI2-185.0000T
DSC1123AI2-250.0000T
DSC1123AI2-074.2500T
DSC1123AI2-312.5000T
DSC1103AI2-156.2500T
DSC1101AI2-066.6666T
DSC1121AI1-100.0000T
DSC1102AI1-250.0000T
DSC1123AI2-055.0000T
DSC6101HI2B-080.0000
DSC6102HI2B-025.0000
DSC6001HI1B-032.7680
DSC6111HI2B-012.0000
DSC6013HI3B-409K600
DSC6011HI3B-048.0000
DSC6101HI2B-010.0000
DSC6011HI3B-032K000
DSC6001HI2B-018.4320
DSC6301HI2BB-012.0000
DSC6301HI2DB-012.0000
DSC6301HI2FB-012.0000
DSC6111HI1B-013.5600
DSC6041HI2B-025.0000
DSC6041HI2B-027.0000
DSC6011HI2B-025.0000
DSC6011HI2B-027.0000
DSC6111HI1B-080.0000
DSC6001HI2B-025.0000
DSC6101HI1B-007K085
DSC6001HI1B-025.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6101HI3B-100.0000
DSC6011HI1B-012.0000
DSC6101HI1B-012.0000
DSC6003HI2B-745K000
DSC6001HI2B-004.0960
DSC6001HI2B-032.0000
DSC6001HI2B-003.5900
DSC6003HI2B-048.0000
DSC6112HI2B-025.0000
DSC6013HI2B-048.0000
DSC6011HI2B-012.0000
DSC6061HI1B-01MC
DSC6111HI3B-027.0000
DSC6111HI3B-074.2500
DSC6051HI2B-012.0000
DSC6151HI2B-025.0000
DSC6151HI2B-027.0000
DSC6331HI2AB-012.0000
DSC6102HI2B-024.0000
DSA6001HI2B-019.2000VAO
DSA6001HI2B-024.0000VAO
DSA6001HI2B-025.0000VAO
DSA6011HI2B-002K730VAO
DSA6331HI2AB-012.0000VAO
DSA6331HI2AB-025.0000VAO
DSC6001MI2B-012.2880
DSC1123CE5-100.0000T
DSC1123CE2-135.0000T
DSC1123CL5-100.0000T
DSC1123CE5-150.0000T
DSC1123CE5-156.2500T
DSC1123CL2-125.0000T
DSC8121CL5T
DSC1124CL2-200.0000T
DSC1101CL5-100.0000T
DSC1103CE1-125.0000T
DSC1123CE1-125.0000T
DSC1101CL5-014.7456T
DSC1121CE1-133.3333T
DSC8123CI5T
DSC1103CE1-156.2500T
DSC1124CE1-010.2400T
DSC1121CE5-050.0000T
DSC1121CL2-040.0000T
DSC1121CL5-050.0000T
DSC1124CL2-100.0000T
DSC1101CL2-024.7500T
DSC1101CL3-PROGT
DSC1101CL5-PROGT

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1101CE2-100.0000T
DSC1123CL1-400.0000T
DSC1123CL1-025.0000T
DSC1103CE5-100.0000T
DSC1103CL5-100.0000T
DSC1123CL5-050.0000T
DSC1123CL5-025.0000T
DSC1103CE5-045.0000T
DSC1121CE1-125.0000T
DSC1123CE2-250.0000T
DSC1123CE2-312.5000T
DSC1103CE1-266.7000T
DSC1103CE1-233.3000T
DSC1123CE1-150.0000T
DSC1124CE1-100.0000T
DSC1121CL5-150.0000T
DSC1124CL1-100.0000T
DSC1122CL2-156.2500T
DSC1121CE1-033.3333T
DSC1121CE5-033.3333T
DSC1101CE5-010.0000T
DSC1101CL2-040.0000T
DSC1121CL1-024.0000T
DSC1121CL1-028.6364T
DSC1121CL1-027.0000T
DSC1103CL5-150.0000T
DSC1103CE2-156.2500T
DSC1101CE2-045.1584T
DSC1101CE2-049.1520T
DSC1104CE2-027.0000T
DSC1123CL5-433.0000T
DSC1121CE1-025.6000T
DSC1121CL5-040.0000T
DSC1121CL5-080.0000T
DSC1101CL1-125.0000T
DSC1124CE2-100.0000T
DSC1124CE5-100.0000T
DSC1100CL3-PROGT
DSC1100CL5-PROGT
DSC1101CL5-030.0000T
DSC1123CL5-322.2656T
DSC1101CE5-025.0000T
DSC1101CE2-025.0000T
DSC1103CL2-233.3333T
DSC1101CE1-024.5790T
DSC1101CE1-022.5792T
DSC1101CE1-011.2896T
DSC1101CL5-052.5000T
DSC1101CE1-024.5760T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103CL2-333.3333T
DSC1123CE2-100.0000T
DSC1101CE5-024.0000T
DSC1101CE5-100.0000T
DSC1101CE5-045.1854T
DSC1101CE5-049.1520T
DSC1103CL2-125.0000T
DSC1103CL2-052.0000T
DSC1103CL5-033.3330T
DSC1103CL5-075.0300T
DSC1123CL2-333.3333T
DSC1101CE5-022.5792T
DSC1101CE5-024.5760T
DSC1101CL3-025.0000T
DSC1121CL5-033.3333T
DSC1123CL2-200.0000T
DSC1123CL3-040.0000T
DSC1123CL1-287.0000T
DSC1121CE5-002.4880T
DSC1101CE1-100.0000T
DSC1101CE1-054.0000T
DSC1122CL1-135.0000T
DSC1121CL1-050.0000T
DSC1101CL2-025.0000T
DSC1101CL2-050.0000T
DSC1101CL2-100.0000T
DSC1101CL2-125.0000T
DSC1123CE3-422.3000T
DSC1103CL1-075.0000T
DSC1123CL2-156.2500T
DSC1123CL1-100.0000T
DSC1123CL2-100.0000T
DSC1124CL3-100.0000T
DSC1103CL1-200.0000T
DSC1103CL1-100.0000T
DSC1103CL1-125.0000T
DSC1103CL1-150.0000T
DSC1103CL1-026.0000T
DSC1103CL1-027.0000T
DSC1103CL3-093.4400T
DSC1103CL3-100.0000T
DSC1103CL3-125.0000T
DSC1103CL3-250.0000T
DSC1101CE1-080.0000T
DSC1103CL1-020.0000T
DSC1124CL5-027.0000T
DSC1121CE1-030.0000T
DSC1121CE2-030.0000T
DSC1101CE3-024.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121CE5-025.0000T

DSC1121CL5-027.0000T

DSC612RL1A-014ST

DSC612RL2A-0130T

DSC612RL2A-0168T

DSC612RL2A-013CT

DSC612RE1A-0169T

DSC613RE2A-016YT

DSC613RE1A-017QT

DSC612RL2A-018KT

DSC613RE1A-0197T

DSC612RE1A-0199T

DSC612RL3A-019BT

DSC612RL1A-019TT

DSC612RL3A-01AMT

DSC612RE2A-01ATT

DSC612RE1A-01B2T

DSC613RE1A-01BVT

DSC613RE2A-01DGT

DSC612RL2A-01E7T

DSC612RE1A-01GQT

DSC612RE2A-01GQT

DSC612RL3A-01KST

DSC612RE3A-01M0T

DSC612RE2A-01MRT

DSA612RL2A-01GATVAO

DSA612RL2A-01H6TVAO

DSA612RL2A-01K9TVAO

DSA612RL2A-01KMTVAO

DSA612RL2A-01MGTVAO

DSA613RL2A-016PTVAO

DSC6001HI2B-012.0000T

DSC6001HI2B-024.0000T

DSC6003HI2B-012.0000T

DSC6001HI3B-032K768T

DSC6003HI3B-010.0000T

DSC6101HI3B-019.2000T

DSC6003HI2B-025.0000T

DSC6003HI2B-024.0000T

DSC6011HI2B-002K000T

DSC6011HI2B-032K768T

DSC6011HI2B-250K000T

DSC6011HI2B-432K000T

DSC6011HI2B-720K000T

DSC6013HI2B-001.0000T

DSC6013HI2B-002K000T

DSC6013HI2B-032K768T

DSC6013HI2B-250K000T

DSC6013HI2B-432K000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6013HI2B-720K000T
DSC6112HI2B-001.0000T
DSC6111HI2B-032K768T
DSC6111HI2B-250K000T
DSC6111HI2B-432K000T
DSC6111HI2B-720K000T
DSC6112HI2B-032K768T
DSC6112HI2B-250K000T
DSC6112HI2B-432K000T
DSC6112HI2B-720K000T
DSC6111HI2B-004K000T
DSC6112HI2B-004K000T
DSC6001HI2B-048.0000T
DSC6003HI3B-027.0000T
DSC6111HI3B-010.0000T
DSC6013HI2B-003.6864T
DSC6021HI3B-016RT
DSC6001HI2B-006.0000T
DSC6001HI2B-008.0000T
DSC6011HI1B-016.0000T
DSC6011HI1B-024.0000T
DSC6011HI1B-025.0000T
DSC6011HI1B-009.6000T
DSC6021HI2B-018ET
DSC6011HI3B-064.0128T
DSC6013HI3B-064.0128T
DSC6003HI2B-019.2000T
DSC6111HI1B-032K768T
DSC6001HI1B-020.0000T
DSC6101HI2B-080.0000T
DSC6102HI2B-025.0000T
DSC6001HI1B-032.7680T
DSC6111HI2B-012.0000T
DSC6013HI3B-409K600T
DSC6011HI3B-048.0000T
DSC6101HI2B-010.0000T
DSC6011HI3B-032K000T
DSC6001HI2B-018.4320T
DSC6301HI2BB-012.0000T
DSC6301HI2DB-012.0000T
DSC6301HI2FB-012.0000T
DSC6111HI1B-013.5600T
DSC6041HI2B-025.0000T
DSC6041HI2B-027.0000T
DSC6011HI2B-025.0000T
DSC6011HI2B-027.0000T
DSC6111HI1B-080.0000T
DSC6001HI2B-025.0000T
DSC6101HI1B-007K085T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6001HI1B-025.0000T
DSC6101HI3B-100.0000T
DSC6011HI1B-012.0000T
DSC6101HI1B-012.0000T
DSC6003HI2B-745K000T
DSC6001HI2B-004.0960T
DSC6001HI2B-032.0000T
DSC6001HI2B-003.5900T
DSC6003HI2B-048.0000T
DSC6112HI2B-025.0000T
DSC6013HI2B-048.0000T
DSC6011HI2B-012.0000T
DSC6061HI1B-01MCT
DSC6111HI3B-027.0000T
DSC6111HI3B-074.2500T
DSC6051HI2B-012.0000T
DSC6151HI2B-025.0000T
DSC6151HI2B-027.0000T
DSC6331HI2AB-012.0000T
DSC6102HI2B-024.0000T
DSA6001HI2B-019.2000TVAO
DSA6001HI2B-024.0000TVAO
DSA6001HI2B-025.0000TVAO
DSA6011HI2B-002K730TVAO
DSA6331HI2AB-012.0000TVAO
DSA6331HI2AB-025.0000TVAO
DSC6001MI2B-012.2880T
DSC2011FL2-F0020T
DSC557-0333FE0T
DSC2033FE2-F0010T
DSC2041FE1-K0003T
DSC2044FE1-H0002T
DSC2010FE1-B0013T
DSC2043FE1-F0023T
DSC557-0333FL0T
DSC2033FL2-F0028T
DSC2130FE1-C0003T
DSC2044FL1-F0022T
DSC2044FL1-H0005T
DSC2044FE1-H0003T
DSC2044FE1-F0024T
DSC2041FE1-F0014T
DSC557-0341FE1T
DSC557-0344FE0T
DSC557-0344FL1T
DSC2044FE2-H0006T
DSC2030FE5-B0018T
DSC2022FE2-F0034T
DSC2111FE1-E0022T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC2033FL1-F002Z1
DSC2010FL2-B0014T
DSC2041FE1-K0002T
DSC2033FL2-F0004T
DSC2031FL2-F0045T
DSC2011FL2-E0005T
DSC2110FL1-A0029T
DSC2110FL2-C0011T
DSC2144FL2-F0022T
DSC2033FL2-F0051T
DSC2033FL2-E0005T
DSC1001DL5-010.2000T
DSC1001DL2-037.1250T
DSC1001DE1-040.0000T
DSC1001DE1-050.0000T
DSC1001DL2-150.0000T
DSC1001DL2-090.0000T
DSC1001DL5-012.0000T
DSC1003DL5-148.5000T
DSC1001DL5-004.0000T
DSC1001DE1-025.0000T
DSC1001DL5-133.3330T
DSC1001DL1-010.0000T
DSC1001DL2-072.0000T
DSC1003DL2-100.0000T
DSC1001DL2-087.0655T
DSC1001DL5-060.0000T
DSC1001DL1-037.1250
DSC1001DL1-080.0000T
DSC1001DL5-014.7456T
DSC1001DL2-049.5000T
DSC1003DE1-050.0000T
DSC1003DL1-125.0000T
DSC1003DL2-025.0000T
DSC1003DL5-025.0000T
DSC1001DL1-024.0000T
DSC1001DL2-040.0000T
DSC1001DL1-001.8432T
DSC1001DL2-001.8432T
DSC1001DL2-033.3333T
DSC1001DL1-033.3333T
DSC1001DE1-075.0000T
DSC8001DL5T
DSC1001DE2-100.0000T
DSC1001DL2-016.0000T
DSC1001DL1-025.2000T
DSC1004DL5-040.0000T
DSC1001DE1-033.3333T
DSC1001DL5-040.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DE1-019.2000T
DSC1001DL2-007.3728T
DSC1001DL5-072.0000T
DSC1003DL2-080.0000T
DSC1001DL5-012.2880T
DSC1003DL1-027.0000T
DSC1004DL1-027.0000T
DSC1001DE2-038.4000T
DSC1101DI5-016.0000T
DSC1101DI2-050.6880T
DSC1103DI2-048.0000T
DSC1101DI5-030.2400T
DSC1124DI2-100.0000T
DSC2311KI1-R0053T
DSC1001DI2-012.2880T
DSC1001DI2-016.0000T
DSC1001DL5-001.0000T
DSC1001DI2-033.3300T
DSC1001DI2-019.2000T
DSC1001DI2-020.0000T
DSC1001DI2-022.0000T
DSC1001DI2-022.5792T
DSC1001DI2-024.0000T
DSC1001DI2-024.5455T
DSC1001DI2-024.5760B
DSC1001DI2-024.5760T
DSC1001DI2-025.0000T
DSC1001DI2-026.0000T
DSC1001DI2-027.0000T
DSC1001DI2-028.3220T
DSC1001DI2-029.5000T
DSC1001DI2-032.0000T
DSC1001DI2-066.6600T
DSC1001DI2-033.3333T
DSC1001DI2-036.8182T
DSC1001DI2-037.1250T
DSC1001DI5-002.4576T
DSC1001DI2-038.4000T
DSC1001DI2-040.0000T
DSC1001DI2-048.0000T
DSC1001DI2-049.0909T
DSC1001DI2-050.0000T
DSC1001DI2-072.0000T
DSC1001DI2-074.1758T
DSC1001DI2-074.2500T
DSC1001DI2-080.0000T
DSC1001DI2-100.0000T
DSC1001DI2-125.0000T
DSC1001DI2-128.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DI4-010.0000T
DSC1001DI4-010.0503T
DSC1001DI4-010.0587T
DSC1001DI4-059.7800T
DSC1001DI4-060.0700T
DSC1001DI4-066.4860T
DSC1001DI4-066.5800T
DSC1004DI2-025.0000T
DSC1001DI5-002.0480T
DSC1001DI2-047.3885T
DSC1001DI1-038.4000T
DSC1001DI2-026.6000T
DSC1001DI1-066.0000T
DSC1001DI5-008.0000T
DSC1001DI5-047.3885T
DSC1001DI5-013.3333T
DSC1001DI5-022.5792T
DSC1001DI5-030.0000T
DSC1001DI2-024.5454T
DSC1001DI5-033.0000T
DSC1001DI1-100.0000T
DSC1004DI2-012.0000T
DSC1003DI2-024.5760T
DSC1001DI1-033.0000T
DSC1001DI1-072.0000T
DSC1001DI1-030.0000T
DSC1001DI1-050.0000B
DSC1001DI5-150.0000T
DSC1004DI2-010.0000T
DSC1001DI1-032.0000T
DSC1001DI2-014.7456T
DSC1003DI2-100.0000T
DSC1001DI2-028.6363T
DSC1001DI2-031.2500T
DSC1004DI2-016.0000T
DSC8003DI2T
DSC1001DI5-003.6864T
DSC1001DI5-004.0000T
DSC8123BL2
DSC1122BE1-156.2500
DSC1124BL1-100.0000
DSC1101BE5-024.5760
DSC1101BE5-022.5792
DSC1121BE2-155.5200
DSC1123BE1-050.0000
DSC1101BE1-012.0000
DSC1121BL5-108.7200
DSC1121BL5-110.5400
DSC1123BL5-125.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1123BE5-100.0000
DSC1123BE1-100.0000
DSC1101BL3-PROG
DSC1101BL5-PROG
DSC1100BL3-PROG
DSC1100BL5-PROG
DSC1121BE5-024.0000
DSC1121BL5-012.0000
DSC1124BE5-156.2500
DSC1123BL5-200.0000
DSC1122BE2-156.2500
DSC1102BE2-312.5000
DSC1121BL3-016.0000
DSC1121BL3-012.2880
DSC1121BE5-144.0800
DSC1123BL1-100.0000
DSC1123BL1-125.0000
DSC1123BE2-200.0000
DSC1103BE5-150.0000
DSC1123BE1-025.0000
DSC1101BL5-024.0000
DSC1122BE5-123.0000
DSC1101BE3-024.0000
DSC1122BL2-018.4320
DSC1101BL5-018.4320
DSC1121BL5-025.0000
DSC1123BL2-200.0000
DSC1101BL5-022.1184
DSC1103BE1-156.2500
DSC1103BL1-100.0000
DSC1104BE2-027.0000
DSC1123BL2-212.5000
DSC1123BL2-250.0000
DSC1121BE5-098.3040
DSC1103BL5-026.8800
DSC1121BL2-040.6800
DSC1123BE2-085.0000
DSC1103BE5-100.0000
DSC1101AE5-007.6800
DSC1101AE5-040.6080
DSC1101AE3-084.6720
DSC1101AE3-090.3168
DSC1104AE2-145.2000
DSC1101AE5-022.5792
DSC1101AE5-024.5760
DSC1103AL1-287.0000
DSC1121AE5-012.0000
DSC1102AE5-416.0000
DSC1121AE5-005.2500

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1123AE2-003.5000
DSC1101AL5-045.1584
DSC1101AL5-049.1520
DSC1123AE2-156.2500
DSC1121AE2-004.9152
DSC1121AE2-133.0000
DSC1102AE2-400.0000
DSC1101AE3-024.0000
DSC1103AL5-150.0000
DSC1103AL5-015.0000
DSC1102AE2-155.5200
DSC1103AE3-416.0000
DSC1121AL5-041.5000
DSC1121AE2-041.5000
DSC1121AE5-041.5000
DSC1121AL2-041.5000
DSC1121AL1-041.5000
DSC1123AE1-159.3750
DSC1103AL1-125.0000
DSC1122AE2-075.0000
DSC1121AL5-012.0000
DSC1101AL2-156.2500
DSC1103AE2-085.0000
DSC1123AE2-085.0000
DSC1121AE5-025.0000
DSC1121AE5-020.0000
DSC1100AL3-PROG
DSC1101AL3-PROG
DSC1100AL5-PROG
DSC1101AL5-PROG
DSC1123AE2-100.0000
DSC1122AE2-156.2500
DSC1123AE1-200.0000
DSC1121AL2-020.0000
DSC1123AE2-040.0000
DSC1121AL5-010.0000
DSC1121AL5-100.0000
DSC1123AL2-125.0000
DSC1103AE2-135.0000
DSC1123AL5-100.0000
DSC1123AL5-148.5000
DSC1121AE5-010.0000
DSC1101AL5-112.4400
DSC1123AL2-100.0000
DSC1103AL2-147.4560
DSC1121AL5-112.2400
DSC1121AE5-022.5792
DSC1121AE5-024.5760
DSC1121AL5-170.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121AL5-024.5760
DSC1121AL5-022.5792
DSC1121AL5-125.0000
DSC1101AE2-027.1200
DSC1123AL1-148.5000
DSC1103AL1-100.0000
DSC1103AE2-212.5000
DSC1124AE5-065.0000
DSC1101AE5-032.0000
DSC1123AL5-156.2500
DSC1123AL5-125.0000
DSC1103AL2-125.0031
DSC1123AE5-148.5000
DSC1123AE5-148.3516
DSC1123AE5-074.1758
DSC1123AE1-125.0000
DSC1101AE2-016.3840
DSC1123AE2-200.0000
DSC1123AE2-300.0000
DSC1123AL2-025.0000
DSC1123AL2-050.0000
DSC8101AL2
DSC8121AL2
DSC1123AE1-148.3500
DSC1123AE1-148.5000
DSC1123AL1-150.0000
DSC1102AE5-412.5000
DSC1101AE3-098.3040
DSC1121AE2-025.0000
DSC1121AE2-156.2500
DSC1121AL2-025.0000
DSC1123AE2-148.3516
DSC1103NE1-125.0000
DSC1122NE1-025.0000
DSC1122NE2-156.2500
DSC1124NE1-100.0000
DSC1122NE1-133.3330
DSC1122NE1-150.0000
DSC1123NE2-156.2500
DSC1123NE2-125.0000
DSC1123NL2-100.0000
DSC1102NE1-148.5000
DSC1102NE1-125.0000
DSC1103NE1-114.2850
DSC1123NE1-100.0000
DSC1123NL5-125.0000
DSC1123NL5-100.0000
DSC1121NL1-025.0000
DSC1101NL3-PROG

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1101NL5-PROG
DSC1100NL3-PROG
DSC1100NL5-PROG
DSC1122NL2-025.0006
DSC1103NL2-147.4560
DSC1103NL2-098.3040
DSC1123NE1-200.0000
DSC1103NL5-125.0000
DSC1103NL2-100.0000
DSC1103NL2-106.2500
DSC1103NL2-135.0000
DSC1101DE2-008.0000
DSC1101DL1-033.3330
DSC1101DL1-100.0000
DSC1101DL2-040.0000
DSC1101DL5-050.0000
DSC1101DL5-013.5600
DSC1101DL5-025.0000
DSC1121DL2-024.7500
DSC1121DL2-025.0000
DSC1123DE1-131.0720
DSC1123DL5-156.2500
DSC1123DE5-200.0000
DSC1123DL2-125.0000
DSC1123DL5-100.0000
DSC1123DL5-125.0000
DSC2311KE1-R0002
DSC1123DL5-212.5000
DSC2311KL1-R0009
DSC2311KL1-R0021
DSC2311KL2-R0009
DSC2311KL2-R0015
DSC2311KL2-R0027
DSC1105DL1-027.0000
DSC2311KE1-R0042
DSC1103DL5-125.0000
DSC2311KE1-R0047
DSC2311KL2-R0048
DSC1101DL5-052.8000
DSC1123DL5-200.0000
DSC1123DL1-125.0000
DSC1101DL1-027.0000
DSC2311KL1-R0002
DSC1121DL2-008.0000
DSC1101DL5-020.0000
DSC1101DL5-016.0000
DSC1121DL2-032.0000
DSC2311KL2-R0040
DSC2311KL2-R0052

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121DE1-050.0000
DSC1101DL2-050.6880
DSC1103DL2-147.4560
DSC1123DE2-399.6800
DSC1123DE2-400.0000
DSC2311KL1-R0054
DSC1103DL2-156.2500
DSC1101DL1-150.0000
DSC1121DL5-026.0000
DSC1121DL1-025.0000
DSC1121DL1-033.0000
DSC1104DL1-027.0000
DSC1123DL5-135.0000
DSC1123DL5-150.0000
DSC1101DL5-024.5760
DSC1101DL5-018.4320
DSC1101DE5-040.0000
DSC1101DE5-012.2880
DSC1121DE2-025.0000
DSC1101DE2-049.1520
DSC1101DE2-045.1584
DSC1123DL2-100.0000
DSC2311KL2-R0002
DSC1121DL2-072.0000
DSC1121DL1-040.0000
DSC1101DL3-PROG
DSC1101DL5-PROG
DSC1100DL3-PROG
DSC1100DL5-PROG
DSC2311KE2-R0016
DSC1123DL5-176.5000
DSC1123DL5-206.5000
DSC1123DL5-136.5000
DSC1103DL1-025.0013
DSC1103DL2-025.0012
DSC1123DE1-148.3516
DSC1101DE2-024.5760
DSC1101DE2-022.5792
DSC1101DE2-100.0000
DSC1121DL5-072.0000
DSC1121DE5-072.0000
DSC1103DL2-100.0000
DSC1124DL2-100.0000
DSC1103DL2-122.8800
DSC1103DL2-098.3040
DSC1101DE2-012.0000
DSC1104DE5-100.0000
DSC1104DL3-100.0000
DSC1124DL5-100.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1124DL1-100.0000
DSC1103DL5-156.2500
DSC1123DL2-250.0000
DSC1121DE1-010.0000
DSC2311KL2-R0071
DSC1101DL2-033.3300
DSC1104DL2-026.0000
DSC2311KL1-R0072
DSC1122DL2-220.0000
DSC1124DL1-027.0000
DSC1123DL2-050.0000
DSC1121DE3-150.3330
DSC1101DL1-020.0000
DSC1123DE1-125.0000
DSC1122DL1-072.0000
DSC1102DL1-212.5000
DSC2311KE2-R0002
DSC2311KE2-R0081
DSC1123DE1-156.2500
DSC1103DL5-027.0000
DSC1103DL5-100.0000
DSC1101DL2-025.0000
DSC1123DL1-025.0000
DSC1122DE5-254.6500
DSC1103DL5-063.5000
DSC1103DL2-135.0000
DSC2311KE1-R0085
DSC1123DL2-156.2500
DSC1123DL1-156.2500
DSC2311KL2-R0091
DSC2311KE2-R0090
DSC1103DE5-254.6500
DSC2033FI2-F0012T
DSC2111FI2-E0029T
DSC2043FI1-F0058T
DSC2011FI1-F0056T
DSA557-0344FI0TVAO
DSA557-0344FI1TVAO
DSC1101CM2-062.2080T
DSC1121CM1-010.0000T
DSC1121CM1-016.0000T
DSC1121CM1-020.0000T
DSC1121CM1-024.0000T
DSC1121CM1-025.0000T
DSC1121CM1-048.0000T
DSC1121CM1-050.0000T
DSC1121CM1-075.0000T
DSC1121CM1-125.0000T
DSC1121CM2-033.3333T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121CM2-027.0000T
DSC1101CM1-075.0000T
DSC1101CM1-005.0000T
DSC1101CM1-033.3333T
DSC1121CM2-040.0000T
DSC1121CM2-006.7800T
DSC1121CM1-012.0000T
DSC1121CM1-012.2880T
DSC1121CM1-040.0000T
DSC1101CM2-012.0000T
DSC1101CM2-048.0000T
DSC1121CM1-066.6660T
DSC1121CM1-100.0000T
DSC1121CM1-036.0000T
DSC1121CM1-018.0000T
DSC1101CM1-040.0000T
DSC1121CM2-008.0000T
DSC1121CM2-025.0000T
DSC1121CM1-030.0000T
DSC1101CM3-024.0000T
DSC1121CM1-014.7456T
DSC1101CM1-032.0000T
DSC1121CM1-032.0000T
DSC1123CM1-375.0000T
DSC1121CM2-003.1152T
DSC1121CM1-003.1152T
DSC1121CM1-005.5296T
DSC1121CM2-024.0000T
DSC1101BM2-025.0000T
DSC1101BM2-100.0000T
DSC1121BM1-008.0000T
DSC1121BM1-025.0000T
DSC1121BM1-027.0000T
DSC1121BM1-030.0000T
DSC1121BM1-048.0000T
DSC1121BM1-100.0000T
DSC1101BM2-074.2500T
DSC1121BM1-010.0000T
DSC1121BM1-024.0000T
DSC1101BM2-027.0000T
DSC1121BM1-050.0000T
DSC1121BM2-016.0000T
DSC1121BM2-030.0000T
DSC1101BM2-050.0000T
DSC1101BM2-054.0000T
DSC1121BM1-024.5760T
DSC1123AI5-270.0000
DSC1122AI2-100.3000
DSC1101AI2-150.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103AI1-155.5200
DSC1103AI1-161.1328
DSC1103AI2-125.0031
DSC1122AI2-125.0000
DSC1123AI1-155.5200
DSC1123AI1-161.1300
DSC1123AI1-161.1328
DSC1101AI5-080.0000
DSC1101AI5-064.0000
DSC1102AI1-156.2500
DSC1102AI2-156.2500
DSC1121AI2-013.0000
DSC1103AI2-148.0000
DSC1124AI1-100.0000
DSC1121AI3-025.0000
DSC1101AI2-027.0000
DSC1101AI1-008.0000
DSC1101AI5-060.0000
DSC1121AI5-022.5792
DSC1102AI5-156.2500
DSC1122AI5-025.0007
DSC1103AI2-300.0000
DSC1123AI2-135.0000
DSC1121AI2-008.0000
DSC1121AI2-016.0000
DSC1121AI2-066.6660
DSC1121AI2-033.3330
DSC1121AI1-156.2500
DSC1121AI1-090.0000
DSC1101AI5-114.2850
DSC1101AI3-125.0000
DSC1103AI5-180.0000
DSC1121AI5-008.0000
DSC1123AI2-155.5200
DSC1102AI2-106.0000
DSC1102AI5-160.0000
DSC1102AI5-400.0000
DSC1121AI2-159.3750
DSC1102AI2-156.2540
DSC1121AI2-081.0000
DSC1121AI2-041.5000
DSC1121AI5-041.5000
DSC1121AI1-041.5000
DSC1123AI2-185.0000
DSC1123AI2-250.0000
DSC1123AI2-074.2500
DSC1123AI2-312.5000
DSC1103AI2-156.2500
DSC1101AI2-066.6666

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121AI1-100.0000
DSC1102AI1-250.0000
DSC1123AI2-055.0000
DSC1121AI1-064.0000
DSC1102AI1-050.0000
DSC1122AI1-159.3750
DSC1101AI1-025.0000
DSC1121AI2-150.0000
DSC1123AI2-062.5000
DSC8121AI5
DSC8123AI5
DSC1123AI2-156.2570
DSC1101AI2-080.0000
DSC1101AI2-040.0000
DSC1101AI2-064.0000
DSC1123AI2-027.0000
DSC1123AI2-050.0000
DSC8121NI2
DSC8122NI2
DSC8123NI2
DSC8124NI2
DSC1101NI1-125.0062
DSC1101NI1-156.2500
DSC1101NI5-100.0000
DSC1103NI2-400.0000
DSC1121NI2-018.4320
DSC1122NI2-150.0000
DSC1123NI1-100.0000
DSC1123NI1-125.0000
DSC1123NI2-125.0000
DSC1123NI2-150.0000
DSC1123NI2-312.5000
DSC1101NI5-025.0000
DSC8122NI5
DSC1101NI5-020.0000
DSC1101NI5-012.8000
DSC1101NI5-016.3840
DSC1124NI1-100.0000
DSC1124NI1-156.2500
DSC1104NI2-100.0000
DSC1122NI5-025.0020
DSC1122NI2-050.0000
DSC1103NI2-125.0000
DSC1121NI1-100.0000
DSC1121NI2-125.0000
DSC1121NI2-025.0000
DSC1101NI1-050.0000
DSC1102NI5-156.2500
DSC1123NI1-156.2500

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1122NI2-156.2500

DSC1103NI2-148.5000

DSC1103NI2-156.2500

DSC1101NI5-018.7500

DSC1122NI2-148.5000

DSC1123NI2-200.0000

DSC1123NI5-100.0000

DSC1123NI5-125.0000

DSC1123NI5-156.2500

DSC1123NI5-322.2656

DSC1101NI2-050.0000

DSC1103NI1-135.0000

DSC1122NI5-025.0007

DSC1123NI3-050.0015

DSC1103NI5-150.0000

DSC1123NI2-100.0000

DSC1122NI5-200.0000

DSC1102NI5-400.0000

DSC1102NI5-200.0000

DSC1101NI2-025.0000

DSC1101NI2-018.7500

DSC1121DI2-024.0000

DSC1101DI2-025.0000

DSC1101DI5-020.0000

DSC1101DI5-026.0000

DSC1101DI5-072.0000

DSC1102DI1-156.2500

DSC400-0333Q0154KI2

DSC400-0111Q0155KI1

DSC400-0111Q0155KI2

DSC400-3133Q0156KI1

DSC400-3133Q0156KI2

DSC400-0133Q0157KI1

DSC400-0133Q0157KI2

DSC400-3113Q0158KI1

DSC400-3113Q0158KI2

DSC400-3113Q0159KI1

DSC400-3113Q0159KI2

DSC400-1111Q0160KI1

DSC400-1111Q0160KI2

DSC400-0333Q0162KI1

DSC400-0333Q0162KI2

DSC400-3333Q0163KI1

DSC400-3333Q0163KI2

DSA400-1111Q0004KI1VAO

DSA400-1111Q0004KI2VAO

DSA400-1111Q0085KI1VAO

DSA400-1111Q0085KI2VAO

DSA400-1111Q0161KI1VAO

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA400-1111Q0161KI2VAO

DSA400-4134Q0152KI1VAO

DSA400-4134Q0152KI2VAO

DSA557-04444KI1VAO

DSA557-054444KI1VAO

DSC400-1111Q0001KE1

DSC400-1111Q0084KE1

DSC400-1111Q0084KE2

DSC400-0101Q0083KE1

DSC400-0101Q0083KE2

DSC400-0414Q0033KE1

DSC400-1111Q0025KE1

DSC400-1444Q0052KE1

DSC400-1444Q0060KE2

DSC400-1444Q0060KI2

DSC400-4134Q0028KE1

DSC400-4134Q0050KE1

DSC400-4244Q0023KE1

DSC557-053344KL1T

DSC400-4244Q0069KE1

DSC557-053333KL1T

DSC400-4244Q0071KE1

DSC557-04444KL1

DSC400-4411Q0072KE1

DSC400-4411Q0072KE2

DSC400-4444Q0015KE1

DSC400-4444Q0015KE2

DSC400-4444Q0022KE1

DSC400-1444Q0060KE1

DSC400-1444Q0060KI1

DSC400-1111Q0073KE1

DSC400-1111Q0073KE2

DSC400-1133Q0079KE1

DSC400-1133Q0079KE2

DSC400-1111Q0001KE2

DSC400-3333Q0078KE1

DSC400-3333Q0078KE2

DSC400-1111Q0081KE1

DSC400-1111Q0081KE2

DSC400-3133Q0080KE1

DSC400-3133Q0080KE2

DSC400-0101Q0082KE1

DSC400-0101Q0082KE2

DSC400-1311Q0076KE1

DSC400-1311Q0076KE2

DSC400-0303Q0086KE1

DSC400-0303Q0086KE2

DSC400-0111Q0087KE1

DSC400-0111Q0087KE2

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-3111Q0088KE1
DSC400-3111Q0088KE2
DSC400-3333Q0089KE1
DSC400-3333Q0089KE2
DSC400-4444Q0023KE1
DSC400-4444Q0023KE2
DSC400-4444Q0059KE1
DSC400-4444Q0059KE2
DSC400-1111Q0090KE1
DSC400-1111Q0090KE2
DSC400-1111Q0091KE1
DSC400-1111Q0091KE2
DSC400-2222Q0022KE1
DSC400-2222Q0022KE2
DSC400-0303Q0092KE1
DSC400-0303Q0092KE2
DSC400-3333Q0093KE1
DSC400-3333Q0093KE2
DSC400-3333Q0094KE1
DSC400-3333Q0094KE2
DSC400-4334Q0022KE1
DSC400-4334Q0022KE2
DSC400-0444Q0009KE1
DSC400-0444Q0009KE2
DSC400-1111Q0095KE1
DSC400-1111Q0095KE2
DSC400-0101Q0096KE1
DSC1101NI5-012.8000T
DSC1101NI5-016.3840T
DSC1104NI2-100.0000T
DSC1122NI5-025.0020T
DSC1122NI2-050.0000T
DSC1103NI2-125.0000T
DSC1121NI1-100.0000T
DSC1121NI2-125.0000T
DSC1121NI2-025.0000T
DSC1101NI1-050.0000T
DSC1102NI5-156.2500T
DSC1123NI1-156.2500T
DSC1122NI2-156.2500T
DSC1103NI2-148.5000T
DSC1103NI2-156.2500T
DSC1101NI5-018.7500T
DSC1122NI2-148.5000T
DSC1123NI2-200.0000T
DSC1123NI5-100.0000T
DSC1123NI5-125.0000T
DSC1123NI5-156.2500T
DSC1123NI5-322.2656T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1101NI2-050.0000T
DSC1103NI1-135.0000T
DSC1122NI5-025.0007T
DSC1123NI3-050.0015T
DSC1103NI5-150.0000T
DSC1123NI2-100.0000T
DSC1122NI5-200.0000T
DSC1102NI5-400.0000T
DSC1102NI5-200.0000T
DSC1101NI2-025.0000T
DSC1101NI2-018.7500T
DSC1121DI2-024.0000T
DSC1101DI2-025.0000T
DSC1101DI5-072.0000T
DSC1101DI5-020.0000T
DSC1101DI5-026.0000T
DSC1101DM2-025.0000T
DSC1101DI5-050.0000T
DSC1101DI5-060.0000T
DSC1101DL5-025.0000T
DSC1102DI1-156.2500T
DSC1103DI2-125.0000T
DSC1103DI2-312.5000T
DSC1103DI2-200.0000T
DSC1103DI5-171.8181T
DSC1103DI2-400.0000T
DSC1104DI1-100.0000T
DSC1104DI1-156.2500T
DSC1121DI1-036.0000T
DSC1121DI1-125.0000T
DSC1121DI5-034.3680T
DSC1121DI2-025.0000T
DSC400-3113Q0158KE1
DSC400-3113Q0158KE2
DSC400-3113Q0159KE1
DSC400-3113Q0159KE2
DSC400-1111Q0160KE1
DSC400-1111Q0160KE2
DSC400-0333Q0162KE1
DSC400-0333Q0162KE2
DSC400-3333Q0163KE1
DSC400-3333Q0163KE2
DSA400-1111Q0004KL1VAO
DSA400-1111Q0004KL2VAO
DSA400-1111Q0085KL1VAO
DSA400-1111Q0085KL2VAO
DSA400-1111Q0161KL1VAO
DSA400-1111Q0161KL2VAO
DSA400-4134Q0152KL1VAO

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA400-4134Q0152KL2VAO

DSA557-04443KL0VAO

DSA557-04444KL1VAO

DSA557-054444KL1VAO

DSC400-1111Q0001KE1T

DSC400-1111Q0084KE1T

DSC400-1111Q0084KE2T

DSC400-0101Q0083KE1T

DSC400-0101Q0083KE2T

DSC400-1111Q0025KE1T

DSC400-1444Q0060KE2T

DSC400-1444Q0060KI2T

DSC400-4244Q0069KE1T

DSC557-04444KL1T

DSC400-4411Q0072KE1T

DSC400-4411Q0072KE2T

DSC400-4444Q0015KE1T

DSC400-4444Q0015KE2T

DSC400-1444Q0060KE1T

DSC400-1444Q0060KI1T

DSC400-1111Q0073KE1T

DSC400-1111Q0073KE2T

DSC400-1133Q0079KE1T

DSC400-1133Q0079KE2T

DSC400-1111Q0001KE2T

DSC400-3333Q0078KE1T

DSC400-3333Q0078KE2T

DSC400-1111Q0081KE1T

DSC400-1111Q0081KE2T

DSC400-3133Q0080KE1T

DSC400-3133Q0080KE2T

DSC400-0101Q0082KE1T

DSC400-0101Q0082KE2T

DSC400-1311Q0076KE1T

DSC400-1311Q0076KE2T

DSC400-0303Q0086KE1T

DSC400-0303Q0086KE2T

DSC400-0111Q0087KE1T

DSC400-0111Q0087KE2T

DSC400-3111Q0088KE1T

DSC400-3111Q0088KE2T

DSC400-3333Q0089KE1T

DSC400-3333Q0089KE2T

DSC400-4444Q0023KE1T

DSC400-4444Q0023KE2T

DSC400-4444Q0059KE1T

DSC400-4444Q0059KE2T

DSC400-1111Q0090KE1T

DSC400-1111Q0090KE2T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-1111Q0091KE1T
DSC400-1111Q0091KE2T
DSC1001BI5-030.0000T
DSC1001BI1-038.4000T
DSC1001BI2-018.4320T
DSC1001BI5-020.0000T
DSC1001BI5-133.3330T
DSC1001BI1-004.0000T
DSC1001BI2-030.0000T
DSC1001BI1-012.2880T
DSC1001BI2-014.3181T
DSC1001BI1-020.0000T
DSC1001BI5-090.0000T
DSC1004BI2-010.0000T
DSC1001BI1-066.6666T
DSC8001BI5T
DSC1001BI2-133.3330T
DSC1001BI1-016.0000T
DSC8003BI2T
DSC1001BI2-012.5000T
DSC1001BI5-013.5600T
DSC1001BI1-100.0000T
DSC1001BI1-012.0000T
DSC1001BI2-033.0000T
DSC1001BI2-026.0000T
DSC1001BI5-084.0000T
DSC1001BI1-033.3330T
DSC1001BI2-012.2888T
DSC1101DI5-060.0000
DSC1121DI1-025.0000
DSC1103DI2-019.2000
DSC1103DI2-125.0000
DSC1103DI2-148.5000
DSC1103DI2-200.0000
DSC1103DI2-312.5000
DSC1103DI2-400.0000
DSC1103DI5-171.8181
DSC1121DI1-036.0000
DSC1104DI1-100.0000
DSC1104DI1-156.2500
DSC1121DI2-011.0590
DSC1121DI2-022.5792
DSC1121DI2-024.5760
DSC1121DI2-027.0000
DSC1121DI5-034.3680
DSC1121DI5-044.0000
DSC1121DI5-044.7360
DSC1122DI2-100.0000
DSC1122DI2-106.2500

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121DI2-125.0000
DSC1121DI5-010.0000
DSC1123DI2-050.0000
DSC1123DI2-086.0000
DSC1121DI2-025.0000
DSC1123DI2-106.2500
DSC1123DI2-125.0000
DSC1123DI2-148.5000
DSC1123DI2-156.2500
DSC1123DI2-200.0000
DSC6003JI1B-100K000T
DSC6011JI1B-003.6864T
DSC6021JI2B-01HMT
DSC6101JI3B-038.4000T
DSC6001JI1B-024.0000T
DSC6332JI3AB-050.0000T
DSC6332JI3FB-050.0000T
DSC6001JI1B-040.0000T
DSC6001JI2B-042.5000T
DSC6021JI2B-01J5T
DSC6013JI2B-004.0960T
DSC6331JI1DB-075.0000T
DSC6331JI1AB-025.0000T
DSC6311JI1FB-075.0000T
DSC6101JI2B-012.0000T
DSC6001JI1B-008K000T
DSC6001JI1B-008.0000T
DSC6001JI2B-008.0000T
DSC6011JI3B-020.0000T
DSC6112JI2B-024.0000T
DSC6311JI1BB-012.0000T
DSC6101JI1B-080.0000T
DSC6021JI2B-01KQT
DSC6011JI1B-024.0000T
DSC6121JI2B-01MHT
DSC6111JI2B-100.0000T
DSC6111JI2B-074.2500T
DSC6111JI2B-027.0000T
DSC6001JI1B-006.5536T
DSC6331JI2AB-010.0000T
DSC6331JI2AB-016.0000T
DSC6331JI2AB-100.0000T
DSC6331JI2CB-012.2880T
DSC6001JI3B-259K200T
DSC6102JI1B-080.0000T
DSC6101JI2B-037.1250T
DSC6001JI2B-001.0000T
DSC6001JI2B-016.0000T
DSC6003JI2B-250K000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA6001JI1B-052K768TVAO
DSA6001JI1B-080.0000TVAO
DSA6003JI1B-020.0000TVAO
DSA6013JI1B-300K000TVAO
DSA6101JI1B-050.0000TVAO
DSA6111JI1B-008.0000TVAO
DSA6331JI1CB-027.0000TVAO
DSA6003JI2B-032K768TVAO
DSA6101JI2B-012.2880TVAO
DSA6101JI2B-018.4320TVAO
DSA6101JI2B-032K768TVAO
DSA6101JI2B-036.8640TVAO
DSA6101JI2B-100.0000TVAO
DSA6111JI2B-032K768TVAO
DSA6331JI2FB-024.5760TVAO
DSA6001JI3B-005.0000TVAO
DSA6011JI3B-032K768TVAO
DSA6023JI3B-01JGTVAO
DSC612PI3A-010JT
DSC612PI3A-010KT
DSC612PI3A-010TT
DSC613PI3A-0105T
DSC612PI3A-010JB
DSC612PI3A-010KB
DSC612PI3A-010TB
DSC613PI3A-0105B
DSC612PI2A-012QT
DSC613PI2A-0131T
DSC612PI2A-0130T
DSC612PI2A-013CT
DSC612PI3A-013JT
DSC612PI2A-015PT
DSC612PI2A-0166T
DSC612PI1A-016ST
DSC612PI3A-0130T
DSC613PI3A-0195T
DSC613PI3A-01CRT
DSC613PI3A-01D4T
DSC613PI3A-01EYT
DSC612PI2A-01GVT
DSC612PI1A-01HTT
DSC612PI3A-012YT
DSC612PI2A-01M1T
DSC612PI2A-01MDT
DSC612PI2A-014JT
DSC612PI2A-01JRT
DSC612PI2A-012YT
DSC613PI2A-01JST
DSC613PI2A-01JTT

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC613PI2A-01JU1
DSC613PI2A-01JVT
DSC612PI2A-01KWT
DSC612PI2A-01JQT
DSA613PI3A-01G8TVAO
DSC612RI3A-010GT
DSC400-3333Q0023KI1
DSC400-3333Q0023KI2
DSC400-3333Q0146KI1
DSC400-3333Q0146KI2
DSC400-1111Q0147KI1
DSC400-1111Q0147KI2
DSC400-1111Q0078KI1
DSC400-1111Q0078KI2
DSC400-0323Q0009KI1
DSC400-0323Q0009KI2
DSC400-1111Q0148KI1
DSC400-1111Q0148KI2
DSC400-1313Q0094KI1
DSC400-1313Q0094KI2
DSC400-1111Q0149KI1
DSC400-1111Q0149KI2
DSC400-1333Q0078KI1
DSC400-1333Q0078KI2
DSC400-1111Q0150KI1
DSC400-1111Q0150KI2
DSC400-3333Q0151KI1
DSC400-3333Q0151KI2
DSC400-4144Q0152KI1
DSC400-4144Q0152KI2
DSC400-3331Q0153KI1
DSC400-3331Q0153KI2
DSC400-2222Q0031KI1
DSC400-2222Q0031KI2
DSC400-0333Q0154KI1
DSC1001CI2-028.6363
DSC1001CI1-016.0000
DSC1001CI1-019.2000
DSC1001CI1-024.0000
DSC1001CI1-025.0000
DSC1001CI1-026.0000
DSC1001CI1-027.0000
DSC1001CI1-020.0000
DSC1001CI1-033.3333
DSC1001CI1-047.3333
DSC1001CI1-048.0000
DSC1001CI1-050.0000
DSC1001CI2-002.0480
DSC1001CI2-004.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CI2-008.0000

DSC1001CI2-011.0592

DSC1001CI2-012.0000

DSC1001CI2-012.2880

DSC1001CI2-014.3181

DSC1001CI2-014.7456

DSC1001CI2-016.0000

DSC1001CI2-018.0000

DSC1001CI2-018.4320

DSC1001CI2-020.0000

DSC1001CI2-022.5792

DSC1001CI2-024.0000

DSC1001CI2-024.5760

DSC1001CI2-025.0000

DSC1001CI2-027.0000

DSC1001CI2-003.5795

DSC1001CI1-007.5000

DSC1001CI2-032.7680

DSC1001CI2-033.0000

DSC1001CI2-033.3300

DSC1001CI2-033.3333

DSC1001CI2-026.0000

DSC1001CI2-037.1250

DSC1001CI2-040.0000

DSC1001CI2-048.0000

DSC1001CI2-050.0000

DSC1001CI2-060.0000

DSC1001CI2-066.6666

DSC1001CI2-074.2500

DSC1001CI2-080.0000

DSC1001CI2-100.0000

DSC1001CI5-004.9152

DSC1001CI5-010.0000

DSC1001CI5-019.2000

DSC1001CI5-020.0000

DSC612PA1A-01H5T

DSA612PA2A-01DMTVAO

DSA612PA3A-0130TVAO

DSA612PA3A-01DQTVAO

DSC612RA3A-010ST

DSC613RA2A-0106T

DSC612RA3A-010SB

DSC613RA2A-0106B

DSC612RA3A-0138T

DSC612RA1A-0173T

DSC612RA1A-0174T

DSC612RA3A-0181T

DSC613RA3A-018BT

DSC612RA3A-01B2T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC612RA3A-014S1

DSC612RA1A-01H5T

DSC612RA1A-01JJT

DSC612RA3A-01JWT

DSC612RA1A-0102T

DSA612RA1A-01KGTVAO

DSA612RA2A-01GMTVAO

DSA613RA2A-01BGTVAO

DSC400-0331Q0026KI2

DSC400-1111Q0084KI1

DSC400-1111Q0084KI2

DSC400-0111Q0138KE1

DSC400-0111Q0138KE2

DSC400-0111Q0139KE1

DSC400-0111Q0139KE2

DSC400-0144Q0140KE1

DSC400-0144Q0140KE2

DSC400-1221Q0141KE1

DSC400-1221Q0141KE2

DSC400-0434Q0009KE1

DSC400-0434Q0009KE2

DSC400-0313Q0136KE1

DSC400-0313Q0136KE2

DSC400-1111Q0142KE1

DSC400-1111Q0142KE2

DSC400-1111Q0143KE1

DSC400-1111Q0143KE2

DSC400-0333Q0144KE1

DSC400-0333Q0144KE2

DSC400-3333Q0145KE1

DSC400-3333Q0145KE2

DSC400-3333Q0023KE1

DSC400-3333Q0023KE2

DSC400-3333Q0146KE1

DSC400-3333Q0146KE2

DSC400-1111Q0147KE1

DSC400-1111Q0147KE2

DSC400-1111Q0078KE1

DSC1103CL5-156.2500

DSC1103CL5-125.0000

DSC1103CE5-254.6500

DSC1124CE2-038.4000

DSC1104CL1-100.0000

DSC1103CL5-135.0000

DSC1103CL5-148.5000

DSC1103CL5-200.0000

DSC1103CE2-100.0000

DSC1123CL2-027.0000

DSC1103CE2-020.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103CL5-212.5000
DSC1101CL3-033.3300
DSC1103BE1-150.0000
DSC1103BL2-125.0000
DSC1103BL2-200.0000
DSC1121BE2-100.0000
DSC1121BE5-025.0000
DSC1122BE1-133.3300
DSC1122BE2-050.0000
DSC1122BE2-150.0000
DSC1123BE2-050.0000
DSC1123BE5-156.2500
DSC1123BL2-125.0000
DSC1123BL5-156.2500
DSC8101BL2
DSC1103BL5-062.5000
DSC8103BL5
DSC1124BE2-100.0000
DSC1104BE2-100.0000
DSC1103BE5-156.2500
DSC1121DI2-125.0000B
DSC1121DI2-125.0000T
DSC1121DI5-010.0000T
DSC1123DI2-050.0000T
DSC1122DI2-100.0000T
DSC1122DI2-125.0000B
DSC1123DI2-148.5000T
DSC1122DI2-125.0000T
DSC1123DI2-148.5000B
DSC1123DI2-086.0000T
DSC1123DI2-100.0000B
DSC1123DI5-200.0000T
DSC2311KI1-R0009T
DSC1123DI2-200.0000T
DSC2311KI2-R0005T
DSC2311KI2-R0009T
DSC2311KI2-R0001T
DSC2311KI2-R0002T
DSC2311KI2-R0041T
DSC8123DI5T
DSC1103DI5-125.0060T
DSC2311KI2-R0043T
DSC1101DI1-025.0000T
DSC1123DI2-156.2500T
DSC2311KI1-R0046T
DSC1121DI1-026.6000T
DSC1122DI2-200.0000T
DSC2311KI1-R0051T
DSC2311KI2-R0049T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103DI2-148.3500T
DSC1103DI2-148.5000T
DSC1121DI5-008.0000T
DSC1123DI2-125.0000T
DSC1123DI2-125.0000B
DSC1123DI2-025.0000B
DSC2311KI1-R0003T
DSC2311KI2-R0003T
DSC2311KI2-R0016T
DSC2311KI2-R0045T
DSC1123DI5-156.2500T
DSC1123DI2-100.0000T
DSC1121DI2-156.2500T
DSC1101DI1-012.0000T
DSC1101DI5-012.0000T
DSC1101DI1-150.0000T
DSC1103DI2-048.0000
DSC1101DI5-030.2400
DSC1124DI2-100.0000
DSC2311KI1-R0053
DSC1123DI2-315.0000
DSC1123DI2-312.0000
DSC1124DI2-315.0000
DSC1123DI2-312.2000
DSC1122DI2-050.0000
DSC2311KI1-R0054
DSC1103DI5-360.0000
DSC2311KI2-R0055
DSC1101DI1-125.0000
DSC1123DI2-025.0000
DSC2311KI2-R0056
DSC1101DI5-013.5288
DSC2311KI2-R0057
DSC1101DI5-032.0000
DSC1122DI2-156.2500
DSC1124DI1-100.0000
DSC2311KI2-R0058
DSC1101DI2-049.1520
DSC1101DI1-038.0000
DSC1121DI5-100.0000
DSC2311KI2-R0059
DSC1103DI2-100.0000
DSC1103DI2-108.0000
DSC1121DI5-072.0000
DSC1121DI5-050.0000
DSC1121DI5-032.0000
DSC1121DI1-100.0000
DSC2311KI1-R0041
DSC2311KI2-R0060

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1102DI5-135.0000
DSC1123DI5-148.4258
DSC1123DI2-148.4258
DSC2311KI1-R0059
DSC1101DI3-025.0000
DSC1103DI2-135.0000
DSC1121DI2-010.0000
DSC1101DI1-100.0000
DSC2311KI2-R0008
DSC1102DI2-125.0000
DSC1124DI1-027.0000
DSC2311KI2-R0061
DSC2311KI2-R0062
DSC2311KI2-R0063
DSC1101DI5-024.0000
DSC1101DI5-100.0000
DSC1101DI5-045.1584
DSC1101DI5-049.1520
DSC1101DI5-018.4320
DSC1121DI3-050.0000
DSC2311KI2-R0065
DSC1124DI2-027.0000
DSC1102DI2-156.2500
DSC1103DI5-074.2500
DSC1103DI5-200.0000
DSC1103DI5-100.0000
DSC2311KI2-R0066
DSC1101DI3-012.0000
DSC1123DI1-125.0000
DSC2311KI2-R0067
DSC1101DI2-060.0000
DSC2311KI2-R0068
DSC1124DI3-100.0000
DSC2311KI1-R0069
DSC2311KI2-R0070
DSC1122DI5-272.8000
DSC1121DI2-100.0000
DSC1124DI3-027.0000
DSC1123DI5-010.0000
DSC1103DI5-300.0000
DSC1101DI5-025.0000
DSC1123DI2-072.0000
DSC1101DI5-036.0000
DSC1101DI1-036.0000
DSC1123DI2-010.0000
DSC1103DI5-160.0000
DSC1101DI2-012.0000
DSC1101DI5-125.0000
DSC2311KI2-R0074

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1123DI2-148.3516

DSC2311KI2-R0073

DSC2311KI2-R0021

DSC2311KI2-R0023

DSC2311KI2-R0079

DSC1104DI2-100.0000

DSC1102DI1-212.5000

DSC1102DI2-212.5000

DSC2311KI2-R0012

DSC1123DI1-100.0000

DSC1104DI5-100.0000

DSC1124DI5-100.0000

DSC2311KI2-R0082

DSC1121DI1-048.0000

DSC1122DI2-121.1090

DSC1101DI1-033.3330

DSC2311KI1-R0083

DSC1103DI2-250.0000

DSC2311KI1-R0070

DSC2311KI1-R0052

DSC1121DI5-125.0000

DSC2311KI2-R0085

DSC2311KI2-R0086

DSC2311KI1-R0078

DSC2311KI1-R0073

DSC1123DI2-160.0000

DSC2311KI2-R0088

DSC2311KI1-R0016

DSC1123DI5-125.0060

DSC1123DI1-322.2656

DSC2311KI1-R0040

DSC1103DI1-156.2500

DSC1103DI2-156.2500

DSC1103DI1-080.0000

DSA2311KI1-R0003VAO

DSA1101DI1-004.0000VAO

DSA1101DI1-050.0000VAO

DSA1121DI3-033.3333VAO

DSA2311KI2-R0064VAO

DSA2311KI2-R0065VAO

DSA2311KI2-R0077VAO

DSA2311KI3-R0067VAO

DSA2311KI1-R0016VAO

DSA2311KI1-R0041VAO

DSA2311KI2-R0015VAO

DSC2010FI2-A0001

DSC2010FI2-A0003

DSC557-0333FI0

DSC6331JI2EB-012.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6011JI2B-024.0000
DSC6003JI2B-050.0000
DSC6311JI2EB-018.4320
DSC6301JI2GB-024.0000
DSC6311JI1AB-025.0000
DSC6011JI2B-018.0000
DSC6101JI1B-048.0000
DSC6013JI2B-050.0000
DSC6001JI1B-027.0000
DSC6331JI3CB-018.4320
DSC6331JI1CB-018.4320
DSC6111JI1B-028.1250
DSC6021JI2B-01G3
DSC6112JI2B-028.1250
DSC6001JI1B-020.0000
DSC6111JI1B-008.0000
DSC6331JI2FB-024.5760
DSC6051JI2B-014.3180
DSC6011JI1B-006.5536
DSC6011JI3B-012.0000
DSC6051JI3B-032K768
DSC6001JI3B-032K768
DSA1001DL2-100.0000TVAO
DSA1001DL2-125.0000TVAO
DSA1004DL2-072.0000TVAO
DSA1001DL3-004.0000TVAO
DSA1001DL3-006.0053TVAO
DSA1001DL3-008.0000TVAO
DSA1001DL3-012.2888TVAO
DSA1001DL3-012.5000TVAO
DSA1001DL3-016.0000TVAO
DSA1001DL3-016.3840TVAO
DSA1001DL3-020.0000TVAO
DSA1001DL3-022.5792TVAO
DSA1001DL3-024.0000TVAO
DSA1001DL3-025.0000TVAO
DSA1001DL3-026.0000TVAO
DSA1001DL3-027.0000TVAO
DSA1001DL3-032.7680TVAO
DSA1001DL3-033.0000TVAO
DSA1001DL3-033.3330TVAO
DSA1001DL3-045.0000TVAO
DSA1001DL3-048.0000TVAO
DSA1001DL3-054.0000TVAO
DSA1001DL3-055.4666TVAO
DSA1001DL3-060.0000TVAO
DSC2031FL2-F0052T
DSC2210FL2-A0026T
DSC2041FL1-F0014T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC2011FE1-F00571

DSA557-0333FL0TVAO
DSA557-0344FL0TVAO
DSA557-0344FL1TVAO
DSC1101CI2-025.0000T
DSC1101CI2-050.0000T
DSC1101CI2-100.0000T
DSC1101CI5-020.0000T
DSC1102CI1-125.0000T
DSC1101CI5-010.0000T
DSC1103CI1-156.2500T
DSC1103CI1-200.0000T
DSC1102CI5-200.0000T
DSC1103CI2-125.0000T
DSC1103CI2-100.0000T
DSC1103CI2-200.0000T
DSC1103CI5-025.0000T
DSC1103CI5-050.0000T
DSC1103CI5-100.0000T
DSC1103CI5-106.2500T
DSC1103CI5-148.5000T
DSC1121CI2-014.7456T
DSC1103CI5-200.0000T
DSC1121CI1-024.0000T
DSC1103CI5-233.3333T
DSC1121CI1-125.0000T
DSC1121CI2-010.0000T
DSC1121CI2-012.2880T
DSC1121CI2-013.0000T
DSC1103CI5-300.0000T
DSC1121CI2-024.0000T
DSC1121CI2-025.0000T
DSC1121CI1-025.0000T
DSC1121CI2-048.0000T
DSC1121CI2-050.0000T
DSC1121CI2-060.0000T
DSC1121CI2-066.6660T
DSC1121CI2-100.0000T
DSC1121CI2-125.0000T
DSC1121CI2-133.3330T
DSC1121CI2-148.5000T
DSC1121CI5-040.0000T
DSC1121CI5-049.1520T
DSC1122CI1-156.2500T
DSC1122CI2-062.5000T
DSC1122CI2-100.0000T
DSC1122CI2-125.0000T
DSC1122CI2-133.3300T
DSC1122CI2-150.0000T

Date: Monday, November 16, 2020

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1122CI2-156.2500T
DSC1122CI2-050.0000T
DSC1123CI1-100.0000T
DSC1123CI1-125.0000T
DSC1123CI1-150.0000T
DSC1123CI1-200.0000T
DSC1123CI2-100.0000T
DSC1123CI2-125.0000T
DSC1123CI2-148.5000T
DSC1123CI2-150.0000T
DSC1123CI2-156.2500T
DSC1121CI2-024.5760T
DSC1121CI2-020.0000T
DSC1122CI2-103.1250T
DSC1124CI5-156.2500T
DSC1101CI5-025.0000T
DSC1103CI5-224.8200T
DSC1123CI2-333.3300T
DSC8122CI2T
DSC1123CI1-022.8800T
DSC1123CI5-156.2500T
DSC1123CI2-212.5000T
DSC1001CI2-024.5760T
DSC1001CI2-025.0000T
DSC1001CI2-026.0000T
DSC1001CI2-027.0000T
DSC1001CI2-027.6000T
DSC1001CI2-028.6363T
DSC1001CI2-080.0000T
DSC1001CI2-032.7680T
DSC1001CI2-033.0000T
DSC1001CI2-033.3300T
DSC1001CI2-033.3333T
DSC1001CI2-034.3000T
DSC1001CI2-036.0000T
DSC1001CI5-032.7680T
DSC1001CI2-037.1250T
DSC1001CI2-040.0000T
DSC1001CI2-048.0000T
DSC1001CI2-050.0000T
DSC1001CI2-054.0000T
DSC1001CI2-060.0000T
DSC1001CI2-066.6660T
DSC1001CI2-066.6666T
DSC1001CI2-074.2500T
DSC1003CI1-050.0000T
DSC1001CI2-100.0000T
DSC1001CI2-125.0000T
DSC1001CI4-002.0480T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CI4-049.1520T
DSC1001CI4-054.0000T
DSC1001CI5-004.0000T
DSC1001CI5-004.9152T
DSC1001CI5-008.0000T
DSC1001CI5-010.0000T
DSC1001CI5-012.0000T
DSC1001CI5-012.2880T
DSC1001CI5-016.0000T
DSC1001CI5-018.4320T
DSC1001CI5-019.2000T
DSC1001CI5-020.0000T
DSC1001CI5-024.0000T
DSC1001CI5-024.5760T
DSC1001CI5-025.0000T
DSC1001CI5-026.0000T
DSC1001CI5-027.0000T
DSC1001CI5-030.0000T
DSC1001CI1-003.6864T
DSC1001CI2-012.5000T
DSC1001CI5-009.6000T
DSC1001CI1-100.0000T
DSC1001CI2-020.0000T
DSC1001CI2-006.0000T
DSC1001CI5-040.0000T
DSC1001CI5-044.0000T
DSC1001CI5-019.0000T
DSC1001CI5-060.0000T
DSC1001CI1-033.0000T
DSC1001CI1-048.0000T
DSC1001CI5-011.0592T
DSC1001CI2-031.2500T
DSC1001CI2-049.1520T
DSC1001CI2-032.0000T
DSC1001CI2-096.0000T
DSC1001CI2-100.0000B
DSC1001CI5-133.3330T
DSC1001CI5-070.4550T
DSC1001CI2-008.1920T
DSC1001CI2-010.4857T
DSC8001CI5T
DSC1001CI1-011.0592T
DSC1001CI2-001.9521T
DSC8003CI2T
DSC1001CI2-019.4400T
DSC1001CI2-026.000T
DSC1001CI2-133.0000T
DSC1001CI5-016.3840T
DSC1001CI5-033.3333T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CI5-032.0000T
DSC1001CI5-033.0000T
DSC1001CI5-033.3330T
DSC1001CI2-030.0000T
DSC1001CI5-048.0000T
DSC1001CI5-050.0000T
DSC1001CI5-064.0000T
DSC1001CI5-100.0000T
DSC1001CI5-125.0000T
DSC1001CI5-150.0000T
DSC1004CI2-027.0000T
DSC1004CI2-033.0000T
DSC1004CI2-054.0000T
DSC1001CI5-080.0000T
DSC1004CI5-050.0000T
DSC1004CI5-125.0000T
DSC8001CI2T
DSC1001CI1-060.0000T
DSC1001CI2-007.3728T
DSC1001CI2-044.2360T
DSC1003CI5-025.0000T
DSC1001CI1-033.3330T
DSC1001CI2-066.6666B
DSC1004CI5-016.0000T
DSC1001CI2-072.0000T
DSC1001CI2-028.3220T
DSC1001CI2-108.0000T
DSC1001CI2-043.0000T
DSC1001CI1-012.0000T
DSC1001CI2-019.2000T
DSC1001CI2-038.4000T
DSC1001CI2-052.0000T
DSC1001CI2-025.0000B
DSC1003CI2-025.0000T
DSC1003CI2-050.0000T
DSC1001CI2-001.9512T
DSC1001CI2-033.3330T
DSC1001CI5-024.3050T
DSC1001CI5-033.3300T
DSC1001CI5-014.3181T
DSC1001CI5-026.8000T
DSC1001CI2-026.8000T
DSC1001CI2-010.4858T
DSC1004CI2-098.3040T
DSC1001CI1-031.9488T
DSC1003CI5-099.7200T
DSC1001CI1-004.0000T
DSC2010FI2-A0024
DSC2010FI2-B0004

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC2010FI2-B0005

DSC2010FI2-B0009

DSC2011FI1-F0017

DSC2011FI2-E0001

DSC2011FI2-E0005

DSC2011FI2-F0016

DSC2011FI2-F0017

DSC2011FI2-F0021

DSC2020FI2-B0012

DSC2022FI2-F0001

DSC2030FI2-C0001

DSC2030FI2-C0004

DSC2030FI2-C0006

DSC2010FI2-A0017

DSC2030FI2-C0012

DSC2030FI5-C0001

DSC2031FI2-J0001

DSC2033FI1-G0002

DSC2033FI2-G0001

DSC2033FI2-G0002

DSC2033FI2-G0004

DSC2033FI2-G0006

DSC2033FI2-G0007

DSC2044FI1-H0006

DSC2042FI2-M0005

DSC2044FI2-F0012

DSC2044FI2-H0001

DSC1001CL2-006.0052T

DSC1001CL1-040.0000T

DSC1003CL1-020.0000T

DSC1001CL1-006.0053T

DSC1001CL3-025.0000T

DSC1001CL2-006.0053T

DSC1001CE2-033.3333T

DSC1001CL3-040.0000T

DSC1004CL2-030.0000T

DSA1001CL2-033.3300TVAO

DSA1001CL2-033.3333TVAO

DSA1001CL2-125.0000TVAO

DSA1001CL3-080.0000TVAO

DSA1001CL3-133.3330TVAO

DSC1001BE1-016.0000T

DSC1001BE1-024.0000T

DSC1001BE1-025.0000T

DSC1001BE1-048.0000T

DSC1001BE1-050.0000T

DSC1001BE1-125.0000T

DSC1001BE1-133.3300T

DSC1001BE2-012.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC100TBE2-125.0000T
DSC1001BL1-027.0000T
DSC1001BL1-048.0000T
DSC1001BL2-027.0000T
DSC1001BL2-050.0000T
DSC1001BL5-008.0000T
DSC400-1111Q0110KE1
DSC400-1111Q0110KE2
DSC400-1111Q0111KE1
DSC400-1111Q0111KE2
DSC400-4111Q0112KE1
DSC400-4111Q0112KE2
DSC400-4334Q0023KE1
DSC400-4334Q0023KE2
DSC400-1133Q0113KE1
DSC400-1133Q0113KE2
DSC400-0101Q0114KE1
DSC400-0101Q0114KE2
DSC400-0101Q0115KE1
DSC400-0101Q0115KE2
DSC400-0111Q0116KE1
DSC400-0111Q0116KE2
DSC400-0111Q0117KE1
DSC400-0111Q0117KE2
DSC400-2222Q0118KE1
DSC400-2222Q0118KE2
DSC400-0244Q0009KE1
DSC400-0244Q0009KE2
DSC400-0101Q0119KE1
DSC400-0101Q0119KE2
DSC400-1111Q0120KE1
DSC400-1111Q0120KE2
DSC400-0111Q0026KE1
DSC400-0111Q0026KE2
DSC400-1111Q0121KE1
DSC400-1111Q0121KE2
DSC400-1114Q0122KE1
DSC400-1114Q0122KE2
DSC400-0321Q0123KE1
DSC400-0321Q0123KE2
DSC400-3333Q0124KE1
DSC400-3333Q0124KE2
DSC400-1331Q0125KE1
DSC400-1331Q0125KE2
DSC400-1333Q0126KE1
DSC400-1333Q0126KE2
DSC400-0223Q0127KE1
DSC400-0223Q0127KE2
DSC400-0133Q0128KE1

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-0133Q0128KE2
DSC400-0331Q0128KE1
DSC400-0331Q0128KE2
DSC400-0101Q0129KE1
DSC400-0101Q0129KE2
DSC400-3333Q0130KE1
DSC400-3333Q0130KE2
DSC400-3111Q0131KE1
DSC400-3111Q0131KE2
DSC400-4111Q0131KE1
DSC400-4111Q0131KE2
DSC400-1111Q0132KE1
DSC400-1111Q0132KE2
DSC400-0311Q0026KE1
DSC400-0311Q0026KE2
DSC400-0211Q0026KE1
DSC400-0211Q0026KE2
DSC400-1111Q0133KE1
DSC400-1111Q0133KE2
DSC400-1121Q0134KE1
DSC400-1121Q0134KE2
DSC400-1411Q0135KE1
DSC400-1411Q0135KE2
DSC400-0212Q0136KE1
DSC400-0212Q0136KE2
DSC400-1111Q0137KE1
DSC400-1111Q0137KE2
DSC1123CI5-100.0000T
DSC1123CI2-020.0000T
DSC1123CI1-027.0000T
DSC1123CI2-333.3333T
DSC1123CI2-312.5000T
DSC1101CI1-025.0000T
DSC1103CI1-125.0000T
DSC1124CI5-156.2578T
DSC1103CI2-148.3500T
DSC1103CI2-148.5000T
DSC1123CI1-156.2500T
DSC1123CI2-300.0000T
DSC1123CI2-200.0000T
DSC1123CI5-125.0000T
DSC1123CI5-032.0000T
DSC1123CI5-040.0000T
DSC1124CI1-156.2500T
DSC1124CI2-100.0000T
DSC1124CI5-156.2422T
DSC1124CI2-200.0000T
DSC1124CI5-100.0000T
DSC1123CI2-062.5000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103CI5-233.2090T
DSC1123CI2-025.0000T
DSC8121CI2T
DSC8123CI2T
DSC1121CI2-030.0000T
DSC1121CI2-051.8400T
DSC1122CI1-156.2500TA
DSC1124CI1-156.2500TA
DSC1121CI1-050.0000T
DSC1121CI5-016.6667T
DSC1121CI5-025.0000T
DSC1121CI5-027.0000T
DSC1121CI5-066.0000T
DSC1121CI5-117.0000T
DSC1103CI1-122.8800T
DSC1121CI2-027.0000T
DSC1101CI1-125.0000T
DSC1102CI5-150.0000T
DSC1123CI1-122.8800T
DSC1121CI5-016.0000T
DSC1121CI2-012.0000T
DSC1104CI5-125.0000T
DSC1121CI2-066.6667T
DSC1124CI2-156.2500T
DSC1102CI1-050.0000T
DSC1102CI1-156.2500T
DSC1102CI1-025.0000T
DSC400-3333Q0093KI2
DSC400-3333Q0094KI1
DSC400-3333Q0094KI2
DSC400-4334Q0022KI1
DSC400-4334Q0022KI2
DSC400-0444Q0009KI1
DSC400-0444Q0009KI2
DSC400-1111Q0095KI1
DSC400-1111Q0095KI2
DSC400-0101Q0096KI1
DSC400-0101Q0096KI2
DSC400-3331Q0097KI1
DSC400-3331Q0097KI2
DSC400-3331Q0098KI1
DSC400-3331Q0098KI2
DSC400-3333Q0099KI1
DSC400-3333Q0099KI2
DSC400-3133Q0100KI1
DSC400-3133Q0100KI2
DSC400-0103Q0102KI1
DSC400-0103Q0102KI2
DSC400-0401Q0103KI1

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-0401Q0103KI2
DSC400-2222Q0104KI1
DSC400-2222Q0104KI2
DSC400-2222Q0105KI1
DSC400-2222Q0105KI2
DSC400-3333Q0104KI1
DSC400-3333Q0104KI2
DSC400-0202Q0106KI1
DSC400-0202Q0106KI2
DSC400-0202Q0107KI1
DSC400-0202Q0107KI2
DSC400-0202Q0108KI1
DSC400-0202Q0108KI2
DSC400-0202Q0109KI1
DSC400-0202Q0109KI2
DSC400-1111Q0110KI1
DSC400-1111Q0110KI2
DSC400-1111Q0111KI1
DSC400-1111Q0111KI2
DSC400-4111Q0112KI1
DSC400-4111Q0112KI2
DSC400-4334Q0023KI1
DSC400-4334Q0023KI2
DSC400-1133Q0113KI1
DSC400-1133Q0113KI2
DSC400-0101Q0114KI1
DSC400-0101Q0114KI2
DSC400-0101Q0115KI1
DSC400-0101Q0115KI2
DSC400-0111Q0116KI1
DSC400-0111Q0116KI2
DSC400-0111Q0117KI1
DSC400-0111Q0117KI2
DSC400-2222Q0118KI1
DSC400-2222Q0118KI2
DSC400-0244Q0009KI1
DSC400-0244Q0009KI2
DSC400-0101Q0119KI1
DSC400-0101Q0119KI2
DSC400-1111Q0120KI1
DSC400-1111Q0120KI2
DSC400-0111Q0026KI1
DSC400-0111Q0026KI2
DSC400-1111Q0121KI1
DSC400-1111Q0121KI2
DSC400-1114Q0122KI1
DSC400-1114Q0122KI2
DSC400-0321Q0123KI1
DSC400-0321Q0123KI2

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-3333Q0124KI1
DSC400-3333Q0124KI2
DSC400-1331Q0125KI1
DSC400-1331Q0125KI2
DSC400-1333Q0126KI1
DSC400-1333Q0126KI2
DSC400-0223Q0127KI1
DSC400-0223Q0127KI2
DSC400-0133Q0128KI1
DSC400-0133Q0128KI2
DSC400-0331Q0128KI1
DSC400-0331Q0128KI2
DSC400-0101Q0129KI1
DSC400-0101Q0129KI2
DSC400-3333Q0130KI1
DSC400-3333Q0130KI2
DSC400-3111Q0131KI1
DSC400-3111Q0131KI2
DSC400-4111Q0131KI1
DSC400-4111Q0131KI2
DSC400-1111Q0132KI1
DSC400-1111Q0132KI2
DSC400-0311Q0026KI1
DSC400-0311Q0026KI2
DSC400-0211Q0026KI1
DSC400-0211Q0026KI2
DSC400-1111Q0133KI1
DSC400-1111Q0133KI2
DSC400-1121Q0134KI1
DSC400-1121Q0134KI2
DSC400-1411Q0135KI1
DSC400-1411Q0135KI2
DSC400-0212Q0136KI1
DSC400-0212Q0136KI2
DSC400-1111Q0137KI1
DSC400-1111Q0137KI2
DSC400-0111Q0138KI1
DSC400-0111Q0138KI2
DSC400-0111Q0139KI1
DSC400-0111Q0139KI2
DSC400-0144Q0140KI1
DSC400-0144Q0140KI2
DSC400-1221Q0141KI1
DSC400-1221Q0141KI2
DSC400-0434Q0009KI1
DSC400-0434Q0009KI2
DSC400-0313Q0136KI1
DSC400-0313Q0136KI2
DSC400-1111Q0142KI1

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-1111Q0142KI2
DSC400-1111Q0143KI1
DSC400-1111Q0143KI2
DSC400-0333Q0144KI1
DSC400-0333Q0144KI2
DSC400-3333Q0145KI1
DSC400-3333Q0145KI2
DSC1121CI5-024.0000T
DSC1123CI1-025.0000T
DSC1101CI2-060.0000T
DSC1103CI2-072.0000T
DSC1101CI2-036.0000T
DSC1123CI2-360.0000T
DSC1123CI2-010.0000T
DSC1103CI3-060.0000T
DSC1103CI3-150.0000T
DSC1103CI3-175.0000T
DSC1103CI1-150.0000T
DSC1103CI2-066.0000T
DSC1102CI5-020.0000T
DSC1101CI5-016.0000T
DSC1101CI5-008.0000T
DSC1121CI2-066.0000T
DSC1124CI2-133.3300T
DSC1103CI2-133.3300T
DSC1102CI1-212.5000T
DSC1103CI1-300.0000T
DSC1104CI2-200.0000T
DSC1101CI5-157.2864T
DSC1101CI1-024.0000T
DSC1124CI2-125.0000T
DSC1123CI5-066.6670T
DSC1123CI2-148.3516T
DSC1101CI5-040.0000T
DSC1121CI2-156.0063T
DSC1103CI3-135.0000T
DSC1121CI2-045.0000T
DSC1121CI2-055.0000T
DSC1123CI3-100.0000T
DSC1123CI3-135.0000T
DSC1123CI3-165.0000T
DSC1123CI3-200.0000T
DSC1121CM1-027.0000T
DSC1101BI5-050.0000T
DSC1104BI5-100.0000T
DSC1121BI2-013.0000T
DSC1121BI2-025.0000T
DSC1121BI2-050.0000T
DSC1121BI2-120.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121BI2-125.0057T
DSC1121BI2-150.0000T
DSC1123BI1-200.0000T
DSC1122BI2-074.2500T
DSC1122BI2-075.0000T
DSC1123BI2-025.0000T
DSC1122BI2-133.3300T
DSC1122BI2-148.5000T
DSC1122BI2-150.0000T
DSC1123BI1-150.0000T
DSC1123BI5-100.0000T
DSC1123BI2-100.0000T
DSC1123BI5-155.5200T
DSC1123BI5-156.2500T
DSC1123BI2-156.2500T
DSC1123BI2-200.0000T
DSC1123BI2-212.5000T
DSC1123BI5-200.0000T
DSC1123BI5-148.3516T
DSC1124BI1-100.0000T
DSC1124BI2-100.0000T
DSC1124BI2-125.0000T
DSC1124BI2-156.2500T
DSC8102BI2T
DSC8123BI2T
DSC8103BI2T
DSC1122BI2-156.2500T
DSC1121BI2-080.0000T
DSC1122BI2-100.0000T
DSC1122BI2-114.2850T
DSC1122BI2-155.5200T
DSC1102BI1-100.0000T
DSC1122BI1-100.0000T
DSC1121BI2-012.2880T
DSC1101BI5-133.0000T
DSC1123BI2-125.0000T
DSC1123BI2-148.5000T
DSC1102BI2-125.0000T
DSC1102BI2-153.6000T
DSC1103BI2-125.0000T
DSC1121BI2-025.0007T
DSC1121BI2-156.2540T
DSC1123BI1-156.2500T
DSC1102BI2-100.0000T
DSC1122BI5-400.0000T
DSC1104BI2-100.0000T
DSC1123BI1-125.0000T
DSC1121BI2-048.0000T
DSC1123BI1-100.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121BI2-100.0000T
DSC1121BI2-125.0000T
DSC8123BI5T
DSC1122BI2-156.2539T
DSC1124BI5-100.0000T
DSC1103BI2-100.0000T
DSC6001JI2B-012.0000
DSC6011JI2B-008.0000
DSC6121JI3B-01GP
DSC6311JI2CB-025.0000
DSC6111JI3B-019.2000
DSC6331JI1BB-018.4320
DSC6001JI2B-007.3730
DSC6301JI1B-050.0000
DSC6102JI1B-500K000
DSC6101JI1B-019.2000
DSC6021JI1B-01H4
DSC6331JI1BB-024.0000
DSC6001JI3B-005K280
DSC6001JI3B-004K280
DSC6021JI1B-01HA
DSC6003JI1B-100K000
DSC6011JI1B-003.6864
DSC6021JI2B-01HM
DSC6112JI2B-024.0000
DSC6101JI3B-038.4000
DSC6001JI1B-024.0000
DSC6332JI3AB-050.0000
DSC6332JI3FB-050.0000
DSC6001JI1B-040.0000
DSC6001JI2B-042.5000
DSC6021JI2B-01J5
DSC6013JI2B-004.0960
DSC6331JI1DB-075.0000
DSC6331JI1AB-025.0000
DSC6311JI1FB-075.0000
DSC6101JI2B-012.0000
DSC6001JI1B-008K000
DSC6001JI1B-008.0000
DSC6001JI2B-008.0000
DSC6011JI3B-020.0000
DSC6311JI1BB-012.0000
DSC6101JI1B-080.0000
DSC6021JI2B-01KQ
DSC6011JI1B-024.0000
DSC6121JI2B-01MH
DSC6111JI2B-100.0000
DSC6111JI2B-074.2500
DSC6111JI2B-027.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6001JI1B-006.5536
DSC6331JI2AB-010.0000
DSC6331JI2AB-016.0000
DSC6331JI2AB-100.0000
DSC6331JI2CB-012.2880
DSC6001JI3B-259K200
DSC6102JI1B-080.0000
DSC6101JI2B-037.1250
DSC6001JI2B-001.0000
DSC6001JI2B-016.0000
DSC6003JI2B-250K000
DSA6001JI1B-032K768VAO
DSA6001JI1B-080.0000VAO
DSA6003JI1B-020.0000VAO
DSA6013JI1B-300K000VAO
DSA6101JI1B-050.0000VAO
DSA6111JI1B-008.0000VAO
DSA6331JI1CB-027.0000VAO
DSA6003JI2B-032K768VAO
DSA6101JI2B-012.2880VAO
DSA6101JI2B-018.4320VAO
DSA6101JI2B-032K768VAO
DSA6101JI2B-036.8640VAO
DSA6101JI2B-100.0000VAO
DSA6111JI2B-032K768VAO
DSA6331JI2FB-024.5760VAO
DSA6001JI3B-005.0000VAO
DSA6011JI3B-032K768VAO
DSA6023JI3B-01JGVAO
DSC612PI3A-010J
DSC612PI3A-010K
DSC612PI3A-010T
DSC613PI3A-0105
DSC612PI2A-012Q
DSC613PI2A-0131
DSC612PI2A-0130
DSC612PI2A-013C
DSC612PI3A-013J
DSC612PI2A-015P
DSC612PI2A-0166
DSC612PI1A-016S
DSC612PI3A-0130
DSC613PI3A-0195
DSC613PI3A-01CR
DSC613PI3A-01D4
DSC613PI3A-01EY
DSC612PI2A-01GV
DSC612PI1A-01HT
DSC612PI3A-012Y

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC612PI2A-01MI
DSC612PI2A-01MD
DSC612PI2A-014J
DSC612PI2A-01JR
DSC612PI2A-012Y
DSC613PI2A-01JS
DSC613PI2A-01JT
DSC613PI2A-01JU
DSC613PI2A-01JV
DSC612PI2A-01KW
DSC1001BL1-060.0000
DSC1001BE2-012.2880
DSC1001BE2-014.7450
DSC1001BE1-001.8432
DSC1001BE1-026.0000
DSC1001BE2-048.0000
DSC1001BE1-014.3182
DSC1001BE1-014.7456
DSC1001BE2-014.7456
DSC1001BE1-133.0000
DSC1001BL5-001.1385
DSC1001BL5-001.1386
DSC1001BL5-001.1387
DSC1001BL5-001.1388
DSC1001BL5-001.1389
DSC1001BL5-108.0000
DSC1001BE5-020.0000
DSC1001BL5-033.3330
DSC1001BL5-026.7000
DSC1001BL5-026.6500
DSC1001BE5-016.0000
DSC1001BL2-048.0000
DSC1001BL2-026.0000
DSC1003BE1-025.0000
DSC1001BL5-026.0000
DSC1001BL5-120.0000
DSC1001BL5-014.7456
DSC1001BL5-033.0000
DSC1001BE2-090.0000
DSC1001BL2-024.0000
DSC1001BL5-125.0000
DSC1001BE5-024.0000
DSC1001BL5-030.0000
DSC1001BE1-066.6666
DSC1001BL5-049.5000
DSC1001BE1-001.4850
DSC1003BL1-010.0000
DSC1001BL5-072.0000
DSC1001BL5-066.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1000BL5-PROG

DSC1000BL5-PROG

DSC1001BE5-033.3330

DSC1001BL5-075.0000

DSC1001BL5-004.0000

DSC1003BE1-024.0000

DSC1001BE5-012.0000

DSC1001BE3-026.0000

DSC1001BL5-058.9824

DSC1001BE1-060.0000

DSC1003BL3-030.0000

DSC1003BL3-008.1920

DSC1001BE3-022.1184

DSC1003BL3-020.0000

DSC1003BL3-032.7680

DSC1003BL3-013.8420

DSC1003BL3-025.0000

DSC1003BL3-010.2400

DSC1003BL3-018.4320

DSC1001BL5-032.0000

DSC1001BE5-030.6400

DSC1001BL5-106.2500

DSC1001BL2-125.0000

DSC1004BL2-025.0000

DSC1004BL2-024.0000

DSC1001BE1-004.0625

DSC1001BE1-004.0960

DSC1001BL2-012.0000

DSC1001BE5-027.0000

DSC1001BE5-030.0000

DSC1001BE1-033.3333

DSC1001BL2-012.5000

DSC1001BL3-001.0000

DSC1001DE1-018.4320

DSC1001DE1-019.6608

DSC1001DE1-024.0000

DSC1001DE1-027.0000

DSC1001DE1-048.0000

DSC1001DE1-074.2500

DSC1001DE1-100.0000

DSC1001DE1-125.0000

DSC1001DE2-016.0000

DSC1001DE2-050.0000

DSC1001DE2-032.0000

DSC1001DE5-016.0000

DSC1001BI2-007.3728T

DSC1001BI2-027.0000T

DSC1001BI2-028.8000T

DSC1001BI2-032.0000T

Date: Monday, November 16, 2020

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001BI2-033.3330T
DSC1001BI2-040.0000T
DSC1001BI2-042.5000T
DSC1001BI2-044.0000T
DSC1001BI2-048.0000T
DSC1001BI2-049.0908T
DSC1001BI2-050.0000T
DSC1001BI2-059.0000T
DSC1001BI2-062.5000T
DSC1001BI2-080.0000T
DSC1001BI2-100.0000T
DSC1001BI2-106.2500T
DSC1001BI2-125.0000T
DSC1001BI2-133.0000T
DSC1001BI2-148.5000T
DSC1001BI5-003.6864T
DSC1001BI5-004.0000T
DSC1001BI5-007.3728T
DSC1001BI5-008.0000T
DSC1001BI5-010.0000T
DSC1001BI5-012.0000T
DSC1001BI5-016.0000T
DSC1001BI5-024.0000T
DSC1001BI5-025.0000T
DSC1001BI5-032.0000T
DSC1001BI5-033.3330T
DSC1001BI5-040.0000T
DSC1001BI5-048.0000T
DSC1001BI5-050.0000T
DSC1001BI5-066.0000T
DSC1001BI5-066.6666T
DSC1001BI5-072.0000T
DSC1001BI5-100.0000T
DSC1001BI5-120.0000T
DSC1001BI5-125.0000T
DSC1003BI1-060.0000T
DSC8001BI2T
DSC6011JI2B-720K000T
DSC6013JI2B-001.0000T
DSC6013JI2B-032K768T
DSC6013JI2B-250K000T
DSC6013JI2B-432K000T
DSC6013JI2B-720K000T
DSC6111JI2B-032K768T
DSC6111JI2B-250K000T
DSC6111JI2B-432K000T
DSC6111JI2B-720K000T
DSC6112JI2B-001.0000T
DSC6112JI2B-032K768T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6112JI2B-250K000T
DSC6112JI2B-432K000T
DSC6112JI2B-720K000T
DSC6111JI2B-004K000T
DSC6112JI2B-004K000T
DSC6011JI1B-012.0000T
DSC6011JI3B-025.0000T
DSC6101JI2B-025.0000T
DSC6102JI2B-025.0000T
DSC6102JI2B-027.0000T
DSC6013JI1B-032.7680T
DSC6013JI1B-008.0000T
DSC6111JI1B-025.0000T
DSC400-0202Q0106KI1T
DSC400-0202Q0106KI2T
DSC400-0202Q0107KI1T
DSC400-0202Q0107KI2T
DSC400-0202Q0108KI1T
DSC400-0202Q0108KI2T
DSC400-0202Q0109KI1T
DSC400-0202Q0109KI2T
DSC400-1111Q0110KI1T
DSC400-1111Q0110KI2T
DSC400-1111Q0111KI1T
DSC400-1111Q0111KI2T
DSC400-4111Q0112KI1T
DSC400-4111Q0112KI2T
DSC400-4334Q0023KI1T
DSC400-4334Q0023KI2T
DSC400-1133Q0113KI1T
DSC400-1133Q0113KI2T
DSC400-0101Q0114KI1T
DSC400-0101Q0114KI2T
DSC400-0101Q0115KI1T
DSC400-0101Q0115KI2T
DSC400-0111Q0116KI1T
DSC400-0111Q0116KI2T
DSC400-0111Q0117KI1T
DSC400-0111Q0117KI2T
DSC400-2222Q0118KI1T
DSC1001BL5-010.0000T
DSC1001BL5-012.0000T
DSC8001BL5T
DSC1001BL5-024.0000T
DSC1001BL5-024.5760T
DSC1001BL5-025.0000T
DSC1001BL5-040.0000T
DSC1001BL5-048.0000T
DSC1001BL5-066.6666T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001BL5-100.0000T
DSC1001BL5-133.3330T
DSC1001BL5-150.0000T
DSC1001BL2-025.0000T
DSC1001BL5-050.0000T
DSC1001BL5-016.0000T
DSC1001BL5-080.0000T
DSC1001BE5-022.5792T
DSC1001BL5-020.0000T
DSC1001BE1-012.0000T
DSC1001BL1-016.0000T
DSC1001BE5-064.0000T
DSC1001BL5-064.0000T
DSC1001BL2-020.0000T
DSC1001BL1-060.0000T
DSC1001BE2-012.2880T
DSC1001BE2-014.7450T
DSC1001BE1-001.8432T
DSC1001BE1-026.0000T
DSC1001BE2-048.0000T
DSC1001BE1-014.3182T
DSC1001BE1-014.7456T
DSC1001BE2-014.7456T
DSC1001BE1-133.0000T
DSC1001BL5-001.1385T
DSC1001BL5-001.1386T
DSC1001BL5-001.1387T
DSC1001BL5-001.1388T
DSC1001BL5-001.1389T
DSC1001BL5-108.0000T
DSC1001BE5-020.0000T
DSC1001BL5-033.3330T
DSC1001BL5-026.7000T
DSC1001BL5-026.6500T
DSC1001BE5-016.0000T
DSC1001BL2-048.0000T
DSC1001BL2-026.0000T
DSC1003BE1-025.0000T
DSC1001BL5-026.0000T
DSC1001BL5-120.0000T
DSC1001BL5-014.7456T
DSC1001BL5-033.0000T
DSC1001BE2-090.0000T
DSC1001BL2-024.0000T
DSC1001BL5-125.0000T
DSC1001BE5-024.0000T
DSC1001BL5-030.0000T
DSC1001BE1-066.6666T
DSC1001BL5-049.5000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001BE1-001.4850T
DSC1003BL1-010.0000T
DSC1001BL5-072.0000T
DSC1001BL5-066.0000T
DSC1000BL3-PROGT
DSC1000BL5-PROGT
DSC1001BE5-033.3330T
DSC1001BL5-075.0000T
DSC1001BL5-004.0000T
DSC1003BE1-024.0000T
DSC1001BE5-012.0000T
DSC1001BE3-026.0000T
DSC612RI2A-01B2
DSC612PI2A-01JQ
DSA613PI3A-01G8VAO
DSC612RI3A-010G
DSC612RI3A-010J
DSC613RI3A-010U
DSC612RI1A-012M
DSC613RI2A-012S
DSC612RI2A-012P
DSC612RI3A-012V
DSC613RI3A-012W
DSC612RI1A-0133
DSC613RI2A-0134
DSC613RI2A-013G
DSC612RI2A-013H
DSC613RI3A-014C
DSC612RI1A-0159
DSC613RI2A-015H
DSC613RI2A-016P
DSC612RI1A-016Q
DSC613RI2A-017C
DSC612RI1A-017M
DSC612RI3A-019C
DSC612RI2A-01A0
DSC612RI2A-01A2
DSC612RI2A-01A3
DSC613RI3A-016P
DSC613RI3A-01A4
DSC612RI1A-01B2
DSC1103BI2-135.0000T
DSC1103BI2-148.5000T
DSC1102BI2-156.2500T
DSC1102BI2-155.2500T
DSC1102BI2-114.2850T
DSC1101BI2-125.0000T
DSC1121BI2-022.5792T
DSC1101BI2-024.5760T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1123BI2-155.5200T
DSC1121BI2-114.2850T
DSC1121BI2-024.5760T
DSC1121BI2-033.3330T
DSC1102BI2-155.5200T
DSC1122BI2-156.2570T
DSC1123BI2-156.2570T
DSC1123BI2-300.0000T
DSC1122BI2-020.0000T
DSC1122BI2-322.0000T
DSC1123BI2-270.0000T
DSC1123BI2-210.0000T
DSC1123BI2-180.0000T
DSC1123BI2-206.0000T
DSC1123BI2-068.0000T
DSC1121BI1-008.0000T
DSC1121BI2-156.2500T
DSC1124BI5-020.0000T
DSC1123BI2-050.0013T
DSC1103BI2-200.0000T
DSC1121BI2-016.3840T
DSC1121BI2-020.0000T
DSC1121BI2-131.0720T
DSC1103BI2-050.0000T
DSC1101BI2-125.0031T
DSC1102BI1-010.0000T
DSC1123BI5-148.5000T
DSC1123BI5-010.0000T
DSC1124BI2-027.0000T
DSC1101BI5-010.0000T
DSC1122BI2-125.0000T
DSC1123BI2-156.0000T
DSC1122BI1-025.0000T
DSC1121BI2-008.0000T
DSC1123BI2-034.0000T
DSC1101BI3-025.0000T
DSC1101BI2-125.0037T
DSC1124BI1-027.0000T
DSC1121BI5-022.5792T
DSC1121BI5-024.5760T
DSC1123BI2-125.0037T
DSC1123BI5-125.0000T
DSC1121BI3-100.0000T
DSC1121BI5-024.0000T
DSC1121BI2-012.0000T
DSC1123BI3-050.0000T
DSC1101BI2-008.0000T
DSC1103BI2-062.5000T
DSC1101BI5-016.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1101BI5-012.0000T
DSC1101BI5-020.0000T
DSC1123BI2-010.0000T
DSC1121BI5-045.1854T
DSC1121BI5-049.1520T
DSC1104BI1-027.0000T
DSC1101BI3-013.5600T
DSC1101BI2-027.1200T
DSC1124BI3-027.0000T
DSC1121BI1-020.0000T
DSC1101BI1-145.2000T
DSC1103BI1-156.2500T
DSC1122BI3-166.6000T
DSC1121BI5-125.0000T
DSC1121BI5-025.6000T
DSC1121BI5-125.0000B
DSC1121BI2-040.6800T
DSC1123BI3-080.0000T
DSC1103BI2-235.0000T
DSC1123BI1-148.5000T
DSC1103BI5-148.5000T
DSC1123BI5-040.0000T
DSC1103BI2-156.2500T
DSC8103AI2T
DSC8123AL2T
DSC1101AI2-148.5000T
DSC1121AI2-156.2500T
DSC8102AI2T
DSC1123AI5-322.2656T
DSC1103AI1-125.0000T
DSC1103AI2-025.0000T
DSC1103AI2-100.0000T
DSC1103AI2-125.0000T
DSC1103AI2-130.0000T
DSC1103AI2-171.8181T
DSC1103AI2-200.0000T
DSC1121AI2-148.5000T
DSC1121AI2-053.1250T
DSC1123AI5-100.0000T
DSC1103AI5-120.0000T
DSC1104AI2-100.0000T
DSC1103AI5-156.2500T
DSC1001CI5-014.7456T
DSC1001CI5-008.1920T
DSC1001CI2-003.0720T
DSC1003CI2-024.0000T
DSC1003CI2-080.0000T
DSC1003CI1-070.0000T
DSC1001CI1-080.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CI5-022.0000T
DSC1001CI2-100.8000T
DSC1003CI2-027.0000T
DSC1001CI5-022.5792T
DSC1001CI2-024.3050T
DSC1001CI1-004.0960T
DSC1001CI5-003.2768T
DSC1001CI5-007.3728T
DSC1001CI2-003.2768T
DSC1001CI3-024.0000T
DSC1001CI3-025.0000T
DSC1001CI3-027.0000T
DSC1001CI3-013.8240T
DSC1001CI5-015.0000T
DSC1001CI5-144.0000T
DSC1001CI5-029.4912T
DSC1001CI2-133.3330T
DSC1001CI3-100.0000T
DSC1001CI2-074.1750T
DSC1001CI5-003.6864T
DSC1004CI2-024.5760T
DSC1001CI3-003.5790T
DSC1001CI1-018.4320T
DSC1001CI1-040.0000T
DSC1001CI2-066.0000T
DSC1001CI2-026.6363T
DSC1001CI1-064.0000T
DSC1001CI2-003.8000T
DSC1001CI3-012.0000T
DSC1001CI3-033.0000T
DSC1003CI5-080.0000T
DSC1001CI1-005.0000T
DSC1001CI3-019.2000T
DSC1001CI3-050.0000T
DSC1001CI1-004.9152T
DSC1003CI2-010.0000T
DSC1004CI5-121.5000T
DSC1001CI2-034.0000T
DSC1001CI5-037.4000T
DSC1004CI2-060.0000T
DSC1001CI2-004.0960T
DSC1001CI5-037.0879T
DSC1001CI2-013.0000T
DSC1004CI1-016.0000T
DSC1001CI1-028.6363T
DSC1001CI3-013.5000T
DSC1001CI1-008.1920T
DSC1001CI2-038.0000T
DSC1001CI3-004.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1004CI5-100.0000T
DSC1001CI5-013.5000T
DSC1001CI2-020.7500T
DSC1003CI5-040.0000T
DSC1001CI5-013.3300T
DSC1003CI2-020.0000T
DSC1001CI2-088.0000T
DSC1001CI2-020.0036T
DSC1001CI2-020.0037T
DSC1001CI1-003.5800T
DSC1001CI1-125.0000T
DSC1001CI2-029.5000T
DSC1001CI5-026.6000T
DSC1004CI5-025.0000T
DSC1004CI5-026.6000T
DSC1001CI5-099.9990T
DSC1001CI2-024.9600T
DSC1003CI1-025.0000T
DSC1001BI1-008.0000T
DSC1001BI1-010.0000T
DSC1001BI1-032.0000T
DSC1001BI1-022.1184T
DSC1001BI1-024.0000T
DSC1001BI1-024.5760T
DSC1001BI1-025.0000T
DSC1001BI1-027.0000T
DSC1001BI1-030.0000T
DSC1001BI1-040.0000T
DSC1001BI1-048.0000T
DSC1001BI1-050.0000T
DSC1001BI1-060.0000T
DSC1001BI1-125.0000T
DSC1001BI2-001.8432T
DSC1001BI2-002.0480T
DSC1001BI2-005.5296T
DSC1001BI2-006.0000T
DSC1001BI2-008.0000T
DSC1001BI2-012.0000T
DSC1001BI2-012.2880T
DSC1001BI2-014.7456T
DSC1001BI2-016.0000T
DSC1001BI2-016.3840T
DSC1001BI2-020.0000T
DSC1001BI2-020.0016T
DSC1001BI2-022.5790T
DSC1001BI2-024.0000T
DSC1001BI2-024.5760T
DSC1001BI2-025.0000T
DSC2040FI2-D0002

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC2040FI2-D0003
DSC2042FI2-M0004
DSC2010FI1-A0003
DSC2033FI2-F0046
DSC2033FI2-F0047
DSC2033FI2-F0048
DSC2133FI2-E0027
DSC2011FI2-F0050
DSC2041FI1-K0001
DSC2040FI2-B0021
DSC2033FI2-F0053
DSC2031FI2-F0023
DSC557-0333FI1
DSC2011FI1-F0054
DSC2030FI2-B0022
DSC2033FI2-H0005
DSC2033FI2-F0060
DSC2110FI1-A0012
DSC2033FI2-F0059
DSC2033FI2-F0012
DSC2111FI2-E0029
DSC2043FI1-F0058
DSC2011FI1-F0056
DSA557-0344FI0VAO
DSA557-0344FI1VAO
DSC1101CE1-024.0000
DSC1101CL2-016.3840
DSC1101CL2-020.0000
DSC1101CL5-027.0000
DSC1101CL5-040.0000
DSC1103CE1-200.0000
DSC1103CE2-135.0000
DSC1103CE2-200.0000
DSC1103CE5-150.0000
DSC1103CE5-156.2500
DSC1103CL5-106.2500
DSC8123CL1
DSC1121CE1-016.0000
DSC8123CL5
DSC1121CE1-025.0012
DSC1121CE5-012.2880
DSC1121CE5-024.5670
DSC1121CE2-025.0000
DSC1121CL2-024.7500
DSC613RI2A-01BC
DSC612RI3A-01CJ
DSC612RI2A-01CM
DSC612RI1A-01DY
DSC613RI2A-01G0

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC612RI1A-01GC
DSC612RI2A-01GE
DSC613RI2A-01GJ
DSC612RI1A-01GV
DSC613RI3A-0131
DSC613RI3A-01J3
DSC612RI2A-01J8
DSC612RI3A-01M3
DSC613RI3A-01M7
DSC613RI3A-01M8
DSC612RI2A-01K9
DSC612RI2A-01KA
DSC612RI2A-01KK
DSC612RI3A-013C
DSC612RI1A-01JM
DSC612RI3A-01K3
DSC612RI3A-01P3
DSA613RI3A-01BMVAO
DSC6001HL2B-026.0000
DSC6003HL2B-024.0000
DSC6003HL3B-014.0000
DSC6003HL3B-032K768
DSC6101HL3B-025.0000
DSC6101HL3B-027.0000
DSC6041HL2B-009.8460
DSC6331HE1CB-024.0000
DSC6013HE1B-032K768
DSC6021HE3B-0157
DSC6023HE3B-015C
DSC6023HE3B-015D
DSC6331HL1AB-072.5000
DSC6102HL2B-072.5000
DSC6101HL2B-072.5000
DSC6101HL2B-072.0000
DSC6011HE1B-084K000
DSC6013HE2B-084K000
DSC6001HE1B-011.0592
DSC6301HL1FB-020.0000
DSC6111HL1B-032K768
DSC6101HL3B-024.0000
DSC6111HL1B-010.0000
DSC6111HL1B-014.7456
DSC6111HL1B-024.0000
DSC6001HE3B-027.1200
DSC6011HE2B-050.0000
DSC6021HE2B-01AB
DSC6011HL3B-003.0720
DSC6001HL2B-009.8460
DSC6001HL2B-012.0000

Date: Monday, November 16, 2020

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC601HE2B-008.7040
DSC6001HE2B-015.0000
DSC6053HE1B-006.2500
DSC6013HE2B-048.0000
DSC6013HL2B-048.0000
DSC6011HE2B-064.0000
DSC6001HE1B-008.0000
DSC6111HE1B-050.0000
DSC6001HE1B-001.0000
DSA6301HL1AB-027.0000VAO
DSA6011HL2B-032K768VAO
DSA6101HL3B-072.0000VAO
DSC6101ML2B-066.6666
DSC6001ML3B-026.0000
DSC6003ML3B-008.1920
DSC6101ML3B-025.0000
DSC6101ML3B-027.0000
DSC6011ME2B-050.0000
DSC6311ML1AB-027.0000
DSC6003ML2B-032K768
DSC6021ML3B-015R
DSC6001ML2B-040.0000
DSC6101ML3B-016.6666
DSC6101ML3B-014.7456
DSC6101ML2B-072.0000
DSC6001ML2B-025.0000
DSC6001ME1B-050.0000
DSC6001ME1B-075.0000
DSC6111ME1B-012.0000
DSC6311ML2DB-016.6700
DSC6011ML3B-003.0720
DSC6101ML3B-032.0000
DSC6301ML1EB-010.0000
DSC6301ML1AB-010.0000
DSC6003ME1B-013.1072
DSC6001ME1B-008.0000
DSC6001ME2B-009.0000
DSC6001ME1B-052.4280
DSC6011ME2B-012.0000
DSA6101ML2B-026.0000VAO
DSA6101ML3B-014.7456VAO
DSA6101ML3B-016.6666VAO
DSA6101ML3B-025.0000VAO
DSA6101ML3B-033.3333VAO
DSA6011ML1B-025.0000VAO
DSC612NL3A-012R
DSC612NL3A-014E
DSC612NL2A-014E
DSC612NL2A-0151

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC613NE2A-016W
DSC612NL3A-0142
DSC612NL3A-019A
DSA612NL2A-019BVAO
DSA612NL2A-01C1VAO
DSA612NL2A-01C3VAO
DSA612NL2A-01C4VAO
DSA612NL2A-01CPVAO
DSC6001JL2B-027.0000
DSC6101JL2B-033.3333
DSC6003JL3B-004.0096
DSC6003JL3B-007.3728
DSC6101JL3B-038.4000
DSC6101JL3B-050.0000
DSC6003JL3B-004.0960T
DSC6311JL1BB-028.6364
DSC6311JL1AB-028.6364
DSC6331JE1CB-024.0000
DSC6001JE1B-024.0000
DSC6003JE1B-024.0000
DSC6101JL2B-026.0000
DSC6111JE1B-033.3333
DSC6011JE2B-032K768
DSC1103BI2-200.0000
DSC6101JA3B-024.0000
DSC6011JA1B-040.0000
DSC6101JA2B-027.0000
DSA6101JA1B-027.0000VAO
DSA6111JA1B-027.0000VAO
DSA6112JA1B-027.0000VAO
DSA6311JA1AB-024.0000VAO
DSA6311JA1AB-025.0000VAO
DSA6311JA1AB-027.0000VAO
DSA6331JA1BB-100.0000VAO
DSA6331JA1CB-100.0000VAO
DSA6001JA2B-003K277VAO
DSA6001JA2B-019.2000VAO
DSA6001JA2B-032K768VAO
DSA6001JA2B-045.0000VAO
DSA6011JA2B-012.0000VAO
DSA6011JA2B-032K768VAO
DSA6021JA2B-01ARVAO
DSA6102JA2B-016.0000VAO
DSA6311JA2AB-024.0000VAO
DSA6311JA2AB-025.0000VAO
DSA6331JA2BB-025.0000VAO
DSA1001DL1-024.0000VAO
DSA1001DL1-024.5760VAO
DSA1001DL1-024.8000VAO

Date: Monday, November 16, 2020

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA1001DL1-024.9000VAO
DSA1001DL1-025.0000VAO
DSA1001DL1-025.1000VAO
DSA1001DL1-033.3330VAO
DSA1001DL1-048.0000VAO
DSA1001DL1-054.0000VAO
DSA1001DL1-060.0000VAO
DSA1001DL1-074.2500VAO
DSA1001DL1-100.0000VAO
DSA1001DL1-125.0000VAO
DSA1004DL1-100.0000VAO
DSA1004DL1-125.0000VAO
DSA1001DL2-006.0053VAO
DSA1001DL2-007.2000VAO
DSA1001DL2-008.0000VAO
DSA1001DL2-010.0000VAO
DSA1001DL2-016.0000VAO
DSA1001DL2-020.0000VAO
DSA1001DL2-024.0000VAO
DSA1001DL2-024.5640VAO
DSA1001DL2-024.5760VAO
DSA1001DL2-026.0000VAO
DSA1001DL2-027.0000VAO
DSA1001DL2-028.6364VAO
DSA1001DL2-030.0000VAO
DSA1001DL2-033.0000VAO
DSA1001DL2-033.3333VAO
DSA1001DL2-036.8640VAO
DSA1001DL2-037.1250VAO
DSA1001DL2-040.0000VAO
DSA1001DL2-048.0000VAO
DSA1001DL2-049.5000VAO
DSA1001DL2-050.0000VAO
DSA1001DL2-054.0000VAO
DSA1001DL2-066.0000VAO
DSA1001DL2-072.0000VAO
DSA1001DL2-080.0000VAO
DSA1001DL2-087.0655VAO
DSA1001DL2-100.0000VAO
DSA1001DL2-125.0000VAO
DSA1004DL2-072.0000VAO
DSA1001DL3-004.0000VAO
DSA1001DL3-006.0053VAO
DSA1001DL3-008.0000VAO
DSA1001DL3-012.2888VAO
DSA1001DL3-012.5000VAO
DSA1001DL3-016.0000VAO
DSA1001DL3-016.3840VAO
DSA1001DL3-020.0000VAO

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA1001DL3-022.5792VAO
DSA1001DL3-024.0000VAO
DSA1001DL3-025.0000VAO
DSA1001DL3-026.0000VAO
DSA1001DL3-027.0000VAO
DSA1001DL3-032.7680VAO
DSA1001DL3-033.0000VAO
DSA1001DL3-033.3330VAO
DSA1001DL3-045.0000VAO
DSA1001DL3-048.0000VAO
DSA1001DL3-054.0000VAO
DSA1001DL3-055.4666VAO
DSA1001DL3-060.0000VAO
DSA1001DL3-080.0000VAO
DSA1001DL3-100.0000VAO
DSA1001DL3-125.0000VAO
DSA1001DL1-027.0000VAO
DSA1001DL1-033.0000VAO
DSC1001AE1-016.6667
DSC1001AE1-033.3333
DSC1001AE1-025.0000
DSC1001AE1-033.0000
DSC1001AE1-048.0000
DSC1001AE1-050.0000
DSC1001AE1-125.0000
DSC1001AE1-133.0000
DSC1001AE2-100.0000
DSC1001AE2-125.0000
DSC1001AL2-027.0000
DSC1001AL5-007.3728
DSC1001AL5-012.0000
DSC1001AL5-016.0000
DSC1001AL5-004.0000
DSC1001AL5-024.5760
DSC1001AL5-025.0000
DSC1001AL5-016.3840
DSC1001AL5-018.4320
DSC1001AL5-080.0000
DSC1001AL5-100.0000
DSC1001AL5-032.0000
DSC1001AL5-040.0000
DSC1001AL5-050.0000
DSC8001AL2
DSC8001AL5
DSC1001AE1-066.6660
DSC1004AL2-001.0000
DSC1004AL1-001.0000
DSC1001AL5-001.8432
DSC1001AE1-019.6608

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001AE1-024.0000
DSC1001AL5-060.0000
DSC1001AL5-125.0000
DSC1001AE2-002.0480
DSC1001AL5-024.0000
DSC1001AE5-024.5760
DSC1001AE1-027.0000
DSC1001AL5-033.0000
DSC1001AL5-033.3333
DSC1001AE1-055.0000
DSC1001AL5-048.0000
DSC1001AL5-008.0000
DSC1001AE1-006.1440
DSC1001AE1-111.0000
DSC1001AL5-027.0000
DSC1001AE1-014.3182
DSC1001AE1-024.5761
DSC1001AE1-003.6864
DSC1001AE1-054.0000
DSC1001DL2-045.1584T
DSC1001DE5-037.4000T
DSC1001DL5-096.0000T
DSC1001DL2-066.0000T
DSC1003DL5-019.2000T
DSC1001DE5-012.0000T
DSC1001DL2-026.0000T
DSC1001DL2-019.2000T
DSC1003DL1-033.3333T
DSC1003DL1-024.5454T
DSC1004DL2-072.0000T
DSC1001DE2-120.0000T
DSC1004DL2-025.0000T
DSC1000DL3-PROGT
DSC1000DL5-PROGT
DSC1001DL2-054.0000T
DSC1001DL3-027.0000T
DSC1001DL3-024.0000T
DSC1001DL5-016.3840T
DSC1001DL2-016.3690T
DSC1001DL2-061.2500T
DSC1003DL2-033.3333T
DSC1001DL5-018.4320T
DSC1001DL5-033.3333T
DSC1001DL2-003.6864T
DSC613RE1A-0136
DSC612RL2A-0137
DSC612RL2A-013D
DSC612RL2A-013E
DSC612RL3A-0142

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC612RE1A-014J
DSC613RL1A-0131
DSC612RL1A-014S
DSC612RL2A-0130
DSC612RL2A-0168
DSC612RL2A-013C
DSC612RE1A-0169
DSC613RE2A-016Y
DSC613RE1A-017Q
DSC612RL2A-018K
DSC613RE1A-0197
DSC612RE1A-0199
DSC612RL3A-019B
DSC612RL1A-019T
DSC612RL3A-01AM
DSC612RE2A-01AT
DSC612RE1A-01B2
DSC613RE1A-01BV
DSC613RE2A-01DG
DSC612RL2A-01E7
DSC612RE1A-01GQ
DSC612RE2A-01GQ
DSC612RL3A-01KS
DSC612RE3A-01M0
DSC612RE2A-01MR
DSA612RL2A-01GAVAO
DSA612RL2A-01H6VAO
DSA612RL2A-01K9VAO
DSA612RL2A-01KMVAO
DSA612RL2A-01MGVAO
DSA613RL2A-016PVAO
DSC6001HL2B-026.0000T
DSC6003HL2B-024.0000T
DSC6003HL3B-014.0000T
DSC6003HL3B-032K768T
DSC6101HL3B-025.0000T
DSC6101HL3B-027.0000T
DSC6041HL2B-009.8460T
DSC6331HE1CB-024.0000T
DSC6013HE1B-032K768T
DSC6021HE3B-0157T
DSC6023HE3B-015CT
DSC6023HE3B-015DT
DSC6331HL1AB-072.5000T
DSC6102HL2B-072.5000T
DSC6101HL2B-072.5000T
DSC6101HL2B-072.0000T
DSC6011HE1B-084K000T
DSC6013HE2B-084K000T

Date: Monday, November 16, 2020

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6001HE1B-011.0592T
DSC6301HL1FB-020.0000T
DSC6111HL1B-032K768T
DSC6101HL3B-024.0000T
DSC6111HL1B-010.0000T
DSC6111HL1B-014.7456T
DSC6111HL1B-024.0000T
DSC6001HE3B-027.1200T
DSC6011HE2B-050.0000T
DSC6021HE2B-01ABT
DSC6011HL3B-003.0720T
DSC6001HL2B-009.8460T
DSC6001HL2B-012.0000T
DSC6011HE2B-008.7040T
DSC6001HE2B-015.0000T
DSC6053HE1B-006.2500T
DSC6013HE2B-048.0000T
DSC6013HL2B-048.0000T
DSC6011HE2B-064.0000T
DSC6001HE1B-008.0000T
DSC6111HE1B-050.0000T
DSC6001HE1B-001.0000T
DSA6301HL1AB-027.0000TVAO
DSA6011HL2B-032K768TVAO
DSA6101HL3B-072.0000TVAO
DSC6101ML2B-066.6666T
DSC6001ML3B-026.0000T
DSC6003ML3B-008.1920T
DSC6101ML3B-025.0000T
DSC6101ML3B-027.0000T
DSC6011ME2B-050.0000T
DSC6311ML1AB-027.0000T
DSC6003ML2B-032K768T
DSC6021ML3B-015RT
DSC6001ML2B-040.0000T
DSC6101ML3B-016.6666T
DSC6101ML3B-014.7456T
DSC6101ML2B-072.0000T
DSC6001ML2B-025.0000T
DSC6001ME1B-050.0000T
DSC6001ME1B-075.0000T
DSC6111ME1B-012.0000T
DSC6311ML2DB-016.6700T
DSC6011ML3B-003.0720T
DSC6101ML3B-032.0000T
DSC6301ML1EB-010.0000T
DSC6301ML1AB-010.0000T
DSC1001AE5-040.0000
DSC1003AE5-100.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001AL5-066.0000
DSC1001AE1-018.1059
DSC1001AL5-030.0000
DSC1001AE1-049.1520
DSC1001AL1-001.0000
DSC1001AL1-048.0000
DSC1001AL5-016.7772
DSC1001AE2-148.5000
DSC1001AE2-048.0000
DSC1001AE5-022.5792
DSC1003AL5-025.0000
DSC1001AE1-001.4850
DSC1001AL2-016.0000
DSC1001AE2-080.0000
DSC1001AL1-020.0000
DSC1001AE1-004.0000
DSC1001AE1-099.0000
DSC1001AE1-098.0000
DSC1001AL2-025.0000
DSC1001AE5-004.0000
DSC1001AE5-020.0000
DSC1001AE5-125.0000
DSC1001AE5-012.0000
DSC1003AE1-022.1184
DSC1001AE1-010.0000
DSC1003AE5-025.0000
DSC1001AL5-001.0000
DSC1001AE2-050.0000
DSC1001AE2-054.0000
DSC1001AE5-029.1621
DSC1001AE5-031.6440
DSC1001AL5-011.0592
DSC1001AL1-050.0000
DSC1001AL5-010.0000
DSC1000AL3-PROG
DSC1000AL5-PROG
DSC1004AE2-024.0000
DSC1001AL5-133.3330
DSC1001AL2-020.0000
DSC1001AL2-060.0000
DSC1001AE3-013.5600
DSC1001AE1-064.0000
DSC1001AE1-040.0000
DSC1003AE3-007.3728
DSC1001AL5-014.7456
DSC1001AE5-017.1776
DSC1001AE5-001.2000
DSC1001AL2-029.4912
DSC1001AL2-050.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1003AL2-005.0000
DSC1001AE1-003.5700
DSC1001AL5-033.3330
DSC1001AL2-024.0000
DSC1001AL2-125.0000
DSC1001AL1-025.0000
DSC1001AL1-027.0000
DSC1001AL2-100.0000
DSC1001AL5-029.4912
DSC1001CE1-004.0000T
DSC1001CE1-006.0000T
DSC1001CE1-012.0000T
DSC1001CE1-012.2880T
DSC1001CE1-015.3600T
DSC1001CE1-016.5000T
DSC1001CE1-020.0000T
DSC1001CE1-020.8300T
DSC1001CE1-024.0000T
DSC1001CE1-024.5760T
DSC1001CE1-025.0000T
DSC1001CE2-001.8432T
DSC1001CE1-033.8688T
DSC1001CE1-048.0000T
DSC1001CE2-024.0000T
DSC1001CE1-069.2480T
DSC1001CE1-086.5600T
DSC1001CE2-025.0000T
DSC1001CE2-011.2896T
DSC1001CE2-050.0000T
DSC1001CE2-026.0000T
DSC1001CE2-027.0000T
DSC1001CE2-032.1100T
DSC1001CE2-033.0000T
DSC1001CL1-020.0000T
DSC1001CE2-037.1250T
DSC1001CE2-040.0000T
DSC1001CL1-016.0000T
DSC1001CL1-025.0000T
DSC1001CE2-054.0000T
DSC1001CE2-074.2500T
DSC1001CE2-100.0000T
DSC1001CL1-125.0000T
DSC1001CL2-012.0000T
DSC1001CL2-020.0000T
DSC1001CL2-022.5972T
DSC1001CL1-030.0000T
DSC1001CL1-033.0000T
DSC1001CL2-037.1250T
DSC1001CL2-033.3333T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CL1-066.0000T
DSC1001CL2-050.0000T
DSC1001CL2-004.0000T
DSC1001CL2-025.0000T
DSC1001CL2-027.0000T
DSC1001CL2-033.3000T
DSC1001CL5-040.0000T
DSC1001CL5-001.8432T
DSC1001CL5-008.0000T
DSC1001CL5-150.0000T
DSC1001CL5-012.0000T
DSC1001CL5-019.2000T
DSC1001CL5-020.0000T
DSC1001CL5-024.0000T
DSC1001CL5-024.5760T
DSC1001CL5-025.0000T
DSC1001CL5-026.0000T
DSC1001CL5-027.0000T
DSC1001CL5-030.0000T
DSC1001CL5-032.0000T
DSC1001CL5-033.3330T
DSC1001CL5-050.0000T
DSC1001CL5-033.0000T
DSC1001CL5-060.0000T
DSC1001CE1-037.1250T
DSC1001CL5-114.0000T
DSC1001CL1-100.0000T
DSC8001CL5T
DSC1001CL5-014.7456T
DSC1001CL5-016.0000T
DSC1001CL5-014.3181T
DSC1001CL5-010.0000T
DSC1001CE1-125.0000T
DSC1001CE1-022.1184T
DSC1001CL5-080.0000T
DSC1001CL5-100.0000T
DSC1001CL5-125.0000T
DSC1001CL5-133.3330T
DSC1001CL5-012.0000TABR
DSC1003CL1-048.0000T
DSC1003CL1-095.0000T
DSC1001CL1-001.8432T
DSC1001CE2-012.2880T
DSC1001CE2-003.5800T
DSC1001CL1-001.6000T
DSC1001CE1-027.0000T
DSC1001CL2-024.0000T
DSC1001CE5-148.5000T
DSC1001CE1-014.3182T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CE2-022.5792T
DSC1001CL1-033.3333T
DSC1001CL1-048.0000T
DSC1001CE1-066.6666T
DSC1001CE2-012.0000T
DSC1001CL1-024.0000T
DSC1001CL2-030.0000T
DSC1001CE1-019.2000T
DSC1001CL1-003.2500T
DSC1001CL2-008.0000T
DSC1001CL2-025.5760T
DSC1001CE1-083.3300T
DSC1001CE2-032.0000T
DSC1001CE1-050.0000T
DSC1001CL5-006.7700T
DSC1001CL5-006.7900T
DSC1001CL5-013.5400T
DSC1001CL5-013.5800T
DSC1001CL5-050.3500T
DSC1001CL5-001.6000T
DSC1001CL5-025.6000T
DSC1001CL5-011.0592T
DSC1001CE2-018.4320T
DSC1001CL5-012.8000T
DSC1001CL2-100.0000T
DSC1001CL2-054.0000T
DSC1004CE1-033.3333T
DSC1003CL2-025.0000T
DSC1001CE5-016.0000T
DSC1001CE1-008.0000T
DSC1001CE5-025.0000T
DSC1001CL5-048.0000T
DSC1001CE1-080.0000T
DSC1004CL5-016.0000T
DSC1001CE1-033.3300T
DSC1001CL2-024.5760T
DSC1001CL1-050.0000T
DSC1001CL2-014.7456T
DSC1001CL2-148.5000T
DSC1001CL2-016.0000T
DSC1001CE5-012.2880T
DSC1003CL2-027.0000T
DSC1004CL2-027.0000T
DSC1001CL5-016.3840T
DSC1001CE5-002.0000T
DSC1001CE5-008.0000T
DSC1001CE1-026.0000T
DSC1004CE1-025.6000T
DSC1001CL2-032.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CL2-033.3300T
DSC1001CL5-004.0000T
DSC1001CE1-033.3333T
DSC1001CL5-075.0000T
DSC1003CL5-050.0000T
DSC1003CL2-024.0000T
DSC1001CE2-060.0000T
DSC1001CL1-002.0000T
DSC1000CL3-PROGT
DSC1000CL5-PROGT
DSC1001CL5-018.4320T
DSC1001CL3-012.2880T
DSC1001DI5-006.0000T
DSC1001DI5-007.3728T
DSC1001DI5-008.0174T
DSC1001DI5-008.1920T
DSC1001DI5-010.0000T
DSC1001DI5-012.0000T
DSC1001DI5-016.0000T
DSC1001DI5-019.2000T
DSC1001DI5-020.0000T
DSC1001DI5-024.0000T
DSC1001DI5-024.5760T
DSC1001DI5-025.0000T
DSC1001DI5-026.0000T
DSC1001DI5-027.0000T
DSC1001DI5-028.6363T
DSC1001DI5-029.4912T
DSC1001DI5-032.0000T
DSC1001DI5-033.3330T
DSC1001DI5-001.8432T
DSC1001DI2-018.0000T
DSC1001DI5-044.0000T
DSC1001DI5-048.0000T
DSC1001DI5-050.0000T
DSC1001DI5-060.0000T
DSC1001DI5-075.0000T
DSC1001DI5-080.0000T
DSC1001DI5-100.0000T
DSC1001DI5-125.0000T
DSC1001DI1-074.2500T
DSC1004DI1-024.0000T
DSC1001DL5-032.0000T
DSC1004DI2-072.0000T
DSC1004DI5-010.0000T
DSC1001DI1-054.0000T
DSC1004DI5-066.4860T
DSC1004DI5-066.5800T
DSC8001DI2T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DI2-006.7800T
DSC1001DI2-054.0000T
DSC1001DI5-047.3385T
DSC1001DI5-038.4000T
DSC1001DI1-060.0000T
DSC1001DI2-030.0000T
DSC1001DI2-001.8432T
DSC1001DI5-033.3333T
DSC1001DI2-066.0000T
DSC1001DI5-133.3330T
DSC1004DI1-006.7800T
DSC1001DI5-018.4320T
DSC1001DI1-018.4320T
DSC1001DI2-004.0000T
DSC1001DI1-004.9152T
DSC1001DI2-045.1584T
DSC1001DI2-049.1520T
DSC1001DI2-011.0592T
DSC1003DI2-027.1200T
DSC1001DI2-032.7680T
DSC1001DI1-016.6666T
DSC1001DI5-087.0655T
DSC1001DI1-045.1584T
DSC1001DI5-025.6000T
DSC1001DI1-045.5840T
DSC1001DI1-013.3300T
DSC1001DI2-003.0720T
DSC1001DI2-057.2727T
DSC1003DI2-013.5288T
DSC1001DI2-096.0000T
DSC1001DI2-023.0000T
DSC1001DI5-054.0000T
DSC1001DI1-029.4912T
DSC1001DI5-013.5288T
DSC1004DI2-133.0000T
DSC1004DI1-050.0000T
DSC1001DI1-007.3728T
DSC1001DI1-080.0000T
DSC1001DI1-002.0000T
DSC1001DI2-064.0000T
DSC1001DI3-024.0000T
DSC1003DI2-024.5670T
DSC1001DI5-032.7680T
DSC1001DI1-011.0592T
DSC1001DI3-012.0000T
DSC1001DI2-033.0000T
DSC1003DI5-025.0000T
DSC1001DI5-011.0592T
DSC1001DI2-133.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1003DI1-012.0000T

DSC1001DI2-002.0970T

DSC1001DI3-100.0000T

DSC1001DI3-133.0000T

DSC1001DI1-064.0000T

DSC1001DI5-019.6800T

DSC1001DI1-025.0008T

DSC1001DI5-090.0000T

DSC1001DI5-014.3181T

DSC1001DI1-116.6666T

DSC1001DI2-066.6670T

DSC1003DI2-050.0000T

DSC1004DI2-050.0000T

DSC1003DI1-052.0000T

DSC1001DI5-009.2160T

DSC1001DI2-060.0000T

DSC1001DI5-005.0196T

DSC1001DI5-037.4000T

DSC1001DI1-028.6363T

DSC1001DI3-012.2880T

DSC1004DI5-024.0000T

DSC1004DI5-016.0000T

DSC1001DI3-040.0000T

DSC1004DI1-026.0000T

DSC1001DI2-070.0000T

DSC1001DI3-060.0000T

DSC1001DI5-057.5580T

DSC1003DI2-024.0000T

DSC1003DI2-033.3333T

DSC1001DI1-036.0000T

DSC1001DI1-038.0000T

DSC1001DI5-030.7200T

DSC1001DI3-027.0000T

DSC1001DI2-014.3181T

DSC1001DI5-040.0000T

DSC1001DI1-069.1200T

DSC1001DI5-032.4000T

DSC1001DI5-041.1420T

DSC1001DI5-014.7456T

DSA1001DI1-005.0000TVAO

DSA1001DI1-012.5000TVAO

DSA1001DI1-019.2000TVAO

DSA1001DI1-020.0000TVAO

DSA1001DI1-024.5760TVAO

DSA1001DI1-025.0000TVAO

DSA1001DI1-033.0000TVAO

DSA1001DI1-050.0000TVAO

DSA1003DI1-050.0000TVAO

DSA1001DI2-012.2880TVAO

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA1001DI2-019.2000TVAO
DSA1001DI2-025.0000TVAO
DSA1001DI2-026.0000TVAO
DSA1001DI2-027.0000TVAO
DSA1001DI2-033.3333TVAO
DSA1001DI2-125.0000TVAO
DSA1001DI3-012.0000TVAO
DSA1001DI3-020.0000TVAO
DSA1001DI3-024.0000TVAO
DSA1001DI3-027.0000TVAO
DSA1001DI3-050.0000TVAO
DSA1001DI3-150.0000TVAO
DSC1001AI1-012.2880T
DSC1001AI2-006.0000T
DSC1001AI1-025.0000T
DSC1001AI2-008.0000T
DSC1001AI2-012.0000T
DSC1001AI2-012.2880T
DSC1001AI2-016.0000T
DSC1001AI2-016.3840T
DSC1001AI2-125.0000T
DSC1001AI2-024.0000T
DSC1001AI2-024.5760T
DSC1001AI2-025.0000T
DSC1001AI2-025.0007T
DSC1001AI2-026.0000T
DSC1001AI2-032.0000T
DSC1001AI2-014.3180T
DSC1001AI2-050.0000T
DSC1001AI2-054.0000T
DSC1001AI5-150.0000T
DSC1001AI2-066.0000T
DSC1001AI2-098.3040T
DSC1001AI2-100.0000T
DSC1001AI2-120.0000T
DSC1001AI2-133.0000T
DSC1001AI5-002.4576T
DSC1001AI5-008.0000T
DSC1001AI5-011.0592T
DSC1001AI5-012.0000T
DSC1001AI5-016.0000T
DSC1001AI5-018.4320T
DSC1001AI5-020.0000T
DSC1001AI5-024.5760T
DSC1001AI5-025.0000T
DSC1001AI5-027.0000T
DSC1001AI5-029.4912T
DSC1001AI5-033.3330T
DSC1001AI5-048.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001AI5-080.0000T
DSC1001AI5-100.0000T
DSC1001AI5-125.0000T
DSC1001AI5-125.0060T
DSC1001AI2-066.6600T
DSC1003AI2-050.0000T
DSC1004AI2-040.0000T
DSC8001AI2T
DSC1001AI1-120.0000T
DSC1001AI2-027.0016T
DSC1001AI2-066.6670T
DSC1001AI1-055.3330T
DSC1001AI5-032.0000T
DSC1001AI2-096.0000T
DSC1001AI5-033.0000T
DSC1001AI2-001.0000T
DSC1001AI2-064.0000T
DSC1004AI2-001.0000T
DSC8003AI2T
DSC1001AI2-048.0000T
DSC1001AI1-050.0000T
DSC1001AI2-010.0000T
DSC1001AI2-027.0000T
DSC1001AI2-011.7000T
DSC1001AI2-012.3667T
DSC1001AI5-040.0000T
DSC1001AI5-024.0000T
DSC1001AI1-033.0000T
DSC1001AI2-040.0000T
DSC1001AI1-049.1520T
DSC1001AI5-012.2880T
DSC1001AI1-016.0000T
DSC1004AI5-099.7200T
DSC1001AI1-001.0000T
DSC1001AI5-066.0000T
DSC1001AI1-066.0000T
DSC1001AI1-020.0000T
DSC1001AI1-013.1072T
DSC1001AI1-024.5760T
DSC1001AI1-030.0000T
DSC1001AI5-050.0000T
DSC1001AI1-008.0000T
DSC1001AI1-032.7680T
DSC1001AI2-002.0480T
DSC1001AI1-033.3333T
DSC1001AI2-065.5360T
DSC1001AI2-032.7680T
DSC1001AI1-003.5700T
DSC1003AI2-075.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001AI5-028.6363T

DSC1001AI2-075.0000T

DSC1004AI1-012.0000T

DSC1004AI1-004.9152T

DSC1004AI1-007.3728T

DSC1001AI2-150.0000T

DSC1001AI1-007.3728T

DSC1001AI1-004.9152T

DSC1001AI1-012.0000T

DSC1003AI3-100.0000T

DSC1001AI2-033.3330T

DSC1001AI5-016.3840T

DSC1001AI5-010.0000T

DSC1001AI5-106.2500T

DSC1003AI5-003.6864T

DSC1003AI3-012.0000T

DSC1001AI1-014.3182T

DSC1001AI3-025.0000T

DSC1001AI3-030.0000T

DSC1001AI1-033.3330T

DSC1001AI1-024.5450T

DSC1001AI5-001.7000T

DSC1001AI5-014.7456T

DSC1001AI2-029.4912T

DSC1001AI3-100.0000T

DSC1001AI1-075.0000T

DSC1001AI2-129.6000T

DSC1001AI3-040.0000T

DSC1001AI2-066.6666T

DSC1001AI1-029.4912T

DSC1001AI5-002.0480T

DSC1001AI1-026.0000T

DSC1001AI1-016.3840T

DSC1001AI1-032.0000T

DSC1001AI5-003.6864T

DSC2311KI1-R0003

DSC2311KI2-R0003

DSC2311KI2-R0016

DSC2311KI2-R0045

DSC1123DI5-156.2500

DSC1123DI2-100.0000

DSC1121DI2-156.2500

DSC1101DI1-012.0000

DSC1101DI5-012.0000

DSC1101DI1-150.0000

DSC1101DI5-016.0000

DSC1101DI2-050.6880

DSA6011JL2B-025.0000TVAO

DSA6011JL2B-027.0000TVAO

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA6101JL2B-032K768TVAO
DSA6101JL2B-049.5000TVAO
DSA6111JL2B-024.0000TVAO
DSA6111JL2B-025.0000TVAO
DSA6111JL2B-027.0000TVAO
DSA6331JL2AB-012.2880TVAO
DSA6331JL2CB-024.0000TVAO
DSA6001JL3B-024.5760TVAO
DSA6011JL3B-012.0000TVAO
DSA6101JL3B-012.2888TVAO
DSA6101JL3B-024.5760TVAO
DSA6101JL3B-027.0000TVAO
DSA6101JL3B-037.1250TVAO
DSA6101JL3B-060.0000TVAO
DSA6101JL3B-087.0655TVAO
DSA6102JL3B-037.1250TVAO
DSA6102JL3B-087.0655TVAO
DSA6112JL3B-054.0000TVAO
DSA6301JL3AB-054.0000TVAO
DSA6311JL3AB-054.0000TVAO
DSA6101JL3B-027.0000BVAO
DSA6101JL1B-020.0000TVAO
DSC613PL3A-0106T
DSC613PL3A-0106B
DSC612PL2A-0132T
DSC613PL2A-0131T
DSC612PL2A-0130T
DSC612PL3A-012YT
DSC612PE3A-013KT
DSC612PE3A-014VT
DSC613PE1A-017QT
DSC612PE3A-017RT
DSC613PE2A-017QT
DSC613PE1A-01CKT
DSC612PL3A-01D5T
DSC613PL2A-01DGT
DSC612PL2A-01ERT
DSC613PE2A-01KDT
DSC613PE2A-01M2T
DSC613PE2A-01KCT
DSA612PL2A-01CSTVAO
DSA612PL3A-01BHTVAO
DSC612RL3A-010KT
DSC612RL3A-010KB
DSC613RL2A-0131T
DSC613RE1A-0135T
DSC613RE1A-0136T
DSC612RL2A-0137T
DSC612RL2A-013DT

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC612RL2A-013E1
DSC612RL3A-0142T
DSC612RE1A-014JT
DSC613RL1A-0131T
DSC1004CE1-050.0000
DSC1004CE2-072.0000
DSC8001CL2
DSC8001CL5
DSC1001CL5-050.0000
DSC1001CL5-033.0000
DSC1001CL5-060.0000
DSC1001CL5-114.0000
DSC1001CL1-100.0000
DSC1001CL5-014.7456
DSC1001CL5-016.0000
DSC1001CL5-014.3181
DSC1001CL5-010.0000
DSC1001CE1-125.0000
DSC1001CE5-148.0000
DSC1001CE2-032.1100
DSC1001CE1-022.1184
DSC1001CL2-040.0000
DSC1003CL2-066.0000
DSC1001CL5-080.0000
DSC1001CL5-100.0000
DSC1001CE2-012.2880
DSC1001CE2-003.5800
DSC1001CL1-001.6000
DSC1001CE1-027.0000
DSC1001CE5-148.5000
DSC1001CE2-022.5792
DSC1001CL1-033.3333
DSC1001CL1-048.0000
DSC1001CE1-066.6666
DSC1001CE2-012.0000
DSC1001CL1-024.0000
DSC1001CL2-030.0000
DSC1001CE1-019.2000
DSC1001CL1-003.2500
DSC1001CL2-008.0000
DSC1001CL2-025.5760
DSC1001CE1-083.3300
DSC1001CE2-032.0000
DSC1001CE1-050.0000
DSC1001CL5-006.7700
DSC1001CL5-006.7900
DSC1001CL5-013.5400
DSC1001CL5-013.5800
DSC1001CL5-050.3500

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CL5-001.6000
DSC1001CL5-025.6000
DSC1001CL5-011.0592
DSC1001CE2-018.4320
DSC1001CL5-012.8000
DSC1001CL2-100.0000
DSC1001CL2-054.0000
DSC1004CE1-033.3333
DSC1003CL2-025.0000
DSC1001CE5-016.0000
DSC1001CE1-008.0000
DSC1001CE5-025.0000
DSC1001CL5-048.0000
DSC1001CE1-080.0000
DSC1004CL5-016.0000
DSC1001CE1-033.3300
DSC1001CL2-024.5760
DSC1001CL1-050.0000
DSC1001CL2-014.7456
DSC1001CL2-148.5000
DSC1001CL2-016.0000
DSC1001CE5-012.2880
DSC1003CL2-027.0000
DSC1004CL2-027.0000
DSC1001CL5-016.3840
DSC1001CE5-002.0000
DSC1001CE5-008.0000
DSC1001CE1-026.0000
DSC1004CE1-025.6000
DSC1001CL2-032.0000
DSC1001CL2-033.3300
DSC1001CL5-004.0000
DSC1001CE1-033.3333
DSC1001CL5-075.0000
DSC1003CL5-050.0000
DSC1003CL2-024.0000
DSC1001CE2-060.0000
DSC1001CL1-002.0000
DSC1000CL3-PROG
DSC1000CL5-PROG
DSC1001CL5-018.4320
DSC1001CL3-012.2880
DSC1001CL5-029.4912
DSC1001CL2-064.0000
DSC1001CL2-003.1250
DSC1001CL2-029.4912
DSC1001CL2-066.6660
DSC1001CL2-125.0000
DSC1001CL5-003.6864

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CL3-080.0000
DSC1001CL3-033.0000
DSC1001CE1-004.0960
DSC6111JI2B-024.0000T
DSC6001JI3B-439K000T
DSC6101JI3B-439K000T
DSC6011JI1B-025.0000T
DSC6013JI1B-025.0000T
DSC6112JI1B-050.0000T
DSC6101JI2B-027.0000T
DSC6011JI2B-025.0000T
DSC6001JI2B-025.0000T
DSC6001JI2B-027.0000T
DSC6001JI1B-025.0000T
DSC6011JI1B-008.0000T
DSC6111JI1B-098.3040T
DSC6011JI3B-001.0640T
DSC6111JI2B-100K000T
DSC6111JI3B-100.0000T
DSC6001JI3B-004K000T
DSC6011JI3B-032K768T
DSC6013JI1B-768K000T
DSC6001JI1B-460K800T
DSC6331JI2BB-025.0000T
DSC6331JI2IB-025.0000T
DSC6001JI2B-001.8432T
DSC6011JI2B-012.0000T
DSC6101JI2B-100.0000T
DSC6101JI2B-024.0000T
DSC6003JI2B-025.0000T
DSC6011JI1B-050.0000T
DSC6331JI2EB-025.0000T
DSC6001JI2B-116K000T
DSC6101JI2B-050.0000T
DSC6001JI2B-068.1818T
DSC6331JI2BB-024.0000T
DSC6013JI1B-012.0000T
DSC6001JI1B-012.0000T
DSC6001JI2B-032K000T
DSC6101JI3B-100.0000T
DSC6001JI3B-024.0000T
DSC6003JI2B-032K768T
DSC6023JI3B-019HT
DSC6011JI1B-014.7456T
DSC6003JI2B-004.5160T
DSC6003JI2B-008.0000T
DSC6003JI2B-027.0950T
DSC6003JI2B-063.2220T
DSC6011JI2B-016.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6013JI1B-032K768T
DSC6001JI3B-014.1875T
DSC6101JI3B-485K000T
DSC6013JI3B-032.0000T
DSC6101JI2B-020.0000T
DSC6001JI2B-024.0000T
DSC6003JI2B-024.0000T
DSC6013JI1B-300K000T
DSC6111JI3B-012.0000T
DSC6101JI1B-007K085T
DSC6121JI2B-01BBT
DSC6001JI1B-032K768T
DSC6102JI3B-001.6800T
DSC6003JI2B-307K000T
DSC6331JI2KB-025.0000T
DSC6001JI2B-032K768T
DSC6001JI2B-012.2880T
DSC6011JI3B-048K500T
DSC6331JI1DB-025.0000T
DSC6001JI1B-010.0000T
DSC6011JI1B-001.0000T
DSC6001JI3B-025.0000T
DSC6101JI2B-040K000T
DSC6331JI2CB-027.0000T
DSC6331JI2CB-024.0000T
DSC6101JI2B-012.2880T
DSC1121BI2-016.3840
DSC1121BI2-020.0000
DSC1121BI2-131.0720
DSC1103BI2-050.0000
DSC1101BI2-125.0031
DSC1102BI1-010.0000
DSC1123BI5-148.5000
DSC1123BI5-010.0000
DSC1124BI2-027.0000
DSC1101BI5-010.0000
DSC1122BI2-125.0000
DSC1123BI2-156.0000
DSC1122BI1-025.0000
DSC1121BI2-008.0000
DSC1123BI2-034.0000
DSC1101BI3-025.0000
DSC1101BI2-125.0037
DSC1124BI1-027.0000
DSC1121BI5-022.5792
DSC1121BI5-024.5760
DSC1123BI2-125.0037
DSC1123BI5-125.0000
DSC1121BI3-100.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1121BI5-024.0000
DSC1121BI2-012.0000
DSC1123BI3-050.0000
DSC1101BI2-008.0000
DSC1103BI2-062.5000
DSC1101BI5-016.0000
DSC1101BI5-012.0000
DSC1101BI5-020.0000
DSC1123BI2-010.0000
DSC1121BI5-045.1854
DSC1121BI5-049.1520
DSC1104BI1-027.0000
DSC1101BI3-013.5600
DSC1101BI2-027.1200
DSC1124BI3-027.0000
DSC1121BI1-020.0000
DSC1101BI1-145.2000
DSC1103BI1-156.2500
DSC1122BI3-166.6000
DSC1121BI5-125.0000
DSC1121BI5-025.6000
DSC1121BI2-040.6800
DSC1123BI3-080.0000
DSC1103BI2-235.0000
DSC1123BI1-148.5000
DSC1103BI5-148.5000
DSC1123BI5-040.0000
DSC1103BI2-156.2500
DSC1101AI2-148.5000
DSC1121AI2-156.2500
DSC8104AI2
DSC8102AI2
DSC8103AI2
DSC1101CL2-040.0000
DSC1121CL1-024.0000
DSC1121CL1-028.6364
DSC1121CL1-027.0000
DSC1103CL5-150.0000
DSC1103CE2-156.2500
DSC1101CE2-045.1584
DSC1101CE2-049.1520
DSC1104CE2-027.0000
DSC1123CL5-433.0000
DSC1121CE1-025.6000
DSC1121CL5-040.0000
DSC1121CL5-080.0000
DSC1101CL1-125.0000
DSC1124CE2-100.0000
DSC1124CE5-100.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1100CL5-PROG

DSC1100CL5-PROG

DSC1101CL5-030.0000

DSC1123CL5-322.2656

DSC1101CE5-025.0000

DSC1101CE2-025.0000

DSC1103CL2-233.3333

DSC1101CE1-024.5790

DSC1101CE1-022.5792

DSC1101CE1-011.2896

DSC1101CL5-052.5000

DSC1101CE1-024.5760

DSC1103CL2-333.3333

DSC1123CE2-100.0000

DSC1101CE5-024.0000

DSC1101CE5-100.0000

DSC1101CE5-045.1854

DSC1101CE5-049.1520

DSC1103CL2-125.0000

DSC1103CL2-052.0000

DSC1103CL5-033.3330

DSC1103CL5-075.0300

DSC1123CL2-333.3333

DSC1101CE5-022.5792

DSC1101CE5-024.5760

DSC1101CL3-025.0000

DSC1121CL5-033.3333

DSC1123CL2-200.0000

DSC1123CL3-040.0000

DSC1123CL1-287.0000

DSC1121CE5-002.4880

DSC1101CE1-100.0000

DSC1101CE1-054.0000

DSC1122CL1-135.0000

DSC1121CL1-050.0000

DSC1101CL2-025.0000

DSC1101CL2-050.0000

DSC1101CL2-100.0000

DSC1101CL2-125.0000

DSC1123CE3-422.3000

DSC1103CL1-075.0000

DSC1123CL2-156.2500

DSC1123CL1-100.0000

DSC1123CL2-100.0000

DSC1124CL3-100.0000

DSC1103CL1-200.0000

DSC1103CL1-100.0000

DSC1103CL1-125.0000

DSC1103CL1-150.0000

Date: Monday, November 16, 2020

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103CL1-026.0000
DSC1103CL1-027.0000
DSC1103CL3-093.4400
DSC1103CL3-100.0000
DSC1103CL3-125.0000
DSC400-2222Q0022KE1T
DSC1121AI1-025.0000T
DSC1103AI5-125.0000T
DSC1121AI2-024.0000T
DSC1121AI2-025.0000T
DSC1121AI2-026.0000T
DSC1121AI2-029.4912T
DSC1121AI2-048.0000T
DSC1121AI2-050.0000T
DSC1121AI2-125.0000T
DSC1121AI1-155.5200T
DSC1121AI2-156.2540T
DSC1121AI5-020.0000T
DSC1122AI1-150.0000T
DSC1122AI1-155.5200T
DSC1122AI2-106.2500T
DSC1122AI2-150.0000T
DSC1122AI2-156.2500T
DSC1122AI2-156.2539T
DSC1122AI2-425.0000T
DSC1122AI5-155.5200T
DSC1122AI5-156.2500T
DSC1123AI1-100.0000T
DSC1123AI5-175.0000T
DSC1123AI1-125.0000T
DSC1004BI5-121.5000
DSC1001BI2-003.1250
DSC1001BI5-066.6660
DSC1004BI5-005.0000
DSC1001BI1-099.0000
DSC1001BI2-099.0000
DSC1001BI5-040.9600
DSC1001BI2-003.6864
DSC1001BI3-020.0000
DSC1001BI2-040.6800
DSC1001BI2-033.3300
DSA1001BI2-125.0000VAO
DSC1001DI5-133.0000T
DSC1001DI1-001.8432
DSC1001DI1-003.6864
DSC1001DI1-005.0000
DSC1001DI1-004.0000
DSC1001DI1-010.0000
DSC1001DI1-012.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DI1-013.3333
DSC1001DI1-014.7456
DSC1001DI1-016.3840
DSC1001DI1-020.0000
DSC1001DI1-024.0000
DSC1001DI1-008.0000
DSC1001DI1-025.0000
DSC1001DI1-026.0000
DSC1001DI1-024.5760
DSC1001DI1-033.3300
DSC1001DI1-033.3330
DSC1001DI1-033.3333
DSC1001DI1-048.0000
DSC1001DI1-050.0000
DSC1001DI1-072.0000
DSC1001DI1-098.3040
DSC1001DI1-100.0000
DSC1001DI1-125.0000
DSC1001DI1-133.0000
DSC1001DI2-001.0000
DSC1001DI2-003.6864
DSC1001DI2-005.0196
DSC1001DI2-005.3125
DSC1001DI2-008.0000
DSC1001DI2-009.6000
DSC1001DI2-012.0000
DSC1001DI2-014.7456
DSC1001DI2-016.0000
DSC1001DI2-019.2000
DSC1001DI2-020.0000
DSC1001DI2-024.0000
DSC1001DI2-024.5760
DSC1001DI2-025.0000
DSC1001DI2-026.0000
DSC1001DI2-027.0000
DSC1001DI2-032.0000
DSC1001DI2-033.3300
DSC1001DI2-033.3333
DSC1001DI2-037.1250
DSC1001DI2-022.0000
DSC1001DI2-038.4000
DSC1001DI2-048.0000
DSC1001DI2-024.5455
DSC1001DI2-050.0000
DSC1001DI2-066.6600
DSC1001DI2-022.5792
DSC1001DI2-080.0000
DSC1001DI2-086.4000
DSC1001DI2-100.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DI2-125.0000
DSC1001DI2-040.0000
DSC1001DI5-002.4576
DSC1001DI5-007.3728
DSC1001DI5-012.0000
DSC1001DI5-016.0000
DSC1001DI5-019.2000
DSC1001DI5-020.0000
DSC1001DI5-025.0000
DSC1001DI5-026.0000
DSC1001DI5-027.0000
DSC1001DI2-072.0000
DSC1001DI2-074.2500
DSC1001DI5-032.2500
DSC1001DI5-033.3333
DSC1001DI5-038.4000
DSC1001DI5-100.0000
DSC1001DI5-125.0000
DSC1001DI5-133.0000
DSC1001DI5-150.0000
DSC1004DI1-024.0000
DSC1004DI2-025.0000
DSC1001DI5-002.0480
DSC1001DI2-047.3885
DSC1001DI1-038.4000
DSC1001DI2-026.6000
DSC1001DI1-066.0000
DSC1001DI5-008.0000
DSC1001DI5-047.3885
DSC1001DI5-013.3333
DSC1001DI5-022.5792
DSC1001DI5-030.0000
DSC1001DI2-024.5454
DSC6301JE2AB-050.0000T
DSC6001JE1B-020.0000T
DSC6101JE1B-030.0000T
DSC6101JE1B-033.0000T
DSC6101JE3B-032K768T
DSC6101JE1B-022.4000T
DSC6001JE2B-016.0000T
DSC6301JE2AB-024.0000T
DSC6121JE2B-01P0T
DSC6152JL3B-027.0000T
DSA6311JL1AB-028.6364TV01
DSA6331JL2CB-012.2880TVAO
DSA6101JL1B-019.2000TVAO
DSA6101JL1B-045.0000TVAO
DSA6102JL1B-008.0000TVAO
DSA6311JL1AB-054.0000TVAO

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA6351JL1CB-027.0000TVAO

DSA6001JL2B-008.0000TVAO

DSA6001JL2B-012.2880TVAO

DSA6001JL2B-025.0000TVAO

DSA6001JL2B-027.0000TVAO

DSA6011JL2B-024.0000TVAO

DSC8101CI2

DSC8101CI5

DSC8102CI2

DSC8102CI5

DSC8103CI2

DSC8103CI5

DSC8104CI2

DSC8104CI5

DSC8121CI1

DSC8121CI2

DSC8121CI5

DSC8122CI2

DSC8123CI2

DSC8123CI5

DSC8124CI2

DSC8124CI5

DSC1121CI1-050.0000

DSC1121CI5-016.6667

DSC1121CI5-025.0000

DSC1121CI5-027.0000

DSC1121CI5-066.0000

DSC1121CI5-117.0000

DSC1103CI1-122.8800

DSC1121CI2-027.0000

DSC1123CI1-150.0000

DSC1101CI1-125.0000

DSC1102CI5-150.0000

DSC1123CI1-122.8800

DSC1123CI2-148.5000

DSC1104CI5-125.0000

DSC1121CI2-066.6667

DSC1124CI2-156.2500

DSC1102CI1-050.0000

DSC1102CI1-156.2500

DSC1102CI1-025.0000

DSC1122CI5-100.0000

DSC1102CI5-156.2500

DSC1124CI5-133.0000

DSC1124CI5-133.3300

DSC1104CI2-316.0000

DSC1103CI5-125.0000

DSC1101CI1-008.0000

DSC1101CI1-010.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1123CI2-035.0000
DSC1101CI5-125.0000
DSC1122CI5-050.0000
DSC1121CI2-155.5200
DSC1122CI2-212.5000
DSC1123CI2-060.0000
DSC1123CI2-175.0000
DSC1103CI5-045.0000
DSC1123CI1-050.0000
DSC1123CI5-096.0000
DSC1123CI2-086.0000
DSC1101CI5-100.0000
DSC1124CI1-027.0000
DSC1104CI1-027.0000
DSC1123CI2-050.0000
DSC1101CI5-027.0000
DSC1103CI5-180.0000
DSC1121CI2-008.0000
DSC1101CI5-026.0000
DSC1103CI5-156.2500
DSC1103CI5-016.0000
DSC1103CI2-106.2500
DSC1103CI2-074.2500
DSC1103CI2-050.0000
DSC1102CI1-135.0000
DSC1123CI5-233.2090
DSC1104CI2-027.0000
DSC1123CI5-150.0000
DSC1123CI2-270.0000
DSC1123CI3-148.5000
DSC1122CI5-433.9200
DSC1103CI5-150.0000
DSC1123CI2-322.2650
DSC1123CI2-266.5000
DSC1121CI5-026.0000
DSC1103CI3-200.0000
DSC1103CI3-125.0000
DSC1103CI5-250.0000
DSC1103CI2-250.0000
DSC1103CI2-300.0000
DSC1124CI2-027.0000
DSC1101CI1-012.0000
DSC1102CI2-400.0000
DSC1101CI2-133.0000
DSC1101CI5-032.0000
DSC1101CI2-032.0000
DSC1104CI2-100.0000
DSC1121CI2-080.0000
DSC1124CI1-100.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1101CI1-050.0000
DSC1101CI2-066.6667
DSC1101CI2-125.0000
DSC1123CI2-266.5250
DSC1101CI1-018.7500
DSC1103CI2-052.0000
DSC1103CI5-075.0300
DSC1103CI5-033.3330
DSC1103CI2-024.0000
DSC1103CI2-025.0000
DSC1123CI2-125.0987
DSC1101CI5-048.0000
DSC1102CI2-148.5000
DSC1101CI5-072.0000
DSC1123CI2-160.0000
DSC1103CI1-026.0000
DSC1103CI1-027.0000
DSC1123CI2-180.0000
DSC1123CI2-265.5250
DSC1123CI2-144.0000
DSC1123CI2-072.0000
DSC1102CI2-156.2500
DSC1103CI5-026.0000
DSC1103CI5-027.0000
DSC1101CI1-085.2070
DSC1101CI5-024.0000
DSC1101CI2-020.0000
DSC1103CI5-103.1250
DSC1103CI2-103.1250
DSC1103CI3-100.0000
DSC1103CI3-250.0000
DSC1104CI3-027.0000
DSC1102CI1-108.0000
DSC1121CI2-045.1580
DSC1121CI2-049.1520
DSC1121CI2-045.1584
DSC1121CI2-014.3181
DSC1121CI5-045.1584
DSC1121CI5-024.0000
DSC1123CI1-025.0000
DSC1101CI2-060.0000
DSC1103CI2-072.0000
DSC1101CI2-036.0000
DSC1123CI2-360.0000
DSC1123CI2-010.0000
DSC1103CI3-060.0000
DSC1103CI3-150.0000
DSC1103CI3-175.0000
DSC1103CI1-150.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103CI2-066.0000
DSC1102CI5-020.0000
DSC1101CI5-016.0000
DSC1101CI5-008.0000
DSC1121CI2-066.0000
DSC1124CI2-133.3300
DSC1103CI2-133.3300
DSC1102CI1-212.5000
DSC1103CI1-300.0000
DSC1104CI2-200.0000
DSC1101CI5-157.2864
DSC1101CI1-024.0000
DSC1124CI2-125.0000
DSC1123CI5-066.6670
DSC1123CI2-148.3516
DSC612RI3A-010JT
DSC613RI3A-010UT
DSC612RI3A-010GB
DSC612RI3A-010JB
DSC613RI3A-010UB
DSC612RI1A-012MT
DSC613RI2A-012ST
DSC612RI2A-012PT
DSC612RI3A-012VT
DSC613RI3A-012WT
DSC612RI1A-0133T
DSC613RI2A-0134T
DSC613RI2A-013GT
DSC612RI2A-013HT
DSC613RI3A-014CT
DSC612RI1A-0159T
DSC613RI2A-015HT
DSC613RI2A-016PT
DSC612RI1A-016QT
DSC613RI2A-017CT
DSC612RI1A-017MT
DSC612RI3A-019CT
DSC612RI2A-01A0T
DSC612RI2A-01A2T
DSC612RI2A-01A3T
DSC613RI3A-016PT
DSC613RI3A-01A4T
DSC612RI1A-01B2T
DSC612RI2A-01B2T
DSC613RI2A-01BCT
DSC612RI3A-01CJT
DSC612RI2A-01CMT
DSC612RI1A-01DYT
DSC613RI2A-01G0T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DE5-019.2000
DSC1001DL1-008.0000
DSC8003DL2
DSC8003DL5
DSC1001DE2-024.0000
DSC1001DL1-027.0000
DSC1001DL1-025.0000
DSC1001DL2-001.0000
DSC1001DL2-001.4850
DSC1001DL2-008.0000
DSC1001DL2-012.0000
DSC1001DL2-013.5600
DSC1001DL2-020.0000
DSC1001DL2-024.0000
DSC1001DL2-025.0000
DSC1001DL2-027.0000
DSC1001DL2-030.0000
DSC1001DL2-033.3333
DSC1001DL2-032.0000
DSC1001DL5-001.0000
DSC1001DL5-001.8432
DSC1001DL5-002.0000
DSC1001DL2-050.0000
DSC1001DL5-008.0000
DSC1001DL5-007.3728
DSC1001DL5-016.0000
DSC1001DL5-010.0000
DSC1001DL5-020.0000
DSC1001DL5-024.0000
DSC1001DL5-025.0000
DSC1001DL5-027.0000
DSC1001DL5-030.0000
DSC1001DL5-031.2500
DSC1001DL5-054.0000
DSC1001DL5-026.0000
DSC1001DL5-100.0000
DSC1003DE1-040.0000
DSC1001DL5-033.0000
DSC1003DL2-008.0000
DSC1001DL5-048.0000
DSC1001DL5-050.0000
DSC1003DL5-020.0000
DSC1003DL5-100.0000
DSC1003DL5-125.0000
DSC1003DL5-148.5000
DSC8001DL2
DSC8001DL5
DSC1001DL5-015.3600
DSC1003DL1-125.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1003DL2-025.0000
DSC1003DL5-025.0000
DSC1001DL5-125.0000
DSC1001DL5-080.0000
DSC1001DE2-020.0000
DSC1003DL2-070.0000
DSC1001DL5-010.2000
DSC1001DL2-037.1250
DSC1001DE1-040.0000
DSC1001DE1-050.0000
DSC1001DL2-150.0000
DSC1001DL5-011.0592
DSC1001DL2-090.0000
DSC1001DL5-012.0000
DSC1001DL5-004.0000
DSC1001DE1-025.0000
DSC1001DL5-133.3330
DSC1001DL1-010.0000
DSC1001DL5-019.2000
DSC1001DL5-033.3330
DSC1001DL5-075.0000
DSC1001DL2-072.0000
DSC1003DL2-100.0000
DSC1001DL2-087.0655
DSC1001DE5-018.4320
DSC1001DL1-080.0000
DSC1001DL2-003.9000
DSC1001DL2-013.5000
DSC1001DL2-049.5000
DSC1001DL2-074.2500
DSC1001DL5-128.0000
DSC1003DE1-024.0000
DSC1001DL1-024.0000
DSC1001DL5-024.5760
DSC1001DL2-040.0000
DSC1001DL1-001.8432
DSC1001DL2-001.8432
DSC1001DL1-033.3333
DSC1001DE1-075.0000
DSC1001DE2-100.0000
DSC1001DL2-016.0000
DSC1001DL1-025.2000
DSC1004DL5-040.0000
DSC1001DE1-033.3333
DSC1001DL5-040.0000
DSC1001DE1-019.2000
DSC1001DL2-007.3728
DSC1001DL5-072.0000
DSC1003DL2-080.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DL5-012.2880
DSC1003DL1-027.0000
DSC1004DL1-027.0000
DSC1001DE2-038.4000
DSC1001DE1-013.0000
DSC1001DL2-012.2880
DSC1001DL2-125.0000
DSC1001DL2-004.0000
DSC1001DL1-016.0000
DSC1001DL2-023.0000
DSC1001DE1-020.0000
DSC1001DL2-026.6500
DSC1001DL5-014.3181
DSC1001DE2-008.0000
DSC1001DE2-012.0000
DSC1001DE2-027.0000
DSC1001DE2-025.0000
DSC1001DL5-016.7722
DSC1004DL1-025.0000
DSC1004DL1-033.0000
DSC1001DL2-048.0000
DSC1001DL2-066.6700
DSC1001DE1-024.3050
DSC1001DL2-002.0000
DSC1001DL1-004.0960
DSC1001DL2-049.1520
DSC1001DL2-045.1584
DSC1001DE5-037.4000
DSC1001DL5-096.0000
DSC1001DL2-066.0000
DSC1003DL5-019.2000
DSC1001DE5-012.0000
DSC1001DL2-026.0000
DSC1001DL2-019.2000
DSC1003DL1-033.3333
DSC1003DL1-024.5454
DSC1004DL2-072.0000
DSC1001DE2-120.0000
DSC1004DL2-025.0000
DSC1000DL3-PROG
DSC1000DL5-PROG
DSC1001DL2-054.0000
DSC1001DL3-027.0000
DSC1001DL3-024.0000
DSC1001DL5-016.3840
DSC1001DL2-016.3690
DSC1001DL2-061.2500
DSC1003DL2-033.3333
DSC1001DL5-018.4320

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DL5-033.3333

DSC1001DL2-003.6864

DSC1001DL5-003.6864

DSC1001DE2-001.0000

DSC1001DE2-090.0000

DSC1004DL5-025.0000

DSC1001DE2-022.0000

DSC1001DL5-037.1250

DSC1001DL5-150.0000

DSC1001DL2-033.3300

DSC1001DE5-025.0000

DSC1001DE1-024.5760

DSC1001DL5-047.0016

DSC1001DL1-005.0196

DSC1001DL2-005.0196

DSC1001DL5-005.0196

DSC1001DE3-080.0000

DSC1001DL1-150.0000

DSC1001DE3-008.0000

DSC1001DE5-150.0000

DSC1003DL1-025.0000

DSC1003DL1-016.0000

DSC1003DL1-050.0000

DSC1003DL1-048.0000

DSC1003DL2-024.0000

DSC1004DE1-026.0000

DSC1001DL1-050.0000

DSC1001DE5-049.1520

DSC1001DE5-045.1584

DSC1001DL1-040.0000

DSC1001DL5-064.0000

DSC1004DE2-025.0000

DSC1001DL5-028.6363

DSC1001DL5-006.0000

DSC1001DL1-033.3330

DSC1001DL5-029.4912

DSC1001DL1-004.0000

DSC1001DL2-100.0000

DSC1001DL5-032.4000

DSC1001DL5-049.5000

DSC1001DL2-012.5000

DSC1001DL1-012.5000

DSC1001DL3-125.0000

DSC1001DL5-026.5980

DSC1001DL5-120.0000

DSC1001DL5-087.0655

DSA1001DL1-008.0000VAO

DSA1001DL1-010.2400VAO

DSA1001DL1-016.6666VAO

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA100IDLT-020.0000VAO

DSC6101HA2B-072.0000

DSC6003HA3B-016.0000

DSC6001HA3B-PROG

DSC6003HA3B-PROG

DSC6101HA3B-PROG

DSC6003HA1B-020.0000

DSC6101HA2B-072.5000

DSC6001HA2B-029.4912

DSC6101HA3B-024.0000

DSC6111HA3B-024.0000

DSC6111HA2B-024.0000

DSC6332HA3AB-002.4576

DSC6332HA3AB-031.9488

DSC6301HA1FB-020.0000

DSC6021HA3B-01D0

DSC6003HA3B-032K768

DSC6011HA1B-032K768

DSC6011HA2B-032K768

DSC6011HA2B-025.0000

DSC6011HA2B-008.0000

DSC6013HA2B-048.0000

DSC6011HA2B-029.4912

DSA6101HA1B-005.0000VAO

DSA6101HA1B-008.0000VAO

DSA6101HA1B-027.0000VAO

DSA6301HA1AB-027.0000VAO

DSA6001HA2B-029.4912VAO

DSA6122HA3B-01ECVAO

DSC6001MA2B-020.0000

DSC6003MA3B-032K768

DSC6101MA3B-019.2000

DSC6101MA3B-027.0000

DSC6001MA3B-PROG

DSC6003MA3B-PROG

DSC6101MA3B-PROG

DSC6331MA1AB-027.0000

DSC6111MA3B-050.0000

DSC6023MA1B-015S

DSC6101MA2B-020.0000

DSC6111MA1B-033.0000

DSC6331MA1AB-025.0000

DSC6101MA3B-016.6666

DSC6111MA1B-033.3300

DSC6101MA3B-026.0000

DSC6011MA3B-006K000

DSC6011MA3B-022K000

DSC6011MA3B-002K000

DSC6011MA3B-020.0000

Date: Monday, November 16, 2020

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6101MA1B-008.0000

DSC6011MA1B-032K768

DSC6011MA3B-025.0000

DSA6001MA1B-013.5600VAO

DSA6101MA1B-033.3300VAO

DSA6121MA1B-01AEVAO

DSA6331MA1AB-025.0000VAO

DSA6331MA1AB-027.0000VAO

DSA6331MA1BB-027.0000VAO

DSA6331MA1DB-027.0000VAO

DSA6101MA2B-008.0000VAO

DSA6101MA2B-010.0000VAO

DSA6311MA2CB-008.0000VAO

DSA6011MA3B-002K000VAO

DSA6011MA3B-020.0000VAO

DSC612NA2A-010J

DSC613NA2A-018Y

DSC612NA1A-01H5

DSC613NA1A-017Q

DSC613NA1A-01KC

DSC613NA1A-01KD

DSC6101JA2B-025.0000

DSC6001JA3B-020.0000

DSC6331JA3BB-004.0000

DSC6331JA3AB-004.0000

DSC6001JA3B-PROG

DSC6003JA3B-PROG

DSC6101JA3B-PROG

DSC6311JA1AB-027.0000

DSC6331JA1CB-054.0000

DSC6311JA1BB-027.0000

DSC6001JA3B-580K000

DSC6311JA1AB-054.0000

DSC6331JA2BB-025.0000

DSC6331JA2IB-025.0000

DSC6331JA2GB-025.0000

DSC6331JA2HB-025.0000

DSC6021JA2B-01AR

DSC6331JA2AB-025.0000

DSC6331JA2DB-024.5760

DSC6011JA3B-016K384

DSC6311JA1AB-045.0000

DSC6311JA1BB-045.0000

DSC6311JA1AB-019.2000

DSC6311JA1BB-019.2000

DSC6001JA2B-016.0000

DSC6102JA1B-125K000

DSC6102JA1B-010K000

DSC6101JA2B-050.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6331JA2AB-004.0000
DSC6331JA2BB-004.0000
DSC400-2222Q0022KE2T
DSC400-0303Q0092KE1T
DSC400-0303Q0092KE2T
DSC400-3333Q0093KE1T
DSC400-3333Q0093KE2T
DSC400-3333Q0094KE1T
DSC400-3333Q0094KE2T
DSC400-4334Q0022KE1T
DSC400-4334Q0022KE2T
DSC400-0444Q0009KE1T
DSC400-0444Q0009KE2T
DSC400-1111Q0095KE1T
DSC400-1111Q0095KE2T
DSC400-0101Q0096KE1T
DSC400-0101Q0096KE2T
DSC400-3331Q0097KE1T
DSC400-3331Q0097KE2T
DSC400-3331Q0098KE1T
DSC400-3331Q0098KE2T
DSC400-3333Q0099KE1T
DSC400-3333Q0099KE2T
DSC400-3133Q0100KE1T
DSC400-3133Q0100KE2T
DSC400-0103Q0102KE1T
DSC400-0103Q0102KE2T
DSC400-0401Q0103KE1T
DSC400-0401Q0103KE2T
DSC400-2222Q0104KE1T
DSC400-2222Q0104KE2T
DSC400-2222Q0105KE1T
DSC400-2222Q0105KE2T
DSC400-3333Q0104KE1T
DSC400-3333Q0104KE2T
DSC400-0202Q0106KE1T
DSC400-0202Q0106KE2T
DSC400-0202Q0107KE1T
DSC400-0202Q0107KE2T
DSC400-0202Q0108KE1T
DSC400-0202Q0108KE2T
DSC400-0202Q0109KE1T
DSC400-0202Q0109KE2T
DSC400-1111Q0110KE1T
DSC400-1111Q0110KE2T
DSC400-1111Q0111KE1T
DSC400-1111Q0111KE2T
DSC400-4111Q0112KE1T
DSC400-4111Q0112KE2T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-4334Q0023KE1T
DSC400-4334Q0023KE2T
DSC400-1133Q0113KE1T
DSC400-1133Q0113KE2T
DSC400-0101Q0114KE1T
DSC400-0101Q0114KE2T
DSC400-0101Q0115KE1T
DSC400-0101Q0115KE2T
DSC400-0111Q0116KE1T
DSC400-0111Q0116KE2T
DSC400-0111Q0117KE1T
DSC400-0111Q0117KE2T
DSC400-2222Q0118KE1T
DSC400-2222Q0118KE2T
DSC400-0244Q0009KE1T
DSC400-0244Q0009KE2T
DSC400-0101Q0119KE1T
DSC400-0101Q0119KE2T
DSC400-1111Q0120KE1T
DSC400-1111Q0120KE2T
DSC400-0111Q0026KE1T
DSC400-0111Q0026KE2T
DSC400-1111Q0121KE1T
DSC400-1111Q0121KE2T
DSC400-1114Q0122KE1T
DSC400-1114Q0122KE2T
DSC400-0321Q0123KE1T
DSC400-0321Q0123KE2T
DSC400-3333Q0124KE1T
DSC400-3333Q0124KE2T
DSC400-1331Q0125KE1T
DSC400-1331Q0125KE2T
DSC400-1333Q0126KE1T
DSC400-1333Q0126KE2T
DSC400-0223Q0127KE1T
DSC400-0223Q0127KE2T
DSC400-0133Q0128KE1T
DSC400-0133Q0128KE2T
DSC400-0331Q0128KE1T
DSC400-0331Q0128KE2T
DSC400-0101Q0129KE1T
DSC400-0101Q0129KE2T
DSC400-3333Q0130KE1T
DSC400-3333Q0130KE2T
DSC400-3111Q0131KE1T
DSC400-3111Q0131KE2T
DSC400-4111Q0131KE1T
DSC400-4111Q0131KE2T
DSC400-1111Q0132KE1T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-1111Q0132KE2T
DSC400-0311Q0026KE1T
DSC400-0311Q0026KE2T
DSC400-0211Q0026KE1T
DSC400-0211Q0026KE2T
DSC400-1111Q0133KE1T
DSC400-1111Q0133KE2T
DSC400-1121Q0134KE1T
DSC400-1121Q0134KE2T
DSC400-1411Q0135KE1T
DSC400-1411Q0135KE2T
DSC400-0212Q0136KE1T
DSC400-0212Q0136KE2T
DSC400-1111Q0137KE1T
DSC400-1111Q0137KE2T
DSC400-0111Q0138KE1T
DSC400-0111Q0138KE2T
DSC400-0111Q0139KE1T
DSC400-0111Q0139KE2T
DSC400-0144Q0140KE1T
DSC400-0144Q0140KE2T
DSC400-1221Q0141KE1T
DSC400-1221Q0141KE2T
DSC400-0434Q0009KE1T
DSC400-0434Q0009KE2T
DSC400-0313Q0136KE1T
DSC400-0313Q0136KE2T
DSC400-1111Q0142KE1T
DSC400-1111Q0142KE2T
DSC400-1111Q0143KE1T
DSC400-1111Q0143KE2T
DSC400-0333Q0144KE1T
DSC400-0333Q0144KE2T
DSC400-3333Q0145KE1T
DSC400-3333Q0145KE2T
DSC400-3333Q0023KE1T
DSC400-3333Q0023KE2T
DSC400-3333Q0146KE1T
DSC400-3333Q0146KE2T
DSC400-1111Q0147KE1T
DSC400-1111Q0147KE2T
DSC400-1111Q0078KE1T
DSC400-1111Q0078KE2T
DSC400-0323Q0009KE1T
DSC400-0323Q0009KE2T
DSC400-1111Q0148KE1T
DSC400-1111Q0148KE2T
DSC400-1313Q0094KE1T
DSC400-1313Q0094KE2T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-1111Q0149KE1T
DSC400-1111Q0149KE2T
DSC400-1333Q0078KE1T
DSC400-1333Q0078KE2T
DSC400-1111Q0150KE1T
DSC400-1111Q0150KE2T
DSC400-3333Q0151KE1T
DSC400-3333Q0151KE2T
DSC400-4144Q0152KE1T
DSC400-4144Q0152KE2T
DSC400-3331Q0153KE1T
DSC400-3331Q0153KE2T
DSC400-2222Q0031KE1T
DSC400-2222Q0031KE2T
DSC400-0333Q0154KE1T
DSC400-0333Q0154KE2T
DSC400-0111Q0155KE1T
DSC400-0111Q0155KE2T
DSC400-3133Q0156KE1T
DSC400-3133Q0156KE2T
DSC400-0133Q0157KE1T
DSC400-0133Q0157KE2T
DSC400-3113Q0158KE1T
DSC400-3113Q0158KE2T
DSC400-3113Q0159KE1T
DSC400-3113Q0159KE2T
DSC400-1111Q0160KE1T
DSC400-1111Q0160KE2T
DSC400-0333Q0162KE1T
DSC400-0333Q0162KE2T
DSC400-3333Q0163KE1T
DSC400-3333Q0163KE2T
DSA400-1111Q0004KL1TVAO
DSA400-1111Q0004KL2TVAO
DSA400-1111Q0085KL1TVAO
DSA400-1111Q0085KL2TVAO
DSA400-1111Q0161KL1TVAO
DSA400-1111Q0161KL2TVAO
DSA400-4134Q0152KL1TVAO
DSA400-4134Q0152KL2TVAO
DSA557-04443KL0TVAO
DSA557-04444KL1TVAO
DSA557-054444KL1TVAO
DSC400-0331Q0026KI2T
DSC400-1111Q0084KI1T
DSC400-1111Q0084KI2T
DSC400-0101Q0083KI1T
DSC400-0344Q0051KI1T
DSC400-0101Q0083KI2T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-1111Q0034KI1T
DSC400-1111Q0044KI2T
DSC400-1111Q0085KI1T
DSC400-1111Q0085KE1T
DSC400-1122Q0036KI1T
DSC400-4411Q0072KI1T
DSC400-4411Q0072KI2T
DSC400-4444Q0038KI1T
DSC557-054444KI1T
DSC400-1111Q0073KI1T
DSC400-1111Q0073KI2T
DSC400-1133Q0079KI1T
DSC400-1133Q0079KI2T
DSC400-1111Q0001KI1T
DSC400-1111Q0001KI2T
DSC400-3333Q0078KI1T
DSC400-3333Q0078KI2T
DSC400-1111Q0081KI1T
DSC400-1111Q0081KI2T
DSC400-3133Q0080KI1T
DSC400-3133Q0080KI2T
DSC400-0101Q0082KI1T
DSC400-0101Q0082KI2T
DSC400-1311Q0076KI1T
DSC400-1311Q0076KI2T
DSC400-0303Q0086KI1T
DSC400-0303Q0086KI2T
DSC400-0111Q0087KI1T
DSC400-0111Q0087KI2T
DSC400-3111Q0088KI1T
DSC400-3111Q0088KI2T
DSC400-3333Q0089KI1T
DSC400-3333Q0089KI2T
DSC400-4444Q0023KI1T
DSC400-4444Q0023KI2T
DSC400-4444Q0059KI1T
DSC400-4444Q0059KI2T
DSC400-1111Q0090KI1T
DSC400-1111Q0090KI2T
DSC400-1111Q0091KI1T
DSC400-1111Q0091KI2T
DSC400-2222Q0022KI1T
DSC400-2222Q0022KI2T
DSC400-0303Q0092KI1T
DSC400-0303Q0092KI2T
DSC400-3333Q0093KI1T
DSC400-3333Q0093KI2T
DSC400-3333Q0094KI1T
DSC400-0101Q0083KI1

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-0353Q0040KI2
DSC400-0344Q0051KI1
DSC400-0101Q0083KI2
DSC400-1111Q0019KI2
DSC400-1111Q0034KI1
DSC557-054444KI2
DSC400-1111Q0044KI2
DSC400-1111Q0085KI1
DSC400-1111Q0085KE1
DSC400-1122Q0036KI1
DSC400-3333Q0016KI1
DSC400-3333Q0041KI2
DSC400-4144Q0054KI1
DSC400-4411Q0072KI1
DSC400-4411Q0072KI2
DSC400-4444Q0038KI1
DSC557-04333KI1
DSC557-04444KI1
DSC557-054444KI1
DSC400-1111Q0073KI1
DSC400-1111Q0073KI2
DSC400-1133Q0079KI1
DSC400-1133Q0079KI2
DSC400-1111Q0001KI1
DSC400-1111Q0001KI2
DSC1001CI5-009.7280
DSC1001CI5-016.3840
DSC1001CI2-133.0000
DSC1001CI5-033.3333
DSC1003CI2-100.0000
DSC1001CI5-032.0000
DSC1001CI5-033.0000
DSC1001CI5-033.3330
DSC1001CI2-030.0000
DSC1001CI5-048.0000
DSC1001CI5-125.0000
DSC1004CI2-027.0000
DSC1004CI5-050.0000
DSC1001CI1-010.0000
DSC1001CI1-033.3330
DSC1004CI5-016.0000
DSC1001CI2-072.0000
DSC1001CI2-108.0000
DSC1001CI2-028.3220
DSC1001CI2-043.0000
DSC1001CI2-019.2000
DSC1001CI2-038.4000
DSC1001CI2-052.0000
DSC1003CI2-025.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1003CI2-050.0000
DSC1001CI2-001.9512
DSC1001CI2-033.3330
DSC1001CI5-024.3050
DSC1001CI5-033.3300
DSC1001CI5-014.3181
DSC1001CI5-026.8000
DSC1001CI2-026.8000
DSC1001CI2-010.4858
DSC1004CI2-098.3040
DSC1001CI1-031.9488
DSC1003CI5-099.7200
DSC1001CI1-004.0000
DSC1001CI5-014.7456
DSC1001CI5-008.1920
DSC1001CI2-003.0720
DSC1003CI2-024.0000
DSC1003CI2-080.0000
DSC1003CI1-070.0000
DSC1001CI1-080.0000
DSC1001CI5-022.0000
DSC1001CI2-100.8000
DSC1003CI2-027.0000
DSC1001CI5-022.5792
DSC1001CI2-024.3050
DSC1001CI1-004.0960
DSC1001CI5-003.2768
DSC1001CI5-007.3728
DSC1001CI2-003.2768
DSC1001CI3-024.0000
DSC1001CI3-025.0000
DSC1001CI3-027.0000
DSC1001CI3-013.8240
DSC1001CI5-015.0000
DSC1001CI5-144.0000
DSC1001CI5-029.4912
DSC1001CI2-133.3330
DSC1001CI3-100.0000
DSC1001CI2-074.1750
DSC1001CI5-003.6864
DSC1004CI2-024.5760
DSC1001CI3-003.5790
DSC1001CI1-018.4320
DSC1001CI1-040.0000
DSC1001CI2-066.0000
DSC1001CI2-026.6363
DSC1001CI1-064.0000
DSC1001CI2-003.8000
DSC1001CI3-012.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CI5-033.0000
DSC1003CI5-080.0000
DSC1001CI1-005.0000
DSC1001CI3-019.2000
DSC1001CI3-050.0000
DSC1001CI1-004.9152
DSC1003CI2-010.0000
DSC1004CI5-121.5000
DSC1001CI2-034.0000
DSC1001CI5-037.4000
DSC1004CI2-060.0000
DSC1001CI2-004.0960
DSC1001CI5-037.0879
DSC1001CI2-013.0000
DSC1001CE2-074.2500
DSC1004CI1-016.0000
DSC1001CI1-028.6363
DSC1001CI3-013.5000
DSC1001CI1-008.1920
DSC1001CI2-038.0000
DSC1001CI3-004.0000
DSC1004CI5-100.0000
DSC1001CI5-013.5000
DSC1001CI2-020.7500
DSC1003CI5-040.0000
DSC1001CI5-013.3300
DSC1003CI2-020.0000
DSC400-3333Q0094KI2T
DSC400-4334Q0022KI1T
DSC400-4334Q0022KI2T
DSC400-0444Q0009KI1T
DSC400-0444Q0009KI2T
DSC400-1111Q0095KI1T
DSC400-1111Q0095KI2T
DSC400-0101Q0096KI1T
DSC400-0101Q0096KI2T
DSC400-3331Q0097KI1T
DSC400-3331Q0097KI2T
DSC400-3331Q0098KI1T
DSC400-3331Q0098KI2T
DSC400-3333Q0099KI1T
DSC400-3333Q0099KI2T
DSC400-3133Q0100KI1T
DSC400-3133Q0100KI2T
DSC400-0103Q0102KI1T
DSC400-0103Q0102KI2T
DSC400-0401Q0103KI1T
DSC400-0401Q0103KI2T
DSC400-2222Q0104KI1T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC400-2222Q0104KI2T
DSC400-2222Q0105KI1T
DSC400-2222Q0105KI2T
DSC400-3333Q0104KI1T
DSC400-3333Q0104KI2T
DSC1123DI5-010.0000T
DSC1103DI5-300.0000T
DSC1101DI5-025.0000T
DSC1123DI2-072.0000T
DSC1101DI5-036.0000T
DSC1101DI1-036.0000T
DSC1123DI2-010.0000T
DSC1103DI5-160.0000T
DSC1101DI2-012.0000T
DSC1101DI5-125.0000T
DSC2311KI2-R0074T
DSC1123DI2-148.3516T
DSC2311KI2-R0073T
DSC2311KI2-R0021T
DSC2311KI2-R0023T
DSC2311KI2-R0079T
DSC1104DI2-100.0000T
DSC1102DI1-212.5000T
DSC1102DI2-212.5000T
DSC2311KI2-R0012T
DSC1123DI1-100.0000T
DSC1104DI5-100.0000T
DSC1124DI5-100.0000T
DSC2311KI2-R0082T
DSC1121DI1-048.0000T
DSC1122DI2-121.1090T
DSC1101DI1-033.3330T
DSC2311KI1-R0083T
DSC6101JE1B-024.0000
DSC6001JL2B-006.0053
DSC6001JE2B-024.0000
DSC6001JE3B-024.0000
DSC6001JE2B-025.0000
DSC6101JE1B-050.0000
DSC6023JE1B-01D6
DSC6021JE1B-01D7
DSC6023JE1B-01D8
DSC6021JE1B-01D9
DSC6023JE1B-01DS
DSC6023JE1B-01DV
DSC6111JE2B-100.0000
DSC6021JE1B-01EA
DSC6001JL1B-025K600
DSC6101JL3B-027.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6311JE1BB-018.4320
DSC6311JE1CB-018.4320
DSC6102JL1B-088.0000
DSC6102JL1B-033.0000
DSC6112JE1B-100.0000
DSC6021JE3B-01GB
DSC6021JL1B-01HB
DSC6001JE1B-052.0000
DSC6121JE1B-01HD
DSC6121JE1B-01HE
DSC6121JE1B-01HG
DSC6011JE1B-027.0000
DSC6311JE2FB-064.0000
DSC6011JE1B-024.0000
DSC6301JE2AB-050.0000
DSC6001JE1B-020.0000
DSC6101JE1B-030.0000
DSC6101JE1B-033.0000
DSC6101JE3B-032K768
DSC6101JE1B-022.4000
DSC6001JE2B-016.0000
DSC6301JE2AB-024.0000
DSC6121JE2B-01P0
DSC6152JL3B-027.0000
DSA6331JL2CB-012.2880VAO
DSA6101JL1B-019.2000VAO
DSA6101JL1B-045.0000VAO
DSA6102JL1B-008.0000VAO
DSA6311JL1AB-054.0000VAO
DSA6331JL1CB-027.0000VAO
DSA6001JL2B-008.0000VAO
DSA6001JL2B-012.2880VAO
DSA6001JL2B-025.0000VAO
DSA6001JL2B-027.0000VAO
DSA6011JL2B-024.0000VAO
DSA6011JL2B-025.0000VAO
DSA6011JL2B-027.0000VAO
DSA6101JL2B-032K768VAO
DSA6101JL2B-049.5000VAO
DSA6111JL2B-024.0000VAO
DSA6111JL2B-025.0000VAO
DSA6111JL2B-027.0000VAO
DSA6331JL2AB-012.2880VAO
DSA6331JL2CB-024.0000VAO
DSA6001JL3B-024.5760VAO
DSA6011JL3B-012.0000VAO
DSA6101JL3B-012.2888VAO
DSA6101JL3B-024.5760VAO
DSA6101JL3B-027.0000VAO

Date: Monday, November 16, 2020

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA6101JL3B-037.1250VAO

DSA6101JL3B-060.0000VAO

DSA6101JL3B-087.0655VAO

DSA6102JL3B-037.1250VAO

DSC1121AE2-025.0000T

DSC1121AE2-156.2500T

DSC1121AE2-075.0000T

DSC1123AE2-148.3516T

DSC1122NE1-025.0000T

DSC1122NE2-150.0000T

DSC1122NE2-156.2500T

DSC1124NE1-100.0000T

DSC1124NL2-100.0000T

DSC1122NE1-133.3330T

DSC1122NE1-150.0000T

DSC1123NE2-156.2500T

DSC1123NE2-125.0000T

DSC1123NL2-100.0000T

DSC1102NE1-148.5000T

DSC1102NE1-125.0000T

DSC1103NE1-114.2850T

DSC1123NE1-100.0000T

DSC1123NL5-125.0000T

DSC1123NL5-100.0000T

DSC1121NL1-025.0000T

DSC1101NL3-PROGT

DSC1101NL5-PROGT

DSC1100NL3-PROGT

DSC1100NL5-PROGT

DSC1122NL2-025.0006T

DSC1103NL2-147.4560T

DSC1103NL2-098.3040T

DSC1123NE1-200.0000T

DSC1103NL5-125.0000T

DSC1103NL2-100.0000T

DSC1103NL2-106.2500T

DSC1103NL2-135.0000T

DSC1101DE2-008.0000T

DSC1101DL1-033.3330T

DSC1101DL5-013.5600T

DSC1121DL2-024.7500T

DSC1121DL2-025.0000T

DSC1123DL2-125.0000T

DSC1123DL5-100.0000T

DSC1123DL5-125.0000T

DSC1123DL5-156.2500T

DSC1123DL5-212.5000T

DSC2311KE1-R0002T

DSC2311KL1-R0015T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC2311KLI1-R0021T
DSC2311KL2-R0015T
DSC2311KL2-R0018T
DSC1105DL1-027.0000T
DSC8121DL5T
DSC2311KE1-R0042T
DSC2311KE1-R0047T
DSC2311KL2-R0048T
DSC1001CL1-125.0000
DSC1001CL2-009.5290
DSC1001CL2-012.0000
DSC1001CL2-020.0000
DSC1001CL2-022.5972
DSC1001CL2-024.0000
DSC1001CL2-025.0000
DSC1001CL1-033.0000
DSC1001CL2-027.0000
DSC1001CL2-033.3333
DSC1001CL2-037.1250
DSC1001CL2-050.0000
DSC1001CL2-004.0000
DSC1001CL5-020.0000
DSC1001CL5-025.0000
DSC1001CL5-026.0000
DSC1001CL5-027.0000
DSC1001CL5-027.1200
DSC1001CL5-032.0000
DSC1001CL5-033.3330
DSC1001CL5-040.0000
DSC1001CL5-125.0000
DSC1001CL5-008.0000
DSC1001CL5-150.0000
DSC1001CL5-28.63636
DSC1001CL5-012.0000
DSC1001CL5-024.0000
DSC1103DI2-250.0000T
DSC2311KI1-R0070T
DSC2311KI1-R0052T
DSC1121DI5-125.0000T
DSC2311KI2-R0085T
DSC2311KI2-R0086T
DSC2311KI1-R0078T
DSC2311KI1-R0073T
DSC1123DI2-160.0000T
DSC2311KI2-R0088T
DSC2311KI1-R0016T
DSC1123DI5-125.0060T
DSC1123DI1-322.2656T
DSC2311KI1-R0040T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103DI1-156.2500T

DSC1103DI2-156.2500T

DSC1103DI1-080.0000T

DSA2311KI1-R0003TVAO

DSA1101DI1-004.0000TVAO

DSA1101DI1-050.0000TVAO

DSA1121DI3-033.3333TVAO

DSA2311KI2-R0064TVAO

DSA2311KI2-R0065TVAO

DSA2311KI2-R0077TVAO

DSA2311KI3-R0067TVAO

DSA2311KI1-R0016TVAO

DSA2311KI1-R0041TVAO

DSA2311KI2-R0015TVAO

DSC2010FI2-A0001T

DSC2010FI2-A0017T

DSC557-0333FI0T

DSC2010FI2-A0024T

DSC2010FI2-B0005T

DSC2011FI1-E0012T

DSC2011FI2-E0001T

DSC2011FI2-F0017T

DSC2011FI2-F0021T

DSC2022FI2-F0001T

DSC2030FI2-C0001T

DSC2030FI2-C0004T

DSC2030FI2-C0006T

DSC2030FI2-C0012T

DSC2031FI2-J0001T

DSC2033FI2-G0002T

DSC2033FI2-G0004T

DSC2033FI2-G0006T

DSC2033FI2-G0007T

DSC2042FI2-M0005T

DSC2044FI1-H0006T

DSC2044FI2-H0001T

DSC2044FI2-H0001B

DSC2133FI2-E0020T

DSC2042FI1-M0005T

DSC2233FI2-F0018T

DSC2044FI1-H0001T

DSC2033FI1-F0028T

DSC2010FI2-B0014T

DSC2210FI2-A0006T

DSC2210FI2-A0028T

DSC2211FI2-E0018T

DSC2033FI2-G0001T

DSC2033FI2-K0003T

DSC2033FI2-F0030T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC2033FI2-F0031T
DSC2042FI1-F0014T
DSC2033FI2-F0032T
DSC2010FI2-B0009T
DSC2011FI1-F0033T
DSC2233FI2-G0002T
DSC2133FI2-G0001T
DSC2033FI1-F0025T
DSC2033FI1-F0026T
DSC2120FI1-A0027T
DSC2030FI2-C0002T
DSC2033FI2-F0022T
DSC2033FI1-F0022T
DSC557-0344FI0T
DSC557-0344FI1T
DSC557-0343FI1T
DSC2011FI2-E0002T
DSC2044FI2-H0006T
DSC2222FI1-F0006T
DSC2022FI1-F0006T
DSC2044FI2-F0022T
DSC2211FI1-E0021T
DSC2144FI2-F0022T
DSC2110FI2-A0008T
DSC2110FI2-A0006T
DSC2011FI2-F0035T
DSC2033FI2-F0003T
DSC2011FI1-F0036T
DSC2033FI2-F0037T
DSC2033FI2-F0038T
DSC2033FI2-F0039T
DSC2041FI1-F0025T
DSC2033FI2-F0040T
DSC2144FI2-E0023T
DSC2123FI2-E0024T
DSC2030FI5-B0011T
DSC2030FI1-B0019T
DSC2011FI2-F0042T
DSC2022FI1-H0006T
DSC2011FI1-F0043T
DSC2122FI2-E0025T
DSC2033FI2-F0044T
DSC2030FI2-B0020T
DSC2033FI1-F0039T
DSC2222FI2-E0026T
DSC2010FI2-A0018T
DSC2010FI2-A0021T
DSC2030FI2-C0009T
DSC2030FI2-C0010T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC2040FI2-D0002T
DSC2040FI2-D0003T
DSC2042FI2-M0004T
DSC2010FI1-A0003T
DSC2033FI2-F0046T
DSC2033FI2-F0047T
DSC2033FI2-F0048T
DSC2133FI2-E0027T
DSC557-0344FI1B
DSC2011FI2-F0050T
DSC2041FI1-K0001T
DSC2040FI2-B0021T
DSC2033FI2-F0053T
DSC2031FI2-F0023T
DSC557-0333FI1T
DSC2011FI1-F0054T
DSC2030FI2-B0022T
DSC2033FI2-H0005T
DSC2033FI2-F0060T
DSC2110FI1-A0012T
DSC2033FI2-F0059T
DSC1121DM2-016.6400T
DSC1121DM2-014.7456T
DSC2311KM1-R0002T
DSC1101DM2-007.3700T
DSC1121DM3-032.0000T
DSC1101DM1-032.0000T
DSC1101DM1-007.3700T
DSC1101DM2-040.0000T
DSC1121DM2-026.0000T
DSC1121DM2-019.2000T
DSC1101DM2-048.0000T
DSC2311KM2-R0065T
DSC1101DM1-020.0000T
DSC2311KM2-R0073T
DSC2311KM2-R0067T
DSC2311KM2-R0015T
DSC2311KM2-R0080T
DSC2311KM2-R0089T
DSC1101DM2-050.0000T
DSC2010FM2-B0006T
DSC2011FM1-E0005T
DSC2011FM2-E0015T
DSC2010FM2-A0001T
DSC2011FM1-E0015T
DSC2011FM1-F0041T
DSC2011FM2-E0005T
DSC2011FM2-F0049T
DSC2210FM2-A0030T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC2210FM2-A00311

DSC2010FM2-A0001B

DSA1101DA1-004.0000TVAO

DSA1101DA1-007.3700TVAO

DSA1101DA1-008.0000TVAO

DSA1101DA1-016.0000TVAO

DSA1101DA1-022.5792TVAO

DSA1101DA1-025.0000TVAO

DSA1101DA1-026.9973TVAO

DSA1101DA1-033.3330TVAO

DSA1101DA1-040.0000TVAO

DSA1105DA1-022.5792TVAO

DSA1121DA1-100.0000TVAO

DSA1123DA1-100.0000TVAO

DSA1125DA1-027.0000TVAO

DSA1125DA1-033.3333TVAO

DSA1101DA2-020.0000TVAO

DSC1001DI1-048.0000T

DSC1001DI1-125.0000T

DSC1001DI1-050.0000T

DSC1001DI1-033.3300T

DSC1001DI1-098.3040T

DSC1001DI2-009.6000T

DSC1001DI2-001.0000T

DSC1001DI2-003.6864T

DSC1001DI2-004.0960T

DSC1001DI2-005.0196T

DSC1001DI2-008.0000T

DSC1001DI2-010.0000T

DSC1001DI2-012.0000T

DSC6101MA3B-019.2000T

DSC6101MA3B-027.0000T

DSC6001MA3B-PROGT

DSC6003MA3B-PROGT

DSC6101MA3B-PROGT

DSC6331MA1AB-027.0000T

DSC6111MA3B-050.0000T

DSC6023MA1B-015ST

DSC6101MA2B-020.0000T

DSC6111MA1B-033.0000T

DSC6331MA1AB-025.0000T

DSC6101MA3B-016.6666T

DSC6111MA1B-033.3300T

DSC6101MA3B-026.0000T

DSC6011MA3B-006K000T

DSC6011MA3B-022K000T

DSC6011MA3B-002K000T

DSC6011MA3B-020.0000T

DSC6101MA1B-008.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6011MA1B-032K768T

DSC6011MA3B-025.0000T

DSA6001MA1B-013.5600TVAO

DSA6101MA1B-033.3300TVAO

DSA6121MA1B-01AETVAO

DSA6331MA1AB-025.0000TVAO

DSA6331MA1AB-027.0000TVAO

DSA6331MA1BB-027.0000TVAO

DSA6331MA1DB-027.0000TVAO

DSA6101MA2B-008.0000TVAO

DSA6101MA2B-010.0000TVAO

DSA6311MA2CB-008.0000TVAO

DSA6011MA3B-002K000TVAO

DSA6011MA3B-020.0000TVAO

DSC612NA2A-010JT

DSC612NA2A-010JB

DSC613NA2A-018YT

DSC612NA1A-01H5T

DSC613NA1A-017QT

DSC613NA1A-01KCT

DSC613NA1A-01KDT

DSC6101JA2B-025.0000T

DSC6001JA3B-020.0000T

DSC6331JA3BB-004.0000T

DSC6331JA3AB-004.0000T

DSC6001JA3B-PROGT

DSC6003JA3B-PROGT

DSC6101JA3B-PROGT

DSC6311JA1AB-027.0000T

DSC6331JA1CB-054.0000T

DSC6311JA1BB-027.0000T

DSC6001JA3B-580K000T

DSC6311JA1AB-054.0000T

DSC6331JA2BB-025.0000T

DSC6331JA2IB-025.0000T

DSC6331JA2GB-025.0000T

DSC6331JA2HB-025.0000T

DSC6021JA2B-01ART

DSC6331JA2AB-025.0000T

DSC6331JA2DB-024.5760T

DSC6011JA3B-016K384T

DSC6311JA1AB-045.0000T

DSC6311JA1BB-045.0000T

DSC6311JA1AB-019.2000T

DSC6311JA1BB-019.2000T

DSC6001JA2B-016.0000T

DSC6102JA1B-125K000T

DSC6102JA1B-010K000T

DSC6101JA2B-050.0000T

Date: Monday, November 16, 2020

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6331JA2AB-004.0000T
DSC6331JA2BB-004.0000T
DSC6101JA3B-024.0000T
DSC6011JA1B-040.0000T
DSC6101JA2B-027.0000T
DSA6311JA1AB-027.0000TV02
DSA6101JA1B-027.0000TVAO
DSA6111JA1B-027.0000TVAO
DSA6112JA1B-027.0000TVAO
DSA6311JA1AB-024.0000TVAO
DSA6311JA1AB-025.0000TVAO
DSA6311JA1AB-027.0000TVAO
DSA6331JA1BB-100.0000TVAO
DSA6331JA1CB-100.0000TVAO
DSA6001JA2B-003K277TVAO
DSA6001JA2B-019.2000TVAO
DSA6001JA2B-032K768TVAO
DSA6001JA2B-045.0000TVAO
DSA6011JA2B-012.0000TVAO
DSA6011JA2B-032K768TVAO
DSA6021JA2B-01ARTVAO
DSA6102JA2B-016.0000TVAO
DSA6311JA2AB-024.0000TVAO
DSA6311JA2AB-025.0000TVAO
DSA6331JA2BB-025.0000TVAO
DSA6331JA2GB-025.0000TVAO
DSA6001JA3B-004.0000TVAO
DSA6001JA3B-010.0000TVAO
DSA6001JA3B-016.0000TVAO
DSA6041JA3B-016.0000TVAO
DSC612PA3A-0118T
DSC612PA3A-0119T
DSC612PA3A-011AT
DSC612PA3A-0176T
DSC613PA2A-018WT
DSC612PA3A-01EQT
DSC612PA3A-010KT
DSC1001DI2-029.5000
DSC1001DI5-033.0000
DSC1004DI2-012.0000
DSC1003DI2-024.5760
DSC1001DI1-033.0000
DSC1001DI1-030.0000
DSC1001DI5-004.0000
DSC1004DI2-010.0000
DSC1001DI1-032.0000
DSC1003DI2-100.0000
DSC1001DI2-028.6363
DSC1001DI2-031.2500

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1004DI2-016.0000
DSC8003DI2
DSC1001DI1-012.8000
DSC1003DI5-024.5760
DSC1004DI2-100.0000
DSC1004DI2-048.0000
DSC1004DI2-060.0000
DSC1004DI2-072.0000
DSC1004DI2-086.4000
DSC1004DI5-025.0000
DSC1004DI5-066.4860
DSC1004DI5-066.5800
DSC1001DI5-010.0000
DSC8001DI1
DSC8001DI2
DSC8001DI5
DSC1001DI5-024.0000
DSC1001DI5-024.5760
DSC1001DI5-033.3330
DSC1001DI5-001.8432
DSC1001DI2-018.0000
DSC1001DI5-044.0000
DSC1001DI5-048.0000
DSC1001DI5-050.0000
DSC1001DI5-060.0000
DSC1001DI5-075.0000
DSC1001DI5-080.0000
DSC1001DI1-074.2500
DSC1001DL5-032.0000
DSC1001DI1-054.0000
DSC1001DI1-027.0000
DSC1001DI2-054.0000
DSC1001DI5-047.3385
DSC1001DI1-060.0000
DSC1001DI2-006.7800
DSC1001DI2-004.0960
DSC1001DI2-030.0000
DSC1001DI2-001.8432
DSC1001DI2-066.0000
DSC1001DI5-133.3330
DSC1004DI1-006.7800
DSC1001DI5-018.4320
DSC1001DI1-018.4320
DSC1001DI2-004.0000
DSC1001DI1-004.9152
DSC1001DI2-045.1584
DSC1001DI2-049.1520
DSC1001DI2-011.0592
DSC1003DI2-027.1200

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001DI2-032.7680
DSC1001DI1-016.6666
DSC1001DI5-087.0655
DSC1001DI1-045.1584
DSC1001DI5-025.6000
DSC1001DI1-045.5840
DSC1001DI1-013.3300
DSC1001DI2-003.0720
DSC1001DI2-057.2727
DSC1003DI2-013.5288
DSC1001DI2-096.0000
DSC1001DI2-023.0000
DSC1001DI5-054.0000
DSC1001DI1-029.4912
DSC1001DI5-013.5288
DSC1004DI2-133.0000
DSC1004DI1-050.0000
DSC1001DI1-007.3728
DSC1001DI1-080.0000
DSC1001DI1-002.0000
DSC1101CE5-045.1584T
DSC1103CE5-135.0000T
DSC1103CE1-100.0000T
DSC1124CE2-027.0000T
DSC1101CL2-026.0000T
DSC1124CL5-100.0000T
DSC1123CE5-393.2160T
DSC1121CE1-124.2000T
DSC1121CL2-020.5710T
DSC1121CL5-125.0000T
DSC1123CL2-026.0000T
DSC1121CL2-024.0000T
DSC1123CL3-125.0000T
DSC1121CL5-003.3000T
DSC1123CL3-100.0000T
DSC1123CL3-250.0000T
DSC1123CL3-093.4400T
DSC1103CL5-156.2500T
DSC1103CL5-125.0000T
DSC1103CE5-254.6500T
DSC1124CE2-038.4000T
DSC1104CL1-100.0000T
DSC1103CL5-135.0000T
DSC1103CL5-148.5000T
DSC1103CL5-200.0000T
DSC1103CE2-100.0000T
DSC1123CL2-027.0000T
DSC1103CE2-020.0000T
DSC1103CL5-212.5000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1101CL3-033.3300T
DSC1101BE1-050.0000T
DSC1102BE2-200.0000T
DSC1103BE1-150.0000T
DSC1103BL2-125.0000T
DSC1103BL2-200.0000T
DSC1121BE2-100.0000T
DSC1122BE1-133.3300T
DSC1122BE1-150.0000T
DSC1122BE2-050.0000T
DSC1122BE2-150.0000T
DSC1123BL2-125.0000T
DSC1123BL5-156.2500T
DSC1103BL5-062.5000T
DSC8103BL5T
DSC1124BE2-100.0000T
DSC1104BE2-100.0000T
DSC1103BE5-156.2500T
DSC1122BE1-156.2500T
DSC1124BL1-100.0000T
DSC1101BE5-024.5760T
DSC1101BE5-022.5792T
DSC1121BE2-155.5200T
DSC1123BE1-050.0000T
DSC1101BE1-012.0000T
DSC1121BL5-108.7200T
DSC1121BL5-110.5400T
DSC1123BL5-125.0000T
DSC1123BL5-100.0000T
DSC1123BE1-100.0000T
DSC1001CL5-029.4912T
DSC1001CL2-064.0000T
DSC1001CL2-003.1250T
DSC1001CL2-029.4912T
DSC1001CL2-066.6660T
DSC1001CL2-125.0000T
DSC1001CL5-003.6864T
DSC1001CL3-080.0000T
DSC1001CL3-033.0000T
DSC1001CE1-004.0960T
DSC1001CL5-044.0000T
DSC1001CL1-016.6400T
DSC1003CL2-050.0000T
DSC1001CE1-100.0000T
DSC1001CE1-110.0000T
DSC1001CE1-032.0000T
DSC1001CL3-024.0000T
DSC1001CL3-072.0000T
DSC1001CE2-019.2000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1001CE2-108.0000T
DSC1001CE3-005.0000T
DSC1001CL2-048.0000T
DSC1001CL2-090.0000T
DSC1001CE2-064.0000T
DSC1001CL3-008.0000T
DSC1001CL1-012.0000T
DSC1001CL2-022.5792T
DSC1001CL5-007.3728T
DSC1001CL5-028.0000T
DSC1004CL2-003.2768T
DSC1001CL1-008.0000T
DSC1001CL2-026.0000T
DSC1001CL5-064.0000T
DSC1001CE2-013.5600T
DSC1001CE5-032.2123T
DSC400-3333Q0078KI1
DSC400-3333Q0078KI2
DSC400-1111Q0081KI1
DSC400-1111Q0081KI2
DSC400-3133Q0080KI1
DSC400-3133Q0080KI2
DSC400-0101Q0082KI1
DSC400-0101Q0082KI2
DSC400-1311Q0076KI1
DSC400-1311Q0076KI2
DSC400-0303Q0086KI1
DSC400-0303Q0086KI2
DSC400-0111Q0087KI1
DSC400-0111Q0087KI2
DSC400-3111Q0088KI1
DSC400-3111Q0088KI2
DSC400-3333Q0089KI1
DSC400-3333Q0089KI2
DSC400-4444Q0023KI1
DSC400-4444Q0023KI2
DSC400-4444Q0059KI1
DSC400-4444Q0059KI2
DSC400-1111Q0090KI1
DSC400-1111Q0090KI2
DSC400-1111Q0091KI1
DSC400-1111Q0091KI2
DSC400-2222Q0022KI1
DSC400-2222Q0022KI2
DSC400-0303Q0092KI1
DSC400-0303Q0092KI2
DSC400-3333Q0093KI1
DSC8103AI5
DSC1102AI1-100.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC8121AI2

DSC1103AI1-125.0000

DSC8122AI2

DSC8123AI2

DSC1103AI2-100.0000

DSC1103AI2-125.0000

DSC1103AI2-171.8181

DSC1103AI2-200.0000

DSC8101AI2

DSC1121AI2-148.5000

DSC8124AI2

DSC1121AI2-053.1250

DSC1123AI5-100.0000

DSC1103AI5-120.0000

DSC1103AI5-125.0000

DSC1103AI5-156.2500

DSC1103AI5-250.0000

DSC1104AI2-100.0000

DSC1121AI1-025.0000

DSC1121AI1-125.0000

DSC1121AI2-025.0000

DSC1121AI2-026.0000

DSC1121AI2-050.0000

DSC1121AI2-125.0000

DSC1121AI5-020.0000

DSC1121AI5-050.0000

DSC1121AI5-125.0032

DSC1122AI1-125.0000

DSC1122AI2-019.4400

DSC1122AI2-150.0000

DSC1122AI2-155.5200

DSC1122AI2-156.2500

DSC1122AI2-425.0000

DSC1122AI2-156.2539

DSC1122AI5-077.7600

DSC1122AI5-125.0000

DSC1122AI5-133.3300

DSC1122AI5-155.5200

DSC1122AI5-156.2500

DSC1123AI1-075.0000

DSC1123AI1-100.0000

DSC1123AI5-175.0000

DSC1123AI1-125.0000

DSC1123AI1-150.0000

DSC1123AI1-200.0000

DSC1123AI2-025.0000

DSC1123AI2-040.0000

DSC1123AI2-100.0000

DSC1123AI2-120.0000

Date: Monday, November 16, 2020

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1123AI2-125.0000
DSC1123AI2-148.5000
DSC1123AI2-150.0000
DSC1123AI2-156.2500
DSC1123AI2-200.0000
DSC1122AI5-025.0020
DSC1123AI5-125.0000
DSC1123AI5-133.3300
DSC1123AI5-135.0000
DSC1123AI5-148.3500
DSC1123AI5-148.5000
DSC1123AI5-150.0000
DSC1123AI5-155.5200
DSC1123AI5-156.2500
DSC1123AI5-200.0000
DSC1123AI5-322.2656
DSC1121AI2-020.0000
DSC1101AI5-019.4400
DSC1123AI5-116.0000
DSC1101AI2-125.0000
DSC1123AI5-185.6250
DSC1123AI2-166.6666
DSC1123AI2-050.0023
DSC1101AI2-120.0000
DSC1122AI2-050.0000
DSC1123AI2-140.0000
DSC1101AI5-099.7200
DSC1121AI1-027.0000
DSC1101AI2-025.0000
DSC1124AI2-100.0000
DSC1121AI2-162.0000
DSC1101AI5-156.2500
DSC1101AI2-156.2500
DSC1101AI5-056.3200
DSC1101AI5-048.0000
DSC1121AI2-012.2880
DSC1121AI5-100.0000
DSC1123AI5-027.0000
DSC1121AI5-027.0000
DSC1121AI2-010.0000
DSC1121AI2-061.4400
DSC1101AI5-032.0000
DSC1103AI2-148.5000
DSC1102AI2-167.3320
DSC1123AI5-019.2000
DSC1101AI5-010.0000
DSC1101CI2-030.0000
DSC1101CI2-050.0000
DSC1101CI2-100.0000

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1101CI5-020.0000
DSC1101CI5-022.5791
DSC1101CI5-024.5760
DSC1101CI5-050.0000
DSC1102CI1-125.0000
DSC1102CI5-025.0000
DSC1102CI5-040.0000
DSC1102CI5-062.5000
DSC1103CI1-156.2500
DSC1102CI5-200.0000
DSC1103CI1-075.0000
DSC1103CI1-100.0000
DSC1103CI1-200.0000
DSC1103CI2-100.0000
DSC1103CI2-125.0000
DSC1103CI2-148.5000
DSC1103CI2-156.2500
DSC1103CI5-025.0000
DSC1103CI5-050.0000
DSC1103CI5-075.0000
DSC1103CI5-100.0000
DSC1103CI5-106.2500
DSC1103CI5-114.0000
DSC1103CI5-140.0000
DSC1103CI5-148.5000
DSC1121CI2-014.7456
DSC1103CI5-200.0000
DSC1103CI5-233.3333
DSC1103CI5-300.0000
DSC1121CI1-024.0000
DSC1121CI1-025.0000
DSC1121CI2-024.0000
DSC1103CI1-125.0000
DSC1121CI2-025.0000
DSC1121CI2-031.2500
DSC1121CI2-066.6660
DSC1121CI2-050.0000
DSC1121CI2-100.0000
DSC1121CI2-115.0000
DSC1121CI2-125.0000
DSC1121CI2-132.0000
DSC1121CI2-168.0000
DSC1121CI5-016.0000
DSC1121CI5-022.5000
DSC1121CI5-040.0000
DSC1121CI5-045.0000
DSC1121CI5-049.1520
DSC1122CI1-125.0000
DSC1122CI1-156.2500

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1122CI2-125.0000
DSC1122CI2-156.2500
DSC1122CI2-150.0000
DSC1122CI5-025.0000
DSC1122CI5-200.0000
DSC1123CI1-010.0000
DSC1123CI1-022.8800
DSC1123CI1-125.0000
DSC1123CI1-200.0000
DSC1123CI2-100.0000
DSC1123CI2-125.0000
DSC1123CI2-025.0000
DSC1123CI2-156.2500
DSC1121CI2-024.5760
DSC1121CI2-020.0000
DSC1122CI2-103.1250
DSC1101CI5-025.0000
DSC1103CI5-224.8200
DSC1123CI2-333.3300
DSC1123CI5-156.2500
DSC1123CI2-212.5000
DSC1123CI5-100.0000
DSC1123CI2-020.0000
DSC1123CI1-027.0000
DSC1123CI2-333.3333
DSC1123CI2-312.5000
DSC1101CI1-025.0000
DSC1124CI5-156.2500
DSC1103CI2-148.3500
DSC1103CI2-200.0000
DSC1123CI2-085.0000
DSC1123CI2-300.0000
DSC8122CI5
DSC1123CI2-150.0000
DSC1123CI2-200.0000
DSC1123CI2-432.0000
DSC1123CI5-026.5625
DSC1123CI5-032.0000
DSC1123CI5-034.0000
DSC1123CI5-040.0000
DSC1123CI5-125.0000
DSC1124CI2-100.0000
DSC1123CI5-409.3750
DSC1124CI1-156.2500
DSC1124CI2-200.0000
DSC1124CI5-100.0000
DSC1123CI2-062.5000
DSC1103CI5-233.2090
DSC8101CI1

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1123AI1-156.2500T
DSC1123AI2-025.0000T
DSC1123AI2-100.0000T
DSC1123AI2-040.0000T
DSC1123AI2-148.5000T
DSC1123AI1-200.0000T
DSC1123AI2-125.0000T
DSC1123AI2-200.0000T
DSC1123AI2-156.2500T
DSC1123AI5-125.0000T
DSC1123AI5-148.5000T
DSC1123AI5-133.3300T
DSC1123AI5-150.0000T
DSC1123AI5-200.0000T
DSC1121AI2-020.0000T
DSC1101AI5-019.4400T
DSC1123AI5-116.0000T
DSC1101AI2-125.0000T
DSC1123AI5-185.6250T
DSC1123AI2-166.6666T
DSC1123AI2-050.0023T
DSC1101AI2-120.0000T
DSC1122AI2-050.0000T
DSC1123AI2-140.0000T
DSC1101AI5-099.7200T
DSC1121AI1-027.0000T
DSC1101AI2-025.0000T
DSC1124AI2-100.0000T
DSC1121AI2-162.0000T
DSC1101AI5-156.2500T
DSC1101AI2-156.2500T
DSC1101AI5-056.3200T
DSC1101AI5-048.0000T
DSC1121AI2-012.2880T
DSC1121AI5-100.0000T
DSC1123AI5-027.0000T
DSC1121AI5-027.0000T
DSC1121AI2-010.0000T
DSC1121AI2-061.4400T
DSC1101AI5-032.0000T
DSC1103AI2-148.5000T
DSC1102AI2-167.3320T
DSC1123AI5-019.2000T
DSC1101AI5-010.0000T
DSC1123AI5-270.0000T
DSC1122AI2-100.3000T
DSC1101AI2-150.0000T
DSC1103AI1-155.5200T
DSC1103AI1-161.1328T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103AI2-125.0031T
DSC1122AI2-125.0000T
DSC1123AI1-155.5200T
DSC1123AI1-161.1300T
DSC6301JL2AB-027.0000T
DSC6301JL2BB-027.0000T
DSC6001JE2B-013.5600T
DSC6021JE1B-0193T
DSC6331JE1EB-012.0000T
DSC6121JE1B-0198T
DSC6111JE1B-033.0000T
DSC6101JL2B-033.0000T
DSC6001JL3B-032.7680T
DSC6011JL2B-032K768T
DSC6301JL1LB-001.0000T
DSC6021JE1B-01B4T
DSC6101JE3B-024.0000T
DSC6003JE2B-032K768T
DSC6001JL3B-025.0000T
DSC6101JE1B-024.0000T
DSC6001JL2B-006.0053T
DSC6001JE2B-024.0000T
DSC6001JE3B-024.0000T
DSC6001JE2B-025.0000T
DSC6101JE1B-050.0000T
DSC6023JE1B-01D6T
DSC6021JE1B-01D7T
DSC6023JE1B-01D8T
DSC6021JE1B-01D9T
DSC6023JE1B-01DST
DSC6023JE1B-01DVT
DSC6111JE2B-100.0000T
DSC6021JE1B-01EAT
DSC6001JL1B-025K600T
DSC6101JL3B-027.0000T
DSC6311JE1BB-018.4320T
DSC6311JE1CB-018.4320T
DSC6102JL1B-088.0000T
DSC6102JL1B-033.0000T
DSC6112JE1B-100.0000T
DSC6021JE3B-01GBT
DSC6021JL1B-01HBT
DSC6001JE1B-052.0000T
DSC6121JE1B-01HDT
DSC6121JE1B-01HET
DSC6121JE1B-01HGT
DSC6011JE1B-027.0000T
DSC6311JE2FB-064.0000T
DSC6011JE1B-024.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSA6102JL3B-087.0655VAO

DSA6112JL3B-054.0000VAO

DSA6301JL3AB-054.0000VAO

DSA6311JL3AB-054.0000VAO

DSA6101JL1B-020.0000VAO

DSC613PL3A-0106

DSC612PL2A-0132

DSC613PL2A-0131

DSC612PL2A-0130

DSC612PL3A-012Y

DSC612PE3A-013K

DSC612PE3A-014V

DSC613PE1A-017Q

DSC612PE3A-017R

DSC613PE2A-017Q

DSC613PE1A-01CK

DSC612PL3A-01D5

DSC613PL2A-01DG

DSC612PL2A-01ER

DSC613PE2A-01KD

DSC613PE2A-01M2

DSC613PE2A-01KC

DSA612PL2A-01CSVAO

DSA612PL3A-01BHVAO

DSC612RL3A-010K

DSC613RL2A-0131

DSC613RE1A-0135

DSC6121JL2B-015G

DSC6003JL2B-032K768

DSC6011JE1B-025.0000

DSC6011JL2B-025.0000

DSC6011JE3B-003K898

DSC6001JE1B-025.0000

DSC6311JL2AB-027.0000

DSC6311JL2BB-027.0000

DSC6111JL2B-008.0000

DSC6011JE1B-840K000

DSC6121JL2B-0170

DSC6101JL3B-025.0000

DSC6001JE3B-040K000

DSC6301JL2AB-027.0000

DSC6301JL2BB-027.0000

DSC6001JE2B-013.5600

DSC6021JE1B-0193

DSC6331JE1EB-012.0000

DSC6121JE1B-0198

DSC6111JE1B-033.0000

DSC6101JL2B-033.0000

DSC6001JL3B-032.7680

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6011JLZB-032K768
DSC6301JL1LB-001.0000
DSC6021JE1B-01B4
DSC6101JE3B-024.0000
DSC6003JE2B-032K768
DSC6001JL3B-025.0000
DSC1123AE2-003.5000T
DSC1101AL5-045.1584T
DSC1101AL5-049.1520T
DSC1123AE2-156.2500T
DSC1121AE2-004.9152T
DSC1121AE2-133.0000T
DSC1102AE2-400.0000T
DSC1101AE3-024.0000T
DSC1103AL5-150.0000T
DSC1103AL5-015.0000T
DSC1102AE2-155.5200T
DSC1103AE3-416.0000T
DSC1121AL5-041.5000T
DSC1121AE2-041.5000T
DSC1121AE5-041.5000T
DSC1121AL2-041.5000T
DSC1121AL1-041.5000T
DSC1123AE1-159.3750T
DSC1103AL1-125.0000T
DSC1122AE2-075.0000T
DSC1121AL5-012.0000T
DSC1101AL2-156.2500T
DSC1103AE2-085.0000T
DSC1123AE2-085.0000T
DSC1121AE5-025.0000T
DSC1121AE5-020.0000T
DSC1100AL3-PROGT
DSC1101AL3-PROGT
DSC1121AE2-020.0000T
DSC1100AL5-PROGT
DSC1101AL5-PROGT
DSC1123AE2-100.0000T
DSC1123AE1-150.0000T
DSC1123AE2-040.0000T
DSC1121AL5-010.0000T
DSC1121AL5-100.0000T
DSC1123AL2-125.0000T
DSC1103AE2-135.0000T
DSC1123AL5-100.0000T
DSC1123AL5-148.5000T
DSC1121AE5-010.0000T
DSC1101AL5-112.4400T
DSC1123AL2-100.0000T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC1103AL2-147.4560T
DSC1121AL5-112.2400T
DSC1121AE5-022.5792T
DSC1121AE5-024.5760T
DSC1121AL5-170.0000T
DSC1121AL5-024.5760T
DSC1121AL5-022.5792T
DSC1121AL5-125.0000T
DSC1101AE2-027.1200T
DSC1123AL1-148.5000T
DSC1103AL1-100.0000T
DSC1103AE2-212.5000T
DSC1124AE5-065.0000T
DSC1101AE5-032.0000T
DSC1123AL5-156.2500T
DSC1123AL5-125.0000T
DSC1103AL2-125.0031T
DSC1123AE5-148.5000T
DSC1123AE5-148.3516T
DSC1123AE5-074.1758T
DSC1123AE1-125.0000T
DSC1101AE2-016.3840T
DSC8121AL2T
DSC1123AE1-148.3500T
DSC1123AE1-148.5000T
DSC1123AL1-150.0000T
DSC1123AE1-100.0000T
DSC1101AE3-098.3040T
DSC6331JI2FB-025.0000T
DSC6111JI1B-200K000T
DSC6001JI2B-022.5792T
DSC6311JI1DB-036.0000T
DSC6311JI1DB-075.0000T
DSC6311JI1DB-100.0000T
DSC6102JI1B-060.0000T
DSC6101JI2B-019.2000T
DSC6331JI2EB-012.0000T
DSC6011JI2B-024.0000T
DSC6003JI2B-050.0000T
DSC6311JI2EB-018.4320T
DSC6301JI2GB-024.0000T
DSC6311JI1AB-025.0000T
DSC6011JI2B-018.0000T
DSC6101JI1B-048.0000T
DSC6013JI2B-050.0000T
DSC6001JI1B-027.0000T
DSC6331JI3CB-018.4320T
DSC6331JI1CB-018.4320T
DSC6111JI1B-028.1250T

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6021JI2B-01G31

DSC6112JI2B-028.1250T

DSC6001JI1B-020.0000T

DSC6111JI1B-008.0000T

DSC6331JI2FB-024.5760T

DSC6051JI2B-014.3180T

DSC6011JI1B-006.5536T

DSC6011JI3B-012.0000T

DSC6051JI3B-032K768T

DSC6001JI3B-032K768T

DSC6001JI2B-012.0000T

DSC6011JI2B-008.0000T

DSC6121JI3B-01GPT

DSC6311JI2CB-025.0000T

DSC6111JI3B-019.2000T

DSC6331JI1BB-018.4320T

DSC6001JI2B-007.3730T

DSC6301JI1IB-050.0000T

DSC6102JI1B-500K000T

DSC6101JI1B-019.2000T

DSC6021JI1B-01H4T

DSC6331JI1BB-024.0000T

DSC6001JI3B-005K280T

DSC6001JI3B-004K280T

DSC6021JI1B-01HAT

DSC6003MI2B-014.0000

DSC6003MI2B-026.0000

DSC6101MI2B-048.0000

DSC6001MI3B-004.0960

DSC6111MI2B-027.0000

DSC6111MI2B-024.5454

DSC6331MI2CB-008.0000

DSC6331MI2DB-008.0000

DSC6331MI2EB-008.0000

DSC6011MI2B-025.0000

DSC6011MI2B-056.0000

DSC6101MI2B-006.1679

DSC6003MI3B-032K768

DSC6003MI3B-012.0000

DSC6003MI2B-027.0000

DSC6111MI2B-006.1679

DSC6011MI1B-007.3728

DSC6102MI2B-125K000

DSC6101MI2B-008.0000

DSC6001MI3B-032K768

DSC6003MI2B-080.0000

DSC6003MI2B-032K768

DSC6003MI2B-050.0000

DSC6111MI2B-025.0000

Date: Monday, November 16, 2020

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC6001MI2B-007.3728
DSC6001MI1B-007.3728
DSC6011MI2B-007.3728
DSC6021MI1B-01B1
DSC6301MI2CB-008.0000
DSC6001MI1B-032K768
DSC6001MI2B-032K768
DSC6001MI2B-027.0000
DSC6102MI3B-038.4000
DSC6001MI2B-032.7680
DSC6111MI3B-033.3333
DSC6011MI3B-048.0000
DSC6101MI2B-024.0000
DSC6101MI1B-050.0000
DSC6101MI1B-024.0000
DSC6011MI2B-004.0960
DSC6311MI2CB-008.0000
DSC6011MI3B-032.0000
DSC6001MI1B-080.0000
DSC6102MI1B-500K000
DSC6101MI1B-019.2000
DSC6111MI3B-025.0000
DSC6011MI2B-024.0000
DSC6011MI2B-006K144
DSC6011MI3B-025.0000
DSC6102MI3B-080.0000
DSC6101MI1B-027.0000
DSC6102MI2B-027.0000
DSC6101MI2B-025.0000
DSC6112MI2B-025.0000
DSC6112MI2B-014.7456
DSC6021MI2B-01K2
DSC6112MI3B-060.0000
DSC6121MI2B-01MP
DSC6122MI2B-01MQ
DSC6101MI1B-020.0000
DSC6011MI1B-012.2880
DSA6001MI1B-024.5760VAO
DSA6001MI2B-032.7680VAO
DSA6003MI2B-032K768VAO
DSA6311MI2CB-008.0000VAO
DSA6003MI3B-032K768VAO
DSA6102MI3B-038.4000VAO
DSC612NI3A-010G
DSC612NI3A-010T
DSC613NI2A-0106
DSC613NI3A-0105
DSC613NI1A-016E
DSC613NI1A-016G

GBNG-11YGIP429 - CCB 3433.001 Final Notice: Implement top marking changes for selected DSCxxx and DSAxxx products available in 6L VDFN, 4L VDFN, 4L VFLGA, 6L VFLGA, 4L VLGA, 14L VQFN and 20L VQFN packages at NSEB assembly site.

DSC613NI3A-01A6

DSC612NI1A-01H3

DSC612NI2A-01K7

DSC612NI3A-013C