



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001033

DATE: 22-Mar-2021

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS32KHZ/WBGA+T&R	N/A	21-Jan-2022	20-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX15029ATB/VY+	N/A	22-Mar-2021	18-Sep-2021	The part was not released
Discontinuance	MAX15029ATB/VY+T	N/A	22-Mar-2021	18-Sep-2021	The part was not released
Discontinuance	MAX17842BGUE/V+	N/A	22-Mar-2022	18-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX17842BGUE/V+T	N/A	22-Mar-2022	18-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX20002ATPB/V+C2	MAX20002ATPB/V+	22-Mar-2021	18-Sep-2021	Part can no longer be manufactured
Discontinuance	MAX20002ATPB/V+TC2	MAX20002ATPB/V+T	22-Mar-2021	18-Sep-2021	Part can no longer be manufactured
Discontinuance	MAX20003ATPA/V+C2	MAX20003ATPA/V+	22-Mar-2021	18-Sep-2021	Part can no longer be manufactured
Discontinuance	MAX20003ATPA/V+TC2	MAX20003ATPA/V+T	22-Mar-2021	18-Sep-2021	Part can no longer be manufactured
Discontinuance	MAX20003ATPB/V+C2	MAX20003ATPB/V+	22-Mar-2021	18-Sep-2021	Part can no longer be manufactured
Discontinuance	MAX20418ATGB/V+	MAX20418ATGC/V+	22-Mar-2021	18-Sep-2021	The part was not released
Discontinuance	MAX20418ATGB/V+T	MAX20418ATGC/V+T	22-Mar-2021	18-Sep-2021	The part was not released
Discontinuance	MAX96716KGTM/VY+	N/A	22-Mar-2022	18-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX96716KGTM/VY+T	N/A	22-Mar-2022	18-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX98390EWX+	MAX98390CEWX+	29-Mar-2022	25-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX98390EWX+T	MAX98390CEWX+T	29-Mar-2022	25-Sep-2022	Part can no longer be manufactured
Discontinuance	MAXQ1850-LNS+	N/A	21-Jan-2022	20-Jul-2022	Part can no longer be manufactured
Discontinuance	VT1697SBFQX+CNR	N/A	22-Mar-2022	18-Sep-2022	Part can no longer be manufactured
Discontinuance	VT281BFCX-ADJ	N/A	22-Jun-2021	19-Dec-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 22-Apr-2021

Affected part numbers	LTB	Replacement	LTS
DS32KHZ/WBGA+T&R	1/21/2022	N/A	7/20/2022
MAX17842BGUE/V+	3/22/2022	N/A	9/18/2022
MAX17842BGUE/V+T	3/22/2022	N/A	9/18/2022
MAX96716KGTM/VY+	3/22/2022	N/A	9/18/2022
MAX96716KGTM/VY+T	3/22/2022	N/A	9/18/2022
MAX98390EWX+	3/29/2022	MAX98390CEWX+	9/25/2022
MAX98390EWX+T	3/29/2022	MAX98390CEWX+T	9/25/2022
MAXQ1850-LNS+	1/21/2022	N/A	7/20/2022
VT1697SBFQX+CNR	3/22/2022	N/A	9/18/2022