



DATE: Jan 17, 2021
TO: Future Electronics (000626)
SUBJECT: ATSAM51J20A Incorrect Marking

Microchip Technology, Inc. (“Microchip”) declares that the devices recently produced with incorrect marking format as following photos. Part number incorrectly marked on parts in specific lots, which is a typographical error and does not affect any form, fit or function of the device.

Incorrect marking	Correct marking
ATSAME53J19A	ATSAMD51J20A

Sales Order No	Line item	Purchase order	Microchip catalog part number	LOT Number	Shipment Number	Shipment Date	Ship Quantity (Units)
21534870	1	CC7QP1	ATSAMD51J20A-AU	184000736100ASE	L1-US-FTH-S13626221	6/30/21	160
21662499	6	ACA3RH	ATSAMD51J20A-AU	183900714100ASE	L1-US-FTH-S14135490	11/26/21	160
21662499	6	ACA3RH	ATSAMD51J20A-AU	185000486110ASE	L1-US-FTH-S14135490	11/26/21	160
21662499	6	ACA3RH	ATSAMD51J20A-AU	183900714300ASE	L1-US-FTH-S14135490	11/26/21	480

If there are any further questions, please contact your Microchip representative.

Regards,

Microchip Technology, Inc.