



Product/Process Change Notice

PCN # P-2203-0011

Date: 2022/3/18

Dear Customer:

Please be informed that Macronix is going to discontinue offering the “Tube” packing option for the 32PLCC package products. The reason for this change is the lead scanning machine is no longer operational and cannot be repaired. The 32PLCC products will continue to be offered in “Tray” or “Tape & Reel” packing options.

The detailed information about this change is described in the following page. If you have any questions, please contact your Macronix representative or sales channel.

Thank you.

Macronix International Co., Ltd.

旺宏電子股份有限公司

PCN No.: P-2203-0011

Issue Date : 2022/3/18

Subject: Remove "Tube" packing option for 32PLCC products.

Affected Macronix Part No.:

Note: these Macronix part numbers are still available to order; however, they will be shipped in "Tray" or "Tape & Reel" packing option only.

MX29F040CQC-70G

MX29F040CQC-90G

MX29F040CQI-70G

MX29F040CQI-90G

MX29LV040CQC-70G

MX29LV040CQI-55Q

MX29LV040CQI-70G

MX29LV040CQI-90G

Package type: 32PLCC package

Change Category: Packing type change

Reason of Change:

The lead scanning machine is no longer operational and cannot be repaired. Macronix will offer "Tray" (default option) or "Tape & Reel" as the replacement option. Macronix part numbers do not include the packing option designator (code). Kindly specify the packing option desired in the comments/remarks section of your purchase order.

Before Change :

Tube packing or

Tray packing or

Tape & Reel packing

After Change :

Tray packing or

Tape & Reel packing

Assessment of Change:

1. No impact to Form, Fit, Function, Quality & Reliability.
2. No change on material, process, machine and production site.

Schedule:

Effective date: 2022/04/01.