

Product discontinuation

PD_077_22

Last order date: 2022-09-30Last delivery date: 2023-03-31

Reason: Product portfolio rationalization

DISCONTINUED				NEW (REPLACEMENT)			
Sales name	SP number	OPN	Package	Sales name	SP number	OPN	Package
IFX21401MB	SP000614692	IFX21401MBHT SA1	PG-SCT595-5	TLE4250-2G	SP000255450	TLE42502GHTS A1	PG-SCT595-5-2
IFX25001TF V50	SP000614696	IFX25001TFV50 ATMA1	PG-TO252-3	TLE42744D V50	SP000461576	TLE42744DV50A TMA1	PG-TO252-3-11
IFX25401TEV	SP000614698	IFX25401TEVAT MA1	PG-TO252-5	TLE42764DV	SP000427326	TLE42764DVAT MA1	PG-TO252-5-11
IFX27001TF V50	SP000622990	IFX27001TFV50 ATMA1	PG-TO252-3	TLE4284D V50	SP000362371	TLE4284DV50A TMA1	PG-TO252-3-11
IFX20001MB V33	SP000623344	IFX20001MBV33 HTSA1	PG-SCT595-5	TLE4296-2G V33	SP000014332	TLE42962GV33 HTSA1	PG-SCT595-5-2
IFX20001MB V50	SP000623428	IFX20001MBV50 HTSA1	PG-SCT595-5	TLE4296-2G V50	SP000014333	TLE42962GV50 HTSA1	PG-SCT595-5-2
IFX27001TFV	SP000624090	IFX27001TFVAT MA1	PG-TO252-3	TLE4284DV	SP000356994	TLE4284DVATM A1	PG-TO252-3-11
IFX27001TF V33	SP000624112	IFX27001TFV33 ATMA1	PG-TO252-3	TLE4284D V33	SP000362370	TLE4284DV33A TMA1	PG-TO252-3-11
IFX24401TE V50	SP000660598	IFX24401TEV50 ATMA1	PG-TO252-5	TLE7276-2D	SP000457394	TLE72762DATM A1	PG-TO252-5-11
IFX20002MB V33	SP001041636	IFX20002MBV33 HTSA1	PG-SCT595-5	TLE4296-2G V33	SP000014332	TLE42962GV33 HTSA1	PG-SCT595-5-2

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended! If Infineon confirms a purchase order with a delivery date beyond last delivery date, the PD with the mentioned last ordering date still remains valid.

2022-03-30 Page **1** of **2**



Product discontinuation

PD_077_22

2022-09-30 Last order date: Last delivery date: 2023-03-31

DISCONTINUED				NEW (REPLACEMENT)			
Sales name	SP number	OPN	Package	Sales name	SP number	OPN	Package
IFX20002MB V50	SP001041644	IFX20002MBV50 HTSA1	PG-SCT595-5	TLE4296-2G V50	SP000014333	TLE42962GV50 HTSA1	PG-SCT595-5-2
IFX1963TEV	SP001045788	IFX1963TEVAT MA1	PG-TO252-5	TLF1963TE	SP000993526	TLF1963TEATM A1	PG-TO252-5-11
IFX2931G V50	SP001370954	IFX2931GV50XU MA2	PG-DSO-8	TLE4264-2G	SP000804364	TLE42642GHTS A2	PG-SOT223-4-21
IFX25001ME V33	SP001586408	IFX25001MEV33 HTSA2	PG-SOT223-4	TLE4274GS V33	SP001130104	TLE4274GSV33 HTSA2	PG-SOT223-4-21
IFX25001TF V33	SP001586410	IFX25001TFV33 ATMA2	PG-TO252-3	TLE4274D V33	SP001130102	TLE4274DV33A TMA2	PG-TO252-3-11
IFX25401TE V50	SP001665282	IFX25401TEV50 ATMA2	PG-TO252-5	TLE42764D V50	SP000636156	TLE42764DV50A TMA1	PG-TO252-5-11

If you have any questions, please do not hesitate to contact your local sales office.



On 16 April 2020, Infineon Technologies acquired Cypress.

We are now in the process of merging and consolidating our tools and processes for PCN, Information Notes, Errata and Product Discontinuance. For further details, please visit our website:

https://www.infineon.com/cms/en/about-infineon/company/cypress-acquisition/

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended! If Infineon confirms a purchase order with a delivery date beyond last delivery date, the PD with the mentioned last ordering date still remains valid.

2022-03-30 Page 2 of 2