

Attn.: _____

HIROSE ELECTRIC CO., LTD.
2-6-3 Nakagawa Chuoh, Tsuzuki-ku, Yokohama, JAPAN

Product Change Notification

We are writing today to inform you that we will make some product changes for the reasons described below.

1	Products affected	Please refer to attachment.									
2	Replacement product	There is no change in product code and product name.									
3	Classification of change	Silicon manufacturer addition and Silicon seal manufacturing place addition									
4	Changes	<p>1 Silicon manufacturer addition</p> <table border="1"> <thead> <tr> <th></th> <th>Before</th> <th>After</th> </tr> </thead> <tbody> <tr> <td>Manufacturer</td> <td>Momentive</td> <td>Momentive SEESUN</td> </tr> <tr> <td>Material</td> <td>Silicon</td> <td>Silicon</td> </tr> </tbody> </table> <p><DF62W-*S-2.2C(**)> <DF62W-*EP-2.2C(**)></p> <p><DF62W(Z)-*P-2.2DSA(**)></p> <p>2 Seal manufacturing place addition China is added to current seal manufacturing place (Japan).</p> <p>These changes will not affect the performances of the product.</p>		Before	After	Manufacturer	Momentive	Momentive SEESUN	Material	Silicon	Silicon
	Before	After									
Manufacturer	Momentive	Momentive SEESUN									
Material	Silicon	Silicon									
5	Reason for change	Current manufacturer stopped silicon. And BCP.									
6	Schedule of change	We have just changed. Sorry for causing inconvenience.									

If you should have any questions, please feel free to contact a Hirose business representative.
Your understanding and cooperation are highly appreciated.

Product List

No.	Product code	Part number	Remark
1	544-0094-0 00	DF62WA-6EP-2.2C	HRS original
2	544-0095-0 11	DF62WA-6S-2.2C(11)	HRS original
3	544-0096-0 00	DF62WD-2EP-2.2C	HRS original
4	544-0097-0 00	DF62WD-3EP-2.2C	HRS original
5	544-1002-7 00	DF62W-2S-2.2C	HRS original
6	544-1002-7 11	DF62W-2S-2.2C(11)	HRS original
7	544-1003-0 00	DF62W-2EP-2.2C	HRS original
8	544-1004-2 00	DF62W-3S-2.2C	HRS original
9	544-1004-2 11	DF62W-3S-2.2C(11)	HRS original
10	544-1005-5 00	DF62W-3EP-2.2C	HRS original
11	544-1006-8 00	DF62W-4S-2.2C	HRS original
12	544-1006-8 11	DF62W-4S-2.2C(11)	HRS original
13	544-1007-0 00	DF62W-4EP-2.2C	HRS original
14	544-1008-3 00	DF62W-6S-2.2C	HRS original
15	544-1008-3 11	DF62W-6S-2.2C(11)	HRS original
16	544-1009-6 00	DF62W-6EP-2.2C	HRS original
17	544-1009-6 10	DF62W-6EP-2.2C(10)	HRS original
18	544-1010-5 00	DF62W-9S-2.2C	HRS original
19	544-1010-5 11	DF62W-9S-2.2C(11)	HRS original
20	544-1011-8 00	DF62W-9EP-2.2C	HRS original
21	544-1019-0 00	DF62W-2EP-2.2C-PA	HRS original
22	544-1021-0 20	DF62W-3P-2.2DSA(20)	HRS original
23	544-1030-0 00	DF62WA-9S-2.2C	HRS original
24	544-1031-0 00	DF62WB-9S-2.2C	HRS original
25	544-1032-0 00	DF62WC-9S-2.2C	HRS original
26	544-1033-0 00	DF62WD-9S-2.2C	HRS original
27	544-1036-0 00	DF62WB-9EP-2.2C	HRS original
28	544-1037-0 00	DF62WC-9EP-2.2C	HRS original
29	544-1040-0 00	DF62WE-9S-2.2C	HRS original
30	544-1041-0 00	DF62WE-9EP-2.2C	HRS original
31	544-1046-0 00	DF62WC-2S-2.2C	HRS original
32	544-1047-0 00	DF62WC-2EP-2.2C	HRS original
33	544-1048-0 18	DF62WEA-9S-2.2C(18)	HRS original
34	544-1050-0 20	DF62WZ-9P-2.2DSA(20)	HRS original
35	544-1050-0 21	DF62WZ-9P-2.2DSA(21)	HRS original
36	544-1050-0 50	DF62WZ-9P-2.2DSA(50)	HRS original
37	544-1051-0 00	DF62WC-4S-2.2C	HRS original
38	544-1052-0 00	DF62WC-4EP-2.2C	HRS original
39	544-1053-0 00	DF62WC-3EP-2.2C	HRS original
40	544-1054-0 00	DF62WC-3S-2.2C	HRS original
41	544-1057-0 00	DF62WC-6S-2.2C	HRS original
42	544-1058-0 00	DF62WC-6EP-2.2C	HRS original
43	544-1059-0 20	DF62WZ-6P-2.2DSA(20)	HRS original

No.	Product code	Part number	Remark
44	544-1056-0 00	DF62WP-3/4/6/2EP-2.2C	HRS original
45	544-1065-0 00	DF62W-9P/4PORT-2EP/HN	Custom made