

[Home](#) / [Product Change Notifications](#) / [SYST-12EITS929](#)

Product Change Notification / SYST-12EITS929

SYST-12EITS929

Microchip has released a new Datasheet for the BM62/64 Bluetooth Stereo Audio Module of devices. If you are using one of these devices please read the document located at [BM62/64 Bluetooth Stereo Audio Module](#).

Notification Status: Final

Description of Change:

- 5.0 "Application Information" - Updated the section
- A.9 "UKCA (UK Conformity Assessed)" - Added UKCA regulatory approval information

Impacts to Data Sheet: See above details

Change Implementation Status: Complete

Date Document Changes Effective: 13 Jul 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Date

13-Jul-2022

PCN Type

Document Change

PCN

SYST-12EITS929

Title

Data Sheet - BM62/64 Bluetooth Stereo Audio Module Datasheet Document Revision

Product Category

Bluetooth Module

Affected CPNs

[SYST-12EITS929 Affected CPN 07132022.pdf](#)

[SYST-12EITS929 Affected CPN 07132022.csv](#)

Attachments

[BM62/64 Bluetooth Stereo Audio Module](#)



[Contact](#) | [Legal](#) | [Privacy Policy](#) | [Cookies](#) | [Careers](#)

Stay on the leading edge with our blog

MicroSolutions



© Copyright 1998-2022 Microchip Technology Inc. All rights reserved.

Affected Catalog Part Numbers (CPN)

BM62SPKS1MC2-0001AA
BM62SPKA1MC2-0001AA
BM62SPKS1MC2-000CFG
BM62SPKS1MC2-R002AA
BM64SPKA1MC1-0001AA
BM64SPKA1MC2-0001AA
BM64SPKS1MC1-0001AA
BM64SPKS1MC2-0001AA
BM64SPKS1MC2-T001BA
BM64SPKS1MC2-Y003AA
BM64SPKS1MC2-Y001AA
BM64SPKS1MC1-Y001AA
BM64SPKS1MC1-00M2AA
BM64SPKS1MC1-M0M1AA
BM64SPKS1MC1-H0M1AA
BM64SPKS1MC2-H0M1AA
BM64SPKS1MC2-A0M1AA
BM64SPKS1MC2-Y0M2AA
BM64SPKS1MC2-Y004AA
BM64SPKS1MC2-Y005AA
BM64SPKS1MC2-0002AA
BM64SPKS1MC2-Y007AA
BM64SPKS1MC2-Y0M3AA
BM64SPKS1MC2-Y008AA
BM64SPKS1MC2-0003AA
BM64SPKS1MC2-00M3AA
BM64SPKS1MC1-0003AA
BM64SPKS1MC1-00M3AA
BM64SPKS1MC1-Y003AA
BM64SPKS1MC2-Y009AA
BM62SPKS1MC2-R003AA