

Information note

N° 10382AERRA

Dear customer,

With this Infineon Technologies AG information note, we would like to inform you about the following

MC-ISAR AURIX Release Notes Addendum V27.0 affecting dedicated TC2xx products



Information note

N° 10382AERRA

▶ Products affected

Please refer to attached affected product list "INF_10382AERRA_[customer-no].pdf"

Detailed change information

Subject MC-ISAR AURIX Release Notes Addendum V27.0 affecting dedicated products

Reason Update of the Release Notes Addendum due to new known issues

Description Old

Version 26.0

Release Notes Addendum

New

Release Notes Addendum Version 27.0

▶ Product identification

Not applicable (no change of product)

Impact of change

Assessment in Application required!

Attachments

INF_10382AERRA_[customer-no].pdf affected product list Release Notes Addendum V27.0 -> MyICP link

https://myicp.infineon.com/sites/auto_sw/Lists/defaultdoclib/MC-

ISAR AURIX/MC-ISAR Aurix Addendum/MC-

ISAR AURIX Releasenotes Addendum V27.0.zip

In case you don't have access, please contact your local Sales/ FAE.

Intended start of delivery

Not applicable

If you have any questions, please do not hesitate to contact your local sales office.

ERR 10382AERRA



MC-ISAR AURIX Release Notes Addendum V27.0 affecting dedicated TC2xx products

Affected products sold to FUTURE ELECTRONICS LTD. (4049887)

Sales name	SP number	OPN	Package	Customer part number
SAK-TC297TP-128F300N BC	I SPOOT RUKRUD	TC297TP128F300NBC KXUMA1	PG-LFBGA-292-6	TC297TP128F300NBCKX UMA1
SAK-TC299TX-128F300S BB	SP001265588	TC299TX128F300SBB KXUMA1	PG-LFBGA-516-5	TC299TX128F300SBBKX UMA1