

Information note

N° 10382AERRA

Dear customer,

With this Infineon Technologies AG information note, we would like to inform you about the following

MC-ISAR AURIX Release Notes Addendum V27.0 affecting dedicated TC2xx products

Infineon Technologies AG

Postal address D-81726 München Internet www.infineon.com Headquarters Am Campeon 1-15, D-85579 Neubiberg Phone +49 (0)89 234-0

Chairman of the Supervisory Board Dr. Wolfgang Eder

Management Board Jochen Hanebeck (CEO), Constanze Hufenbecher, Dr. Sven Schneider, Andreas Urschitz, Dr. Rutger Wijburg

Registered office Neubiberg Commercial register Amtsgericht München HRB 126492

Information note

N° 10382AERRA

► Products affected

Please refer to attached affected product list
“INF_10382AERRA_*customer-no*”.pdf”

► Detailed change information

Subject

MC-ISAR AURIX Release Notes Addendum V27.0 affecting dedicated products

Reason

Update of the Release Notes Addendum due to new known issues

Description

Old

- Release Notes Addendum Version 26.0

New

- Release Notes Addendum Version 27.0

► Product identification

Not applicable (no change of product)

► Impact of change

Assessment in Application required!

► Attachments

INF_10382AERRA_*customer-no*”.pdf affected product list
Release Notes Addendum V27.0 -> MyICP link
https://myicp.infineon.com/sites/auto_sw/Lists/defaultdoclib/MC-ISAR_AURIX/MC-ISAR_Aurix_Addendum/MC-ISAR_AURIX_Releasenotes_Addendum_V27.0.zip

In case you don't have access, please contact your local Sales/ FAE.

► Intended start of delivery

Not applicable

If you have any questions, please do not hesitate to contact your local sales office.

ERR 10382AERRA

MC-ISAR AURIX Release Notes Addendum V27.0 affecting dedicated TC2xx products

Affected products sold to FUTURE ELECTRONICS INC. (4000624)

Sales name	SP number	OPN	Package	Customer part number
SAK-TC233L-32F200F AC	SP001674224	TC233L32F200FACKXUMA1	PG-TQFP-100-23	TC233L32F200FACKXUMA1
SAK-TC233LP-32F200N AC	SP001397720	TC233LP32F200NACKXUMA1	PG-TQFP-100-23	TC233LP32F200NACKXUMA1
SAK-TC234LP-32F200N AC	SP001397714	TC234LP32F200NACKXUMA1	PG-TQFP-144-27	TC234LP32F200NACKXUMA1
SAK-TC264D-40F200N BC	SP001676268	TC264D40F200NBCKXUMA2	PG-LQFP-144-22	TC264D40F200NBCKXUMA2
SAK-TC275T-64F200W DC	SP001662592	TC275T64F200WDCKXUMA1	PG-LQFP-176-22	TC275T64F200WDCKXUMA1
SAK-TC275TP-64F200N DC	SP001397622	TC275TP64F200NDCKXUMA1	PG-LQFP-176-22	TC275TP64F200NDCKXUMA1
SAK-TC275TP-64F200W DC	SP001366138	TC275TP64F200WDCKXUMA1	PG-LQFP-176-22	TC275TP64F200WDCKXUMA1
SAK-TC297TP-128F300N BC	SP001396392	TC297TP128F300NBCKXUMA1	PG-LFBGA-292-6	TC297TP128F300NBCKXUMA1
SAK-TC299TX-128F300N BC	SP001397678	TC299TX128F300NBCKXUMA1	PG-LFBGA-516-5	TC299TX128F300NBCKXUMA1
SAL-TC264D-40F200N BC	SP001662630	TC264D40F200NBCLXUMA1	PG-LQFP-144-22	TC264D40F200NBCLXUMA1