

To: Littelfuse Sales, Sales Support & Customers Valued Customer

From: Littelfuse Product Management – Industrial Business Unit

Subject: Stamping removal on JLLN/JLLS

Document Number: LFPCN_PG0154

Date: 01/23/2023

With regards to the above reference, Littelfuse would like to inform you that there is an update on follow fuse series: JLLN/JLLS to remove stamping on cap. There is NO CHANGE in any way to the construction or performance of the fuse.



This change is effective immediately.

This change doesn't affect fit, form or function of the part numbers.

I will appreciate if you could also send this e-mail to anyone else whom I could have un-intentionally missed out.

Thank you for your continued business. If you have any questions, or need additional information please contact our Littelfuse representative.

Sincerely,

Zuleyma Davila

Associate Product Manager

Industrial Business Unit

Littelfuse, Inc.

Office: +52 878-782-6222

Techline: +1 800-TEC-FUSE

www.littelfuse.com/electrical

List of Part Number

JLLN001.T	JLLN002.T	JLLN003.T	JLLN006.T	JLLN010.T	JLLN015.T	JLLN020.T
JLLS001.T	JLLS002.T	JLLS003.T	JLLS006.T	JLLS010.T	JLLS015.T	JLLS020.T
JLLN001.TXP	JLLN002.TXP	JLLN003.TXP	JLLN006.TXP	JLLN010.TXP	JLLN015.TXP	JLLN020.TXP
JLLS001.TXP	JLLS002.TXP	JLLS003.TXP	JLLS006.TXP	JLLS010.TXP	JLLS015.TXP	JLLS020.TXP
JLLS001.TXV	JLLS002.TXV	JLLS003.TXV	JLLS006.TXV	JLLS010.TXTC	JLLS015.TXTC	JLLS020.TXV
				JLLS010.TXV	JLLS015.TXV	
JLLN025.T	JLLN030.T	JLLN035.T	JLLN040.T	JLLN045.T	JLLN050.T	JLLS060.M
JLLS025.T	JLLS030.T	JLLS035.T	JLLS040.T	JLLS045.T	JLLS050.T	JLLN060.T
JLLN025.TXP	JLLN030.TXP	JLLN035.TXL	JLLN040.TXL	JLLN045.TXL	JLLN050.TXL	JLLS060.T
JLLS025.TXP	JLLS030.TXP	JLLN035.TXLS	JLLN040.TXLS	JLLN045.TXLS	JLLN050.TXLS	JLLN060.TXL
JLLS025.TXTC	JLLS030.TXTC	JLLN035.TXLSE	JLLN040.TXLSE	JLLN045.TXLSE	JLLN050.TXLSE	JLLN060.TXLS
JLLS025.TXV	JLLS030.TXV	JLLN035.TXP	JLLN040.TXP	JLLN045.TXP	JLLN050.TXP	JLLN060.TXLSE
		JLLS035.TXP	JLLS040.TXP	JLLS045.TXP	JLLS050.TXP	JLLN060.TXP
		JLLS035.TXTC	JLLS040.TXTC	JLLS045.TXTC	JLLS050.TXTC	JLLS060.TXP
		JLLN035.TXV	JLLN040.TXV	JLLN045.TXV	JLLN050.TXV	JLLN060.TXTC
						JLLS060.TXTC
						JLLN060.TXV
JLLN070.V	JLLN080.V	JLLN090.V	JLLN100.V	JLLN110.X	JLLN125.X	JLLN150.X
JLLS070.V	JLLS080.V	JLLS090.V	JLLS100.V	JLLS110.X	JLLS125.X	JLLS150.X
JLLN070.VXP	JLLN080.VXP	JLLN090.VXP	JLLN100.VXP	JLLN110.XXP	JLLN125.XXP	JLLN150.XXP
JLLS070.VXP	JLLS080.VXP	JLLS090.VXP	JLLS100.VXP	JLLS110.XXP	JLLS125.XXP	JLLS150.XXP
JLLN070.VXSC	JLLN080.VXSC	JLLN090.VXSC	JLLN100.VXSC	JLLN110.XXSC	JLLN125.XXSC	JLLN150.XXSC
JLLS070.VXSC	JLLS080.VXSC	JLLS090.VXSC	JLLS100.VXSC	JLLS110.XXSC	JLLS125.XXSC	JLLS150.XXSC
JLLS070.VXSCP	JLLS080.VXSCP	JLLS090.VXSCP	JLLS100.VXSCP	JLLS110.XXTC	JLLS125.XXTC	JLLN150.XXTC
JLLS070.VXTC	JLLS080.VXTC	JLLS090.VXTC	JLLS100.VXTC			JLLS150.XXTC
JLLN175.X	JLLN200.X	JLLN225.X	JLLN250.X	JLLN300.X	JLLN350.X	JLLN400.X
JLLS175.X	JLLS200.X	JLLS225.X	JLLS250.X	JLLS300.X	JLLS350.X	JLLS400.X
JLLN175.XXP	JLLN200.XXP	JLLN225.XXP	JLLN250.XXP	JLLN300.XXP	JLLN350.XXP	JLLN400.XXP
JLLS175.XXP	JLLS200.XXP	JLLS225.XXP	JLLS250.XXP	JLLS300.XXP	JLLS350.XXP	JLLS400.XXP
JLLN175.XXSC	JLLN200.XXSC	JLLN225.XXSC	JLLN250.XXSC	JLLN300.XXSC	JLLN350.XXSC	JLLN400.XXSC
JLLS175.XXSC	JLLS200.XXSC	JLLS225.XXSC	JLLS250.XXSC	JLLS300.XXSC	JLLS350.XXSC	JLLS400.XXSC
JLLS175.XXTC	JLLS200.XXTC	JLLS225.XXTC	JLLS250.XXTC	JLLS300.XXTC	JLLS350.XXTC	
JLLS175.Z						
JLLS175.ZXP						
JLLN450.X	JLLN500.X	JLLN600.X	JLLN700.X	JLLN800.X	JLLS900.X	JLLN1000X
JLLS450.X	JLLS500.X	JLLS600.X	JLLS700.X	JLLS800.X	JLLS900.XXP	JLLS1000X
JLLN450.XXP	JLLN500.XXP	JLLN600.XXP	JLLN700.XXP	JLLN800.XXP	JLLS900.XXSC	JLLN1000XXP
JLLS450.XXP	JLLS500.XXP	JLLS600.XXP	JLLS700.XXP	JLLS800.XXP		JLLS1000XXP
JLLN450.XXSC	JLLN500.XXSC	JLLN600.XXSC	JLLN700.XXSC	JLLN800.XXSC		JLLN1000XXSC
JLLS450.XXSC	JLLS500.XXSC	JLLS600.XXSC	JLLS700.XXSC	JLLS800.XXSC		JLLS1000XXSC

JLLN1100X	JLLN1200X
JLLS1100X	JLLS1200X
JLLN1100XXP	JLLN1200XXP
JLLS1100XXP	JLLS1200XXP
JLLN1100XXSC	JLLN1200XXSC
JLLS1100XXSC	JLLS1200XXSC