

Information note

N° 10387AERRA

Dear customer,

With this Infineon Technologies AG information note, we would like to inform you about the following

Errata Advance Information 2022-12 affecting TC3xx Microcontrollers

Infineon Technologies AG

Postal address D-81726 München Internet www.infineon.com Headquarters Am Campeon 1-15, D-85579 Neubiberg Phone +49 (0)89 234-0

Chairman of the Supervisory Board Dr. Wolfgang Eder

Management Board Jochen Hanebeck (CEO), Constanze Hufenbecher, Dr. Sven Schneider, Andreas Urschitz, Dr. Rutger Wijburg

Registered office Neubiberg Commercial register Amtsgericht München HRB 126492

Information note

N° 10387AERRA

► **Products affected**

Please refer to attached affected product list
 “INF_10387AERRA_[customer-no].pdf”

► **Detailed change information**

Subject Errata Advance Information: New/updated errata/ApHint text modules - Advance information 2022-12 for TC3xx Microcontrollers

Reason Functional Problems, Application Hints, Documentation Updates

Description

<u>Old</u>	<u>New</u>
<ul style="list-style-type: none"> Not applicable (initial version) 	<ul style="list-style-type: none"> Errata Advance Information TC3xx_Errata_Advance_Info_2022_12_v1_0_10387AERRA

► **Product identification**

Not applicable (no change of product)

► **Impact of change**

Assessment in Application required!

► **Attachments**

INF_10387AERRA_[customer-no].pdf affected product list
 3_cip10387.pdf TC3xx_Errata_Advance_Info_2022_12
 myICP link:
https://myicp.infineon.com/sites/microcontrollers%2Daurix_customer_doc/Lists/defaultdoclib/AURIX%20TC3xx/00%20AURIX%20TC3xx%20General/00%20Hardware%20Documentation/04%20Errata%20Sheet/Errata%20Advance%20Information/TC3xx_Errata_Advance_Info_2022_12_v1_0_10387AERRA.pdf
In case you don't have access, please contact your local Sales/ FAE.

► **Intended start of delivery**

Not applicable

If you have any questions, please do not hesitate to contact your local sales office.

ERR 10387AERRA



Errata Advance Information 2022-12 affecting TC3xx Microcontrollers

Affected products sold to FUTURE ELECTRONICS INC. (4000624)

Sales name	SP number	OPN	Package	Customer part number
SAK-TC367DP-64F300S AA	SP001694656	TC367DP64F300SAAKXUMA1	PG-LFBGA-292-11	
SAK-TC377TP-96F300S AA	SP001694648	TC377TP96F300SAAKXUMA1	PG-LFBGA-292-11	TC377TP96F300SAAKXUMA1
SAK-TC397XA-256F300S BD	SP005351382	TC397XA256F300SBDKXUMA1	PG-LFBGA-292-12	
SAL-TC377TP-96F300S AA	SP001724092	TC377TP96F300SAALXUMA1	PG-LFBGA-292-11	

ERR 10387AERRA



Errata Advance Information 2022-12 affecting TC3xx Microcontrollers

Affected products sold to FUTURE ELECTRONICS INC. (4048203)

Sales name	SP number	OPN	Package	Customer part number
SAK-TC364DP-64F300F AA	SP001713956	TC364DP64F300FAAKXUMA1	PG-TQFP-144-27	TC364DP64F300FAAKXUMA, TC364DP64F300FAAKXUMA1