

1 Products affected

Product hierarchy no. *				Part no.	SBU	Product Type	Customer part no.
SBU	PG	PUG	Type				
02	007	060	0000002304	See list below	Connectors	4751	-

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected for type <4751>				
3-103-837	3-103-838	3-103-840	3-103-841	3-103-873
3-103-874				

2 Type of change

- Change of material

3 Detailed description of change

Current product appearance	New product appearance
Color of gray products RAL7040	Color of gray products RAL7035
Color of white products RAL9016	Color of white products RAL9006

4 Reason of change

- Due to Material shortage, change to new plastic raw material to secure availability.

5 Release date

The change takes effect in ww 18/2023 (Date code 2318 or higher on label).
Parts on stock will be used upon depletion.

6 Impact of change and recommended action

- Form
- Fit Slight change of colour
- Function
- Manufacturing
- Label
- Packaging

7 Reference Documents

Kind of document	Document Title
Data Sheet	Data Sheet 4751

Change Notice					Product Change Notification		
owner	creation date	release date	released by	change order	rev	page	D10-071-475
mansurva	21.02.2023	29.03.2023	muehlema	2025566	A	1 of 1	