

Information note

N° 099/22

Dear customer,

With this Infineon Technologies AG information note, we would like to inform you about the following

Rainier -0900 products – Firmware update revB (V9)

Infineon Technologies AG

Postal address D-81726 München Internet www.infineon.com Headquarters Am Campeon 1-15, D-85579 Neubiberg Phone +49 (0)89 234-0

Chairman of the Supervisory Board Dr. Herbert Deiss

Management Board Jochen Hanebeck (CEO), Constanze Hufenbecher, Dr. Sven Schneider, Andreas Urschitz, Dr. Rutger Wijburg

Registered office Neubiberg Commercial register Amtsgericht München HRB 126492

Information note

N° 099/22

Products affected

Please refer to attached affected product list
"INF_099_22_[customer-no].pdf"

Detailed change information

Subject Firmware update to revB (V9) of Rainier -0900 products.

Reason Implementation of final production firmware (V9).

Description	<u>Old</u>	<u>New</u>
Firmware Revision	<ul style="list-style-type: none"> V1 	<ul style="list-style-type: none"> V9
Date Code on Device	<ul style="list-style-type: none"> Contains "E" or Shipped by 2022-12-08 	<ul style="list-style-type: none"> Shipped after 2022-12-09

Product identification

External traceability via ship date

Impact of change

- Output accuracy may be wider over temperature
- SVI3 interface not fully tested

Recommendation for -0900 parts

- Distributor/Customer inventory can be used for Consumer applications
- Customer may return V1 inventory for replacement with V9

Attachments

INF_099_22_[customer-no].pdf affected product list

Intended start of delivery

2022-12-09

If you have any questions, please do not hesitate to contact your local sales office.

INF 099/22



Rainier -0900 products - Firmware update revB (V9)

Affected products sold to FUTURE ELECTRONICS INC. (4000624)

Sales name	SP number	OPN	Package	Customer part number
XDPE19283B-0900	SP005751735	XDPE19283B0900XUMA1	PG-VQFN-40-13	XDPE19283B0900XUMA1