

**Product Change Notice**  
PCN#: EE-PCN23008M  
(EE-PCN23008M replaces EE-PCN23008)  
4/26/2023

**CLASSIFICATION OF CHANGE:**

Plating appearance change

**DESCRIPTION OF CHANGE:**

Fuse clip 1Axxxx silver plating color changed in new manufacturing line

**REASON FOR CHANGE:**

Add new manufacturing line to enlarge product capacity

**EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:**

Fuse clip 1Axxxx is adding new product line, there is no effect on the quality, reliability, or performance. The new manufacture line produced fuse clip is bright silver plating without material change. The plating appearance changed from matt silver plating to bright silver plating shows as below



**Matt Silver Plating**



**Bright Silver Plating**

**PARTS FAMILIES AFFECTED**

BK-1A1119-05
BK-1A1120-05
BK-1A1907-05
BK-1A3399-01
BK-1A5018-07

**TIME SCHEDULE:**

Effective immediately

**ISSUED BY:**

Roald Bai  
Product Manager – Circuit Protection

**CONTACT INFORMATION:**

For questions or comments, please [Contact us](#)