



Eaton  
Electronics Division  
5735 W. Las Positas Blvd #100  
Pleasanton, CA 94588  
[www.eaton.com/electronics](http://www.eaton.com/electronics)

## Product Change Notice

PCN#: EE-PCN18032

8/20/2018

### CLASSIFICATION OF CHANGE:

Manufacture location

### DESCRIPTION OF CHANGE:

A new Taiwan manufacture location will be added for various fuse holders.

### REASON FOR CHANGE:

Enhance the capability for the future growth.

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

### PARTS FAMILIES AFFECTED

See attached for detailed part numbers.

### TIME SCHEDULE:

Effective immediately

### ISSUED BY:

Wayne Wang  
Product Manager – Circuit Protection

### CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).

<b>Eaton Family</b>	<b>Eaton Part Number</b>
HR/HM/HH	BK-9838
HR/HM/HH	BK-9841
HR/HM/HH	BK-1A1853
HR/HM/HH	BK-HHJ-1K0118
HR/HM/HH	BK-HHJ-A-R
HR/HM/HH	BK-HHJ-B-R
HR/HM/HH	BK-HHJ-C-R
HR/HM/HH	BK-HME
HR/HM/HH	BK-HMF
HR/HM/HH	BK-HMG
HR/HM/HH	BK-HMH
HR/HM/HH	BK-HMI
HR/HM/HH	BK-HMJ
HR/HM/HH	BK-HMK
HR/HM/HH	BK-HRE
HR/HM/HH	BK-HRG
HR/HM/HH	BK-HRI
HR/HM/HH	BK-HRJ
HR/HM/HH	BK-HRK-R
HR/HM/HH	HHJ-A-R
HR/HM/HH	HME
HR/HM/HH	HMF
HR/HM/HH	HMG
HR/HM/HH	HMH
HR/HM/HH	HMI
HR/HM/HH	HMJ
HR/HM/HH	HMJ-LESS-FUSE
HR/HM/HH	HMK
HR/HM/HH	HRE
HR/HM/HH	HRF
HR/HM/HH	HRG
HR/HM/HH	HRH
HR/HM/HH	HRI
HR/HM/HH	HRJ
HR/HM/HH	HRJ-LESS-FUSE
HR/HM/HH	HRK-R

<b>Eaton Family</b>	<b>Eaton Part Number</b>
HFB	BK-HFB-R
HFB	BK-HFB-10
HFB	HFB-R
HFB	HFB-10
HFB	BK1-HFB-R
HFB	BK1-HFB-10
HFB	BK-1A2294
HFB	BK-1A2294-01
HHB	BK-HHB-R
HHB	HHB-1K0187
HHB	BK-HHB-Y408
HHB	BK-HHB-B408
HHB	BK-HHB-Y419
HHB	HHB-R
HHB	BK-HHB-B419
HHB	BK-HHB-RED
HHB	BK-HHB-R419
HHB	BK-HHB-R408