



ROHM Co.,Ltd.

21 Saiin Mizosaki-cho, Ukyo-ku, Kyoto 615-8585 Japan
TEL: +81-75-311-2121 FAX: +81-75-315-0172
http://www.rohm.com

Product/Process Change Notification **PCN#: 101800A**

This is an announcement of change to products which are currently supplied by ROHM.
ROHM sincerely requires acknowledgment of receipt of this notification within 30 days of the date of this notice.
Lack of acknowledgment of this notice within 30 days constitutes acceptance of the change.
Your understanding and cooperation would be highly appreciated.

Issue Date: 7th, Feb. 2019

Title of change	
Material (Mold Resin) Change for LSI WL-CSP Package	
Identification of change	
Can be traced via Marking Lot No. (Cannot be identified through appearance)	
Detailed description of change	
Before Material : Mold Resin (Epoxy Resin A) Method : Resin Printing	After Material : Mold Resin (Epoxy Resin B) Method : Resin Molding
Affected product(s)	
Manufacture part number	Customer part number
Reason for change	
Improve PKG apperance quality (Reduce internal micro void)	
Anticipated impact on form, fit, function, quality or reliability	
Not expected (Change already applied for some mass production parts)	
Planned date for change	
30th Jun. 2019	
Qualification plan schedule, results and samples	
If required, pleases contact your local ROHM sales office.	
Comments	
Supplier contact	

After acknowledgement of the customer, lack of additional response within 90 day period constitutes acceptance of the change according to JEDEC Standard J-STD-046.

Rohm P/N	PCN
BU18SA4WGWL-E2	101800A
BU26507GUL-E2	101800A
BU52003GUL-E2	101800A
BU52015GUL-E2	101800A
BU9889GUL-WE2	101800A
BD2200GUL-E2	101800A
BD2201GUL-E2	101800A
BD2204GUL-E2	101800A
BD26502GUL-E2	101800A
BD27400GUL-E2	101800A
BD5465GUL-E2	101800A
BD5466GUL-E2	101800A
BD5467GUL-E2	101800A
BD5468GUL-E2	101800A
BD5469GUL-E2	101800A
BD6042GUL-E2	101800A
BD6044GUL-E2	101800A
BD6046GUL-E2	101800A
BD6088GUL-E2	101800A
BD60910GU-E2	101800A
BD6164GUT-E2	101800A
BD6360GUL-E2	101800A
BD6369GUL-E2	101800A
BD6376GUL-E2	101800A
BD6529GUL-E2	101800A
BD6581GU-E2	101800A
BD65B60GWL-E2	101800A
BD7710GWL-E2	101800A
BD8316GWL-E2	101800A
BD8317GWL-E2	101800A
BD8664GW-E2	101800A
BD8665GW-E2	101800A
BD8668GW-E2	101800A
BD88200GUL-E2	101800A
BD88210GUL-E2	101800A
BD88215GUL-E2	101800A
BD88220GUL-E2	101800A
BD88400GUL-E2	101800A
BD88410GUL-E2	101800A
BD88415GUL-E2	101800A
BD88420GUL-E2	101800A
BD91411GW-E2	101800A
BD9866GUL-E2	101800A
BDS2EJAAGUL-E2	101800A
BH18SA3WGUT-E2	101800A
BH28SA3WGUT-E2	101800A

BH30SA3WGUT-E2	101800A
BH7606GU-E2	101800A
BH76906GU-E2	101800A
BRCB016GWL-3E2	101800A
BU21021GUL-E2	101800A
BU21023GUL-E2	101800A
BU21025GUL-E2	101800A
BU21029GUL-E2	101800A
BU24020GU-E2	101800A
BU24024GU-E2	101800A
BU24031GW-E2	101800A
BU24032GW-E2	101800A
BU24033GW-E2	101800A
BU24035GW-E2	101800A
BU24038GW-E2	101800A
BU25SA4WGWL-E2	101800A
BU28SA4WGWL-E2	101800A
BU2FSA4WGWL-E2	101800A
BU30SA4WGWL-E2	101800A
BU33SA4WGWL-E2	101800A
BU52001GUL-E2	101800A
BU52004GUL-E2	101800A
BU9829GUL-WE2	101800A
BU9833GUL-WE2	101800A
BU9880GUL-WE2	101800A
BD2802GU-E2	101800A
BD5460GUL-E2	101800A
BD5461GUL-E2	101800A
BD6040GUL-E2	101800A
BD6041GUL-E2	101800A
BD6066GU-E2	101800A
BD6067GU-E2	101800A
BD6069GUT-E2	101800A
BD82103GWL-E2	101800A
BD8316GWL-BFE2	101800A
BD8665GW-BFE2	101800A
BD9122GUL-E2	101800A
BH15RB1WGUT-E2	101800A
BH18RB1WGUT-E2	101800A
BH25RB1WGUT-E2	101800A
BH28RB1WGUT-E2	101800A
BH29RB1WGUT-E2	101800A
BH30RB1WGUT-E2	101800A
BH31RB1WGUT-E2	101800A
BH33RB1WGUT-E2	101800A
BU52002GUL-E2	101800A
BU9847GUL-WE2	101800A

BD26503GUL-E2	101800A
BD6061GUT-E2	101800A
BU9832GUL-WE2	101800A
BU9844GUL-WE2	101800A