



Product Change Notification / JAON-04WEXT659

Date:

07-Oct-2021

Product Category:

Wireless Modules

PCN Type:

Manufacturing Change

Notification Subject:

CCB 4832 Final Notice: Implement top marking changes for selected ATZBRF233, ATSAMR21G18, ATWILCxxxx, ATWINCxxxx, ATSAMW25H18, RN2483A and WFI32E01xx device families available in various module packages.

Affected CPNs:

[JAON-04WEXT659_Affected_CPN_10072021.pdf](#)

[JAON-04WEXT659_Affected_CPN_10072021.csv](#)

Notification Text:

PCN Status: Final Notification

PCN Type: Manufacturing Change

Microchip Parts Affected: Please open one of the files found in the Affected CPNs section.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

Description of Change: Implement top marking changes for selected ATZBRF233, ATSAMR21G18, ATWILCxxxx, ATWINCxxxx, ATSAMW25H18, RN2483A and WFI32E01xx device families available in various module packages.

Pre and Post Change Summary:

	Pre Change	Post Change
--	------------	-------------

Top Marking	No UKCA Logo	With UKCA Logo
	Date Code: YWXX	Traceability Code: YYWWNNN
	See Pre and Post Change Summary for comparison.	

Impacts to Data Sheet: None

Change Impact:None

Reason for Change:To improve productivity by implementing top marking changes for selected ATZBRF233, ATSAMR21G18, ATWILCxxxx, ATWINCxxxx, ATSAMW25H18, RN2483A and WFI32E01xx device families available in various module packages.

Change Implementation Status:In Progress

Estimated First Ship Date:October 22, 2021 (date code: 2143)

NOTE: Please be advised that after the estimated first ship date customers may receive pre and post change parts.

Time Table Summary:

	October 2021				
Workweek	41	42	43	44	45
Final PCN Issue Date	X				
Estimated first ship date			X		

Method to Identify Change: Traceability code, Top marking

Qualification Report:Not Applicable

Revision History:October 7, 2021: Issued final notification.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

Attachments:

[PCN_JAON-04WEXT659_Pre and Post Change_Summary.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

ATZB-RF-233-1-CR
ATSAMR21G18-MR210UA
ATSAMR21G18-MR210UAT
ATWILC1000-MR110PB
ATWINC1510-MR210UB
ATWINC1500-MR210PB1952
ATWINC1500-MR210PB1954
ATWINC1500-MR210PB1961
ATWINC1500-MR210PB1952-T
ATWINC1500-MR210PB1944
ATWINC1510-MR210PB1944
ATWINC1510-MR210PB1952
ATWINC1510-MR210PB1954
ATWINC1510-MR210PB1961
ATWINC1510-MR210PB1963
ATWINC1510-MR210PB1963-T
ATWINC1510-MR210PB1967
ATWINC1500-MR210PB
ATWINC1510-MR210PB
ATWINC1500-MR210PB1172
ATWINC1510-MR210PB1140
ATWINC1500-MR210PB1140
ATWINC1500-MR210UB
ATWILC1000-MR110UB
ATWILC1000-MR110UB-T
ATWINC1500-MR210UB1140
ATWINC1510-MR210UB1140
ATWINC1500-MR210UB1954
ATWINC1500-MR210UB1944
ATWINC1500-MR210UB1961
ATWINC1510-MR210UB1944
ATWINC1510-MR210UB1952
ATWINC1510-MR210UB1954
ATWINC1510-MR210UB1961
ATSAMW25H18-MR210PB1952
ATSAMW25H18-MR210PB
ATSAMW25H18-MR210PB1944
ATSAMW25H18-MR210PB1954
ATSAMW25H18-MR210PB1961
ATWILC1000-MR110PB-T
ATWINC1500-MR210PB1961-T
ATWINC1500-MR210PB1965-T
ATWINC1510-MR210PB1961-T
ATWINC1500-MR210UB1961-T
ATWINC3400-MR210CA
ATWINC3400-MR210UA


JAON-04WEXT659 - CCB 4832 Final Notice: Implement top marking changes for selected ATZBRF233, ATSAMR21G18, ATWILCxxxx, ATWINCxxxx, ATSAMW25H18, RN2483A and WFI32E01xx device families available in various module packages.

~~ATWINC3400-MR210CA122~~
ATWINC3400-MR210UA122
ATWINC3400-MR210CA123
ATWINC3400-MR210CA123-T
ATWINC3400-MR210CA122-T
ATWINC3400-MR210CA142
ATWINC3400-MR210UA142
ATWILC3000-MR110CA
ATWILC3000-MR110UA
ATWILC3000-MR110UA-T
ATWINC3400-MR210CA131
ATWINC3400-MR210UA131
ATWINC3400-MR210CA131-T
ATWINC3400-MR210UA131-T
ATWINC3400-MR210CA142-T
ATWINC3400-MR210UA142-T
RN2483A-I/RM103
RN2483A-I/RM104
RN2483A-I/RM105
WFI32E01PE-I
WFI32E01UE-I
WFI32E01PC-I
WFI32E01UC-I

CCB 4832
Pre and Post Change Summary
PCN# JAON-04WEXT659







A Leading Provider of Smart, Connected and Secure Embedded Control Solutions







SMART | CONNECTED | SECURE





Pre and Post Change Summary – Marking

Affected CPNs	Pre Change	Post Change	Changes
<p>ATSAMR21G18-MR210UA ATSAMR21G18-MR210UAT</p>	 <p>ATSAMR21G18-MR210UA FCC: VNR-ATSAMR210UA-0 IC: 20266-ATSAMR210UA0 MAC ID: XXXXXXXXXXXX D/C: D Y Y W W CE</p>	 <p>ATSAMR21G18-MR210UA FCC: VNR-ATSAMR210UA-0 IC: 20266-ATSAMR210UA0 MAC ID: F8F005D2F2C1 2132TPT CE UK CA</p>	<p>Date code format (YMXX to YYWWNNN); Add UKCA logo</p>
<p>ATWILC1000-MR110PB ATWILC1000-MR110PB-T</p>	 <p>ATWILC1000-MR110PB FCC ID: 2ADHKATWILC1000 IC :20266-ATWILC1000 CMIIT ID: 2018DJ1313 MAC ID: F8F00596F374 CE 9EM1</p>	 <p>ATWILC1000-MR110PB FCC ID: 2ADHKATWILC1000 IC :20266-ATWILC1000 CMIIT ID: 2018DJ1313 MAC ID: F8F0056E0FDF 2132TPT CE UK CA</p>	<p>Date code format (YMXX to YYWWNNN); Add UKCA logo</p>





Pre and Post Change Summary – Marking

Affected CPNs	Pre Change	Post Change	Changes
<p>ATWILC1000-MR110UB ATWILC1000-MR110UB-T</p>			<p>Date code format (YMXX to YYWWNNN); Add UKCA logo</p>
<p>ATWILC3000-MR110CA</p>			<p>Date code format (YMXX to YYWWNNN); Add UKCA logo</p>





Pre and Post Change Summary – Marking

Affected CPNs	Pre Change	Post Change	Changes
<p>ATWILC3000-MR110UA ATWILC3000-MR110UA-T</p>	 <p>Microchip Technology Inc. ATWILC3000-MR110UA FCC ID: 2ADHKWILC3000U IC: 20266-WILC3000UA MAC ID: F8F005DDDA96</p> <p>QR code, CE, 9HF7</p>	 <p>Microchip Technology Inc. ATWILC3000-MR110UA FCC ID: 2ADHKWILC3000U IC: 20266-WILC3000UA MAC ID: F8F005626E22 2132TPT</p> <p>QR code, CE, UKCA</p>	<p>Date code format (YMXX to YYWWNNN); Add UKCA logo</p>
<p>ATWINC1500-MR210PB1952 ATWINC1500-MR210PB1954 ATWINC1500-MR210PB1961 ATWINC1500-MR210PB1944 ATWINC1500-MR210PB ATWINC1500-MR210PB1172 ATWINC1500-MR210PB1140 ATWINC1500-MR210PB1961-T ATWINC1500-MR210PB1965-T ATWINC1500-MR210PB1952-T</p>	 <p>ATWINC1500-MR210PB FCC ID: 2ADHKATWINC1500 IC: 20266-WINC1500PB CMIIT ID: 2018DJ1305 ANATEL: 08497-18-08759 MAC ID: F8F0057000AD</p> <p>QR code, CE, 0ISR</p>	 <p>ATWINC1500-MR210PB FCC ID: 2ADHKATWINC1500 IC: 20266-WINC1500PB CMIIT ID: 2018DJ1305 ANATEL: 08497-18-08759 MAC ID: F8F0056ECB7E 2132TPT</p> <p>QR code, CE, UKCA</p>	<p>Date code format (YMXX to YYWWNNN); Add UKCA logo</p>





Pre and Post Change Summary – Marking

Affected CPNs	Pre Change	Post Change	Changes
<p>ATWINC1500-MR210UB ATWINC1500-MR210UB1140 ATWINC1500-MR210UB1954 ATWINC1500-MR210UB1944 ATWINC1500-MR210UB1961 ATWINC1500-MR210UB1961-T</p>			<p>Date code format (YMXX to YYWWNNN); Add UKCA logo</p>
<p>ATWINC1510-MR210PB1944 ATWINC1510-MR210PB1952 ATWINC1510-MR210PB1954 ATWINC1510-MR210PB1961 ATWINC1510-MR210PB1963 ATWINC1510-MR210PB1967 ATWINC1510-MR210PB ATWINC1510-MR210PB1140 ATWINC1510-MR210PB1963-T ATWINC1510-MR210PB1961-T</p>			<p>Date code format (YMXX to YYWWNNN); Add UKCA logo</p>







Pre and Post Change Summary – Marking

Affected CPNs	Pre Change	Post Change	Changes
<p>ATWINC1510-MR210UB ATWINC1510-MR210UB1140 ATWINC1510-MR210UB1944 ATWINC1510-MR210UB1952 ATWINC1510-MR210UB1954 ATWINC1510-MR210UB1961</p>			<p>Date code format (YMXX to YYWWNNN) ; Add UKCA logo</p>
<p>ATWINC3400-MR210CA ATWINC3400-MR210CA123 ATWINC3400-MR210CA142 ATWINC3400-MR210CA122 ATWINC3400-MR210CA131 ATWINC3400-MR210CA123-T ATWINC3400-MR210CA142-T ATWINC3400-MR210CA122-T ATWINC3400-MR210CA131-T</p>			<p>Date code format (YMXX to YYWWNNN) ; Add UKCA logo</p>

Pre and Post Change Summary – Marking

Affected CPNs	Pre Change	Post Change	Changes
<p>ATWINC3400-MR210UA ATWINC3400-MR210UA142 ATWINC3400-MR210UA122 ATWINC3400-MR210UA131 ATWINC3400-MR210UA142-T ATWINC3400-MR210UA131-T</p>			<p>Date code format (YMXX to YYWWNNN); Add UKCA logo</p>
<p>ATSAMW25H18-MR210PB1952 ATSAMW25H18-MR210PB ATSAMW25H18-MR210PB1944 ATSAMW25H18-MR210PB1954 ATSAMW25H18-MR210PB1961</p>			<p>Date code format (YMXX to YYWWNNN); Add UKCA logo</p>

Pre and Post Change Summary – Marking

Affected CPNs	Pre Change	Post Change	Changes
RN2483A-I/RM103 RN2483A-I/RM104 RN2483A-I/RM105	 <p>MICROCHIP RN2483A 2034G65</p>	 <p>MICROCHIP RN2483A 2034G69 UK CA</p>	Add UKCA Logo
ATZB-RF-233-1-CR	 <p>ATMEL M/N: ATZB-RF-233-1-C SN: 020000000388 FCC ID: VW4A091729 IC ID: 11019A-091729</p>	 <p>MICROCHIP UK CA 2193 M/N: ATZB-RF-233-1-C SN: 0000000000001 FCC ID: VW4A091729 IC: 11019A-091729</p>	Add MCHP logo Add UKCA Add date code
WFI32E01PE-I WFI32E01UE-I WFI32E01PC-I WFI32E01UC-I	 <p>MICROCHIP WFI32E01PC FCC ID: 2ADHKWFI32E01 IC: 20266-WFI32E01 2121M4B CE</p>	 <p>MICROCHIP WFI32E01PE FCC ID: 2ADHKWFI32E01 IC: 20266-WFI32E01 2121M4C CE UK CA</p>	Add UKCA Logo