



Product Change Notification

Current Date: 10-Oct-2016

TE Connectivity

Product Change Notification: P-16-013650

PCN Date: 07-OCT-16

Customer: Future Electronics(0000080100)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

DEUTSCH DT Series Cavity Laser Marking


Description of Changes

Process Change. Contact cavities identification marking will use new technology type laser.

New vs Current Laser Marking



New vs Current Laser Marking



Reason for Changes:

Product improvement. Dear customer, we are contacting you to notify you of a process change to the contact cavity identification marking on the end cap of the DT Series connectors, plug and receptacles. We are upgrading the marking lasers to use newer laser technology. The only change you will notice is the way the contact cavity marking looks (see photos on this PCN). This change only affects part form and does not affect fit or function. Shipment of both versions may be mixed. IMPORTANT: This is a continual improvement so the current and previous revisions of these parts can be used interchangeably in the field. These changes are being phased in gradually and previous revision can remain stocked until use. The product drawings are not affected.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	16-DEC-2016
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2020

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DT04-08PA-E008</a>	NO			"ZPF000000000130416"			
<a href="#">DT04-2P-CE01</a>	NO			"ZPF000000000130154"			
<a href="#">DT04-2P-CE01</a>	NO			"ZPF000000000130154"			
<a href="#">DT04-2P-CE03</a>	NO			"ZPF000000000130156"			
<a href="#">DT04-2P-CE03</a>	NO			"ZPF000000000130156"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DT04-2P-E005</a>	NO			"ZPF000000000130163", "DT04-2P-E005-LD", "DT04-2P-E005-LS", "DT04-2P-E005-MS", "DT04-2P-E005-L", "DT04-2P-E005-M"			
<a href="#">DT04-2P-E005</a>	NO			"ZPF000000000130163", "DT04-2P-E005-LD", "DT04-2P-E005-LS", "DT04-2P-E005-MS", "DT04-2P-E005-L", "DT04-2P-E005-M"			
<a href="#">DT04-3P-E003</a>	NO			"ZPF000000000130216"			
<a href="#">DT04-3P-E005</a>	NO			"ZPF000000000130218", "DT04-3P-E005-LD", "DT04-3P-E005-LS", "DT04-3P-E005-MS", "DT04-3P-E005-L", "DT04-3P-E005-M"			
<a href="#">DT04-3P-E005</a>	NO			"ZPF000000000130218", "DT04-3P-E005-LD", "DT04-3P-E005-LS", "DT04-3P-E005-MS", "DT04-3P-E005-L", "DT04-3P-E005-M"			
<a href="#">DT06-12SA-CE13</a>	NO			"ZPF000000000130675"			
<a href="#">DT06-2S-E008</a>	NO			"ZPF000000000130185"			
<a href="#">DT06-2S-E008</a>	NO			"ZPF000000000130185"			
<a href="#">DT06-2S-EP06</a>	NO			"ZPF000000000130180", "DT06-2S-EP06-LD", "DT06-2S-EP06-LS", "DT06-2S-EP06-MS", "DT06-2S-EP06-E", "DT06-2S-EP06-M", "DT06-2S-EP06-L"			
<a href="#">DT06-2S-EP06</a>	NO			"ZPF000000000130180", "DT06-2S-EP06-LD", "DT06-2S-EP06-LS", "DT06-2S-EP06-MS", "DT06-2S-EP06-E", "DT06-2S-EP06-L", "DT06-2S-EP06-M"			
<a href="#">DT06-2S-EP06</a>	NO			"ZPF000000000130180", "DT06-2S-EP06-LD", "DT06-2S-EP06-LS", "DT06-2S-EP06-MS", "DT06-2S-EP06-E", "DT06-2S-EP06-L", "DT06-2S-EP06-M"			
<a href="#">DT06-3S-CE13</a>	NO			"ZPF000000000130231"			
<a href="#">DT06-3S-EP06</a>	NO			"ZPF000000000130240", "DT06-3S-EP06-LD", "DT06-3S-EP06-LS", "DT06-3S-EP06-MS", "DT06-3S-EP06-L", "DT06-3S-EP06-M"			
<a href="#">DT06-3S-EP06</a>	NO			"ZPF000000000130240", "DT06-3S-EP06-LD", "DT06-3S-EP06-LS", "DT06-3S-EP06-MS", "DT06-3S-EP06-L", "DT06-3S-EP06-M"			
<a href="#">DT06-4S-E003</a>	NO			"ZPF000000000130318"			
<a href="#">DT06-6S-CE05</a>	NO			"ZPF000000000130360", "DT06-6S-CE05-MS", "DT06-6S-CE05-SC", "DT06-6S-CE05-M", "DT06-6S-CE05-S"			
<a href="#">DT06-6S-CE05</a>	NO			"ZPF000000000130360", "DT06-6S-CE05-MS", "DT06-6S-CE05-SC", "DT06-6S-CE05-M", "DT06-6S-CE05-S"			
<a href="#">DT06-6S-EP06</a>	NO			"ZPF000000000130364", "DT06-6S-EP06-LD", "DT06-6S-EP06-LS", "DT06-6S-EP06-MS", "DT06-6S-EP06-L", "DT06-6S-EP06-M"			
<a href="#">DT06-6S-EP06</a>	NO			"ZPF000000000130364", "DT06-6S-EP06-LD", "DT06-6S-EP06-LS", "DT06-6S-EP06-MS", "DT06-6S-EP06-L", "DT06-6S-EP06-M"			

Customer: Future Electronics Inc( 184927 )

Location: Pointe Claire

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DT04-2P-CE01</a>	NO			"ZPF000000000130154"			
<a href="#">DT04-2P-CE03</a>	NO			"ZPF000000000130156"			
<a href="#">DT04-2P-E005</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"ZPF00000000130163", "DT04-2P-E005-LD", "DT04-2P-E005-LS", "DT04-2P-E005-MS", "DT04-2P-E005-L", "DT04-2P-E005-M"			
<a href="#">DT04-3P-E005</a>	NO			"ZPF00000000130218", "DT04-3P-E005-LD", "DT04-3P-E005-LS", "DT04-3P-E005-MS", "DT04-3P-E005-L", "DT04-3P-E005-M"			
<a href="#">DT06-2S-E008</a>	NO			"ZPF00000000130185"			
<a href="#">DT06-2S-EPO6</a>	NO			"ZPF00000000130180", "DT06-2S-EP06-LD", "DT06-2S-EP06-LS", "DT06-2S-EP06-MS", "DT06-2S-EP06-E", "DT06-2S-EP06-L", "DT06-2S-EP06-M"			
<a href="#">DT06-3S-EPO6</a>	NO			"ZPF00000000130240", "DT06-3S-EP06-LD", "DT06-3S-EP06-LS", "DT06-3S-EP06-MS", "DT06-3S-EP06-L", "DT06-3S-EP06-M"			
<a href="#">DT06-6S-CE05</a>	NO			"ZPF00000000130360", "DT06-6S-CE05-MS", "DT06-6S-CE05-SC", "DT06-6S-CE05-M", "DT06-6S-CE05-S"			
<a href="#">DT06-6S-EPO6</a>	NO			"ZPF00000000130364", "DT06-6S-EP06-LD", "DT06-6S-EP06-LS", "DT06-6S-EP06-MS", "DT06-6S-EP06-L", "DT06-6S-EP06-M"			

Customer: Future Electronics Inc( 1290208 )

Location: Southaven

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DT04-08PA-E008</a>	NO			"ZPF00000000130416"			
<a href="#">DT04-2P-CE01</a>	NO			"ZPF00000000130154"			
<a href="#">DT04-2P-CE03</a>	NO			"ZPF00000000130156"			
<a href="#">DT04-2P-E005</a>	NO			"ZPF00000000130163", "DT04-2P-E005-LD", "DT04-2P-E005-LS", "DT04-2P-E005-MS", "DT04-2P-E005-L", "DT04-2P-E005-M"			
<a href="#">DT04-3P-E003</a>	NO			"ZPF00000000130216"			
<a href="#">DT04-3P-E005</a>	NO			"ZPF00000000130218", "DT04-3P-E005-LD", "DT04-3P-E005-LS", "DT04-3P-E005-MS", "DT04-3P-E005-L", "DT04-3P-E005-M"			
<a href="#">DT06-12SA-CE13</a>	NO			"ZPF00000000130675"			
<a href="#">DT06-2S-E008</a>	NO			"ZPF00000000130185"			
<a href="#">DT06-2S-EPO6</a>	NO			"ZPF00000000130180", "DT06-2S-EP06-LD", "DT06-2S-EP06-LS", "DT06-2S-EP06-MS", "DT06-2S-EP06-E", "DT06-2S-EP06-L", "DT06-2S-EP06-M"			
<a href="#">DT06-2S-EPO6</a>	NO			"ZPF00000000130180", "DT06-2S-EP06-LD", "DT06-2S-EP06-LS", "DT06-2S-EP06-MS", "DT06-2S-EP06-E", "DT06-2S-EP06-L", "DT06-2S-EP06-M"			
<a href="#">DT06-3S-CE13</a>	NO			"ZPF00000000130231"			
<a href="#">DT06-3S-EPO6</a>	NO			"ZPF00000000130240", "DT06-3S-EP06-LD", "DT06-3S-EP06-LS", "DT06-3S-EP06-MS", "DT06-3S-EP06-L", "DT06-3S-EP06-M"			
<a href="#">DT06-4S-E003</a>	NO			"ZPF00000000130318"			
<a href="#">DT06-6S-CE05</a>	NO			"ZPF00000000130360", "DT06-6S-CE05-MS", "DT06-6S-CE05-SC", "DT06-6S-CE05-M", "DT06-6S-CE05-S"			
<a href="#">DT06-6S-EPO6</a>	NO			"ZPF00000000130364", "DT06-6S-EP06-LD", "DT06-6S-EP06-LS", "DT06-6S-EP06-MS", "DT06-6S-EP06-L", "DT06-6S-EP06-M"			

Customer: Future Electronics Inc( 1290208 )

Location: Southaven

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">DT04-08PA-E008</a>	NO			"ZPF000000000130416"			
<a href="#">DT04-2P-CE01</a>	NO			"ZPF000000000130154"			
<a href="#">DT04-2P-CE03</a>	NO			"ZPF000000000130156"			
<a href="#">DT04-2P-E005</a>	NO			"ZPF000000000130163", "DT04-2P-E005-LD", "DT04-2P-E005-LS", "DT04-2P-E005-MS", "DT04-2P-E005-L", "DT04-2P-E005-M"			
<a href="#">DT04-3P-E003</a>	NO			"ZPF000000000130216"			
<a href="#">DT04-3P-E005</a>	NO			"ZPF000000000130218", "DT04-3P-E005-LD", "DT04-3P-E005-LS", "DT04-3P-E005-MS", "DT04-3P-E005-L", "DT04-3P-E005-M"			
<a href="#">DT06-12SA-CE13</a>	NO			"ZPF000000000130675"			
<a href="#">DT06-2S-E008</a>	NO			"ZPF000000000130185"			
<a href="#">DT06-2S-EP06</a>	NO			"ZPF000000000130180", "DT06-2S-EP06-LD", "DT06-2S-EP06-LS", "DT06-2S-EP06-MS", "DT06-2S-EP06-E", "DT06-2S-EP06-L", "DT06-2S-EP06-M"			
<a href="#">DT06-2S-EP06</a>	NO			"ZPF000000000130180", "DT06-2S-EP06-LD", "DT06-2S-EP06-LS", "DT06-2S-EP06-MS", "DT06-2S-EP06-E", "DT06-2S-EP06-L", "DT06-2S-EP06-M"			
<a href="#">DT06-3S-CE13</a>	NO			"ZPF000000000130231"			
<a href="#">DT06-3S-EP06</a>	NO			"ZPF000000000130240", "DT06-3S-EP06-LD", "DT06-3S-EP06-LS", "DT06-3S-EP06-MS", "DT06-3S-EP06-L", "DT06-3S-EP06-M"			
<a href="#">DT06-4S-E003</a>	NO			"ZPF000000000130318"			
<a href="#">DT06-6S-CE05</a>	NO			"ZPF000000000130360", "DT06-6S-CE05-MS", "DT06-6S-CE05-SC", "DT06-6S-CE05-M", "DT06-6S-CE05-S"			
<a href="#">DT06-6S-EP06</a>	NO			"ZPF000000000130364", "DT06-6S-EP06-LD", "DT06-6S-EP06-LS", "DT06-6S-EP06-MS", "DT06-6S-EP06-L", "DT06-6S-EP06-M"			