

**【Revision and Reissue】**

**HIROSE ELECTRIC CO., LTD.**  
5-23, OSAKI 5-CHOME, SHINAGAWA-KU, TOKYO, JAPAN

**Product Change Notification**

We've already announced we would start to manufacture domestic products in China (Dongguan) and Indonesia factory. However, we're writing to inform you that we changed a part of contents of the notice. We're sincerely apologize the inconvenience this may cause.

Please inform you that again and request that you kindly offer your consent to this matter.

In addition, this is to add production site so there will be no change in production method, material and so on. Please refer to the attached on details of this change.

1	Products affected	Please refer to the attached.																																																																																																								
2	Classification of Change	Addition to production site																																																																																																								
3	Change	<p>Regarding the affected series produced in Japan factory as described below, they will be produced in ①Japan factory or China (Dongguan) factory, ②Japan factory or Indonesia factory from now.</p> <p>Japan factory will be the mother factory for the products, and keep control on production to shipment as ever.</p> <p><u>Revision</u> : Rescheduled...timing to add production site is rescheduled Canceled...plan to add production site is canceled</p> <table border="1"> <thead> <tr> <th rowspan="2">Affected series</th> <th rowspan="2">Revision</th> <th rowspan="2">the Number of products</th> <th rowspan="2">Mother factory</th> <th colspan="2">Production site</th> </tr> <tr> <th>Current</th> <th>After the change</th> </tr> </thead> <tbody> <tr> <td>LF07</td> <td>Rescheduled</td> <td>2</td> <td rowspan="16">ICHINOSEKI HIROSE ELECTRIC CO., LTD.</td> <td rowspan="16">Japan</td> <td rowspan="6">Japan/China (Dongguan)</td> </tr> <tr> <td>LF10</td> <td>Rescheduled</td> <td>12</td> </tr> <tr> <td>LF13</td> <td>Rescheduled</td> <td>8</td> </tr> <tr> <td>RM12</td> <td>Rescheduled</td> <td>13</td> </tr> <tr> <td>RM15</td> <td>Rescheduled</td> <td>102</td> </tr> <tr> <td>RM21</td> <td>Rescheduled</td> <td>16</td> </tr> <tr> <td>RM24</td> <td>Rescheduled</td> <td>9</td> <td rowspan="10">KORIYAMA HIROSE ELECTRIC CO., LTD.</td> <td rowspan="10">Japan</td> <td rowspan="10">Japan/Indonesia</td> </tr> <tr> <td>RM31</td> <td>Rescheduled</td> <td>4</td> </tr> <tr> <td>RPC</td> <td>Rescheduled</td> <td>3</td> </tr> <tr> <td>RP6</td> <td>Rescheduled</td> <td>1</td> </tr> <tr> <td>RP13</td> <td>Rescheduled</td> <td>7</td> </tr> <tr> <td>RP20</td> <td>Rescheduled</td> <td>1</td> </tr> <tr> <td>RP37</td> <td>Rescheduled</td> <td>11</td> </tr> <tr> <td>CR6</td> <td>Canceled</td> <td>10</td> </tr> <tr> <td>DF1EC</td> <td>Rescheduled</td> <td>9</td> </tr> <tr> <td></td> <td>Canceled</td> <td>18</td> </tr> <tr> <td>FX8C</td> <td>Rescheduled</td> <td>7</td> <td rowspan="12"></td> <td rowspan="12"></td> <td rowspan="12">Japan/Indonesia</td> </tr> <tr> <td></td> <td>Canceled</td> <td>36</td> </tr> <tr> <td>A2</td> <td>Rescheduled</td> <td>11</td> </tr> <tr> <td></td> <td>Canceled</td> <td>21</td> </tr> <tr> <td>A3</td> <td>Rescheduled</td> <td>2</td> </tr> <tr> <td></td> <td>Canceled</td> <td>25</td> </tr> <tr> <td>3560</td> <td>Canceled</td> <td>2</td> </tr> <tr> <td>TM5</td> <td>Canceled</td> <td>10</td> </tr> <tr> <td>MQ172</td> <td>Canceled</td> <td>3</td> </tr> <tr> <td>TM2REAX</td> <td>Canceled</td> <td>1</td> </tr> <tr> <td>1600</td> <td>Canceled</td> <td>30</td> </tr> <tr> <td>EX10E</td> <td>Canceled</td> <td>2</td> </tr> <tr> <td>EX10F</td> <td>Canceled</td> <td>1</td> </tr> </tbody> </table>	Affected series	Revision	the Number of products	Mother factory	Production site		Current	After the change	LF07	Rescheduled	2	ICHINOSEKI HIROSE ELECTRIC CO., LTD.	Japan	Japan/China (Dongguan)	LF10	Rescheduled	12	LF13	Rescheduled	8	RM12	Rescheduled	13	RM15	Rescheduled	102	RM21	Rescheduled	16	RM24	Rescheduled	9	KORIYAMA HIROSE ELECTRIC CO., LTD.	Japan	Japan/Indonesia	RM31	Rescheduled	4	RPC	Rescheduled	3	RP6	Rescheduled	1	RP13	Rescheduled	7	RP20	Rescheduled	1	RP37	Rescheduled	11	CR6	Canceled	10	DF1EC	Rescheduled	9		Canceled	18	FX8C	Rescheduled	7			Japan/Indonesia		Canceled	36	A2	Rescheduled	11		Canceled	21	A3	Rescheduled	2		Canceled	25	3560	Canceled	2	TM5	Canceled	10	MQ172	Canceled	3	TM2REAX	Canceled	1	1600	Canceled	30	EX10E	Canceled	2	EX10F	Canceled	1
Affected series	Revision	the Number of products					Mother factory	Production site																																																																																																		
			Current	After the change																																																																																																						
LF07	Rescheduled	2	ICHINOSEKI HIROSE ELECTRIC CO., LTD.	Japan	Japan/China (Dongguan)																																																																																																					
LF10	Rescheduled	12																																																																																																								
LF13	Rescheduled	8																																																																																																								
RM12	Rescheduled	13																																																																																																								
RM15	Rescheduled	102																																																																																																								
RM21	Rescheduled	16																																																																																																								
RM24	Rescheduled	9			KORIYAMA HIROSE ELECTRIC CO., LTD.	Japan	Japan/Indonesia																																																																																																			
RM31	Rescheduled	4																																																																																																								
RPC	Rescheduled	3																																																																																																								
RP6	Rescheduled	1																																																																																																								
RP13	Rescheduled	7																																																																																																								
RP20	Rescheduled	1																																																																																																								
RP37	Rescheduled	11																																																																																																								
CR6	Canceled	10																																																																																																								
DF1EC	Rescheduled	9																																																																																																								
	Canceled	18																																																																																																								
FX8C	Rescheduled	7			Japan/Indonesia																																																																																																					
	Canceled	36																																																																																																								
A2	Rescheduled	11																																																																																																								
	Canceled	21																																																																																																								
A3	Rescheduled	2																																																																																																								
	Canceled	25																																																																																																								
3560	Canceled	2																																																																																																								
TM5	Canceled	10																																																																																																								
MQ172	Canceled	3																																																																																																								
TM2REAX	Canceled	1																																																																																																								
1600	Canceled	30																																																																																																								
EX10E	Canceled	2																																																																																																								
EX10F	Canceled	1																																																																																																								
4	Reason for change	To improve productivity																																																																																																								
5	Timing of change	Please refer to the attached.																																																																																																								
6	Date of your acknowledgement	Please refer to the attached.																																																																																																								

We kindly request that you inform Hirose business representative of your acknowledgement by the aforesaid date.

In the absence of a response by this date, please be advised the product that described above will be delivered.

If you should have any questions, please feel free to contact a Hirose business representative.

Your understanding and cooperation are highly appreciated.









**Acknowledgement**

(Customer → Hirose Electric business representative)

**Product Change Notification**  
**Request for Your Acknowledgement**

We acknowledge the aforementioned matter.

Customer's name: \_\_\_\_\_

Acknowledgement stamp (or signature): \_\_\_\_\_

HIROSE ELECTRIC CO., LTD.

-----  
(Cut on this line)

**Document Receipt**

(Customer → Hirose Electric business representative)

**Product Change Notification**  
**Request for Your Acknowledgement**

We received the document concerning the above.

Customer's name: \_\_\_\_\_

Acknowledgment stamp (or signature): \_\_\_\_\_

HIROSE ELECTRIC CO., LTD.