

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	012	0000000529	See list below	Circuit protection	FAU socket	n/a

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)



List of part numbers affected				
0031.3573	0031.3577			

## 2 Type of change

- Change of packaging

## 3 Detailed description of change

We are going to layer the products and separate the layers by foam. The total quantity each box will not change:

Old product appearance	New product appearance
<b>Bulk packaging</b> 	<b>General cargo packaging</b> 

## 4 Reason of change

- Due to the bulk packaging it sometimes happened that some terminals got bent. We expect to improve the quality rate extensively.

## 5 Release date

The change takes effect in ww 03/2018 (Date code 1803 or higher on label).

## 6 Impact of change and recommended action

Form	No	No change in form
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	Yes	Packaging improvement

## 7 Reference Documents / Attachments

Kind of document	Remarks
<a href="#">Data Sheet</a>	

Product Change Notification					FAU packaging improvement		
owner	creation date	release date	released by	change order no	rev	page	D10-022-461
zbindeja	12.01.2018	15.01.2018	haeckima	2014519	A	1 of 1	