

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	063	0000000598	0031.1667	Circuit protection	FEU fingergrip carrier 6.3x32	n/a
			0000000685	0031.1812		FEU (Grip) carrier 6.3x32	
				0031.1761		FEU with fingergrip 6.3x32	
		003	0000000523	0031.1765		FEU with fingergrip 6.3x32	
				0031.1755		FEU with fingergrip 6.3x32	
						FEU with fingergrip 6.3x32	
			0000000679	0031.1804		FEU (Grip) with fuse carrier 6.3x32	



\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

## 2 Type of change

- Improved electrical contact

## 3 Detailed description of change

The contact spring on FEU finger grip carrier and FEU (Grip) carrier for 6.3x32mm fuse is improved.

Old holding spring	New holding spring
	

## 4 Reason of change

Product improvement.

## 5 Release date

The change will be rolled-out starting ww 06/2018 (Date code 1806 or higher on label) and lasts approx. 6 months, depending on stock.

## 6 Impact of change and recommended action

Form	Yes	Contact spring of fuse carrier changed
Fit	No	No change for dimension
Function	No	No functional change
Production Site	No	No change of the production site
Product Label	No	No label on the change
Packaging	No	No change in packaging

## 7 Reference Documents / Attachments

Kind of document	Remarks
<a href="#">Data sheet</a>	Fusecarrier FEU
<a href="#">Data sheet</a>	Fuseholder FEU grip
<a href="#">Data sheet</a>	Fusecarrier FEU grip

Product Change Notification					FEU fingergrip improvement		
owner	creation date	release date	released by	change order no	rev	page	D10-016-241
dislercy	08.06.2017	21.12.2017	haeckima	2013038	A	1 of 1	

SCHURTER INC  
447 Aviation Boulevard  
Santa Rosa, CA 95403



TEL 707 636 3000  
FAX 707 636 3033  
[www.schurter.com](http://www.schurter.com)

January 30, 2018

Hello,

SCHURTER strives to offer the highest level of customer satisfaction with our products and services. This is why SCHURTER Inc. is informing you of a product improvement that is being made to SCHURTER's FEU series.

Please see the official Product Change Notice which is located on the SCHURTER website at [www.schurter.com](http://www.schurter.com).

For your convenience, attached is an Excel spreadsheet with the complete list of part numbers impacted by this improvement. These part numbers are also listed in the PCN. Also attached for your convenience is an Excel spreadsheet that lists the names of the customers and the part numbers and quantities of the parts they have purchased from you since 2015.

For any technical questions about these changes, please contact Nikila Kareesan at [nkareesan@schurterinc.com](mailto:nkareesan@schurterinc.com) or by phone at (707) 636-5497.

For all other questions, feel free to contact your SCHURTER, Inc. Inside Sales Representative.

Best Regards,

A handwritten signature in black ink that reads 'Gisela Babb'.

Gisela Babb

Quality Manager  
SCHURTER, Inc.

447 Aviation Blvd.  
Santa Rosa CA 95403  
Direct Phone (707) 636-5493