

## PRODUCT CHANGE NOTIFICATION (PCN)

<b>PCN#</b>	WPC-180306-001	<b>Issuing Date</b>	March 06 <sup>th</sup> , 2018
-------------	----------------	---------------------	-------------------------------

**PRODUCT(S) AFFECTED :**

**Attachment:** Yes No


Product Name	Description	Supplying Schedule
W5500 Ethernet Shield	Revision: Rev1.0 → Rev1.1	March 06 <sup>th</sup> , 2018

**Description of Changes**

In Rev 1.0, GND pin of "RESET" button(S1) was floating.

This change in Rev1.1 will solve the floating problem. (Connect to GND with adding VIA.)

Refer to below picture.



**DISTRIBUTORS NOTIFICATION :**

**DISTRIBUTOR ACKNOWLEDGEMENT :** Distributors may use this form to acknowledge receipt of this notification. Please fill in the below form and return it to us.

Distributor	Date	
Name	Title	
E-mail		
Comments		