



Not Recommended for New Design: PAN93x0, PAN90x5 Series WiFi RF Modules

NRFND.PG15.9.17.2019

9.17.2019

About This Notice:	Please be advised that the PAN93x0 and PAN90x5 Series WiFi RF Modules from Panasonic are now designated as Not Recommended For New Design due to low market demand.
Features:	N/A
Effective Date:	Immediate
Affected Parts and/or Replacements:	See Attached.
Datasheet(s):	See Attached.
Notes:	

Panasonic NRFND.PG15.9.17.2019

Affected Series And Part Numbers

NRFND		Recommended Replacements	
Series Name	Affected Parts	Series Name	Recommended Replacement
PAN9320	ENW-49A01A3EF ENW-49A02A3EF	PAN9420	ENW-49C01A3KF
PAN9310	ENW-49A01C3EF ENW-49A02C3EF	PAN9420	ENW-49C02A3KF
PAN9055	ENW-F9101A1JF ENW-F9101A1EF	PAN9026	ENW-F9209A1EF
PAN9045	ENW-F9101C1JF ENW-F9101C1EF	PAN9026	ENW-F9209A1EF