

### 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description
SBU	PG	PUG	Type			
02	007	051	0000002103	See list in attached file	Connectors	Cordsets 2.5 A
02	007	051	0000002104		Connectors	Cordsets 10 A
02	007	051	0000002105		Connectors	Cordsets 16 A
02	007	051	0000002959		Connectors	VAC13KS V-Lock Cordset
02	007	051	0000002960		Connectors	VAC17KS V-Lock Cordset
02	007	051	0000002961		Connectors	VAC19KS V-Lock Cordset

### 2 Type of change

- Modified packaging label
- Modified product label

### 3 Detailed description of change

Old packaging label (standard size)	New packaging label (standard size)
Old product label (example for V-Lock cord set)	New product label (example for V-Lock cord set)

### 4 Reason of change

A new WEEE regulation sets for potential b2c products a new labelling requirement (stroke-through wheeled bin) for the European market.

### 5 Release date

The change has been rolled-out starting ww 50/2019 (Date code 1950 or higher on label) and lasts approx. 8 months depending on the stock variant.

### 6 Impact of change and recommended action

Form	No	-
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	Yes	Addition of packaging label and product label.
Packaging	No	-

Product Change Notification					PCN - Change of cordset label		
owner	creation date	release date	released by	change order no	rev	page	D10-037-841
bachmajo	26.06.2019	16.12.2019	limachcl	2017893	A	1 of 2	

**7 Reference Documents / Attachments**

Please find the corresponding article number list attached in the official mailing as well as in the SCHURTER Partner Service on our website.

Product Change Notification					PCN - Change of cordset label		
owner	creation date	release date	released by	change order no	rev	page	D10-037-841
bachmajo	26.06.2019	16.12.2019	limachcl	2017893	A	2 of 2	